Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Oct'2026
Year: 2026

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI/AEI	Remedies suggested by CEI/EI/AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	**Chandni Chowk:** A "current on pole" complaint (260401100978) was at 18:44 hrs received from 4582, Cloth Market, Chandni Chowk, Delhi. As per complainant, an unidentified person was electrocuted while repairing a shop shed; however, no victim was found at site. NCC staff reached the site promptly. The team identified current leakage from an inverter through the internal wiring of Shop No. 4586. The matter was informed to and recorded in the presence of the IO, Delhi Police, P.S. Lahori Gate.	01.04.2026	Public (Fatal)	Based on site inspection, probable cause is consumer Internal wiring.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
2	A PCR complaint (26042200951) regarding current leakage was received from Gali No. 1, Khajani Nagar, Delhi-110094. Site inspection revealed that a sewer cleaning vehicle DL-1L Z1214 driven by Sh. Narender S/o Sh. Rampal, hit HT pole No. KWNZ808, causing it to tilt/fall onto the wall of House No. 40, Khajani Nagar, Delhi. Two ladies (approx. 22–30 years) suffered electric shock. Supply was restored by installing a new RCC pole with 25 kVA DT after police clearance.	22.04.2026	Public (Non-Fatal)	Probable cause is HT pole damage due to vehicle hit (DL-1L Z1214) leading to pole tilting.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
3	The 33 kV feeder (Ghonda Grid–Seelampur Grid, Ckt-2) tripped at 21:18 hrs on 15.09.2026 due to a cable fault. The feeder was restored at 23:37 hrs by energising the healthy cable. On 16.09.2026, FLC pinpointed the fault near Gali No. 29, Jafrabad Road (Nala side), where RCC protection covers were found missing and the cable damaged, indicating suspected external interference. Local inputs suggested that an unidentified person may have struck the cable, resulting in an electrical flash and subsequent hospitalisation. However, the person remains untraced, and no incident was officially reported to BYPL. The cable was subsequently repaired and RCC covers reinstated. CC protection work is in progress.	15.09.2026	Public (Non-Fatal)	Based on site inspection, probable cause is illegal interference with BYPL network.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
4	The 66 kV Harsh Vihar–Ghonda Grid feeder (Ckt-1) tripped at 08:10 hrs on 18.09.2026. PC results and feeder patrolling were found healthy, and the feeder was restored at 09:30 hrs. Subsequently, BYPL System Control reported a meter fire at D-504, Gali No. 2, Ashok Nagar, Main Wazirabad Road, Delhi-110093. On inspection, one single-phase energy meter was found burnt and bypassed. It was also learnt that one person sustained non-fatal electric shock while shifting an iron pipe from the top floor to the lower floor and was admitted to Rajeev Gandhi Trauma Centre, Tahirpur.	18.09.2026	Public (Non-Fatal)	Based on site inspection, probable cause is illegal interference with BYPL network.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
5	On 23.10.2026, at approximately 17:45 hrs, a public complaint was received at Mukhiya Market Complaint Centre regarding an incident at House No. D-112, D-Block, Gali No. 3, Harijan Basti, Karawal Nagar, during tile-fixing work. BYPL team reached the site and observed bamboo scaffolding erected near the HVDS network without prior intimation. The person engaged in the work reportedly came in contact with the HV line. Police were present at the site. PCR complaint No. 26102300983 regarding a reported house fire was received at 19:09 hrs; however, no fire was observed. Supply was restored at 20:45 hrs after ensuring site safety. The incident was telephonically reported to the concerned Electrical Inspector on 24.10.2026.	23.10.2026	Public (Fatal)	Based on site inspection, probable cause is illegal interference with BYPL network.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA

(Signature of the Licensee)