

Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: July’ 2025
Year: 2025

Sl. No .	Location Of Accident t and Details Of Victim	Date of occurrence	Type of accident	Cause of accide nt	Findings of CEI/E I /AEI	Remedi es sugges ted by CEI/EI /AEI in various cases	Whethe r the remedy suggest ed is complie d	Action taken to avoid recurren ce of such accident S	Amount paid as compen sa Tion
1	A no supply complaint was received at 12:11 AM. On-site inspection revealed that sewer digging work by SKV School had damaged a 4*300 sqmm LT cable belonging to BYPL. As per local residents, a laborer suffered a flash injury during the incident.	06.04.2025	Non-Fatal	Based on site inspection, probable cause is Interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA

(Signature of the Licensee)