

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Sep’ 2026
Year: 2026

Sl. No.	Location Of Accident and Details Of Victim	Date of Occurrence	Type of Accident	Cause of Accident	Findings of CEI/EI/AEI	Remedies suggested by CEI/EI/AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	Chandni Chowk: A “current on pole” complaint (260401100978) was at 18:44 hrs received from 4582, Cloth Market, Chandni Chowk, Delhi. As per complainant, an unidentified person was electrocuted while repairing a shop shed; however, no victim was found at site. NCC staff reached the site promptly. The team identified current leakage from an inverter through the internal wiring of Shop No. 4586. The matter was informed to and recorded in the presence of the IO, Delhi Police, P.S. Lahori Gate.	01.04.2026	Public (Fatal)	Based on site inspection, probable cause is consumer Internal wiring.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
2	A PCR complaint (26042200951) regarding current leakage was received from Gali No. 1, Khajani Nagar, Delhi-110094. Site inspection revealed that a sewer cleaning vehicle DL-1L Z1214 driven by Sh. Narender S/o Sh. Rampal, hit HT pole No. KWNZ808, causing it to tilt/fall onto the wall of House No. 40, Khajani Nagar, Delhi. Two ladies (approx. 22–30 years) suffered electric shock. Supply was restored by installing a new RCC pole with 25 kVA DT after police clearance.	22.04.2026	Public (Non-Fatal)	Probable cause is HT pole damage due to vehicle hit (DL-1L Z1214) leading to pole tilting.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
3	33KV feeder from Ghonda Grid to Seelampur Grid Ckt-2, tripped off at 21:18 Hrs. on 15.09.2026. Our Breakdown team comprising of Sh. Pawan Kumar, Sr. Mgr(O) & Sh. Karan Singh, AM(O), take PC results and 01 number (out of two) 33KV cable faulty, and CKT energised on 2nd healthy cable at 23:37 Hrs. dated 15.09.2026. During cable route patrolling of this feeder, no digging observed. On dated 16.09.2026, FLC team was called for pin-point the fault location and found RCC covers were missing and damage/cut on the 33KV EHV cable at the fault pin-point location at opposite gali no. 29,Jafrabad Road (Towards Nala Side),12:05 Hrs. This seems that some external hit / force is applied on this cable intentionally for some ulterior motive. Our team approached the site for cable fault revival work at around 17:00 Hrs. on 16.09.2026 where some local persons informed us about the last night incident: This cable was hit by an unknown person and during this an electric flash occurred from this cable on his face and his allies took him to hospital for treatment). The person is still un-traced and not any authority notified this incident in our notice. After the faulty cable revival work, this cable is covered with RCC protection covers and is in process to cover with CC layer.	15.09.2026	Public (Non-Fatal)	Illegal interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
4	66kv Harsh Vihar to Ghonda, Ckt. No. 01 of BYPL, at D-504, Gali No.2, Ashok Nagar, Main Wazirabad Road, Delhi-110093. 66KV feeder from Harsh Vihar Grid to Ghonda Grid Ckt-1, tripped off at 08:10 Hrs. on 18.09.2026. Our Breakdown team comprising of Sh. Raj Kumar Sharma A.M.(O) and Sh. Kamal Kishor, Sr. Asstt. Mgr. (O), take PC results and found results healthy. During feeder patrolling no abnormality noticed. Line clearance given to BYPL system control and CKT energised on at 09:30 Hrs. dated 18.09.2026. As per message received from BYPL system control at 08:20 Hrs. today, regarding fire in electricity meter. During inspection by BYPL 11KV team 01 number single phase energy meter found burnt at above said address and same was by-passed. During this visit, it came in the notice of BYPL lineman that one number person was electrocuted today at this site, while doing the iron pipe shifting work from top floor to lower floor and he was admitted (Non-Fatal) in Rajeev Gandhi Trauma Centre, Tahir Pur.	18.09.2026	Public (Non-Fatal)	Illegal interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA

(Signature of the Licensee)