

Name of Distribution Licensee: BSES Rajdhani Power Limited												
Period of Outage: OCTOBER 2025												
Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1	01-10-2025	Part of : D-BLOCK KALKA JI,	239	Other Outage	Planned Outage	01-10-2025	10:46	01-10-2025	13:41	2:55	0.001458	REPLACEMENT OF LT BUSHING ROD,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
2	02-10-2025	Part of : J2-BLOCK DDA FLAT KALKA JI,ALAKNANDA SHOPPING COMPLEX,BLOCK J 3 GOVINDPURI KALKAJI	3359	Other Outage	Unplanned Outage	02-10-2025	18:05	02-10-2025	18:57	0:52	0.001748	CABLE FAULT
3	03-10-2025	Part of : NILGIRI APARTMENT	196	Other Outage	Planned Outage	03-10-2025	11:00	03-10-2025	13:10	2:10	0.000000	REPLACEMET OF HT BUSHING ROD
4	03-10-2025	Part of : A10-BLOCK KALKA JI EXTN	1191	Other Outage	Planned Outage	03-10-2025	11:10	03-10-2025	13:56	2:46	0.000000	REPLACEMENT OF LT BUSHING ROD
5	04-10-2025	Part of : GOVINDPURI EXTENSION KALKAJI	1440	Other Outage	Planned Outage	04-10-2025	11:15	04-10-2025	13:40	2:25	0.001208	REPLACEMENT OF LT BUSHING ROD,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
6	04-10-2025	Part of : TUGHLAQABAD VILLAGE	1415	Other Outage	Planned Outage	04-10-2025	11:06	04-10-2025	13:40	2:34	0.004278	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
7	05-10-2025	Part of : B-BLOCK OKHLA PHASE-1,	224	Other Outage	Planned Outage	05-10-2025	10:26	05-10-2025	13:45	3:19	0.003869	APPLY OF INSULATION TAPE HT/LT BUSHINGS,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
8	06-10-2025	Part of : C-BLOCK KALKA JI ,1-BLOCK KALKA JI,2-BLOCK KALKA JI,9-BLOCK KALKA JI	1537	Other Outage	Unplanned Outage	06-10-2025	06:29	06-10-2025	07:07	0:38	0.000697	HT SYSTEM FAULT
9	06-10-2025	Part of : KALI MANDIR SOCIETY CHITTARANJAN PARK	422	Other Outage	Planned Outage	06-10-2025	11:21	06-10-2025	13:18	1:57	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
10	06-10-2025	Part of : TUGHLAKABAD EXTN	1445	Other Outage	Planned Outage	06-10-2025	11:15	06-10-2025	13:16	2:01	0.000034	REPLACEMENT OF LT BUSHING ROD
11	07-10-2025	Part of : BALAJI ESTATE KALKAJI	12	Other Outage	Planned Outage	07-10-2025	11:05	07-10-2025	13:42	2:37	0.003925	REPLACEMET OF HT BUSHING ROD
12	08-10-2025	Part of : B-BLOCK CR PARK	682	Other Outage	Planned Outage	08-10-2025	11:43	08-10-2025	15:01	3:18	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD
13	08-10-2025	Part of : TUGHLAKABAD EXTN.	1659	Other Outage	Planned Outage	08-10-2025	11:07	08-10-2025	14:16	3:09	0.000053	REPLACEMET OF HT BUSHING ROD
14	09-10-2025	Part of : TUGHLAKABAD EXTN	5216	Other Outage	Unplanned Outage	09-10-2025	11:59	09-10-2025	12:51	0:52	0.001199	CABLE FAULT
15	09-10-2025	Part of : NARMADA APARTMENT,YAMUNA APARTMENT,L1-BLOCK LIG KALKA JI,ARAWALI SHOPPING CENTRE,GODAVARI APARTMENT,ARAWALI APARTMENT,NILGIRI APARTMENT,	2336	Other Outage	Planned Outage	09-10-2025	14:37	09-10-2025	16:05	1:28	0.000024	TIGHTENING OF HARDWARE FITTINGS
16	09-10-2025	Part of : TUGHLAQABAD VILLAGE TUGHLAKABAD,	1795	Other Outage	Planned Outage	09-10-2025	10:49	09-10-2025	14:35	3:46	0.004394	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD
17	09-10-2025	Part of : TUGHLAKABAD EXTN,	2291	Other Outage	Planned Outage	09-10-2025	11:06	09-10-2025	13:56	2:50	0.000047	REPLACEMENT OF LT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
18	11-10-2025	Part of : CONTAINER DEPOT (HT CONSUMER)	2	Other Outage	Unplanned Outage	11-10-2025	12:00	11-10-2025	12:40	0:40	0.000000	FAULT IN HT CONSUMER PANEL (CONTAINER DEPOT)
19	11-10-2025	Part of : 1-BLOCK KALKA JI	81	Other Outage	Planned Outage	11-10-2025	11:07	11-10-2025	13:41	2:34	0.001283	REPLACEMENT OF HT BUSHING ROD
20	12-10-2025	Part of : EFFULIANT TREATMENT PLANT (HTC)	0	Other Outage	Unplanned Outage	12-10-2025	17:14	12-10-2025	17:57	0:43	0.000179	FAULT IN HT CONSUMER PANEL (ETP)
21	12-10-2025	Part of : A-BLOCK OKHLA PHASE-1	309	Other Outage	Planned Outage	12-10-2025	10:35	12-10-2025	14:03	3:28	0.005778	DT OIL SAMPLING TO CHECK BDV VALUE,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD
22	13-10-2025	Part of : TUGHLAKABAD EXTN,	1404	Other Outage	Planned Outage	13-10-2025	11:13	13-10-2025	14:05	2:52	0.000048	REPLACEMENT OF HT BUSHING ROD
23	13-10-2025	Part of : POCKET 52 CHITTARANJAN PARK,	254	Other Outage	Planned Outage	13-10-2025	10:58	13-10-2025	13:41	2:43	0.000906	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
24	13-10-2025	Part of : H-BLOCK KALKA JI,	418	Other Outage	Planned Outage	13-10-2025	11:02	13-10-2025	14:01	2:59	0.003729	REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
25	14-10-2025	Part of : E-BLOCK CR PARK	596	Other Outage	Planned Outage	14-10-2025	10:54	14-10-2025	14:14	3:20	0.001111	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
26	14-10-2025	Part of : C-BLOCK KALKA JI	935	Other Outage	Planned Outage	14-10-2025	11:06	14-10-2025	13:57	2:51	0.001425	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
27	14-10-2025	Part of : M-BLOCK GK-2	137	Other Outage	Planned Outage	14-10-2025	09:46	14-10-2025	12:06	2:20	0.000000	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
28	15-10-2025	Part of : TUGHLAKABAD EXTN.	3192	Other Outage	Planned Outage	15-10-2025	11:15	15-10-2025	14:22	3:07	0.000000	REPLACEMENT OF HT BUSHING ROD
29	15-10-2025	Part of : N-BLOCK CHITTARANJAN PARK	221	Other Outage	Planned Outage	15-10-2025	11:08	15-10-2025	14:21	3:13	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
30	15-10-2025	Part of : TUGHLAQABAD VILLAGE	679	Other Outage	Planned Outage	15-10-2025	11:21	15-10-2025	14:01	2:40	0.001111	LT CIRCUIT MAINTENANCE WORK
31	16-10-2025	Part of : TUGHLAKABAD EXTN	1280	Other Outage	Planned Outage	16-10-2025	11:18	16-10-2025	13:55	2:37	0.000000	REPLACEMENT OF LT BUSHING ROD
32	16-10-2025	Part of : SUBASH KHAND GOVINDPURI	415	Other Outage	Planned Outage	16-10-2025	11:05	16-10-2025	13:53	2:48	0.003267	REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
33	17-10-2025	Part of : TUGHLAKABAD EXTN,	1592	Other Outage	Planned Outage	17-10-2025	10:59	17-10-2025	13:58	2:59	0.000000	REPLACEMENT OF LT BUSHING ROD
34	17-10-2025	Part of : TUGHLAQABAD VILLAGE TUGHLAKABAD,	375	Other Outage	Planned Outage	17-10-2025	12:01	17-10-2025	14:57	2:56	0.000733	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF HT BUSHING ROD
35	18-10-2025	Part of : D-BLOCK KALKA JI	331	Other Outage	Planned Outage	18-10-2025	11:37	18-10-2025	13:31	1:54	0.001900	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
36	22-10-2025	Part of : 16-BLOCK KALKA JI	440	Other Outage	Planned Outage	22-10-2025	11:00	22-10-2025	15:28	4:28	0.006700	REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
37	24-10-2025	Part of : BLOCK BB ENCLAVE 2 GREATER KAILASH	307	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	13:45	2:24	0.000800	REPLACEMENT OF LT BUSHING ROD
38	25-10-2025	Part of : TUGHLAKABAD EXTN,	1173	Other Outage	Planned Outage	25-10-2025	11:16	25-10-2025	13:54	2:38	0.000000	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
39	25-10-2025	Part of : SHAHEED RAJIV GANDHI COLONY GOVINDPURI,	1766	Other Outage	Planned Outage	25-10-2025	11:09	25-10-2025	13:57	2:48	0.005600	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
40	26-10-2025	Part of : TEHKHAND VILLAGE	2008	Other Outage	Unplanned Outage	26-10-2025	04:56	26-10-2025	05:49	0:53	0.000559	HT SYSTEM FAULT
41	26-10-2025	Part of : HINDUSTAN STEEL YARD,D-BLOCK OKHLA PHASE-1,B-BLOCK OKHLA PHASE-1,TEHKHAND TELEPHONE EXCHANGE	572	Other Outage	Unplanned Outage	26-10-2025	04:56	26-10-2025	05:49	0:53	0.000442	HT SYSTEM FAULT
42	26-10-2025	Part of : EFFULIANT TREATMENT PLANT (HTC)	80	Other Outage	Planned Outage	26-10-2025	10:58	26-10-2025	13:52	2:54	0.002417	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
43	28-10-2025	Part of : F-BLOCK OKHLA PHASE-1	731	Other Outage	Unplanned Outage	28-10-2025	18:25	28-10-2025	19:06	0:41	0.000672	CABLE FAULT
44	28-10-2025	Part of : H-BLOCK KALKA JI	597	Other Outage	Planned Outage	28-10-2025	11:10	28-10-2025	14:03	2:53	0.003604	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTTENEING OF NUT BOLT
45	29-10-2025	Part of : BLOCK 13 NEHRU ENCLAVE EAST KALKAJI,D-BLOCK KALKA JI,BALAJI ESTATE KALKAJI	665	Other Outage	Unplanned Outage	29-10-2025	15:14	29-10-2025	15:56	0:42	0.000257	BIRDAGE
46	29-10-2025	Part of : A4-BLOCK KALKA JI EXTN,	1567	Other Outage	Planned Outage	29-10-2025	15:14	29-10-2025	15:58	0:44	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
47	29-10-2025	Part of : G-BLOCK KALKA JI ,	672	Other Outage	Planned Outage	29-10-2025	11:00	29-10-2025	14:03	3:03	0.003813	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTTENEING OF NUT BOLT
48	29-10-2025	Part of : TUGHLAKABAD EXTN,	727	Other Outage	Planned Outage	29-10-2025	11:34	29-10-2025	13:53	2:19	0.000000	REPLACEMENT OF LT BUSHING ROD
49	29-10-2025	Part of : W-BLOCK GK-2,	117	Other Outage	Planned Outage	29-10-2025	10:59	29-10-2025	13:49	2:50	0.000944	REPLACEMENT OF LT BUSHING ROD
50	30-10-2025	Part of : D-BLOCK OKHLA PHASE-1,SEWAGE PUMP OKHLA PHASE-1	161	Other Outage	Unplanned Outage	30-10-2025	15:08	30-10-2025	16:02	0:54	0.001035	CABLE FAULT
51	30-10-2025	Part of : POCKET 52 CHITTARANJAN PARK	385	Other Outage	Planned Outage	30-10-2025	12:16	30-10-2025	14:07	1:51	0.000617	REPLACEMENT OF LT BUSHING ROD
52	30-10-2025	Part of : N-BLOCK KALKA JI	1141	Other Outage	Planned Outage	30-10-2025	11:16	30-10-2025	13:58	2:42	0.004050	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF LUGS,SUB STATION CLEANING
53	31-10-2025	Part of : DD-BLOCK KALKA JI	93	Other Outage	Planned Outage	31-10-2025	11:11	31-10-2025	14:00	2:49	0.004225	INSTALLATION OF BUS BAR,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,SUB STATION CLEANING
54	31-10-2025	Part of : TUGHLAKABAD EXTN	1380	Other Outage	Planned Outage	31-10-2025	11:07	31-10-2025	13:52	2:45	0.000000	REPLACEMET OF HT BUSHING ROD
55	31-10-2025	Part of : TUGHLAKABAD	989	Other Outage	Planned Outage	31-10-2025	11:10	31-10-2025	13:51	2:41	0.004472	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMET OF HT BUSHING ROD
56	01-10-2025	Part of : MAIDAN GARHI VILLAGE CHHATARPUR,PHASE 1 CHHATARPUR ENCLAVE CHHATARPUR,RAJPUR KHURD VILLAGE CHHATARPUR,	3786	Other Outage	Unplanned Outage	01-10-2025	11:47	01-10-2025	12:53	1:06	0.000183	HT O/H CIRCUIT REPAIR
57	01-10-2025	Part of : ANSAL VILLAS SAT BARI,	209	Other Outage	Planned Outage	01-10-2025	12:42	01-10-2025	14:26	1:44	0.001444	GUARD WIRE LACS INSTALLTION PER SPAN
58	01-10-2025	Part of : ADARSH ENCLAVE AYA NAGAR EXTENSION AYA NAGAR,PHASE-V AYA NAGAR EXTENSION AYA NAGAR,	4595	Other Outage	Planned Outage	01-10-2025	11:17	01-10-2025	14:03	2:46	0.001614	REPLACEMENT OF LT BUSHING ROD
59	01-10-2025	Part of : MANDI VILLAGE,	417	Other Outage	Planned Outage	01-10-2025	11:33	01-10-2025	14:04	2:31	0.000587	LT AB SAGGING PER SPAN
60	03-10-2025	Part of : CHATERPUR	0	Other Outage	Unplanned Outage	03-10-2025	01:05	03-10-2025	01:43	0:38	0.000961	HVDS FAULT
61	03-10-2025	Part of : BLOCK A1 CHHATARPUR VILLAGE	624	Other Outage	Planned Outage	03-10-2025	11:11	03-10-2025	13:10	1:59	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
62	03-10-2025	Part of : RADHEY MOHAN DRIVE	13	Other Outage	Planned Outage	03-10-2025	11:07	03-10-2025	13:05	1:58	0.001639	HT CONDUCTOR REPLACEMET
63	03-10-2025	Part of : RAJPUR KHURD VILLAGE CHHATARPUR PHASE 2	4129	Other Outage	Planned Outage	03-10-2025	11:14	03-10-2025	12:51	1:37	0.000000	3PH HT AB END TERMINATION REPLACEMENT
64	03-10-2025	Part of : SULTANPUR	383	Other Outage	Planned Outage	03-10-2025	10:22	03-10-2025	15:24	5:02	0.008389	BIRD SPIKES INSTALLATION PER POLE
65	03-10-2025	Part of : BLOCK E AYA NAGAR EXTENSION	559	Other Outage	Planned Outage	03-10-2025	11:00	03-10-2025	15:23	4:23	0.001753	REPLACEMET OF HT BUSHING ROD
66	04-10-2025	Part of : L&T CHATERPUR (HTC)	0	Other Outage	Unplanned Outage	04-10-2025	19:02	04-10-2025	19:44	0:42	0.001435	HT SYSTEM FAULT
67	04-10-2025	Part of : POCKET B,C & D DR AMBEDKAR COLONY CHHATARPUR,MITTAL GARDEN SAINIK FARM,BUTTERFLY PARK QILA RAI PITHORA SAINIK FARM	3095	Other Outage	Planned Outage	04-10-2025	10:58	04-10-2025	12:47	1:49	0.000303	REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS
68	04-10-2025	Part of : MANDI VILLAGE	263	Other Outage	Planned Outage	04-10-2025	11:12	04-10-2025	15:19	4:07	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
69	05-10-2025	Part of : ASOLA,BHATI KALAN,ASOLA WILD LIFE SANCTUARY ASOLA	600	Other Outage	Unplanned Outage	05-10-2025	02:05	05-10-2025	03:13	1:08	0.001303	TRANSIENT FAULT
70	06-10-2025	Part of : DERA VILLAGE	118	Other Outage	Planned Outage	06-10-2025	11:27	06-10-2025	13:10	1:43	0.001431	HT SLEEVE INSTALLATION PER SPAN
71	06-10-2025	Part of : RAJPUR KHURD EXTENSION CHHATARPUR,ANSAL VILLAS SAT BARI	2168	Other Outage	Planned Outage	06-10-2025	11:31	06-10-2025	13:01	1:30	0.000000	3PH HT AB END TERMINATION REPLACEMENT
72	06-10-2025	Part of : SULTANPUR	1205	Other Outage	Planned Outage	06-10-2025	12:18	06-10-2025	13:20	1:02	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
73	07-10-2025	Part of : JAUNAPUR VILLAGE	885	Other Outage	Planned Outage	07-10-2025	10:29	07-10-2025	15:11	4:42	0.001097	REPLACEMET OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
74	08-10-2025	Part of : BLOCK A1 CHHATARPUR VILLAGE,GHITORNI VILLAGE	2985	Other Outage	Planned Outage	08-10-2025	11:26	08-10-2025	13:25	1:59	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
75	08-10-2025	Part of : DERA VILLAGE	91	Other Outage	Planned Outage	08-10-2025	11:08	08-10-2025	13:17	2:09	0.001792	CONDUCTOR REPLACEMET PER SPAN
76	08-10-2025	Part of : RAJPUR KHURD EXTENSION CHHATARPUR	220	Other Outage	Planned Outage	08-10-2025	10:10	08-10-2025	13:23	3:13	0.001608	REPLACEMET OF HT BUSHING ROD
77	09-10-2025	Part of : POCKET B DR AMBEDKAR COLONY CHHATARPUR,DR AMBEDKAR COLONY CHHATARPUR,POCKET A DR AMBEDKAR COLONY CHHATARPUR,	3718	Other Outage	Unplanned Outage	09-10-2025	13:40	09-10-2025	13:46	0:06	0.000100	REPAIRING OF HT O/H CIRCUIT
78	09-10-2025	Part of : AYA NAGAR VILLAGE AYA NAGAR,	806	Other Outage	Planned Outage	09-10-2025	11:03	09-10-2025	14:57	3:54	0.001560	REPLACEMENT OF LT BUSHING ROD
79	09-10-2025	Part of : SAT BARI,	261	Other Outage	Planned Outage	09-10-2025	11:16	09-10-2025	14:17	3:01	0.002514	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
80	09-10-2025	Part of : MANGLAPURI VILLAGE SULTANPUR,	623	Other Outage	Planned Outage	09-10-2025	11:03	09-10-2025	13:15	2:12	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
81	10-10-2025	Part of : DERA VILLAGE,NEW GAWALPAHARI VILLAGE,MANDI VILLAGE,GAWALPAHARI VILLAGE	2490	Other Outage	Unplanned Outage	10-10-2025	12:26	10-10-2025	12:46	0:20	0.000056	CABLE FAULT
82	10-10-2025	Part of : ASOLA	76	Other Outage	Planned Outage	10-10-2025	12:36	10-10-2025	12:56	0:20	0.000278	CONDUCTOR REPLACEMET PER SPAN
83	10-10-2025	Part of : BLOCK F AYA NAGAR EXTENSION	327	Other Outage	Planned Outage	10-10-2025	14:23	10-10-2025	15:44	1:21	0.000000	LT REPLACEMENT OF LT BUSHING ROD
84	11-10-2025	Part of : ANSAL VILLAS SAT BARI	1431	Other Outage	Unplanned Outage	11-10-2025	12:20	11-10-2025	12:51	0:31	0.000310	BIRDAGE
85	11-10-2025	Part of : ASOLA,ANSAL VILLAS SAT BARI	740	Other Outage	Unplanned Outage	11-10-2025	11:11	11-10-2025	12:21	1:10	0.000000	MAINTENANCE/REPAIR OF RMU
86	11-10-2025	Part of : SULTANPUR	204	Other Outage	Planned Outage	11-10-2025	11:53	11-10-2025	14:05	2:12	0.000000	PRC REPLACEMENT
87	12-10-2025	Part of : SAT BARI,ANSAL VILLAS SAT BARI,JAIN FARM SULTANPUR,ADARSH COLONY KHARAK VILLAGE	1431	Other Outage	Unplanned Outage	12-10-2025	01:11	12-10-2025	01:56	0:45	0.000500	BIRDAGE
88	13-10-2025	Part of : ASOLA,	76	Other Outage	Planned Outage	13-10-2025	15:08	13-10-2025	16:54	1:46	0.000000	BIRD SPIKES INSTALLATION PER POLE
89	13-10-2025	Part of : ASOLA WILD LIFE SANCTUARY ASOLA,	1	Other Outage	Planned Outage	13-10-2025	15:08	13-10-2025	16:53	1:45	0.000058	TAPPING OF JUMPERS
90	13-10-2025	Part of : RAJPUR KHURD VILLAGE CHHATARPUR,	1433	Other Outage	Planned Outage	13-10-2025	11:43	13-10-2025	13:19	1:36	0.000000	REPLACEMET OF HT BUSHING ROD
91	13-10-2025	Part of : BLOCK A1 CHHATARPUR VILLAGE CHHATARPUR,	772	Other Outage	Planned Outage	13-10-2025	11:45	13-10-2025	15:56	4:11	0.000697	REPLACEMET OF HT BUSHING ROD
92	13-10-2025	Part of : SAT BARI,	212	Other Outage	Planned Outage	13-10-2025	12:19	13-10-2025	15:46	3:27	0.000000	REPLACEMET OF HT BUSHING ROD
93	13-10-2025	Part of : BLOCK D CHHATARPUR VILLAGE CHHATARPUR,BLOCK A1 CHHATARPUR VILLAGE CHHATARPUR,CHHATARPUR,BLOCK G CHHATARPUR VILLAGE CHHATARPUR,BLOCK C CHHATARPUR EXTENSION CHHATARPUR,BLOCK F CHHATARPUR VILLAGE CHHATARPUR.	4578	Other Outage	Planned Outage	13-10-2025	10:27	13-10-2025	13:20	2:53	0.000000	3PH HT AB END TERMINATION REPLACEMENT
94	13-10-2025	Part of : SULTANPUR,	976	Other Outage	Planned Outage	13-10-2025	11:52	13-10-2025	13:55	2:03	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
95	14-10-2025	Part of : PHASE 2 CHHATARPUR ENCLAVE,MITTAL GARDEN SAINIK FARM	5956	Other Outage	Unplanned Outage	14-10-2025	19:26	14-10-2025	19:59	0:33	0.000688	CABLE FAULT
96	14-10-2025	Part of : RAJPUR KHURD VILLAGE CHHATARPUR	1474	Other Outage	Planned Outage	14-10-2025	11:53	14-10-2025	13:50	1:57	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
97	14-10-2025	Part of : WESTEND DLF CHATTARPUR FARMS DLF FARMS,JAUNAPUR VILLAGE JAUNAPUR,BHIM BASTI JUANAPUR,AMBEDKAR COLONY MANDI,MANDI VILLAGE,SULTANPUR	3479	Other Outage	Planned Outage	14-10-2025	10:58	14-10-2025	13:25	2:27	0.004083	BIRD SPIKES INSTALLATION PER POLE,JUMPER REPLACEMENT PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
98	14-10-2025	Part of : ASOLA	94	Other Outage	Planned Outage	14-10-2025	11:20	14-10-2025	13:51	2:31	0.000000	REPLACEMENT OF LT BUSHING ROD
99	14-10-2025	Part of : BLOCK C CHHATARPUR EXTENSION	442	Other Outage	Planned Outage	14-10-2025	10:38	14-10-2025	13:48	3:10	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
100	14-10-2025	Part of : BLOCK G AYA NAGAR EXTENSION	258	Other Outage	Planned Outage	14-10-2025	10:57	14-10-2025	13:59	3:02	0.000000	REPLACEMENT OF LT BUSHING ROD
101	15-10-2025	Part of : ASOLA	1099	Other Outage	Planned Outage	15-10-2025	13:29	15-10-2025	15:19	1:50	0.000000	HT CONDUCTOR REPLACEMENT
102	15-10-2025	Part of : MITTAL GARDEN SAINIK FARM,DR AMBEDKAR COLONY CHHATARPUR	211	Other Outage	Planned Outage	15-10-2025	10:02	15-10-2025	12:26	2:24	0.000000	3PH HT AB END TERMINATION REPLACEMENT
103	16-10-2025	Part of : RAJPUR KHURD VILLAGE CHHATARPUR	1474	Other Outage	Planned Outage	16-10-2025	13:20	16-10-2025	15:32	2:12	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
104	16-10-2025	Part of : ARJUN GARH AYA NAGAR	559	Other Outage	Planned Outage	16-10-2025	11:49	16-10-2025	14:59	3:10	0.001267	REPLACEMENT OF LT BUSHING ROD
105	16-10-2025	Part of : CHHATARPUR ENCLAVE	13	Other Outage	Planned Outage	16-10-2025	10:24	16-10-2025	12:54	2:30	0.000833	REPLACEMET OF HT BUSHING ROD
106	16-10-2025	Part of : ASOLA	390	Other Outage	Planned Outage	16-10-2025	11:01	16-10-2025	14:19	3:18	0.001650	GUARD WIRE LACS INSTALLTION PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
107	16-10-2025	Part of : RADHEY MOHAN DRIVE	53	Other Outage	Planned Outage	16-10-2025	10:58	16-10-2025	13:30	2:32	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
108	17-10-2025	Part of : DERA VILLAGE,	6	Other Outage	Planned Outage	17-10-2025	12:19	17-10-2025	14:09	1:50	0.001528	FEEDER PILLAR CLEANING
109	17-10-2025	Part of : DERA VILLAGE,	127	Other Outage	Planned Outage	17-10-2025	12:18	17-10-2025	14:08	1:50	0.001528	HRC FUSE/HRC BASE REPLACEMENT
110	17-10-2025	Part of : DERA VILLAGE,	312	Other Outage	Planned Outage	17-10-2025	12:18	17-10-2025	14:11	1:53	0.001569	TAPPING OF SERVICE CABLES
111	17-10-2025	Part of : DERA VILLAGE,	1	Other Outage	Planned Outage	17-10-2025	12:19	17-10-2025	14:06	1:47	0.001486	FEEDER COVER /SERVICE PILLAR COVER INSTALLTION
112	17-10-2025	Part of : CHHATARPUR ENCLAVE CHHATARPUR,	243	Other Outage	Planned Outage	17-10-2025	10:08	17-10-2025	12:50	2:42	0.000900	REPLACEMET OF HT BUSHING ROD
113	17-10-2025	Part of : ADARSH ENCLAVE AYA NAGAR EXTENSION AYA NAGAR,	514	Other Outage	Planned Outage	17-10-2025	12:51	17-10-2025	15:04	2:13	0.000000	REPLACEMENT OF LT BUSHING ROD
114	18-10-2025	Part of : Ansal Villas Sat Bari,Fatehpur Beri,Chandan Hola,Asola	1750	Other Outage	Unplanned Outage	18-10-2025	15:35	18-10-2025	16:05	0:30	0.000367	BIRDAGE
115	21-10-2025	Part of : ASOLA WILD LIFE SANCTUARY ASOLA,	27	Other Outage	Planned Outage	21-10-2025	14:09	21-10-2025	16:59	2:50	0.000000	REPLACEMET OF HT BUSHING ROD
116	22-10-2025	Part of : RAJPUR KHURD EXTENSION CHHATARPUR	0	Other Outage	Unplanned Outage	22-10-2025	12:21	22-10-2025	12:43	0:22	0.000098	BIRDAGE
117	22-10-2025	Part of : PHASE 1 CHHATARPUR ENCLAVE	745	Other Outage	Planned Outage	22-10-2025	12:19	22-10-2025	14:15	1:56	0.000000	REPLACEMET OF HT BUSHING ROD
118	22-10-2025	Part of : ANSAL VILLAS SAT BARI	39	Other Outage	Planned Outage	22-10-2025	11:35	22-10-2025	13:28	1:53	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
119	23-10-2025	Part of : DR AMBEDKAR COLONY CHHATARPUR	717	Other Outage	Planned Outage	23-10-2025	10:12	23-10-2025	13:52	3:40	0.003056	REPLACEMENT OF HT BUSHING ROD
120	24-10-2025	Part of : ASOLA,ASOLA WILD LIFE SANCTUARY	1611	Other Outage	Unplanned Outage	24-10-2025	09:56	24-10-2025	10:31	0:35	0.000496	CABLE FAULT
121	24-10-2025	Part of : FATEHPUR BERI	366	Other Outage	Planned Outage	24-10-2025	14:09	24-10-2025	14:33	0:24	0.000200	BUS BAR REPLACEMENT PER PHASE
122	24-10-2025	Part of : WESTEND DLF CHATTARPUR FARMS DLF FARMS,JAUNAPUR VILLAGE,AMBEDKAR COLONY MANDI,MANDI VILLAGE	3479	Other Outage	Planned Outage	24-10-2025	10:30	24-10-2025	14:07	3:37	0.006028	BIRD SPIKES INSTALLATION PER POLE,JUMPER REPLACEMENT PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN,TAPPING OF JUMPERS
123	24-10-2025	Part of : BLOCK G AYA NAGAR EXTENSION	252	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	14:08	2:47	0.000649	REPLACEMENT OF LT BUSHING ROD
124	25-10-2025	Part of : DERA VILLAGE,NEW GAWALPAHARI VILLAGE,MANDI VILLAGE,GAWALPAHARI VILLAGE	2493	Other Outage	Unplanned Outage	25-10-2025	15:19	25-10-2025	16:14	0:55	0.000214	CABLE FAULT
125	25-10-2025	Part of : MANGLAPURI VILLAGE SULTANPUR,	629	Other Outage	Planned Outage	25-10-2025	11:28	25-10-2025	12:28	1:00	0.000000	1PH DB REPLACEMENT,3PH DB REPLACEMENT,JUMPER REPLACEMENT PER POLE
126	25-10-2025	Part of : JAUNAPUR VILLAGE JAUNAPUR,	125	Other Outage	Planned Outage	25-10-2025	10:22	25-10-2025	13:54	3:32	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
127	28-10-2025	Part of : DERA VILLAGE, JAUNAPUR VILLAGE, NEW GAWALPAHARI VILLAGE, FATEHPUR BERI, ASOLA	575	Other Outage	Unplanned Outage	28-10-2025	10:23	28-10-2025	10:46	0:23	0.000300	BIRDAGE
128	28-10-2025	Part of : CHANDAN HOLA	74	Other Outage	Planned Outage	28-10-2025	14:07	28-10-2025	15:09	1:02	0.000517	BUS BAR REPLACEMENT PER PHASE
129	28-10-2025	Part of : ASOLA	964	Other Outage	Planned Outage	28-10-2025	12:58	28-10-2025	14:10	1:12	0.001000	FEEDER COVER /SERVICE PILLAR COVER INSTALLTION
130	28-10-2025	Part of : SULTANPUR	100	Other Outage	Planned Outage	28-10-2025	10:54	28-10-2025	14:01	3:07	0.001247	REPLACEMENT OF LT BUSHING ROD
131	28-10-2025	Part of : CHHATARPUR	396	Other Outage	Planned Outage	28-10-2025	10:22	28-10-2025	13:31	3:09	0.001050	REPLACEMET OF HT BUSHING ROD
132	29-10-2025	Part of : ANSAL VILLAS SAT BARI,FATEHPUR BERI,CHANDAN HOLA,ASOLA	1751	Other Outage	Unplanned Outage	29-10-2025	08:33	29-10-2025	08:55	0:22	0.000141	ELECTROCUTION OF MONKEY
133	29-10-2025	Part of : GADAIPUR DLF FARMS,	5	Other Outage	Planned Outage	29-10-2025	11:17	29-10-2025	16:39	5:22	0.001252	REPLACEMENT OF LT BUSHING ROD
134	29-10-2025	Part of : ANSAL VILLAS SAT BARI,MAIDAN GARHI VILLAGE CHHATARPUR,DLF FARMS,ASOLA WILD LIFE SANCTUARY ASOLA,BLOCK C CHHATARPUR EXTENSION CHHATARPUR,RAJPUR KHURD EXTENSION CHHATARPUR,	296	Other Outage	Planned Outage	29-10-2025	12:02	29-10-2025	14:10	2:08	0.001778	FEEDER PILLAR CLEANING
135	29-10-2025	Part of : CHANDAN HOLA,	294	Other Outage	Planned Outage	29-10-2025	11:51	29-10-2025	14:04	2:13	0.001108	BUS BAR REPLACEMENT PER PHASE
136	29-10-2025	Part of : CHHATARPUR ENCLAVE CHHATARPUR,	129	Other Outage	Planned Outage	29-10-2025	10:32	29-10-2025	13:52	3:20	0.000000	REPLACEMET OF HT BUSHING ROD
137	29-10-2025	Part of : MANDI VILLAGE,	45	Other Outage	Planned Outage	29-10-2025	10:59	29-10-2025	14:20	3:21	0.000000	1PH DB REPLACEMENT,3PH DB REPLACEMENT,CONDUCTOR REPLACEMENT PER SPAN,INSULATOR REPLACEMENT PER POLE,JUMPER REPLACEMENT PER POLE,LT AB SAGGING PER SPAN
138	29-10-2025	Part of : RADHEY MOHAN DRIVE,	56	Other Outage	Planned Outage	29-10-2025	10:59	29-10-2025	14:20	3:21	0.000000	1PH DB REPLACEMENT,3PH DB REPLACEMENT,JUMPER REPLACEMENT PER POLE,LT AB SAGGING PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
139	30-10-2025	Part of : MAIDAN GARHI VILLAGE CHHATARPUR,ANSAL VILLAS SAT BARI,ASOLA WILD LIFE SANCTUARY ASOLA,RAJPUR KHURD EXTENSION CHHATARPUR,DLF FARMS	296	Other Outage	Planned Outage	30-10-2025	13:48	30-10-2025	14:52	1:04	0.000889	REPLACEMENT OF HT BUSHING ROD
140	30-10-2025	Part of : ANSAL VILLAS SAT BARI	49	Other Outage	Planned Outage	30-10-2025	13:51	30-10-2025	14:51	1:00	0.000500	BUS BAR REPLACEMENT PER PHASE
141	30-10-2025	Part of : AYA NAGAR PHASE 1 AYA NAGAR	306	Other Outage	Planned Outage	30-10-2025	13:39	30-10-2025	15:51	2:12	0.000880	REPLACEMENT OF LT BUSHING ROD
142	30-10-2025	Part of : AYA NAGAR PHASE 1 AYA NAGAR	28	Other Outage	Planned Outage	30-10-2025	10:28	30-10-2025	12:41	2:13	0.000517	REPLACEMENT OF LT BUSHING ROD
143	30-10-2025	Part of : RAJPUR KHURD EXTENSION CHHATARPUR	882	Other Outage	Planned Outage	30-10-2025	10:28	30-10-2025	13:52	3:24	0.000000	REPLACEMENT OF HT BUSHING ROD
144	30-10-2025	Part of : BHIM BASTI JUANAPUR	813	Other Outage	Planned Outage	30-10-2025	10:58	30-10-2025	13:32	2:34	0.000000	1PH DB REPLACEMENT,1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,JUMPER REPLACEMENT PER POLE,PRC REPLACEMENT PER FEEDER
145	31-10-2025	Part of : POCKET A & B DR AMBEDKAR COLONY CHHATARPUR	2676	Other Outage	Planned Outage	31-10-2025	14:16	31-10-2025	16:11	1:55	0.000000	3PH HT AB END TERMINATION REPLACEMENT
146	31-10-2025	Part of : ASOLA	17	Other Outage	Planned Outage	31-10-2025	14:48	31-10-2025	16:02	1:14	0.000411	REPLACEMET OF HT BUSHING ROD
147	31-10-2025	Part of : ANSAL VILLAS SAT BARI	33	Other Outage	Planned Outage	31-10-2025	13:52	31-10-2025	15:55	2:03	0.001025	BUS BAR REPLACEMENT PER PHASE
148	31-10-2025	Part of : RAJPUR KHURD VILLAGE CHHATARPUR	267	Other Outage	Planned Outage	31-10-2025	12:05	31-10-2025	15:08	3:03	0.000000	REPLACEMET OF HT BUSHING ROD
149	31-10-2025	Part of : DR AMBEDKAR COLONY CHHATARPUR	489	Other Outage	Planned Outage	31-10-2025	10:19	31-10-2025	13:33	3:14	0.002694	REPLACEMET OF HT BUSHING ROD
150	31-10-2025	Part of : DLF FARMS GADPUR FARM,JAUNAPUR,SULTANPUR, WESTEND DLF CHATTARPUR FARMS	1482	Other Outage	Planned Outage	31-10-2025	10:02	31-10-2025	14:30	4:28	0.007444	BIRD SPIKES INSTALLATION PER POLE,JUMPER REPLACEMENT PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES
151	01-10-2025	Part of : BLOCK E HAUZ KHAS,	231	Other Outage	Planned Outage	01-10-2025	10:39	01-10-2025	12:10	1:31	0.000025	EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,INSULATOR REPLACEMENT PER POLE,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
152	02-10-2025	Part of : BLOCK V GREEN PARK,BLOCK B 7 ARJUN NAGAR SAFDARJUNG ENCLAVE,BLOCK Z GREEN PARK EXTENSION	2489	Other Outage	Unplanned Outage	02-10-2025	03:14	02-10-2025	04:18	1:04	0.001813	CABLE FAULT
153	03-10-2025	Part of : P-BLOCK HAUZ KHAS ENCLAVE	112	Other Outage	Unplanned Outage	03-10-2025	11:38	03-10-2025	13:12	1:34	0.000000	REPAIR OF DAMAGED WIRE ON POLES
154	03-10-2025	Part of : BLOCK S PANCHSHILA PARK SOUTH	171	Other Outage	Planned Outage	03-10-2025	11:05	03-10-2025	13:05	2:00	0.000100	LT CONDUCTOR REPLACEMENT REPLACEMENT
155	04-10-2025	Part of : BLOCK A 2 NAUROJI NAGAR SAFDARJUNG ENCLAVE	425	Other Outage	Planned Outage	04-10-2025	11:28	04-10-2025	13:19	1:51	0.000463	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
156	04-10-2025	Part of : BLOCK K SOUTH EXTENSION II	815	Other Outage	Planned Outage	04-10-2025	11:03	04-10-2025	13:37	2:34	0.001198	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
157	06-10-2025	Part of : BLOCK A SOAMI NAGAR NORTH PANCHSHEEL ENCLAVE	203	Other Outage	Planned Outage	06-10-2025	11:41	06-10-2025	13:04	1:23	0.000277	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
158	06-10-2025	Part of : BLOCK A 1 NAUROJI NAGAR SAFDARJUNG ENCLAVE	171	Other Outage	Planned Outage	06-10-2025	11:53	06-10-2025	13:20	1:27	0.000846	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
159	06-10-2025	Part of : BLOCK G HAUZ KHAS	137	Other Outage	Planned Outage	06-10-2025	11:39	06-10-2025	13:43	2:04	0.000103	LT AB SAGGING PER SPAN
160	07-10-2025	Part of : D-BLOCK GULMOHAR PARK	748	Other Outage	Planned Outage	07-10-2025	10:53	07-10-2025	14:01	3:08	0.001828	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
161	07-10-2025	Part of : B 4-BLOCK SAFDARJUNG ENCLAVE	945	Other Outage	Planned Outage	07-10-2025	11:06	07-10-2025	14:13	3:07	0.001039	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
162	08-10-2025	Part of : BLOCK E HAUZ KHAS	846	Other Outage	Planned Outage	08-10-2025	11:29	08-10-2025	14:45	3:16	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
163	08-10-2025	Part of : HUMAYUNPUR SAFDARJUNG ENCLAVE	1617	Other Outage	Planned Outage	08-10-2025	11:20	08-10-2025	13:36	2:16	0.000756	CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
164	09-10-2025	Part of : BLOCK B 3 SAFDARJUNG ENCLAVE,	457	Other Outage	Planned Outage	09-10-2025	11:36	09-10-2025	16:41	5:05	0.000847	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
165	09-10-2025	Part of : BLOCK E SOAMI NAGAR NORTH SOAMI NAGAR,	439	Other Outage	Planned Outage	09-10-2025	11:46	09-10-2025	14:06	2:20	0.000311	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
166	09-10-2025	Part of : BLOCK M SOUTH EXTENSION II,	3	Other Outage	Planned Outage	09-10-2025	11:33	09-10-2025	12:31	0:58	0.000081	LT AB SAGGING PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
167	09-10-2025	Part of : NEETI BAGH,	167	Other Outage	Planned Outage	09-10-2025	10:58	09-10-2025	12:35	1:37	0.000027	1PH DB REVAMPING,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
168	10-10-2025	Part of : E-BLOCK MARKET HAUZ KHAS	0	Other Outage	Unplanned Outage	10-10-2025	23:23	11-10-2025	00:07	0:44	0.000110	HT SYSTEM FAULT
169	10-10-2025	Part of : BLOCK A QUTAB INSTITUTIONAL AREA	21	Other Outage	Planned Outage	10-10-2025	15:27	10-10-2025	16:00	0:33	0.000073	RELAY REPLACEMET/VPI/FPI
170	10-10-2025	Part of : SOCIETY DEV ALTERNATIVES (HT CONSUMER)	1	Other Outage	Planned Outage	10-10-2025	13:04	10-10-2025	14:07	1:03	0.000140	RELAY REPLACEMET/VPI/FPI
171	10-10-2025	Part of : ANDREWS GANJ EXTENSION	19	Other Outage	Planned Outage	10-10-2025	11:05	10-10-2025	12:36	1:31	0.000329	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
172	10-10-2025	Part of : ANDREWS GANJ EXTENSION	130	Other Outage	Planned Outage	10-10-2025	11:04	10-10-2025	11:30	0:26	0.000036	LT FEEDER PILLAR CLEANING,HRC FUSE/HRC BASE REPLACEMENT,TAPPING OF MAIN CABLES,TAPPING OF SERVICE CABLES
173	11-10-2025	Part of : POCKET A KATWARIA SARAI	63	Other Outage	Planned Outage	11-10-2025	12:17	11-10-2025	14:21	2:04	0.000276	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
174	11-10-2025	Part of : UDAY PARK SOUTH EXTENSION-2	593	Other Outage	Planned Outage	11-10-2025	11:05	11-10-2025	13:10	2:05	0.000868	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
175	11-10-2025	Part of : S-BLOCK PANCHSHILA PARK SOUTH	186	Other Outage	Planned Outage	11-10-2025	11:37	11-10-2025	13:28	1:51	0.000093	PRC REPLACEMENT
176	12-10-2025	Part of : INSTITUTIONAL AREA HAUZ KHAS	4	Other Outage	Planned Outage	12-10-2025	10:55	12-10-2025	12:45	1:50	0.000153	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING
177	13-10-2025	Part of : DEER PARK HAUZ KHAS,	120	Other Outage	Planned Outage	13-10-2025	12:28	13-10-2025	14:00	1:32	0.000256	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
178	13-10-2025	Part of : MAYFAIR GARDEN HAUZ KHAS,	304	Other Outage	Planned Outage	13-10-2025	10:59	13-10-2025	13:18	2:19	0.000386	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
179	13-10-2025	Part of : BLOCK C QUTAB INSTITUTIONAL AREA,	5	Other Outage	Planned Outage	13-10-2025	11:26	13-10-2025	13:34	2:08	0.000178	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
180	13-10-2025	Part of : BLOCK B 4 SAFDARJUNG ENCLAVE,	945	Other Outage	Planned Outage	13-10-2025	11:09	13-10-2025	13:45	2:36	0.000867	REPLACEMET OF FAULTY END BOX
181	13-10-2025	Part of : POLICE COLONY SOUTH EXTENSION II,	369	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	12:08	1:08	0.000113	EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
182	14-10-2025	Part of : JNU NEW CAMPUS (HTC)	2	Other Outage	Unplanned Outage	14-10-2025	15:18	14-10-2025	16:31	1:13	0.000629	FAULT IN HT CONSUMER PANEL (JNU CAMPUS)

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
183	14-10-2025	Part of : GULMOHAR ENCLAVE	1221	Other Outage	Planned Outage	14-10-2025	10:58	14-10-2025	12:30	1:32	0.000307	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
184	14-10-2025	Part of : BLOCK A SOUTH EXTENSION II	448	Other Outage	Planned Outage	14-10-2025	12:15	14-10-2025	16:00	3:45	0.001250	DT REPLACEMENT
185	14-10-2025	Part of : BLOCK A SOAMI NAGAR NORTH SOAMI NAGAR	318	Other Outage	Planned Outage	14-10-2025	10:52	14-10-2025	13:02	2:10	0.000181	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
186	14-10-2025	Part of : BEER SARAI	87	Other Outage	Planned Outage	14-10-2025	11:43	14-10-2025	14:57	3:14	0.000485	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
187	14-10-2025	Part of : BLOCK C 4 SAFDARJUNG DEVELOPMENT AREA HAUZ KHAS	307	Other Outage	Planned Outage	14-10-2025	11:35	14-10-2025	13:11	1:36	0.000267	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
188	15-10-2025	Part of : E-BLOCK HAUZ KHAS	846	Other Outage	Planned Outage	15-10-2025	12:15	15-10-2025	13:26	1:11	0.000099	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
189	15-10-2025	Part of : NCERT CAMPUS KATWARIA SARAI	341	Other Outage	Planned Outage	15-10-2025	10:58	15-10-2025	15:55	4:57	0.000413	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
190	15-10-2025	Part of : ANDREWS GANJ	223	Other Outage	Planned Outage	15-10-2025	11:00	15-10-2025	12:50	1:50	0.000183	LT CIRCUIT MAINTENANCE WORK
191	16-10-2025	Part of : ASIAN GAMES VILLAGE COMPLEX SIRI FORT	382	Other Outage	Unplanned Outage	16-10-2025	15:53	16-10-2025	16:34	0:41	0.000285	CABLE FAULT
192	16-10-2025	Part of : BLOCK D SOAMI NAGAR SOUTH	508	Other Outage	Planned Outage	16-10-2025	12:14	16-10-2025	14:13	1:59	0.000364	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
193	16-10-2025	Part of : BLOCK C 6 HAUZ KHAS ENCLAVE	2	Other Outage	Planned Outage	16-10-2025	11:09	16-10-2025	12:59	1:50	0.000458	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
194	16-10-2025	Part of : BLOCK D SOUTH EXTENSION II	192	Other Outage	Planned Outage	16-10-2025	11:00	16-10-2025	13:21	2:21	0.000274	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
195	17-10-2025	Part of : AYUR VIGYAN NAGAR SADIQ NAGAR	107	Other Outage	Unplanned Outage	17-10-2025	21:03	17-10-2025	21:49	0:46	0.000511	CABLE FAULT
196	17-10-2025	Part of : HTC:D-14 NDSE -II	1	Other Outage	Planned Outage	17-10-2025	15:02	17-10-2025	16:46	1:44	0.000289	GUARD WIRES SAGGING PER SPAN,TAPPING OF UG CABLE TO OH JUMPER CONNECTION

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
197	17-10-2025	Part of : HUMAYUNPUR SAFDARJUNG ENCLAVE,	1349	Other Outage	Planned Outage	17-10-2025	11:07	17-10-2025	13:01	1:54	0.000475	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
198	17-10-2025	Part of : BLOCK B KATWARIA SARAI,	1722	Other Outage	Planned Outage	17-10-2025	12:34	17-10-2025	14:55	2:21	0.000313	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
199	18-10-2025	Part of : BLOCK C SOUTH EXTENSION II	515	Other Outage	Planned Outage	18-10-2025	10:58	18-10-2025	12:31	1:33	0.000336	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
200	19-10-2025	Part of : BLOCK C7 BHIM NAGAR HAUZ KHAS, DEER PARK HAUZ KHAS, BLOCK C 3 SAFDARJUNG DEVELOPMENT AREA HAUZ KHAS, PURULATOR HAUZ KHAS (HTC)	1695	Other Outage	Unplanned Outage	19-10-2025	23:44	20-10-2025	00:29	0:45	0.000525	HT SYSTEM FAULT
201	22-10-2025	Part of : BLOCK A KATWARIA SARAI	614	Other Outage	Planned Outage	22-10-2025	12:13	22-10-2025	14:01	1:48	0.000150	REPLACEMENT OF GAS KIT AND OIL SEAL
202	23-10-2025	Part of : ANDREWS GANJ,ANDREWS GANJ EXTENSION,M & E -BLOCK SOUTH EXTENSION-2	1193	Other Outage	Unplanned Outage	23-10-2025	01:45	23-10-2025	02:49	1:04	0.001422	TREE TOUCHING
203	24-10-2025	Part of : BLOCK A SOUTH EXTENSION II	211	Other Outage	Unplanned Outage	24-10-2025	10:26	24-10-2025	10:48	0:22	0.000061	DT METER/CT REPLACEMENT
204	24-10-2025	Part of : BLOCK B 3 SAFDARJUNG ENCLAVE	538	Other Outage	Planned Outage	24-10-2025	11:06	24-10-2025	13:04	1:58	0.000524	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
205	24-10-2025	Part of : POCKET B KATWARIA SARAI	477	Other Outage	Planned Outage	24-10-2025	11:31	24-10-2025	13:10	1:39	0.000193	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
206	24-10-2025	Part of : POLICE COLONY SOUTH EXTENSION II	358	Other Outage	Planned Outage	24-10-2025	10:58	24-10-2025	13:45	2:47	0.000232	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
207	24-10-2025	Part of : SHAHPUR JAT VILLAGE SIRI FORT	422	Other Outage	Planned Outage	24-10-2025	11:32	24-10-2025	13:35	2:03	0.000854	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING
208	24-10-2025	Part of : ANDREWS GANJ	365	Other Outage	Planned Outage	24-10-2025	14:52	24-10-2025	16:40	1:48	0.000150	3PH DB REPLACEMENT,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,JUMPER REPLACEMENT PER POLE,PRC REPLACEMENT PER FEEDER
209	25-10-2025	Part of : LAL GUMBAD BASTI SADHNA ENCLAVE PANCHSHILA PARK,	317	Other Outage	Planned Outage	25-10-2025	11:22	25-10-2025	15:26	4:04	0.000339	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
210	25-10-2025	Part of : BLOCK E SOUTH EXTENSION II,	21	Other Outage	Planned Outage	25-10-2025	10:56	25-10-2025	13:32	2:36	0.000303	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
211	25-10-2025	Part of : BLOCK B 3 SAFDARJUNG ENCLAVE,	746	Other Outage	Planned Outage	25-10-2025	11:08	25-10-2025	15:11	4:03	0.001350	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
212	26-10-2025	Part of : PANCHSHILA PARK NORTH	394	Other Outage	Planned Outage	26-10-2025	11:38	26-10-2025	13:55	2:17	0.000076	1PH DB REVAMPING,3PH DB REPLACEMENT,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,PRC REPLACEMET PER FEEDER
213	28-10-2025	Part of : BLOCK S PANCHSHILA PARK SOUTH, ASIAN GAMES VILLAGE COMPLEX SIRI FORT, BLOCK N PANCHSHILA PARK NORTH	473	Other Outage	Unplanned Outage	28-10-2025	07:48	28-10-2025	08:10	0:22	0.000416	HT SYSTEM FAULT
214	28-10-2025	Part of : BLOCK C PANCHSHEEL ENCLAVE	126	Other Outage	Planned Outage	28-10-2025	11:28	28-10-2025	13:26	1:58	0.000262	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
215	28-10-2025	Part of : GAUTAM NAGAR	956	Other Outage	Planned Outage	28-10-2025	10:58	28-10-2025	13:50	2:52	0.000573	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
216	29-10-2025	Part of : BLOCK A 1 NAUROJI NAGAR SAFDARJUNG ENCLAVE,	515	Other Outage	Planned Outage	29-10-2025	11:25	29-10-2025	13:09	1:44	0.000867	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
217	29-10-2025	Part of : INDIAN INSTITUTE OF TECHNOLOGY DELHI HAUZ KHAS,	336	Other Outage	Planned Outage	29-10-2025	12:42	29-10-2025	16:42	4:00	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
218	29-10-2025	Part of : BLOCK S PANCHSHILA PARK SOUTH PANCHSHILA PARK,	167	Other Outage	Planned Outage	29-10-2025	10:54	29-10-2025	14:19	3:25	0.000228	EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,INSULATOR REPLACEMENT PER POLE,JUMPER REPLACEMENT PER POLE,PRC REPLACEMET PER FEEDER
219	30-10-2025	Part of : YUSUF SARAI	207	Other Outage	Unplanned Outage	30-10-2025	12:02	30-10-2025	12:56	0:54	0.000015	REPAIRING OF LT CIRCUIT
220	30-10-2025	Part of : C-2 GREEN PARK EXT (HTC)	1	Other Outage	Planned Outage	30-10-2025	11:04	30-10-2025	12:54	1:50	0.000306	PROPOER CLEANING OF OPERATING MECHANISM USING CRCS PER WAY,REPLACEMENT OF FAULTY END BOX
221	30-10-2025	Part of : BLOCK X HAUZ KHAS	154	Other Outage	Planned Outage	30-10-2025	11:06	30-10-2025	14:00	2:54	0.000387	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
222	31-10-2025	Part of : C-BLOCK SOUTH EXTENSION-2	231	Other Outage	Planned Outage	31-10-2025	12:31	31-10-2025	13:52	1:21	0.000450	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
223	31-10-2025	Part of : L-5 GREEN PARK EXT.	1	Other Outage	Planned Outage	31-10-2025	11:23	31-10-2025	12:47	1:24	0.000233	CLEANING OF HT BUSHING PER WAY,PROPOER CLEANING OF OPERATING MECHANISM USING CRCS PER WAY
224	31-10-2025	Part of : PANCHSHILA PARK NORTH	220	Other Outage	Planned Outage	31-10-2025	11:24	31-10-2025	13:21	1:57	0.000260	LT CONDUCTOR REPLACEMENT
225	01-10-2025	Part of : BLOCK B DEVLİ SANGAM VIHAR,DEOLI GAON NAI BASTI SANGAM VIHAR,BLOCK A TIGRI EXTENSION SANGAM VIHAR	6824	Other Outage	Unplanned Outage	01-10-2025	15:44	01-10-2025	16:30	0:46	0.000984	CABLE DAMAGE BY OUTSIDE AGENCY (DMRC)
226	01-10-2025	Part of : BLOCK D SANGAM VIHAR,BLOCK B TIGRI EXTENSION SANGAM VIHAR,BLOCK L DEVLİ SANGAM VIHAR,BLOCK C DEVLİ SANGAM VIHAR,BLOCK B DEVLİ SANGAM VIHAR,	3804	Other Outage	Planned Outage	01-10-2025	11:10	01-10-2025	13:05	1:55	0.000351	REPLACEMENT OF LT BUSHING ROD
227	01-10-2025	Part of : POCKET C RAJU PARK SANGAM VIHAR,	796	Other Outage	Planned Outage	01-10-2025	11:35	01-10-2025	13:49	2:14	0.000409	3PH HT AB CABLE REPLACEMENT PER SPAN
228	01-10-2025	Part of : BLOCK L 2 DEVLİ SANGAM VIHAR,BLOCK L DEVLİ SANGAM VIHAR,	1951	Other Outage	Planned Outage	01-10-2025	10:44	01-10-2025	12:44	2:00	0.000367	3PH HT AB CABLE REPLACEMENT PER SPAN
229	02-10-2025	Part of : POCKET C DUGGAL COLONY KHANPUR,JJ COLONY DUGGAL COLONY KHANPUR	746	Other Outage	Unplanned Outage	02-10-2025	08:20	02-10-2025	09:02	0:42	0.001108	HVDS FAULT
230	02-10-2025	Part of : POCKET A, B, C, D & F JAWAHAR PARK KHANPUR,BLOCK F KHANPUR COLONY KHANPUR	4580	Other Outage	Unplanned Outage	02-10-2025	00:32	02-10-2025	01:25	0:53	0.000029	HT SYSTEM FAULT
231	02-10-2025	Part of : POCKET A, B C, D & E JAWAHAR PARK KHANPUR,BLOCK F KHANPUR COLONY	4580	Other Outage	Unplanned Outage	02-10-2025	12:23	02-10-2025	13:04	0:41	0.000000	REPAIRING OF RMU
232	03-10-2025	Part of : A,C,R,F,HR & RZ-BLOCK PULPEHLADPUR	4627	Other Outage	Unplanned Outage	03-10-2025	11:31	03-10-2025	12:10	0:39	0.000596	HT SYSTEM FAULT
233	03-10-2025	Part of : BLOCK F 2 SANGAM VIHAR	1152	Other Outage	Planned Outage	03-10-2025	11:57	03-10-2025	13:01	1:04	0.000196	REPLACEMET OF HT BUSHING ROD
234	03-10-2025	Part of : BLOCK A LAL KUAN	932	Other Outage	Planned Outage	03-10-2025	11:52	03-10-2025	14:11	2:19	0.000425	HT AB SAGGING
235	03-10-2025	Part of : JAWAHAR PARK SANGAM VIHAR	892	Other Outage	Planned Outage	03-10-2025	11:04	03-10-2025	14:16	3:12	0.000587	REPLACEMET OF HT BUSHING ROD
236	03-10-2025	Part of : BLOCK B DEVLİ SANGAM VIHAR	491	Other Outage	Planned Outage	03-10-2025	10:40	03-10-2025	12:57	2:17	0.000419	REPLACEMET OF HT BUSHING ROD
237	03-10-2025	Part of : DEOLI GAON NAI BASTI SANGAM VIHAR	62	Other Outage	Planned Outage	03-10-2025	10:23	03-10-2025	13:08	2:45	0.000504	3PH HT AB CABLE REPLACEMENT
238	04-10-2025	Part of : DDA PARK LAL KUAN, VISHWAKARMA COLONY PULPEHLADPUR, PWD OFFICE OKHLA PHASE-1 (HTC)	4084	Other Outage	Unplanned Outage	04-10-2025	19:08	04-10-2025	19:27	0:19	0.000459	HT SYSTEM FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
239	04-10-2025	Part of : BLOCK E SANGAM VIHAR	1654	Other Outage	Planned Outage	04-10-2025	11:03	04-10-2025	12:55	1:52	0.000342	3PH HT AB END TERMINATION REPLACEMENT
240	04-10-2025	Part of : BLOCK B DEVL I SANGAM VIHAR	883	Other Outage	Planned Outage	04-10-2025	11:02	04-10-2025	12:47	1:45	0.001458	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
241	04-10-2025	Part of : BLOCK G JJ COLONY DR AMBEDKAR NAGAR SECTOR 4 MADANGIR	1832	Other Outage	Planned Outage	04-10-2025	11:23	04-10-2025	14:19	2:56	0.000538	REPLACEMENT OF LT BUSHING ROD
242	04-10-2025	Part of : TIGRI EXTENSION TIGRI SANGAM VIHAR	1305	Other Outage	Planned Outage	04-10-2025	10:46	04-10-2025	12:54	2:08	0.000391	REPLACEMET OF HT BUSHING ROD
243	04-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR	2448	Other Outage	Planned Outage	04-10-2025	10:11	04-10-2025	12:53	2:42	0.000495	3PH HT AB CABLE REPLACEMENT PER SPAN
244	06-10-2025	Part of : TIGRI EXTENSION TIGRI SANGAM VIHAR	1	Other Outage	Unplanned Outage	06-10-2025	22:41	06-10-2025	23:26	0:45	0.000125	FAULT IN HT CONSUMER PANEL(VAYUSENABAD IAF)
245	06-10-2025	Part of : MADANGIRI PHASE-2	0	Other Outage	Planned Outage	06-10-2025	11:08	06-10-2025	14:10	3:02	0.000556	REPLACEMET OF HT BUSHING ROD
246	06-10-2025	Part of : BLOCK C & G VISHWAKARMA COLONY PULPEHLADPUR	1849	Other Outage	Planned Outage	06-10-2025	10:25	06-10-2025	13:48	3:23	0.000620	3PH HT AB CABLE REPLACEMENT PER SPAN
247	06-10-2025	Part of : BLOCK C DEVL I SANGAM VIHAR,BLOCK L DEVL I SANGAM VIHAR,BLOCK G DEVL I SANGAM VIHAR	3284	Other Outage	Planned Outage	06-10-2025	10:07	06-10-2025	12:57	2:50	0.000519	3PH HT AB END TERMINATION REPLACEMENT
248	08-10-2025	Part of : DEOLI GAON NAI BASTI SANGAM VIHAR	446	Other Outage	Unplanned Outage	08-10-2025	00:10	08-10-2025	00:22	0:12	0.000000	RMU BYPASS
249	08-10-2025	Part of : RAILWAY COLONY TUGHLAKABAD,BLOCK G VISHWAKARMA COLONY PULPEHLADPUR,HR-BLOCK PULPEHLADPUR	4918	Other Outage	Unplanned Outage	08-10-2025	12:05	08-10-2025	13:35	1:30	0.000625	REPAIR/REPLACEMENT OF DEFECTIVE MECHANISM
250	08-10-2025	Part of : BLOCK H DR AMBEDKAR NAGAR MADANGIR	1319	Other Outage	Planned Outage	08-10-2025	11:06	08-10-2025	14:01	2:55	0.000535	REPLACEMET OF HT BUSHING ROD
251	08-10-2025	Part of : BLOCK R ZTO F PULPEHLADPUR	10	Other Outage	Planned Outage	08-10-2025	11:21	08-10-2025	14:24	3:03	0.000559	REPLACEMET OF HT BUSHING ROD
252	08-10-2025	Part of : BLOCK J 1 DEVL I SANGAM VIHAR,BLOCK J 2 DEVL I SANGAM VIHAR	2186	Other Outage	Planned Outage	08-10-2025	10:35	08-10-2025	13:58	3:23	0.000620	3PH HT AB CABLE REPLACEMENT PER SPAN
253	08-10-2025	Part of : DEOLI GAON NAI BASTI SANGAM VIHAR,BLOCK A TIGRI EXTENSION SANGAM VIHAR	1606	Other Outage	Planned Outage	08-10-2025	10:07	08-10-2025	12:55	2:48	0.000513	3PH HT AB CABLE REPLACEMENT PER SPAN
254	09-10-2025	Part of : RAILWAY COLONY TUGHLAKABAD,BLOCK G VISHWAKARMA COLONY PULPEHLADPUR,HR-BLOCK PULPEHLADPUR,BLOCK B PULPEHLADPUR,DDA LIG FLATS PULPEHLADPUR,BLOCK C PULPEHLADPUR,BLOCK A PULPEHLADPUR	4918	Other Outage	Unplanned Outage	09-10-2025	16:59	09-10-2025	17:45	0:46	0.001303	HVDS FAULT
255	09-10-2025	Part of : BLOCK A JJ COLONY DR AMBEDKAR NAGAR SECTOR 4 MADANGIR,	1032	Other Outage	Planned Outage	09-10-2025	11:31	09-10-2025	12:35	1:04	0.000267	REPLACEMET OF HT BUSHING ROD
256	09-10-2025	Part of : BLOCK A VISHWAKARMA COLONY PULPEHLADPUR,BLOCK D VISHWAKARMA COLONY PULPEHLADPUR,BLOCK C VISHWAKARMA COLONY PULPEHLADPUR,	1894	Other Outage	Planned Outage	09-10-2025	10:52	09-10-2025	14:03	3:11	0.000584	3PH HT AB CABLE REPLACEMENT PER SPAN
257	09-10-2025	Part of : MADANGIR VILLAGE MADANGIR,	886	Other Outage	Planned Outage	09-10-2025	11:11	09-10-2025	13:53	2:42	0.000495	REPLACEMET OF HT BUSHING ROD
258	09-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR,	2780	Other Outage	Planned Outage	09-10-2025	10:15	09-10-2025	12:49	2:34	0.000471	3PH HT AB CABLE REPLACEMENT PER SPAN
259	10-10-2025	Part of : DURGA VIHAR DEVL I SANGAM VIHAR	441	Other Outage	Unplanned Outage	10-10-2025	10:41	10-10-2025	12:42	2:01	0.000504	MOBILE TRANSFORMER REPLACEMENT
260	10-10-2025	Part of : BLOCK C DEVL I SANGAM VIHAR	1315	Other Outage	Planned Outage	10-10-2025	11:09	10-10-2025	13:05	1:56	0.000354	REPLACEMET OF HT BUSHING ROD
261	10-10-2025	Part of : BLOCK B SECTOR 5 DAKSHINPURI,BLOCK A SECTOR 5 DAKSHINPURI	2626	Other Outage	Planned Outage	10-10-2025	11:54	10-10-2025	14:42	2:48	0.000513	REPLACEMET OF HT BUSHING ROD
262	10-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR	1467	Other Outage	Planned Outage	10-10-2025	10:15	10-10-2025	12:41	2:26	0.000446	3PH HT AB CABLE REPLACEMENT PER SPAN
263	10-10-2025	Part of : BLOCK A,C & D VISHWAKARMA COLONY PULPEHLADPUR	1894	Other Outage	Planned Outage	10-10-2025	10:21	10-10-2025	13:46	3:25	0.000626	3PH HT AB CABLE REPLACEMENT PER SPAN
264	11-10-2025	Part of : DEVL I BANDH ROAD SANGAM VIHAR	0	Other Outage	Unplanned Outage	11-10-2025	23:44	12-10-2025	00:25	0:41	0.000000	CABLE DAMAGE BY OUTSIDE AGENCY (DJB)
265	11-10-2025	Part of : B-BLOCK DEVL I SANGAM VIHAR	79	Other Outage	Planned Outage	11-10-2025	10:57	11-10-2025	12:18	1:21	0.000248	REPLACEMENT OF HT BUSHING ROD
266	11-10-2025	Part of : D-BLOCK SANGAM VIHAR	1341	Other Outage	Planned Outage	11-10-2025	10:56	11-10-2025	12:23	1:27	0.000266	REPLACEMENT OF HT BUSHING ROD
267	11-10-2025	Part of : F 2, F 3 & G 2-BLOCK G 2 SANGAM VIHAR	1295	Other Outage	Planned Outage	11-10-2025	10:59	11-10-2025	16:18	5:19	0.000975	3PH HT AB CABLE REPLACEMENT
268	11-10-2025	Part of : DURGA VIHAR DEVL I SANGAM VIHAR,POCKET B JAWAHAR PARK KHANPUR	507	Other Outage	Planned Outage	11-10-2025	11:03	11-10-2025	14:15	3:12	0.000587	3PH HT AB CABLE REPLACEMENT
269	11-10-2025	Part of : L 2-BLOCK DEVL I SANGAM VIHAR	908	Other Outage	Planned Outage	11-10-2025	11:34	11-10-2025	13:57	2:23	0.000437	REPLACEMENT OF HT BUSHING ROD
270	11-10-2025	Part of : LAL KUAN	525	Other Outage	Planned Outage	11-10-2025	11:16	11-10-2025	13:59	2:43	0.000498	REPLACEMENT OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
271	13-10-2025	Part of : BLOCK C LAL KUAN,BLOCK A VISHWAKARMA COLONY PULPEHLADPUR,BLOCK G VISHWAKARMA COLONY PULPEHLADPUR,BLOCK C VISHWAKARMA COLONY PULPEHLADPUR,BLOCK B VISHWAKARMA COLONY PULPEHLADPUR,BLOCK F VISHWAKARMA COLONY PULPEHLADPUR	2991	Other Outage	Unplanned Outage	13-10-2025	21:38	13-10-2025	22:07	0:29	0.000451	CABLE FAULT
272	13-10-2025	Part of : HTC:MTC:JAMIA HAMDARD UNIVERSITY	0	Other Outage	Unplanned Outage	13-10-2025	15:26	13-10-2025	16:11	0:45	0.001075	CABLE FAULT
273	13-10-2025	Part of : RPS COLONY MADANGIR,KHANPUR EXTENSION SANGAM VIHAR,POCKET A DUGGAL COLONY KHANPUR,KHANPUR VILLAGE KHANPUR,BLOCK G SECTOR 5 DAKSHINPURI,JAWAHAR PARK SANGAM VIHAR,	2303	Other Outage	Planned Outage	13-10-2025	14:26	13-10-2025	14:43	0:17	0.000000	GUARD WIRE LACS INSTALLTION PER SPAN
274	13-10-2025	Part of : DEOLI GAON NAI BASTI SANGAM VIHAR,	62	Other Outage	Planned Outage	13-10-2025	12:34	13-10-2025	13:22	0:48	0.000147	3PH HT AB CABLE REPLACEMENT PER SPAN
275	13-10-2025	Part of : KHANPUR VILLAGE KHANPUR,	223	Other Outage	Planned Outage	13-10-2025	13:46	13-10-2025	15:33	1:47	0.000327	3PH DB REVAMPING
276	13-10-2025	Part of : BLOCK B TIGRI EXTENSION SANGAM VIHAR,	1219	Other Outage	Planned Outage	13-10-2025	11:17	13-10-2025	13:08	1:51	0.000339	REPLACEMET OF HT BUSHING ROD
277	13-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR,	3440	Other Outage	Planned Outage	13-10-2025	11:53	13-10-2025	13:21	1:28	0.000269	3PH HT AB CABLE REPLACEMENT PER SPAN
278	13-10-2025	Part of : BLOCK A PULPEHLADPUR,HR-BLOCK PULPEHLADPUR,	1099	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	14:15	3:15	0.000596	3PH HT AB CABLE REPLACEMENT PER SPAN
279	13-10-2025	Part of : BLOCK D SANGAM VIHAR,	986	Other Outage	Planned Outage	13-10-2025	11:17	13-10-2025	13:59	2:42	0.000495	REPLACEMET OF HT BUSHING ROD
280	13-10-2025	Part of : SHIV PARK DUGGAL COLONY KHANPUR,	466	Other Outage	Planned Outage	13-10-2025	11:03	13-10-2025	13:41	2:38	0.000483	REPLACEMENT OF LT BUSHING ROD
281	14-10-2025	Part of : DDA LIG FLATS PULPEHLADPUR,BLOCK C, F & G VISHWAKARMA COLONY PULPEHLADPUR	1854	Other Outage	Unplanned Outage	14-10-2025	16:56	14-10-2025	17:16	0:20	0.000322	CABLE FAULT
282	14-10-2025	Part of : RPS COLONY MADANGIR	1738	Other Outage	Planned Outage	14-10-2025	12:14	14-10-2025	13:06	0:52	0.000578	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
283	14-10-2025	Part of : BLOCK C DEVL I SANGAM VIHAR	1041	Other Outage	Planned Outage	14-10-2025	13:31	14-10-2025	15:31	2:00	0.000367	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
284	14-10-2025	Part of : BLOCK A & B PULPEHLADPUR,HR-BLOCK PULPEHLADPUR	492	Other Outage	Planned Outage	14-10-2025	10:54	14-10-2025	13:53	2:59	0.000547	3PH HT AB CABLE REPLACEMENT PER SPAN
285	14-10-2025	Part of : JJ COLONY DR AMBEDKAR NAGAR SECTOR 4 MADANGIR	1429	Other Outage	Planned Outage	14-10-2025	11:24	14-10-2025	13:41	2:17	0.000419	REPLACEMENT OF LT BUSHING ROD
286	14-10-2025	Part of : BLOCK E SANGAM VIHAR	1411	Other Outage	Planned Outage	14-10-2025	11:14	14-10-2025	14:02	2:48	0.000513	REPLACEMENT OF HT BUSHING ROD
287	14-10-2025	Part of : BLOCK G DEVL I SANGAM VIHAR	3274	Other Outage	Planned Outage	14-10-2025	10:00	14-10-2025	12:54	2:54	0.000532	3PH HT AB END TERMINATION REPLACEMENT
288	15-10-2025	Part of : POCKET C JAWAHAR PARK KHANPUR	101	Other Outage	Planned Outage	15-10-2025	11:36	15-10-2025	13:56	2:20	0.000428	REPLACEMENT OF FAULTY END BOX
289	15-10-2025	Part of : DDA LIG FLATS PULPEHLADPUR,C & HR-BLOCK PULPEHLADPUR	2224	Other Outage	Planned Outage	15-10-2025	11:04	15-10-2025	13:40	2:36	0.000477	3PH HT AB CABLE REPLACEMENT
290	15-10-2025	Part of : JJ COLONY DR AMBEDKAR NAGAR SECTOR 4 MADANGIR	626	Other Outage	Planned Outage	15-10-2025	11:02	15-10-2025	13:57	2:55	0.000535	REPLACEMENT OF HT BUSHING ROD
291	15-10-2025	Part of : TALIMABAD SANGAM VIHAR	1560	Other Outage	Planned Outage	15-10-2025	10:52	15-10-2025	13:44	2:52	0.000526	REPLACEMENT OF HT BUSHING ROD
292	15-10-2025	Part of : L & L2-BLOCK L 2 DEVL I SANGAM VIHAR	1951	Other Outage	Planned Outage	15-10-2025	09:59	15-10-2025	12:57	2:58	0.000544	3PH HT AB END TERMINATION REPLACEMENT
293	16-10-2025	Part of : DR AMBEDKAR NAGAR MADANGIR	1767	Other Outage	Planned Outage	16-10-2025	12:02	16-10-2025	13:53	1:51	0.000339	REPLACEMET OF HT BUSHING ROD
294	16-10-2025	Part of : BLOCK J 1 DEVL I SANGAM VIHAR	2814	Other Outage	Planned Outage	16-10-2025	10:50	16-10-2025	13:52	3:02	0.000556	3PH HT AB CABLE REPLACEMENT PER SPAN
295	16-10-2025	Part of : BLOCK C VISHWAKARMA COLONY PULPEHLADPUR	286	Other Outage	Planned Outage	16-10-2025	11:32	16-10-2025	13:44	2:12	0.000403	REPLACEMET OF HT BUSHING ROD
296	16-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR	3411	Other Outage	Planned Outage	16-10-2025	09:57	16-10-2025	12:59	3:02	0.000556	3PH HT AB END TERMINATION REPLACEMENT
297	17-10-2025	Part of : BATRA HOSPITAL	0	Other Outage	Unplanned Outage	17-10-2025	12:59	17-10-2025	13:15	0:16	0.000000	CABLE FAULT
298	17-10-2025	Part of : JJ COLONY DUGGAL COLONY KHANPUR,POCKET C DUGGAL COLONY KHANPUR	767	Other Outage	Unplanned Outage	17-10-2025	20:14	17-10-2025	20:53	0:39	0.000000	HT SYSTEM FAULT
299	17-10-2025	Part of : TALIMABAD SANGAM VIHAR,	1560	Other Outage	Planned Outage	17-10-2025	10:51	17-10-2025	13:55	3:04	0.000562	REPLACEMET OF HT BUSHING ROD
300	17-10-2025	Part of : KHANPUR VILLAGE KHANPUR,	222	Other Outage	Planned Outage	17-10-2025	11:18	17-10-2025	13:56	2:38	0.000483	ACB REPLACEMENT PER ACB
301	17-10-2025	Part of : BLOCK L DEVL I SANGAM VIHAR,	3274	Other Outage	Planned Outage	17-10-2025	10:11	17-10-2025	13:00	2:49	0.000516	3PH HT AB END TERMINATION REPLACEMENT
302	20-10-2025	Part of : SURAJ CAMP,PREM NAGAR,AIRFORCE STATION,TUGHLAKABAD,TUKLAQABAD FORT	1276	Other Outage	Unplanned Outage	20-10-2025	17:17	20-10-2025	17:52	0:35	0.000418	BIRDAGE
303	23-10-2025	Part of : A & B -BLOCK SECTOR 5 DAKSHINPURI	2659	Other Outage	Unplanned Outage	23-10-2025	06:56	23-10-2025	07:37	0:41	0.000467	CABLE FAULT
304	24-10-2025	Part of : BLOCK D SANGAM VIHAR	986	Other Outage	Planned Outage	24-10-2025	11:45	24-10-2025	12:09	0:24	0.000073	REPLACEMENT OF HT BUSHING ROD
305	24-10-2025	Part of : BLOCK B CHUNGI NO 1 KOTLA MAHINGIRAN LAL KUAN	706	Other Outage	Planned Outage	24-10-2025	11:01	24-10-2025	13:55	2:54	0.000532	REPLACEMENT OF HT BUSHING ROD
306	24-10-2025	Part of : KHANPUR VILLAGE	813	Other Outage	Planned Outage	24-10-2025	11:02	24-10-2025	13:54	2:52	0.000526	REPLACEMENT OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
307	24-10-2025	Part of : BLOCK B DEVL I SANGAM VIHAR	1773	Other Outage	Planned Outage	24-10-2025	10:17	24-10-2025	12:50	2:33	0.000468	3PH HT AB CABLE REPLACEMENT PER SPAN
308	24-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR	2780	Other Outage	Planned Outage	24-10-2025	10:30	24-10-2025	12:46	2:16	0.000416	3PH HT AB END TERMINATION REPLACEMENT
309	25-10-2025	Part of : HTC: JAMIA HAMDARD UNIVERSITY	0	Other Outage	Unplanned Outage	25-10-2025	07:44	25-10-2025	08:28	0:44	0.000562	FAULT IN HT CONSUMER PANEL (JAMIA HAMDARD UNIVERSITY)
310	25-10-2025	Part of : BLOCK I 1 SANGAM VIHAR,	2022	Other Outage	Planned Outage	25-10-2025	11:36	25-10-2025	14:26	2:50	0.000519	REPLACEMET OF HT BUSHING ROD
311	25-10-2025	Part of : BLOCK B DEVL I SANGAM VIHAR,	752	Other Outage	Planned Outage	25-10-2025	11:08	25-10-2025	14:02	2:54	0.000532	REPLACEMET OF HT BUSHING ROD
312	25-10-2025	Part of : POCKET C RAJU PARK SANGAM VIHAR,	796	Other Outage	Planned Outage	25-10-2025	11:04	25-10-2025	14:10	3:06	0.000568	3PH HT AB CABLE REPLACEMENT PER SPAN
313	25-10-2025	Part of : BLOCK A VISHWAKARMA COLONY PULPEHLADPUR,BLOCK D VISHWAKARMA COLONY PULPEHLADPUR,BLOCK C VISHWAKARMA COLONY PULPEHLADPUR,	1894	Other Outage	Planned Outage	25-10-2025	10:15	25-10-2025	12:59	2:44	0.000501	3PH HT AB CABLE REPLACEMENT PER SPAN
314	27-10-2025	Part of : RAILWAY COLONY,G-BLOCK VISHWAKARMA COLONY,A,B,C & HR-BLOCK PULPEHLADPUR,DDA LIG FLATS	4944	Other Outage	Unplanned Outage	27-10-2025	23:20	27-10-2025	23:38	0:18	0.000265	HVDS FAULT
315	28-10-2025	Part of : RAILWAY COLONY TUGHLAKABAD, BLOCK G VISHWAKARMA COLONY PULPEHLADPUR,BLOCK A,B,C & HR PULPEHLADPUR,DDA LIG FLATS PULPEHLADPUR	4948	Other Outage	Unplanned Outage	28-10-2025	21:29	28-10-2025	21:49	0:20	0.000400	HT SYSTEM FAULT
316	28-10-2025	Part of : BATRA HOSPITAL (HTC)	0	Other Outage	Unplanned Outage	28-10-2025	16:17	28-10-2025	16:48	0:31	0.000000	CABLE FAULT
317	28-10-2025	Part of : BLOCK J 2 DEVL I SANGAM VIHAR	2469	Other Outage	Planned Outage	28-10-2025	11:15	28-10-2025	13:57	2:42	0.000495	3PH HT AB CABLE REPLACEMENT PER SPAN
318	28-10-2025	Part of : KHANPUR EXTENSION SANGAM VIHAR,KHANPUR VILLAGE,POCKET A DUGGAL COLONY KHANPUR	1230	Other Outage	Planned Outage	28-10-2025	10:53	28-10-2025	14:09	3:16	0.000599	3PH HT AB CABLE REPLACEMENT PER SPAN
319	28-10-2025	Part of : BLOCK J DEVL I SANGAM VIHAR	1007	Other Outage	Planned Outage	28-10-2025	11:03	28-10-2025	14:03	3:00	0.000550	REPLACEMET OF HT BUSHING ROD
320	28-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR	2782	Other Outage	Planned Outage	28-10-2025	10:12	28-10-2025	12:57	2:45	0.000504	3PH HT AB CABLE REPLACEMENT PER SPAN
321	29-10-2025	Part of : DR AMBEDKAR NAGAR MADANGIR,	1768	Other Outage	Planned Outage	29-10-2025	12:07	29-10-2025	14:02	1:55	0.000351	REPLACEMET OF HT BUSHING ROD
322	29-10-2025	Part of : BLOCK B JJ COLONY KHANPUR,	1468	Other Outage	Planned Outage	29-10-2025	11:45	29-10-2025	13:23	1:38	0.000299	GUARD WIRES SAGGING PER SPAN
323	29-10-2025	Part of : BLOCK A PULPEHLADPUR,BLOCK RZ H PULPEHLADPUR,BLOCK C PULPEHLADPUR,HR-BLOCK PULPEHLADPUR,BLOCK R ZTO F PULPEHLADPUR,	781	Other Outage	Planned Outage	29-10-2025	11:20	29-10-2025	13:58	2:38	0.000483	3PH HT AB CABLE REPLACEMENT PER SPAN
324	29-10-2025	Part of : BLOCK I 1 SANGAM VIHAR,	2022	Other Outage	Planned Outage	29-10-2025	11:12	29-10-2025	13:50	2:38	0.000483	REPLACEMET OF HT BUSHING ROD
325	29-10-2025	Part of : BLOCK L 2 DEVL I SANGAM VIHAR,	3411	Other Outage	Planned Outage	29-10-2025	09:58	29-10-2025	13:03	3:05	0.000565	3PH HT AB END TERMINATION REPLACEMENT
326	30-10-2025	Part of : ASOLA WILD LIFE SANCTUARY, TUGHLAKABAD	824	Other Outage	Planned Outage	30-10-2025	11:30	30-10-2025	14:06	2:36	0.000477	REPLACEMENT OF HT BUSHING ROD
327	30-10-2025	Part of : JAWAHAR PARK SANGAM VIHAR,POCKET C JAWAHAR PARK KHANPUR	101	Other Outage	Planned Outage	30-10-2025	10:46	30-10-2025	13:43	2:57	0.000541	3PH HT AB CABLE REPLACEMENT PER SPAN
328	30-10-2025	Part of : BLOCK G VISHWAKARMA COLONY PULPEHLADPUR,BLOCK B & C VISHWAKARMA COLONY PULPEHLADPUR,BLOCK C LAL KUAN	1849	Other Outage	Planned Outage	30-10-2025	10:08	30-10-2025	13:04	2:56	0.000538	3PH HT AB CABLE REPLACEMENT PER SPAN
329	31-10-2025	Part of : L 2-BLOCK DEVL I SANGAM VIHAR	1467	Other Outage	Planned Outage	31-10-2025	10:11	31-10-2025	11:57	1:46	0.000324	3PH HT AB END TERMINATION REPLACEMENT
330	31-10-2025	Part of : G 2 & H-BLOCK SANGAM VIHAR	2332	Other Outage	Planned Outage	31-10-2025	11:32	31-10-2025	15:02	3:30	0.000642	3PH HT AB CABLE REPLACEMENT
331	31-10-2025	Part of : SECTOR 7 PUSHPA VIHAR,MADANGIR VILLAGE,DR AMBEDKAR NAGAR MADANGIR,JAHANPANAH CITY FOREST	3425	Other Outage	Planned Outage	31-10-2025	11:10	31-10-2025	14:01	2:51	0.000523	REPLACEMET OF HT BUSHING ROD
332	31-10-2025	Part of : DURGA VIHAR DEVL I SANGAM VIHAR	877	Other Outage	Planned Outage	31-10-2025	10:08	31-10-2025	12:50	2:42	0.000900	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
333	02-10-2025	Part of : MUJEEB BAGH JAMIA NAGAR OKHLA,NOOR NAGAR OKHLA,JAMIA NAGAR OKHLA	551	Other Outage	Unplanned Outage	02-10-2025	11:35	02-10-2025	12:02	0:27	0.000150	CABLE FAULT
334	02-10-2025	Part of : BLOCK J & E PART 1 ABUL FAZAL ENCLAVE JAMIA NAGAR OKHLA	3175	Other Outage	Unplanned Outage	02-10-2025	18:02	02-10-2025	18:35	0:33	0.000578	HT SYSTEM FAULT
335	02-10-2025	Part of : MASHGARH OKHLA,POCKET A & B SUKHDEV VIHAR OKHLA	1272	Other Outage	Unplanned Outage	02-10-2025	12:08	02-10-2025	12:51	0:43	0.000561	CABLE FAULT
336	03-10-2025	Part of : BLOCK C SHAHEEN BAGH JASOLA VIHAR	1390	Other Outage	Planned Outage	03-10-2025	14:41	03-10-2025	16:54	2:13	0.001921	REPLACEMENT OF GAS KIT AND OIL SEAL
337	03-10-2025	Part of : BLOCK D NEW FRIENDS COLONY EAST	780	Other Outage	Planned Outage	03-10-2025	11:11	03-10-2025	14:24	3:13	0.001608	REPLACEMET OF HT CLEATS
338	04-10-2025	Part of : JAMIA NAGAR OKHLA	857	Other Outage	Planned Outage	04-10-2025	12:57	04-10-2025	16:09	3:12	0.001333	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
339	04-10-2025	Part of : ISWAR NAGAR NEW FRIENDS COLONY	163	Other Outage	Planned Outage	04-10-2025	11:02	04-10-2025	13:54	2:52	0.000478	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN,TIGHTENING OF HARDWARE FITTINGS
340	06-10-2025	Part of : NOOR NAGAR OKHLA	1805	Other Outage	Planned Outage	06-10-2025	13:18	06-10-2025	15:59	2:41	0.002236	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
341	06-10-2025	Part of : POCKET B SUKHDEV VIHAR OKHLA	311	Other Outage	Planned Outage	06-10-2025	11:06	06-10-2025	14:16	3:10	0.000000	AUXILARY SUPPLY FOR RELAYS,CT REPLACEMET,DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE,END TERMINATION COVER REPLACEMENT,REPLACEMET OF FAULTY END BOX
342	06-10-2025	Part of : EAST NEW FRIENDS COLONY	140	Other Outage	Planned Outage	06-10-2025	11:03	06-10-2025	14:15	3:12	0.001600	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
343	06-10-2025	Part of : VILLAGE JASOLA JASOLA VIHAR	683	Other Outage	Planned Outage	06-10-2025	10:17	06-10-2025	12:45	2:28	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
344	08-10-2025	Part of : GAFOOR NAGAR OKHLA	768	Other Outage	Unplanned Outage	08-10-2025	16:34	08-10-2025	17:33	0:59	0.000410	REPLACEMENT OF SOCKETS
345	08-10-2025	Part of : GAFOOR NAGAR OKHLA	768	Other Outage	Planned Outage	08-10-2025	13:44	08-10-2025	16:21	2:37	0.001308	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
346	08-10-2025	Part of : BLOCK R JOGA BAI OKHLA	2568	Other Outage	Planned Outage	08-10-2025	11:11	08-10-2025	14:12	3:01	0.002263	CHECKING VALUE OF FENCING EARTHING,INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS
347	08-10-2025	Part of : SUKHDEV VIHAR OKHLA	778	Other Outage	Planned Outage	08-10-2025	11:11	08-10-2025	14:15	3:04	0.001533	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
348	09-10-2025	Part of : BLOCK R JOGA BAI OKHLA,	4590	Other Outage	Planned Outage	09-10-2025	12:59	09-10-2025	16:50	3:51	0.003529	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD
349	09-10-2025	Part of : BLOCK K PART 1 ABUL FAZAL ENCLAVE JAMIA NAGAR OKHLA,	1065	Other Outage	Planned Outage	09-10-2025	10:33	09-10-2025	13:12	2:39	0.002297	REPLACEMENT OF LT BUSHING ROD
350	10-10-2025	Part of : BLOCK C JOGA BAI EXTENSION OKHLA	1148	Other Outage	Unplanned Outage	10-10-2025	16:50	10-10-2025	17:32	0:42	0.000793	CABLE FAULT
351	10-10-2025	Part of : NEW FRIENDS COLONY EAST NEW	138	Other Outage	Planned Outage	10-10-2025	10:59	10-10-2025	13:53	2:54	0.001692	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
352	11-10-2025	Part of : NOOR NAGAR OKHLA	477	Other Outage	Planned Outage	11-10-2025	14:37	11-10-2025	16:28	1:51	0.000771	APPLY OF INSULATION TAPE HT/LT BUSHINGS
353	13-10-2025	Part of : NOOR NAGAR OKHLA,	1508	Other Outage	Planned Outage	13-10-2025	13:00	13-10-2025	16:33	3:33	0.002958	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
354	13-10-2025	Part of : BLOCK D NEW FRIENDS COLONY EAST NEW FRIENDS COLONY,	456	Other Outage	Planned Outage	13-10-2025	10:58	13-10-2025	14:27	3:29	0.002032	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
355	14-10-2025	Part of : JOGA BAI OKHLA	716	Other Outage	Planned Outage	14-10-2025	12:57	14-10-2025	14:46	1:49	0.001968	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING
356	15-10-2025	Part of : POCKET 8 JASOLA VIHAR	258	Other Outage	Planned Outage	15-10-2025	11:16	15-10-2025	13:35	2:19	0.002008	REPLACEMENT OF HT BUSHING ROD
357	15-10-2025	Part of : POCKET A SUKHDEV VIHAR OKHLA	445	Other Outage	Planned Outage	15-10-2025	11:07	15-10-2025	13:44	2:37	0.001526	REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS
358	16-10-2025	Part of : NOOR NAGAR OKHLA	477	Other Outage	Planned Outage	16-10-2025	11:01	16-10-2025	11:30	0:29	0.000306	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
359	16-10-2025	Part of : AZIM DAIRY OKHLA	765	Other Outage	Planned Outage	16-10-2025	13:02	16-10-2025	15:26	2:24	0.000800	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
360	16-10-2025	Part of : BLOCK A NEW FRIENDS COLONY EAST	166	Other Outage	Planned Outage	16-10-2025	11:04	16-10-2025	13:37	2:33	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
361	17-10-2025	Part of : OKHLA VILLAGE OKHLA,AZIM DAIRY OKHLA,BATLA HOUSE OKHLA	4245	Other Outage	Unplanned Outage	17-10-2025	08:47	17-10-2025	09:20	0:33	0.000623	HT SYSTEM FAULT
362	17-10-2025	Part of : JAMIA NAGAR OKHLA,	857	Other Outage	Planned Outage	17-10-2025	11:13	17-10-2025	12:10	0:57	0.000570	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS
363	17-10-2025	Part of : NOOR NAGAR OKHLA,	1508	Other Outage	Planned Outage	17-10-2025	13:07	17-10-2025	14:09	1:02	0.000637	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,SUB STATION CLEANING
364	17-10-2025	Part of : BLOCK N PART 1 ABUL FAZAL ENCLAVE JAMIA NAGAR OKHLA,	1299	Other Outage	Planned Outage	17-10-2025	14:04	17-10-2025	16:33	2:29	0.002276	REPLACEMENT OF LT BUSHING ROD
365	18-10-2025	Part of : CANAL COLONY OKHLA	856	Other Outage	Planned Outage	18-10-2025	10:31	18-10-2025	12:27	1:56	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
366	23-10-2025	Part of : MUJEEB BAGH JAMIA NAGAR OKHLA,	1597	Other Outage	Planned Outage	23-10-2025	12:58	23-10-2025	15:41	2:43	0.001675	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
367	23-10-2025	Part of : G-BLOCK ABUL FAZAL ENCLAVE PART 1 JAMIA NAGAR OKHLA	1924	Other Outage	Planned Outage	23-10-2025	10:08	23-10-2025	12:50	2:42	0.000135	REPLACEMENT OF HT BUSHING ROD
368	24-10-2025	Part of : BATLA HOUSE OKHLA	1812	Other Outage	Planned Outage	24-10-2025	13:09	24-10-2025	14:09	1:00	0.000917	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,REPLACEMENT OF SILICAGEL IN BREATHER
369	24-10-2025	Part of : BLOCK G SRINIVAS PURI	350	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	13:35	2:14	0.000931	GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT/LT CLEATS,TIGHTENEING OF NUT BOLT
370	25-10-2025	Part of : BLOCK B JOGA BAI EXTENSION JOGA BAI OKHLA,	1649	Other Outage	Planned Outage	25-10-2025	12:01	25-10-2025	15:08	3:07	0.001922	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),REPLACEMET OF HT/LT CLEATS
371	25-10-2025	Part of : SUKHDEV VIHAR OKHLA,	781	Other Outage	Planned Outage	25-10-2025	10:58	25-10-2025	13:48	2:50	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
372	25-10-2025	Part of : SUKHDEV VIHAR OKHLA,	54	Other Outage	Planned Outage	25-10-2025	10:58	25-10-2025	13:04	2:06	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR
373	28-10-2025	Part of : BLOCK H & G SRINIVAS PURI, NURSING HOSTEL SRINIVASPURI (HTC)	1012	Other Outage	Unplanned Outage	28-10-2025	09:23	28-10-2025	09:51	0:28	0.000000	CABLE FAULT
374	28-10-2025	Part of : OKHLA VILLAGE, AZIM DAIRY OKHLA, BATLA HOUSE OKHLA	4246	Other Outage	Unplanned Outage	28-10-2025	15:31	28-10-2025	16:19	0:48	0.000920	CABLE FAULT
375	28-10-2025	Part of : SARAI JALINA OKHLA	201	Other Outage	Planned Outage	28-10-2025	10:59	28-10-2025	13:12	2:13	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
376	28-10-2025	Part of : NEW FRIENDS COLONY EAST	142	Other Outage	Planned Outage	28-10-2025	11:05	28-10-2025	13:14	2:09	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
377	29-10-2025	Part of : SARAI JALINA OKHLA,	1197	Other Outage	Planned Outage	29-10-2025	12:58	29-10-2025	15:08	2:10	0.000903	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
378	29-10-2025	Part of : BLOCK C OKHLA VIHAR JAMIA NAGAR OKHLA,	1535	Other Outage	Planned Outage	29-10-2025	10:25	29-10-2025	13:07	2:42	0.002340	REPLACEMENT OF LT BUSHING ROD
379	30-10-2025	Part of : POCKET 1 JASOLA VIHAR	772	Other Outage	Unplanned Outage	30-10-2025	18:20	30-10-2025	18:45	0:25	0.000125	CABLE FAULT
380	30-10-2025	Part of : BLOCK B TAIMOOR NAGAR NEW FRIENDS COLONY	1058	Other Outage	Planned Outage	30-10-2025	10:58	30-10-2025	13:46	2:48	0.000000	REPLACEMENT OF FAULTY END BOX
381	30-10-2025	Part of : VILLAGE JASOLA JASOLA VIHAR	1160	Other Outage	Planned Outage	30-10-2025	10:00	30-10-2025	12:43	2:43	0.002038	REPLACEMENT OF LT BUSHING ROD
382	31-10-2025	Part of : A & C-BLOCK SHAHEEN BAGH JASOLA VIHAR	3089	Other Outage	Unplanned Outage	31-10-2025	14:40	31-10-2025	15:17	0:37	0.000442	CABLE FAULT
383	31-10-2025	Part of : POCKET A SUKHDEV VIHAR OKHLA	470	Other Outage	Planned Outage	31-10-2025	11:00	31-10-2025	13:44	2:44	0.001822	REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING
384	03-10-2025	Part of : OKHLA INDUSTRIAL AREA PHASE-3	59	Other Outage	Unplanned Outage	03-10-2025	13:38	03-10-2025	14:30	0:52	0.002051	HT SYSTEM FAULT
385	03-10-2025	Part of : CSP FLATS EAST OF KAILASH	474	Other Outage	Unplanned Outage	03-10-2025	12:05	03-10-2025	12:53	0:48	0.000413	CABLE FAULT
386	03-10-2025	Part of : POCKET E & Z OKHLA INDUSTRIAL AREA PHASE 2	142	Other Outage	Unplanned Outage	03-10-2025	03:03	03-10-2025	04:18	1:15	0.000813	CABLE FAULT
387	05-10-2025	Part of : BLOCK 2 NIRMAL COLONY LAJPAT NAGAR IV LAJPAT NAGAR,KAILASH COLONY GREATER KAILASH,OKHLA PHASE III OKHLA INDUSTRIAL AREA,BLOCK M GREATER KAILASH I GREATER KAILASH	219	Other Outage	Unplanned Outage	05-10-2025	09:29	05-10-2025	10:19	0:50	0.000736	TREE TOUCHING
388	05-10-2025	Part of : OKHLA PHASE III OKHLA INDUSTRIAL AREA,BLOCK G KAILASH HILL EAST OF KAILASH	219	Other Outage	Unplanned Outage	05-10-2025	15:08	05-10-2025	16:11	1:03	0.000438	TRANSIENT FAULT
389	05-10-2025	Part of : POCKET E OKHLA PHASE II OKHLA INDUSTRIAL AREA,	70	Other Outage	Planned Outage	05-10-2025	11:09	05-10-2025	14:00	2:51	0.001663	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING ROD
390	06-10-2025	Part of : BLOCK W GREATER KAILASH I GREATER KAILASH,SIRI FORT	909	Other Outage	Unplanned Outage	06-10-2025	16:47	06-10-2025	17:35	0:48	0.000853	HT SYSTEM FAULT
391	06-10-2025	Part of : OKHLA PHASE III OKHLA INDUSTRIAL AREA	59	Other Outage	Unplanned Outage	06-10-2025	15:11	06-10-2025	16:01	0:50	0.001597	HT SYSTEM FAULT
392	06-10-2025	Part of : POCKET C OKHLA PHASE II OKHLA INDUSTRIAL AREA	313	Other Outage	Unplanned Outage	06-10-2025	09:50	06-10-2025	10:56	1:06	0.000458	CABLE FAULT
393	06-10-2025	Part of : BLOCK C GREATER KAILASH I	146	Other Outage	Planned Outage	06-10-2025	11:06	06-10-2025	15:26	4:20	0.003756	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
394	08-10-2025	Part of : BLOCK A DAYANAND COLONY LAJPAT NAGAR	281	Other Outage	Planned Outage	08-10-2025	10:05	08-10-2025	11:52	1:47	0.001546	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
395	09-10-2025	Part of : BLOCK A OKHLA PHASE II OKHLA INDUSTRIAL AREA	47	Other Outage	Unplanned Outage	09-10-2025	03:50	09-10-2025	05:03	1:13	0.000203	FAULT IN HT CONSUMER PANEL (ESS NO. 2 INSIDE DSIIDC COMPLEX)
396	09-10-2025	Part of : BLOCK H KAILASH COLONY GREATER KAILASH,	375	Other Outage	Planned Outage	09-10-2025	11:01	09-10-2025	17:17	6:16	0.005431	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
397	11-10-2025	Part of : CSP FLATS EAST OF KAILASH	474	Other Outage	Unplanned Outage	11-10-2025	11:39	11-10-2025	15:02	3:23	0.000000	MAINTENANCE/REPAIR OF RMU
398	11-10-2025	Part of : S-BLOCK GREATER KAILASH-1	335	Other Outage	Planned Outage	11-10-2025	11:44	11-10-2025	16:16	4:32	0.003929	APPLY OF INSULATION TAPE HT/LT BUSHINGS

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
399	12-10-2025	Part of : POCKET A SANJAY COLONY II OKHLA PHASE II OKHLA INDUSTRIAL AREA	488	Other Outage	Planned Outage	12-10-2025	11:01	12-10-2025	13:54	2:53	0.001922	REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER
400	13-10-2025	Part of : POCKET Z OKHLA PHASE II OKHLA INDUSTRIAL AREA,POCKET B OKHLA PHASE II OKHLA INDUSTRIAL AREA,POCKET X OKHLA PHASE II OKHLA INDUSTRIAL AREA	560	Other Outage	Unplanned Outage	13-10-2025	01:32	13-10-2025	02:24	0:52	0.000448	HT SYSTEM FAULT
401	14-10-2025	Part of : BLOCK N GREATER KAILASH I	588	Other Outage	Planned Outage	14-10-2025	14:11	14-10-2025	16:02	1:51	0.001603	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
402	14-10-2025	Part of : BLOCK A KAILASH COLONY GREATER KAILASH	133	Other Outage	Planned Outage	14-10-2025	10:58	14-10-2025	12:55	1:57	0.001690	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
403	14-10-2025	Part of : BLOCK A APB GARHI EAST OF KAILASH	673	Other Outage	Planned Outage	14-10-2025	09:58	14-10-2025	12:56	2:58	0.002571	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR
404	15-10-2025	Part of : R-BLOCK GREATER KAILASH-1	340	Other Outage	Planned Outage	15-10-2025	11:18	15-10-2025	13:47	2:29	0.002152	APPLY OF INSULATION TAPE HT/LT BUSHINGS
405	16-10-2025	Part of : POCKET B & C OKHLA PHASE II OKHLA INDUSTRIAL AREA	1578	Other Outage	Unplanned Outage	16-10-2025	19:20	16-10-2025	20:03	0:43	0.000776	HT SYSTEM FAULT
406	16-10-2025	Part of : HARKESH NAGAR OKHLA INDUSTRIAL AREA	1678	Other Outage	Planned Outage	16-10-2025	11:01	16-10-2025	13:53	2:52	0.001911	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
407	16-10-2025	Part of : HEMKUNT COLONY GREATER KAILASH	184	Other Outage	Planned Outage	16-10-2025	11:43	16-10-2025	13:58	2:15	0.001950	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
408	16-10-2025	Part of : KAILASH HILL EAST OF KAILASH	493	Other Outage	Planned Outage	16-10-2025	09:58	16-10-2025	13:16	3:18	0.002860	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,REPLACMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
409	17-10-2025	Part of : SHYAM NAGAR OKHLA INDUSTRIAL AREA	195	Other Outage	Unplanned Outage	17-10-2025	14:06	17-10-2025	14:41	0:35	0.000788	BIRDAGE
410	17-10-2025	Part of : BLOCK G KAILASH HILL EAST OF KAILASH,	253	Other Outage	Planned Outage	17-10-2025	09:58	17-10-2025	12:56	2:58	0.002472	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF HT/LT CLEATS,REPLACMET OF LUGS,SUB STATION CLEANING
411	24-10-2025	Part of : MOUNT KAILASH APARTMENT EAST OF KAILASH	116	Other Outage	Planned Outage	24-10-2025	10:01	24-10-2025	11:55	1:54	0.001647	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
412	25-10-2025	Part of : CSP FLATS EAST OF KAILASH,	474	Other Outage	Unplanned Outage	25-10-2025	14:04	25-10-2025	15:12	1:08	0.000944	DIGGING ON CABLE ROUTE
413	25-10-2025	Part of : BLOCK Q LAJPAT NAGAR IV LAJPAT NAGAR,	486	Other Outage	Unplanned Outage	25-10-2025	14:00	25-10-2025	15:57	1:57	0.001138	DIGGING ON CABLE ROUTE

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
414	25-10-2025	Part of : BLOCK M GREATER KAILASH I GREATER KAILASH,	95	Other Outage	Planned Outage	25-10-2025	11:16	25-10-2025	15:31	4:15	0.003683	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
415	26-10-2025	Part of : POCKET B OKHLA PHASE II OKHLA INDUSTRIAL AREA	976	Other Outage	Planned Outage	26-10-2025	11:03	26-10-2025	13:56	2:53	0.000000	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
416	29-10-2025	Part of : BLOCK C ENCLAVE 1 GREATER KAILASH,	171	Other Outage	Planned Outage	29-10-2025	11:11	29-10-2025	14:00	2:49	0.002441	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
417	30-10-2025	Part of : MASJID MOTH GREATER KAILASH	359	Other Outage	Planned Outage	30-10-2025	11:01	30-10-2025	13:58	2:57	0.002557	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
418	31-10-2025	Part of : POCKET D & T OKHLA INDUSTRIAL AREA PHASE-2,SHYAM NAGAR	449	Other Outage	Unplanned Outage	31-10-2025	05:32	31-10-2025	06:20	0:48	0.000120	TRANIENSET FAULT
419	31-10-2025	Part of : POCKET D & T OKHLA INDUSTRIAL AREA PHASE-2,SHYAM NAGAR	449	Other Outage	Unplanned Outage	31-10-2025	07:37	31-10-2025	09:19	1:42	0.000510	HT SYSTEM FAULT
420	31-10-2025	Part of : Q-BLOCK LAJPAT NAGAR IV	470	Other Outage	Planned Outage	31-10-2025	09:58	31-10-2025	12:55	2:57	0.001229	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
421	03-10-2025	Part of : BLOCK C 2 LODI COLONY	232	Other Outage	Planned Outage	03-10-2025	11:29	03-10-2025	14:22	2:53	0.004806	REPLACEMET OF HT BUSHING ROD
422	03-10-2025	Part of : BLOCK L LAJPAT NAGAR-2	816	Other Outage	Planned Outage	03-10-2025	11:04	03-10-2025	15:27	4:23	0.002995	REPLACEMET OF HT BUSHING ROD
423	03-10-2025	Part of : SUNDAR NAGAR	159	Other Outage	Planned Outage	03-10-2025	11:23	03-10-2025	15:24	4:01	0.001406	REPLACEMET OF HT BUSHING ROD
424	04-10-2025	Part of : SARAI KALE KHAN, SARAI KALE KHAN VILLAGE, BLOCK A GANGA VIHAR, ASST HORTICULTURE SARAI KALE KHAN (HTC)	1737	Other Outage	Unplanned Outage	04-10-2025	12:35	04-10-2025	13:18	0:43	0.000657	CABLE DAMAGED BY OUTSIDE AGENCY (DJB)
425	05-10-2025	Part of : SIDDHARTHA ENCLAVE SUNLIGHT COLONY,SUNLIGHT COLONY	883	Other Outage	Unplanned Outage	05-10-2025	00:14	05-10-2025	00:44	0:30	0.000308	CABLE FAULT
426	06-10-2025	Part of : NATIONAL ZOOLOGICAL PARK SUNDAR NAGAR,SUNDAR NAGAR	251	Other Outage	Unplanned Outage	06-10-2025	22:52	06-10-2025	23:39	0:47	0.000222	HT SYSTEM FAULT
427	06-10-2025	Part of : BEHLOLPUR BANGAR SARAI KALE KHAN,NIZAMUDDIN EAST,BLOCK B SARAI KALE KHAN,BLOCK A SARAI KALE KHAN	3017	Other Outage	Unplanned Outage	06-10-2025	11:23	06-10-2025	12:14	0:51	0.000000	CABLE FAULT
428	06-10-2025	Part of : BLOCK C LAJPAT NAGAR II	1253	Other Outage	Planned Outage	06-10-2025	11:40	06-10-2025	15:55	4:15	0.002692	REPLACEMET OF HT BUSHING ROD
429	06-10-2025	Part of : BLOCK D DEFENCE COLONY	113	Other Outage	Planned Outage	06-10-2025	11:48	06-10-2025	15:54	4:06	0.000683	REPLACEMET OF HT BUSHING ROD
430	07-10-2025	Part of : B & D-BLOCK SARAI KALE KHAN,A-BLOCK GANGA VIHAR	1737	Other Outage	Unplanned Outage	07-10-2025	13:50	07-10-2025	14:43	0:53	0.001266	CABLE FAULT
431	07-10-2025	Part of : B,E,F & M-BLOCK SEWA NAGAR,,KASTURBA NAGAR SEWA NAGAR	3012	Other Outage	Unplanned Outage	07-10-2025	06:59	07-10-2025	07:50	0:51	0.000949	CABLE FAULT
432	08-10-2025	Part of : RISHI NAGAR, PREM NAGAR BK DUTT COLONY, AMRIT NAGAR, PILLANGI VILLAGE KOTLA MUBARAKPUR	2115	Other Outage	Unplanned Outage	08-10-2025	11:11	08-10-2025	12:15	1:04	0.000604	HT SYSTEM FAULT
433	08-10-2025	Part of : BLOCK M JANGUPURA EXTENSION	195	Other Outage	Planned Outage	08-10-2025	13:21	08-10-2025	14:39	1:18	0.000325	REPLACEMET OF HT BUSHING ROD
434	08-10-2025	Part of : BLOCK D DEFENCE COLONY	91	Other Outage	Planned Outage	08-10-2025	11:23	08-10-2025	14:36	3:13	0.000536	REPLACEMET OF HT BUSHING ROD
435	09-10-2025	Part of : NATIONAL ZOOLOGICAL PARK SUNDAR NAGAR,SUNDAR NAGAR	209	Other Outage	Unplanned Outage	09-10-2025	20:23	09-10-2025	21:14	0:51	0.000312	FAULT IN HT CONSUMER PANEL (D.P.S SCHOOL, SUNDER NAGAR)
436	09-10-2025	Part of : HTC:TYAGRAJ STADIUM	0	Other Outage	Unplanned Outage	09-10-2025	10:38	09-10-2025	11:15	0:37	0.000000	CABLE FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
437	09-10-2025	Part of : SIDDHARTHA ENCLAVE SUNLIGHT COLONY,	534	Other Outage	Planned Outage	09-10-2025	11:27	09-10-2025	15:38	4:11	0.005369	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),REPLACEMET OF HT/LT CLEATS
438	09-10-2025	Part of : BLOCK C DEFENCE COLONY,	359	Other Outage	Planned Outage	09-10-2025	11:22	09-10-2025	15:34	4:12	0.003500	REPLACEMENT OF LT BUSHING ROD
439	10-10-2025	Part of : ISBT SARAI KALE KHAN SARAI KALE KHAN,BLOCK A GANGA VIHAR SARAI KALE KHAN	13	Other Outage	Unplanned Outage	10-10-2025	12:42	10-10-2025	13:11	0:29	0.000789	CABLE FAULT
440	10-10-2025	Part of : BLOCK G SOUTH EXTENSION PART 1	55	Other Outage	Planned Outage	10-10-2025	11:13	10-10-2025	14:07	2:54	0.000580	REPLACEMET OF HT BUSHING ROD
441	11-10-2025	Part of : H & L-BLOCK LAJPAT NAGAR-2,KASTURBA NIKETAN NEAR BARAT GHAR	822	Other Outage	Unplanned Outage	11-10-2025	19:20	11-10-2025	20:06	0:46	0.000000	HVDS FAULT
442	11-10-2025	Part of : B,E,F & M-BLOCK SEWA NAGAR,KASTURBA NAGAR	3012	Other Outage	Unplanned Outage	11-10-2025	08:29	11-10-2025	09:23	0:54	0.001485	CABLE FAULT
443	11-10-2025	Part of : RISHI NAGAR SOUTH EXTENSION PART-1	646	Other Outage	Unplanned Outage	11-10-2025	15:23	11-10-2025	17:09	1:46	0.000736	GAS REFILLING
444	11-10-2025	Part of : SOOCHNA BHAWAN & CGO COMPLEX (HT CONSUMER)	0	Other Outage	Unplanned Outage	11-10-2025	11:49	11-10-2025	14:50	3:01	0.000251	RELAY REPLACEMENT
445	11-10-2025	Part of : J-BLOCK SOUTH EXTENSION PART-1	157	Other Outage	Planned Outage	11-10-2025	11:09	11-10-2025	14:06	2:57	0.000983	REPLACEMENT OF HT BUSHING ROD
446	11-10-2025	Part of : PRAGATI VIHAR	12	Other Outage	Planned Outage	11-10-2025	11:08	11-10-2025	14:02	2:54	0.000967	REPLACEMENT OF HT BUSHING ROD
447	13-10-2025	Part of : BLOCK A LAJPAT NAGAR II LAJPAT NAGAR,	401	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	15:47	4:47	0.001594	REPLACEMET OF HT BUSHING ROD
448	13-10-2025	Part of : DEFENCE COLONY BHOGAL JANGPURA,	500	Other Outage	Planned Outage	13-10-2025	11:02	13-10-2025	14:51	3:49	0.001272	REPLACEMET OF HT BUSHING ROD
449	13-10-2025	Part of : BLOCK N SOUTH EXTENSION PART 1,	426	Other Outage	Planned Outage	13-10-2025	10:55	13-10-2025	14:25	3:30	0.001167	REPLACEMET OF HT BUSHING ROD
450	14-10-2025	Part of : BLOCK E, F & M SEWA NAGAR,KASTURBA NAGAR SEWA NAGAR	3012	Other Outage	Unplanned Outage	14-10-2025	13:32	14-10-2025	14:23	0:51	0.001020	CABLE DAMAGED BY OUTSIDE AGENCY ITDC
451	14-10-2025	Part of : BLOCK H LAJPAT NAGAR III	55	Other Outage	Planned Outage	14-10-2025	11:20	14-10-2025	15:02	3:42	0.000925	REPLACEMENT OF HT BUSHING ROD
452	14-10-2025	Part of : BLOCK A DEFENCE COLONY	53	Other Outage	Planned Outage	14-10-2025	11:22	14-10-2025	15:00	3:38	0.000908	REPLACEMENT OF HT BUSHING ROD
453	14-10-2025	Part of : AVIATION COLONY INA COLONY	65	Other Outage	Planned Outage	14-10-2025	11:31	14-10-2025	14:58	3:27	0.000863	REPLACEMENT OF HT BUSHING ROD
454	14-10-2025	Part of : SUNLIGHT COLONY	1724	Other Outage	Planned Outage	14-10-2025	11:10	14-10-2025	14:59	3:49	0.002863	REPLACEMENT OF HT BUSHING ROD
455	15-10-2025	Part of : DEFENCE COLONY,JAWAHARLAL NEHRU STADIUM PRAGATI VIHAR	5	Other Outage	Unplanned Outage	15-10-2025	18:04	15-10-2025	18:57	0:53	0.000191	CABLE FAULT
456	15-10-2025	Part of : POCKET C SIDDHARTHA NAGAR	2257	Other Outage	Unplanned Outage	15-10-2025	11:27	15-10-2025	13:18	1:51	0.001696	REPAIRING HVDS CIRCUIT
457	15-10-2025	Part of : E-BLOCK DEFENCE COLONY	199	Other Outage	Planned Outage	15-10-2025	11:55	15-10-2025	13:34	1:39	0.000550	REPLACEMENT OF HT BUSHING ROD
458	15-10-2025	Part of : F-BLOCK LAJPAT NAGAR-1	639	Other Outage	Planned Outage	15-10-2025	12:22	15-10-2025	15:26	3:04	0.001022	REPLACEMENT OF HT BUSHING INULATOR
459	16-10-2025	Part of : SEWA NAGAR, KASTURBA NAGAR SEWA NAGAR, SUBASH MARKET KOTLA MUBARAKPUR, ALIGANJ KOTLA MUBARAKPUR, ITDC (HTC)	3013	Other Outage	Unplanned Outage	16-10-2025	05:20	16-10-2025	06:09	0:49	0.000776	FAULT IN HT CONSUMER PANEL (ITDC)
460	16-10-2025	Part of : BLOCK H JANGUPURA EXTENSION	212	Other Outage	Planned Outage	16-10-2025	11:16	16-10-2025	14:31	3:15	0.000813	REPLACEMET OF HT BUSHING ROD
461	16-10-2025	Part of : BLOCK L LAJPAT NAGAR III	505	Other Outage	Planned Outage	16-10-2025	10:59	16-10-2025	14:30	3:31	0.001172	REPLACEMET OF HT BUSHING ROD
462	17-10-2025	Part of : BLOCK C DEFENCE COLONY,DEFENCE COLONY,BLOCK A DEFENCE COLONY	1605	Other Outage	Unplanned Outage	17-10-2025	11:23	17-10-2025	12:14	0:51	0.001757	CABLE DAMAGE BY OUTSIDE AGENCY (DJB)
463	17-10-2025	Part of : NATIONAL ZOOLOGICAL PARK SUNDAR NAGAR,	1	Other Outage	Planned Outage	17-10-2025	11:32	17-10-2025	14:49	3:17	0.000274	REPLACEMET OF HT BUSHING ROD
464	19-10-2025	Part of : NATIONAL ZOOLOGICAL PARK SUNDAR NAGAR, RESIDENTIAL FLAT ZOO CAMPUS, ZOO PUMP HOUSE (HTC), SUNDAR NAGAR	209	Other Outage	Unplanned Outage	19-10-2025	04:20	19-10-2025	04:49	0:29	0.000121	CABLE FAULT
465	24-10-2025	Part of : BLOCK C LAJPAT NAGAR I	528	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	14:33	3:12	0.001067	REPLACEMENT OF HT BUSHING ROD
466	24-10-2025	Part of : BLOCK M SEWA NAGAR	925	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	14:08	2:47	0.000928	REPLACEMENT OF HT BUSHING ROD
467	25-10-2025	Part of : BLOCK M JANGUPURA EXTENSION JANGPURA,	343	Other Outage	Planned Outage	25-10-2025	11:18	25-10-2025	14:04	2:46	0.001291	REPLACEMET OF HT BUSHING ROD
468	27-10-2025	Part of : SUNDAR NAGAR,NATIONAL ZOOLOGICAL PARK	209	Other Outage	Unplanned Outage	27-10-2025	23:07	27-10-2025	23:51	0:44	0.000171	CABLE FAULT
469	27-10-2025	Part of : B,E,F & M -BLOCK SEWA NAGAR,KASTURBA NAGAR	3012	Other Outage	Unplanned Outage	27-10-2025	17:08	27-10-2025	17:47	0:39	0.000585	CABLE DAMAGE BY OUTSIDE AGENCY (ITDC)
470	28-10-2025	Part of : INA TYPE A QUARTERS INA COLONY, AVIATION COLONY INA COLONY, INA COLONY	1081	Other Outage	Unplanned Outage	28-10-2025	22:31	28-10-2025	23:04	0:33	0.000321	CABLE FAULT
471	29-10-2025	Part of : KILOKARI PHASE 1 SUNLIGHT COLONY,VIDYUT VIHAR PHASE 1 SUNLIGHT COLONY,POCKET A SIDDHARTHA NAGAR	2216	Other Outage	Unplanned Outage	29-10-2025	16:23	29-10-2025	17:09	0:46	0.000588	CABLE FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
472	29-10-2025	Part of : BLOCK B GANGA VIHAR SARAI KALE KHAN,BLOCK A GANGA VIHAR SARAI KALE KHAN	209	Other Outage	Unplanned Outage	29-10-2025	04:11	29-10-2025	05:07	0:56	0.000109	CABLE FAULT
473	29-10-2025	Part of : BLOCK O JANGUPURA EXTENSION JANGPURA,	412	Other Outage	Planned Outage	29-10-2025	11:37	29-10-2025	15:23	3:46	0.000753	REPLACEMET OF HT BUSHING ROD
474	29-10-2025	Part of : MEHARCHAND MARKET LODI COLONY,	1	Other Outage	Planned Outage	29-10-2025	11:34	29-10-2025	13:46	2:12	0.000183	REPLACEMET OF HT BUSHING ROD
475	30-10-2025	Part of : BLOCK 5 NEHRU NAGAR LAJPAT NAGAR	1245	Other Outage	Planned Outage	30-10-2025	13:01	30-10-2025	16:16	3:15	0.001246	REPLACEMENT OF HT BUSHING ROD
476	31-10-2025	Part of : NEHRU NAGAR LAJPAT NAGAR	241	Other Outage	Planned Outage	31-10-2025	12:12	31-10-2025	14:59	2:47	0.000464	REPLACEMENT OF HT BUSHING ROD
477	31-10-2025	Part of : PANT NAGAR JANGPURA	832	Other Outage	Planned Outage	31-10-2025	12:13	31-10-2025	14:56	2:43	0.001087	REPLACEMENT OF HT BUSHING ROD
478	04-10-2025	Part of : POCKET 2 SECTOR 2 DWARKA	6	Other Outage	Planned Outage	04-10-2025	11:26	04-10-2025	13:07	1:41	0.000112	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
479	04-10-2025	Part of : GAIL (PLOT NO.-16) B.C.PLACE (HTC)	1	Other Outage	Planned Outage	04-10-2025	12:11	04-10-2025	17:43	5:32	0.003228	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
480	04-10-2025	Part of : BHIKAJI CAMA PLACE RAMAKRISHNA PURAM	338	Other Outage	Planned Outage	04-10-2025	12:12	04-10-2025	14:54	2:42	0.001575	INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
481	04-10-2025	Part of : INDIAN AIR LINES AND AIR INDIA ESTATE VASANT VIHAR	13	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	14:07	2:57	0.001475	DT REPLACEMENT,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACMET OF LUGS,TIGHTENEING OF NUT BOLT
482	06-10-2025	Part of : SOM VIHAR RAMAKRISHNA PURAM	93	Other Outage	Planned Outage	06-10-2025	11:11	06-10-2025	14:44	3:33	0.002130	INSTALLATION OF BUS BAR,REPLACMET OF HT BUSHING ROD,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
483	06-10-2025	Part of : BLOCK I MOTI BAGH SOUTH	83	Other Outage	Planned Outage	06-10-2025	10:19	06-10-2025	13:49	3:30	0.000583	DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
484	07-10-2025	Part of : FIIB BLDG, MES SIGNAL ENCLAVE,288 JANTA FLATS,NIRYAT BHAWAN,VASANT VIHAR	5	Other Outage	Unplanned Outage	07-10-2025	16:38	07-10-2025	17:21	0:43	0.000406	CABLE FAULT
485	07-10-2025	Part of : SUBROTO PARK,DHAULA KUAN ENCLAVE	8	Other Outage	Unplanned Outage	07-10-2025	20:02	07-10-2025	21:52	1:50	0.000458	TREE TRIMMING
486	07-10-2025	Part of : SECTOR 12 RAMAKRISHNA PURAM	50	Other Outage	Planned Outage	07-10-2025	10:46	07-10-2025	14:07	3:21	0.000670	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS
487	08-10-2025	Part of : BLOCK B ANAND NIKETAN	281	Other Outage	Planned Outage	08-10-2025	11:14	08-10-2025	14:17	3:03	0.000610	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
488	08-10-2025	Part of : SOM VIHAR RAMAKRISHNA PURAM	126	Other Outage	Planned Outage	08-10-2025	11:15	08-10-2025	13:53	2:38	0.001492	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
489	08-10-2025	Part of : CGHC COLONY VASANT VIHAR	395	Other Outage	Planned Outage	08-10-2025	10:16	08-10-2025	12:58	2:42	0.002025	INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACMET OF HT BUSHING ROD,TIGHTENEING OF NUT BOLT
490	09-10-2025	Part of : BLOCK BA MUNIRKA,BLOCK CA MUNIRKA,MUNIRKA,MOTILAL NEHRU CAMP OLD JNU CAMPUS MUNIRKA,BLOCK BC MUNIRKA	3552	Other Outage	Unplanned Outage	09-10-2025	01:11	09-10-2025	01:52	0:41	0.000387	CABLE FAULT
491	09-10-2025	Part of : JHARERA VILLAGE ASMARA LINES DELHI CANTONMENT,	628	Other Outage	Planned Outage	09-10-2025	12:49	09-10-2025	15:22	2:33	0.000723	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),MOBILE TRANSFORMER INSTALLATION FOR PLINT REPLACMET,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
492	09-10-2025	Part of : SECTOR 12 RAMAKRISHNA PURAM,	1553	Other Outage	Planned Outage	09-10-2025	11:43	09-10-2025	14:03	2:20	0.001478	APPLY OF INSULATION TAPE HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MOBILE TRANSFORMER INSTALLATION FOR PLINT REPLACEMET,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
493	09-10-2025	Part of : CGHC COLONY VASANT VIHAR,	591	Other Outage	Planned Outage	09-10-2025	10:26	09-10-2025	13:06	2:40	0.001333	INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,TIGHTENEING OF NUT BOLT
494	10-10-2025	Part of : SOM VIHAR RAMAKRISHNA PURAM	136	Other Outage	Planned Outage	10-10-2025	11:17	10-10-2025	13:08	1:51	0.001018	APPLY OF INSULATION TAPE HT/LT BUSHINGS,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
495	11-10-2025	Part of : BHIKAJI CAMA PLACE RAMAKRISHNA PURAM	278	Other Outage	Planned Outage	11-10-2025	11:31	11-10-2025	14:13	2:42	0.001710	REPLACEMENT OF HT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD
496	11-10-2025	Part of : E-BLOCK ANAND NIKETAN	311	Other Outage	Planned Outage	11-10-2025	11:11	11-10-2025	14:03	2:52	0.000621	GENERAL SURFACE CLEANING OF HT/LT BUSHINGS
497	11-10-2025	Part of : BASANT GAON VASANT VIHAR	190	Other Outage	Planned Outage	11-10-2025	10:29	11-10-2025	14:14	3:45	0.004375	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,TIGHTENEING OF NUT BOLT
498	13-10-2025	Part of : BLOCK D 2 WEST END,	65	Other Outage	Planned Outage	13-10-2025	11:01	13-10-2025	13:51	2:50	0.000331	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
499	13-10-2025	Part of : SOM VIHAR RAMAKRISHNA PURAM,	85	Other Outage	Planned Outage	13-10-2025	11:08	13-10-2025	13:59	2:51	0.001615	CHECKING VALUE OF FENCING EARTHING,INSTALLATION OF HT BOOTS,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
500	14-10-2025	Part of : BLOCK E VASANT VIHAR	187	Other Outage	Planned Outage	14-10-2025	10:16	14-10-2025	13:54	3:38	0.003331	DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS
501	14-10-2025	Part of : JHARERA VILLAGE ASMARA LINES DELHI CANTONMENT	474	Other Outage	Planned Outage	14-10-2025	11:47	14-10-2025	16:15	4:28	0.001117	REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
502	14-10-2025	Part of : MOHAMMADPUR RAMAKRISHNA PURAM	414	Other Outage	Planned Outage	14-10-2025	11:02	14-10-2025	13:40	2:38	0.000000	REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
503	15-10-2025	Part of : D 2-BLOCK WEST END COLONY	213	Other Outage	Planned Outage	15-10-2025	10:52	15-10-2025	12:52	2:00	0.000367	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
504	15-10-2025	Part of : SECTOR 2 RAMAKRISHNA PURAM	217	Other Outage	Planned Outage	15-10-2025	10:58	15-10-2025	14:10	3:12	0.002027	INSTALLATION OF BUS BAR,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS
505	15-10-2025	Part of : MUNIRKA VIHAR	1937	Other Outage	Planned Outage	15-10-2025	10:15	15-10-2025	13:46	3:31	0.003517	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER
506	16-10-2025	Part of : NEAR PWD DHAULA KUAN FLYOVER	1	Other Outage	Planned Outage	16-10-2025	11:30	16-10-2025	13:15	1:45	0.000204	CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
507	17-10-2025	Part of : WEST BLOCK RAMAKRISHNA PURAM,	18	Other Outage	Planned Outage	17-10-2025	13:16	17-10-2025	14:54	1:38	0.000136	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
508	17-10-2025	Part of : BLOCK D 2 WEST END,	161	Other Outage	Planned Outage	17-10-2025	10:30	17-10-2025	12:28	1:58	0.000393	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
509	17-10-2025	Part of : WEST BLOCK RAMAKRISHNA PURAM,	48	Other Outage	Planned Outage	17-10-2025	11:02	17-10-2025	14:11	3:09	0.000525	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
510	17-10-2025	Part of : BLOCK BA MUNIRKA,	415	Other Outage	Planned Outage	17-10-2025	10:34	17-10-2025	14:14	3:40	0.003972	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,TIGHTENEING OF NUT BOLT
511	18-10-2025	Part of : HTC EAST BLOCK CPWD , R.K.PURAM	0	Other Outage	Unplanned Outage	18-10-2025	14:53	18-10-2025	15:39	0:46	0.000217	FAULT IN HT CONSUMER PANEL (EAST BLOCK CPWD)
512	18-10-2025	Part of : BLOCK A VASANT VIHAR	691	Other Outage	Planned Outage	18-10-2025	12:03	18-10-2025	12:43	0:40	0.000000	CLEANING OF HT BUSHING PER WAY,DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
513	22-10-2025	Part of : MOTILAL NEHRU COLLEGE, SOUTH CAMPUS NEW	1	Other Outage	Planned Outage	22-10-2025	13:35	22-10-2025	14:44	1:09	0.000192	CLEANING OF HT BUSHING PER WAY,PROPER SEALING RMU PER WAY,REPLACEMENT OF FAULTY END BOX
514	23-10-2025	Part of : SECTOR 5 RAMAKRISHNA PURAM	3	Other Outage	Planned Outage	23-10-2025	10:58	23-10-2025	13:57	2:59	0.000298	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
515	23-10-2025	Part of : CGHC COLONY VASANT VIHAR	1	Other Outage	Planned Outage	23-10-2025	10:42	23-10-2025	13:33	2:51	0.002613	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING ROD
516	24-10-2025	Part of : SECTOR 5 RAMAKRISHNA PURAM	1	Other Outage	Planned Outage	24-10-2025	11:18	24-10-2025	14:23	3:05	0.000257	REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
517	24-10-2025	Part of : SECTOR 4 SHANTI NIKETAN	235	Other Outage	Planned Outage	24-10-2025	10:24	24-10-2025	13:53	3:29	0.000581	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
518	25-10-2025	Part of : MUNIRKA,MUNIRKA ENCLAVE MUNIRKA,BASANT LOK VASANT VIHAR	2776	Other Outage	Unplanned Outage	25-10-2025	16:32	25-10-2025	17:22	0:50	0.000611	CABLE FAULT
519	25-10-2025	Part of : HTC:MSO SEWA BHAWAN, WEST BLK, R.K.PURAM	1	Other Outage	Planned Outage	25-10-2025	14:43	25-10-2025	16:08	1:25	0.000354	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
520	25-10-2025	Part of : WEST BLOCK RAMAKRISHNA PURAM,	2	Other Outage	Planned Outage	25-10-2025	11:02	25-10-2025	14:02	3:00	0.000800	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
521	25-10-2025	Part of : DHAULA KUAN ENCLAVE I DHAULA KUAN,	42	Other Outage	Planned Outage	25-10-2025	10:58	25-10-2025	13:50	2:52	0.000334	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
522	25-10-2025	Part of : MUNIRKA,	611	Other Outage	Planned Outage	25-10-2025	10:09	25-10-2025	13:08	2:59	0.003481	REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,TIGHTENEING OF NUT BOLT
523	26-10-2025	Part of : BLOCK A, E & F VASANT VIHAR	901	Other Outage	Unplanned Outage	26-10-2025	00:32	26-10-2025	01:14	0:42	0.000560	CABLE FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
524	28-10-2025	Part of : RAMA COLONY RAMAKRISHNA PURAM	956	Other Outage	Planned Outage	28-10-2025	11:02	28-10-2025	14:03	3:01	0.001408	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
525	28-10-2025	Part of : BLOCK BA MUNIRKA	265	Other Outage	Planned Outage	28-10-2025	11:38	28-10-2025	15:12	3:34	0.000594	MOBILE TRANSFORMER INSTALLATION FOR PLINT REPLACEMET
526	29-10-2025	Part of : SECTOR 4 RAMAKRISHNA PURAM,	300	Other Outage	Planned Outage	29-10-2025	11:12	29-10-2025	14:07	2:55	0.001069	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,INSTALLATION OF HT BOOTS,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
527	29-10-2025	Part of : SECTOR 3 SHANTI NIKETAN,	128	Other Outage	Planned Outage	29-10-2025	11:01	29-10-2025	13:51	2:50	0.000519	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
528	29-10-2025	Part of : INDIAN AIR LINES AND AIR INDIA ESTATE VASANT VIHAR,	972	Other Outage	Planned Outage	29-10-2025	10:16	29-10-2025	13:52	3:36	0.000600	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF LT BUSHING ROD
529	30-10-2025	Part of : WEST BLOCK RAMAKRISHNA PURAM	350	Other Outage	Planned Outage	30-10-2025	11:23	30-10-2025	14:05	2:42	0.000450	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
530	30-10-2025	Part of : BLOCK B MOTI BAGH SOUTH	168	Other Outage	Planned Outage	30-10-2025	10:52	30-10-2025	13:41	2:49	0.000423	CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
531	30-10-2025	Part of : BLOCK D VASANT VIHAR	494	Other Outage	Planned Outage	30-10-2025	10:17	30-10-2025	13:51	3:34	0.000951	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
532	31-10-2025	Part of : DCP OFFICE NANAKPURA M BAGH (HT CONSUMER)	1	Other Outage	Planned Outage	31-10-2025	11:08	31-10-2025	12:24	1:16	0.000106	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
533	31-10-2025	Part of : MOHAMMADPUR RAMAKRISHNA PURAM	434	Other Outage	Planned Outage	31-10-2025	11:06	31-10-2025	14:37	3:31	0.001465	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
534	01-10-2025	Part of : SAINIK FARM,	234	Other Outage	Planned Outage	01-10-2025	13:53	01-10-2025	16:39	2:46	0.004611	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
535	01-10-2025	Part of : SAINIK FARM,	673	Other Outage	Planned Outage	01-10-2025	12:07	01-10-2025	15:02	2:55	0.004861	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
536	03-10-2025	Part of : A 1-BLOCK NEB SARAI SAINIK FARM	702	Other Outage	Unplanned Outage	03-10-2025	09:53	03-10-2025	10:39	0:46	0.000204	CABLE DAMAGE BY OUTSIDE AGENCY (DMRC)
537	03-10-2025	Part of : SECTOR 1 & 5- PUSHPA VIHAR	1547	Other Outage	Unplanned Outage	03-10-2025	04:11	03-10-2025	05:11	1:00	0.000433	CABLE FAULT
538	03-10-2025	Part of : SAIYAD UL AJAIB EXTENSION SAINIK FARM	1341	Other Outage	Planned Outage	03-10-2025	11:21	03-10-2025	13:57	2:36	0.004333	APPLY OF INSULATION TAPE HT BUSHINGS
539	03-10-2025	Part of : SAVITRI NAGAR VILLAGE SHEIKH SARAI	1603	Other Outage	Planned Outage	03-10-2025	10:42	03-10-2025	13:38	2:56	0.000000	REPLACEMET OF HT BUSHING ROD
540	04-10-2025	Part of : BLOCK D,H & L MALVIYA NAGAR,BLOCK 70 & 80 MALVIYA NAGAR	1469	Other Outage	Unplanned Outage	04-10-2025	07:34	04-10-2025	08:55	1:21	0.004050	CABLE FAULT
541	04-10-2025	Part of : CHIRAG DELHI	2753	Other Outage	Planned Outage	04-10-2025	11:18	04-10-2025	15:08	3:50	0.000000	REPLACEMET OF HT BUSHING ROD
542	04-10-2025	Part of : POCKET E BEES SUTRI HARIJAN BASTI SAINIK FARM	1007	Other Outage	Planned Outage	04-10-2025	11:08	04-10-2025	14:00	2:52	0.002007	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT/LT CLEATS
543	05-10-2025	Part of : ASHOK VIHAR PRESS ENCLAVE SAKET,BLOCK F SAKET	210	Other Outage	Unplanned Outage	05-10-2025	16:50	05-10-2025	17:48	0:58	0.000113	HT SYSTEM FAULT
544	06-10-2025	Part of : SAIYAD UL AJAIB VILLAGE SAINIK FARM	765	Other Outage	Planned Outage	06-10-2025	16:15	06-10-2025	17:14	0:59	0.001639	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
545	06-10-2025	Part of : BLOCK A 1 NEB SARAI SAINIK FARM	1196	Other Outage	Planned Outage	06-10-2025	13:00	06-10-2025	14:58	1:58	0.003278	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,MOBILE TRANSFORMER INSTALLATION FOR PLINT
546	06-10-2025	Part of : POCKET L PHASE II SHEIKH SARAI	913	Other Outage	Planned Outage	06-10-2025	10:36	06-10-2025	13:27	2:51	0.000000	REPLACEMET,REPLACEMET OF LUGS
547	06-10-2025	Part of : BLOCK A GITANJALI ENCLAVE MALVIYA NAGAR	203	Other Outage	Planned Outage	06-10-2025	10:02	06-10-2025	13:01	2:59	0.000249	REPLACEMENT OF HT BUSHING ROD
548	07-10-2025	Part of : PANCHSHEEL EXTENSION,N-BLOCK MALVIYA NAGAR,H-BLOCK PANCHSHEEL VIHAR SHEIKH SARAI	3285	Other Outage	Unplanned Outage	07-10-2025	14:56	07-10-2025	15:51	0:55	0.000825	REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
549	07-10-2025	Part of : H-BLOCK NEB SARAI SAINIK FARM	133	Other Outage	Planned Outage	07-10-2025	10:51	07-10-2025	13:38	2:47	0.004639	HT SYSTEM FAULT
												APPLY OF INSULATION TAPE HT/LT BUSHINGS,

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
550	08-10-2025	Part of : CHHATRI WALA KUNA LADO SARAI	800	Other Outage	Planned Outage	08-10-2025	12:46	08-10-2025	16:15	3:29	0.005806	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
551	08-10-2025	Part of : SAIYAD UL AJAIB VILLAGE SAINIK FARM	1048	Other Outage	Planned Outage	08-10-2025	11:14	08-10-2025	14:10	2:56	0.004889	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
552	08-10-2025	Part of : GITANJALI ENCLAVE MALVIYA NAGAR	185	Other Outage	Planned Outage	08-10-2025	10:05	08-10-2025	12:58	2:53	0.000481	CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF LT BUSHING ROD
553	08-10-2025	Part of : CHIRAG DELHI	1365	Other Outage	Planned Outage	08-10-2025	10:57	08-10-2025	13:53	2:56	0.000000	REPLACEMET OF HT BUSHING ROD
554	09-10-2025	Part of : POCKET E BEES SUTRI HARIJAN BASTI SAINIK FARM,BLOCK A 1 NEB SARAI SAINIK FARM,	503	Other Outage	Planned Outage	09-10-2025	13:07	09-10-2025	17:28	4:21	0.007250	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,INSTALLATION OF HT BOOTS,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING TIGHTENEING OF NUT BOLT
555	09-10-2025	Part of : BLOCK B SHIVALIK MALVIYA NAGAR,	793	Other Outage	Planned Outage	09-10-2025	10:59	09-10-2025	14:41	3:42	0.000000	REPLACEMET OF HT BUSHING ROD
556	09-10-2025	Part of : BLOCK A PARYAVARAN COMPLEX SAINIK FARM,	2295	Other Outage	Planned Outage	09-10-2025	11:00	09-10-2025	13:54	2:54	0.004833	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,TIGHTENEING OF NUT BOLT
557	09-10-2025	Part of : VIJAY MANDAL ENCLAVE KALU SARAI,	315	Other Outage	Planned Outage	09-10-2025	10:03	09-10-2025	13:19	3:16	0.000544	REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
558	10-10-2025	Part of : BLOCK D SAKET	470	Other Outage	Planned Outage	10-10-2025	15:06	10-10-2025	16:36	1:30	0.002500	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
559	10-10-2025	Part of : BLOCK G 6 MALVIYA NAGAR	551	Other Outage	Planned Outage	10-10-2025	10:58	10-10-2025	12:42	1:44	0.000000	REPLACEMET OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
560	10-10-2025	Part of : SAIYAD UL AJAIB VILLAGE SAINIK FARM	200	Other Outage	Planned Outage	10-10-2025	13:09	10-10-2025	16:03	2:54	0.004833	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
561	11-10-2025	Part of : H-BLOCK PANCHSHEEL VIHAR SHEIKH SARAI VILLAGE	2006	Other Outage	Planned Outage	11-10-2025	12:24	11-10-2025	15:01	2:37	0.000000	REPLACEMENT OF HT BUSHING ROD
562	11-10-2025	Part of : A 1-BLOCK NEB SARAI SAINIK FARM	157	Other Outage	Planned Outage	11-10-2025	11:52	11-10-2025	14:50	2:58	0.004944	APPLY OF INSULATION TAPE HT/LT BUSHINGS
563	11-10-2025	Part of : POCKET K SHEIKH SARA PHASE-2	683	Other Outage	Planned Outage	11-10-2025	11:01	11-10-2025	13:51	2:50	0.000000	REPLACEMENT OF HT BUSHING ROD
564	13-10-2025	Part of : BLOCK A 1 NEB SARAI SAINIK FARM,	204	Other Outage	Planned Outage	13-10-2025	14:18	13-10-2025	15:52	1:34	0.002611	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
565	13-10-2025	Part of : ADHCHINI VILLAGE QUTAB ENCLAVE,	237	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	12:13	1:13	0.000000	REPLACEMENT OF LT BUSHING ROD
566	13-10-2025	Part of : BUTTERFLY PARK QILA RAI PITHORA SAINIK FARM,	360	Other Outage	Planned Outage	13-10-2025	12:39	13-10-2025	14:53	2:14	0.003722	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
567	13-10-2025	Part of : BLOCK A SHIVALIK MALVIYA NAGAR,	1084	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	14:32	3:32	0.000000	REPLACEMET OF HT BUSHING ROD
568	13-10-2025	Part of : MMTC COLONY SARVODYA ENCLAVE,	99	Other Outage	Planned Outage	13-10-2025	09:46	13-10-2025	12:44	2:58	0.000247	GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),REPLACEMENT OF LT BUSHING ROD
569	14-10-2025	Part of : BLOCK C SARVODYA ENCLAVE	253	Other Outage	Planned Outage	14-10-2025	12:14	14-10-2025	13:01	0:47	0.000000	REPLACEMENT OF LT BUSHING ROD
570	14-10-2025	Part of : NAI BASTI LADO SARAI	724	Other Outage	Planned Outage	14-10-2025	11:54	14-10-2025	15:41	3:47	0.007567	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
571	14-10-2025	Part of : PHASE II SHEIKH SARAI	2447	Other Outage	Planned Outage	14-10-2025	10:56	14-10-2025	14:06	3:10	0.000000	REPLACEMENT OF HT BUSHING ROD
572	14-10-2025	Part of : BHAVISHYANIDHI ENCLAVE MALVIYA NAGAR	64	Other Outage	Planned Outage	14-10-2025	10:42	14-10-2025	13:00	2:18	0.000383	REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
573	15-10-2025	Part of : A-BLOCK SARVODYA ENCLAVE	256	Other Outage	Planned Outage	15-10-2025	11:22	15-10-2025	13:19	1:57	0.000000	REPLACEMENT OF HT BUSHING ROD
574	15-10-2025	Part of : D-BLOCK SAKET	470	Other Outage	Planned Outage	15-10-2025	10:41	15-10-2025	14:31	3:50	0.007667	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
575	15-10-2025	Part of : POLICE TRAINING CENTRE NAVJIVAN VIHAR MALVIYA NAGAR	386	Other Outage	Planned Outage	15-10-2025	10:08	15-10-2025	12:51	2:43	0.000226	REPLACEMENT OF HT BUSHING ROD
576	15-10-2025	Part of : B-BLOCK SHIVALIK MALVIYA NAGAR	793	Other Outage	Planned Outage	15-10-2025	11:03	15-10-2025	13:16	2:13	0.000000	REPLACEMENT OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
577	16-10-2025	Part of : BLOCK H & G MALVIYA NAGAR, BLOCK B SHIVALIK MALVIYA NAGAR	2826	Other Outage	Unplanned Outage	16-10-2025	00:26	16-10-2025	01:15	0:49	0.000436	CABLE FAULT
578	16-10-2025	Part of : BANDALO WALA MOHALLA LADO SARAI	1171	Other Outage	Planned Outage	16-10-2025	11:52	16-10-2025	16:03	4:11	0.006972	1PH DB REVAMPING,3PH DB REPLACEMENT,3PH DB REVAMPING,AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,CONDUCTOR REPLACEMENT PER SPAN,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,INSULATOR REPLACEMENT PER POLE,JUMPER REPLACEMENT PER POLE,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
579	16-10-2025	Part of : BUTTERFLY PARK QILA RAI PITHORA SAINIK FARM	273	Other Outage	Planned Outage	16-10-2025	11:08	16-10-2025	14:06	2:58	0.004944	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
580	16-10-2025	Part of : SAIYAD UL AJAIB EXTENSION SAINIK FARM	251	Other Outage	Planned Outage	16-10-2025	11:08	16-10-2025	14:06	2:58	0.004944	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
581	16-10-2025	Part of : BLOCK B SARVODYA ENCLAVE	189	Other Outage	Planned Outage	16-10-2025	10:01	16-10-2025	12:35	2:34	0.000214	REPLACEMET OF HT BUSHING ROD
582	16-10-2025	Part of : BLOCK F 2 MALVIYA NAGAR	1337	Other Outage	Planned Outage	16-10-2025	10:32	16-10-2025	14:35	4:03	0.000000	REPLACEMET OF HT BUSHING ROD
583	17-10-2025	Part of : GITANJALI ENCLAVE MALVIYA NAGAR,	185	Other Outage	Planned Outage	17-10-2025	11:59	17-10-2025	13:15	1:16	0.000000	REPLACEMET OF HT BUSHING ROD
584	17-10-2025	Part of : BLOCK B SAINIK FARMS COLONY SAINIK FARM,	32	Other Outage	Planned Outage	17-10-2025	14:01	17-10-2025	16:14	2:13	0.003694	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
585	17-10-2025	Part of : BLOCK A 1 NEB SARAI SAINIK FARM,	1218	Other Outage	Planned Outage	17-10-2025	12:23	17-10-2025	16:09	3:46	0.006278	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
586	17-10-2025	Part of : BLOCK B SAINIK FARMS COLONY SAINIK FARM,	43	Other Outage	Planned Outage	17-10-2025	11:12	17-10-2025	13:57	2:45	0.004583	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
587	17-10-2025	Part of : HAUZ RANI MALVIYA NAGAR,	1617	Other Outage	Planned Outage	17-10-2025	10:35	17-10-2025	13:40	3:05	0.000000	REPLACEMENT OF HT BUSHING ROD
588	17-10-2025	Part of : MMTC COLONY SARVODYA ENCLAVE,	126	Other Outage	Planned Outage	17-10-2025	10:04	17-10-2025	12:46	2:42	0.000225	REPLACEMENT OF LT BUSHING ROD
589	18-10-2025	Part of : BLOCK A, C, D & E PARYAVARAN COMPLEX SAINIK FARM,FREEDOM FIGHTER VIHAR SAINIK FARM	2444	Other Outage	Planned Outage	18-10-2025	11:59	18-10-2025	13:35	1:36	0.003200	1PH HT AB CABLE REPLACEMENT PER SPAN,1PH HT AB END TERMINATION REPLACEMENT,3PH HT AB CABLE REPLACEMENT PER SPAN
590	22-10-2025	Part of : NEW COLONY KHIDKI EXTENSION MALVIYA NAGAR	1530	Other Outage	Planned Outage	22-10-2025	12:26	22-10-2025	14:24	1:58	0.000000	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMET OF HT BUSHING ROD
591	22-10-2025	Part of : POCKET K PHASE II SHEIKH SARAI	683	Other Outage	Planned Outage	22-10-2025	10:21	22-10-2025	11:31	1:10	0.000000	REPLACEMET OF HT BUSHING ROD
592	24-10-2025	Part of : CHHATRI WALA KUNA LADO SARAI	108	Other Outage	Planned Outage	24-10-2025	11:03	24-10-2025	13:56	2:53	0.004806	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
593	24-10-2025	Part of : MMTC COLONY SARVODYA ENCLAVE	7	Other Outage	Planned Outage	24-10-2025	10:04	24-10-2025	13:01	2:57	0.000000	REPLACEMENT OF FAULTY END BOX,SF6 GAS FILLING
594	24-10-2025	Part of : BANDALO WALA MOHALLA LADO SARAI	675	Other Outage	Planned Outage	24-10-2025	14:09	24-10-2025	15:32	1:23	0.001844	CONDUCTOR REPLACEMENT PER SPAN,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,LT AB SAGGING PER SPAN
595	25-10-2025	Part of : BLOCK C PARYAVARAN COMPLEX SAINIK FARM,BLOCK A PARYAVARAN COMPLEX SAINIK FARM,BLOCK E PARYAVARAN COMPLEX SAINIK FARM,FREEDOM FIGHTER VIHAR SAINIK FARM,BLOCK D PARYAVARAN COMPLEX SAINIK FARM,	2444	Other Outage	Planned Outage	25-10-2025	12:49	25-10-2025	15:36	2:47	0.004639	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT REPLACEMENT,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
596	25-10-2025	Part of : BLOCK T MALVIYA NAGAR,	1048	Other Outage	Planned Outage	25-10-2025	10:46	25-10-2025	13:48	3:02	0.000000	REPLACEMET OF HT BUSHING ROD APPLY OF INSULATION TAPE HT/LT
597	28-10-2025	Part of : BLOCK D PARYAVARAN COMPLEX SAINIK FARM	440	Other Outage	Planned Outage	28-10-2025	12:36	28-10-2025	14:55	2:19	0.003861	BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
598	28-10-2025	Part of : BANDALO WALA MOHALLA LADO SARAI	1173	Other Outage	Planned Outage	28-10-2025	11:47	28-10-2025	13:55	2:08	0.003556	3PH DB REPLACEMENT,CONDUCTOR REPLACEMENT PER SPAN,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSULATOR REPLACEMENT PER POLE,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
599	28-10-2025	Part of : BLOCK F 4 MALVIYA NAGAR	575	Other Outage	Planned Outage	28-10-2025	10:54	28-10-2025	14:16	3:22	0.000000	REPLACEMET OF HT BUSHING ROD
600	28-10-2025	Part of : SAINIK FARM	67	Other Outage	Planned Outage	28-10-2025	10:59	28-10-2025	13:54	2:55	0.004861	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
601	28-10-2025	Part of : POLICE TRAINING CENTRE NAVJIVAN VIHAR MALVIYA NAGAR	204	Other Outage	Planned Outage	28-10-2025	10:16	28-10-2025	12:56	2:40	0.000222	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
602	29-10-2025	Part of : BHAVISHYANIDHI ENCLAVE MALVIYA NAGAR,	44	Other Outage	Planned Outage	29-10-2025	14:42	29-10-2025	15:53	1:11	0.000099	CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMET OF HT BUSHING ROD
603	29-10-2025	Part of : SAINIK FARM,	3	Other Outage	Planned Outage	29-10-2025	13:31	29-10-2025	15:41	2:10	0.003611	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
604	29-10-2025	Part of : SAINIK FARM,	189	Other Outage	Planned Outage	29-10-2025	10:39	29-10-2025	13:33	2:54	0.004833	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
605	29-10-2025	Part of : BLOCK A 1 NEB SARAI SAINIK FARM,	433	Other Outage	Planned Outage	29-10-2025	11:33	29-10-2025	15:43	4:10	0.006944	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
606	29-10-2025	Part of : NEW COLONY KHIDKI EXTENSION MALVIYA NAGAR,	1531	Other Outage	Planned Outage	29-10-2025	10:47	29-10-2025	13:46	2:59	0.000000	REPLACEMET OF HT BUSHING ROD
607	30-10-2025	Part of : VIJAY MANDAL ENCLAVE KALU SARAI	16	Other Outage	Planned Outage	30-10-2025	14:18	30-10-2025	16:02	1:44	0.000144	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS
608	30-10-2025	Part of : BLOCK A 1 NEB SARAI SAINIK FARM	433	Other Outage	Planned Outage	30-10-2025	12:15	30-10-2025	15:46	3:31	0.005861	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
609	30-10-2025	Part of : HAUZ RANI MALVIYA NAGAR	1617	Other Outage	Planned Outage	30-10-2025	10:52	30-10-2025	14:11	3:19	0.000000	REPLACEMENT OF HT BUSHING ROD
610	30-10-2025	Part of : NAI BASTI LADO SARAI	486	Other Outage	Planned Outage	30-10-2025	11:00	30-10-2025	14:01	3:01	0.005028	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
611	31-10-2025	Part of : GANDHI PARK MALVIYA NAGAR	962	Other Outage	Planned Outage	31-10-2025	10:45	31-10-2025	13:00	2:15	0.000000	REPLACEMET OF HT BUSHING ROD
612	31-10-2025	Part of : NEAR CHHATRI WALA KUNA LADO SARAI	182	Other Outage	Planned Outage	31-10-2025	11:17	31-10-2025	13:44	2:27	0.004083	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
613	31-10-2025	Part of : NEAR CHHATRI WALA KUNA LADO SARAI	170	Other Outage	Planned Outage	31-10-2025	11:08	31-10-2025	13:52	2:44	0.004556	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
614	31-10-2025	Part of : ADHCHINI VILLAGE QUTAB ENCLAVE	150	Other Outage	Planned Outage	31-10-2025	10:01	31-10-2025	12:57	2:56	0.000244	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
615	01-10-2025	Part of : POCKET A SARITA VIHAR,	108	Other Outage	Planned Outage	01-10-2025	11:48	01-10-2025	16:17	4:29	0.005231	REPLACEMET OF HT BUSHING ROD
616	01-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR,	1178	Other Outage	Planned Outage	01-10-2025	11:48	01-10-2025	16:19	4:31	0.003764	3PH HT AB CABLE REPLACEMENT PER SPAN
617	03-10-2025	Part of : RAJ NAGAR,MADANPUR KHADAR	1601	Other Outage	Unplanned Outage	03-10-2025	06:47	03-10-2025	07:17	0:30	0.000342	BIRDAGE
618	03-10-2025	Part of : VILLAGE-JAITPUR	653	Other Outage	Planned Outage	03-10-2025	14:04	03-10-2025	15:06	1:02	0.000344	GENERAL SURFACE CLEAINING OF HT BUSHINGS,OIL TOP UP IN TRANSFORMER
619	03-10-2025	Part of : HARSH VIHAR MOLARBAND	1407	Other Outage	Planned Outage	03-10-2025	11:32	03-10-2025	13:06	1:34	0.000731	OIL TOP UP IN TRANSFORMER
620	03-10-2025	Part of : BADARPUR VILLAGE	769	Other Outage	Planned Outage	03-10-2025	12:54	03-10-2025	16:19	3:25	0.001139	HT AB SAGGING
621	03-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR	1440	Other Outage	Planned Outage	03-10-2025	11:04	03-10-2025	16:31	5:27	0.004542	3PH HT AB CABLE REPLACEMENT
622	03-10-2025	Part of : BLOCK C MOLARBAND EXTENSION BADARPUR	17	Other Outage	Planned Outage	03-10-2025	11:36	03-10-2025	16:14	4:38	0.003089	3PH HT AB CABLE REPLACEMENT
623	04-10-2025	Part of : BLOCK E MOHAN COOPERATIVE INDUSTRIAL ESTATE BADARPUR	155	Other Outage	Unplanned Outage	04-10-2025	00:02	04-10-2025	00:50	0:48	0.000293	CABLE FAULT
624	04-10-2025	Part of : GAGAN VIHAR MITHAPUR EXTENSION	645	Other Outage	Planned Outage	04-10-2025	11:51	04-10-2025	12:43	0:52	0.000867	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF LT BUSHING INSULATOR,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
625	04-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR	1	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	15:56	4:46	0.004767	DT REPLACEMET PER DT
626	04-10-2025	Part of : LAKHPAT COLONY MITHAPUR	1383	Other Outage	Planned Outage	04-10-2025	11:50	04-10-2025	14:34	2:44	0.002733	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
627	04-10-2025	Part of : POCKET A SARITA VIHAR	176	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	15:55	4:45	0.006333	REPLACEMET OF HT BUSHING ROD
628	06-10-2025	Part of : BLOCK B MOHAN COOPERATIVE INDUSTRIAL ESTATE BADARPUR,SAIDABAD SARITA VIHAR	26	Other Outage	Unplanned Outage	06-10-2025	15:33	06-10-2025	16:07	0:34	0.000510	CABLE FAULT
629	06-10-2025	Part of : BLOCK E MOHAN COOPERATIVE INDUSTRIAL ESTATE BADARPUR	155	Other Outage	Unplanned Outage	06-10-2025	04:08	06-10-2025	04:52	0:44	0.000220	CABLE FAULT
630	06-10-2025	Part of : MITHAPUR	859	Other Outage	Planned Outage	06-10-2025	11:08	06-10-2025	13:06	1:58	0.001639	3PH DB REPLACEMENT,LT AB SAGGING PER SPAN
631	06-10-2025	Part of : POCKET A SARITA VIHAR	210	Other Outage	Planned Outage	06-10-2025	11:08	06-10-2025	14:52	3:44	0.004978	REPLACEMET OF HT BUSHING ROD
632	08-10-2025	Part of : MITHAPUR	1359	Other Outage	Planned Outage	08-10-2025	12:41	08-10-2025	16:22	3:41	0.009208	LT AB SAGGING PER SPAN
633	08-10-2025	Part of : ALI VIHAR ALI,PRIYANKA CAMP ALI	986	Other Outage	Planned Outage	08-10-2025	10:59	08-10-2025	16:04	5:05	0.007625	3PH HT AB CABLE REPLACEMENT PER SPAN
634	08-10-2025	Part of : KHADDA COLONY JAIPUR	1626	Other Outage	Planned Outage	08-10-2025	10:57	08-10-2025	16:07	5:10	0.004306	3PH HT AB CABLE REPLACEMENT PER SPAN
635	09-10-2025	Part of : MADANPUR KHADAR,RAJ NAGAR MADANPUR KHADAR	1891	Other Outage	Unplanned Outage	09-10-2025	13:20	09-10-2025	13:49	0:29	0.000435	CABLE FAULT
636	09-10-2025	Part of : ABC BLOCK HARI NAGAR MOLARBAND,K-BLOCK SAURABH VIHAR,RAJ NAGAR MADANPUR KHADAR,O-BLOCK SAURABH VIHAR,E-BLOCK HARI NAGAR EXT PART-2,D-BLOCK SAURABH,J BLOCK SAURABH VIHAR,N-BLOCK SAURABH VIHAR,NTPC WATER TREATMENT PLANT BADARPUR	4318	Other Outage	Unplanned Outage	09-10-2025	23:28	10-10-2025	00:02	0:34	0.000529	CABLE FAULT
637	09-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR,MADANPUR KHADAR,BLOCK G SHAHEEN BAGH JASOLA VIHAR	6731	Other Outage	Unplanned Outage	09-10-2025	13:02	09-10-2025	13:48	0:46	0.000460	CABLE FAULT
638	09-10-2025	Part of : NTPC WATER TREATMENT PLANT BADARPUR,	4	Other Outage	Unplanned Outage	09-10-2025	11:42	09-10-2025	13:39	1:57	0.000000	REPAIRING OF HT O/H CIRCUIT
639	09-10-2025	Part of : L-BLOCK SAURABH VIHAR,K-BLOCK SAURABH VIHAR,M-BLOCK SAURABH VIHAR,JAIPUR,H BLOCK SAURABH VIHAR,	2022	Other Outage	Unplanned Outage	09-10-2025	11:34	09-10-2025	13:38	2:04	0.000000	REPAIRING OF HT O/H CIRCUIT
640	09-10-2025	Part of : MITHAPUR,	2674	Other Outage	Planned Outage	09-10-2025	11:46	09-10-2025	12:43	0:57	0.000633	LT AB SAGGING PER SPAN
641	09-10-2025	Part of : BADARPUR VILLAGE BADARPUR,	770	Other Outage	Planned Outage	09-10-2025	11:38	09-10-2025	16:06	4:28	0.001489	LT AB SAGGING PER SPAN
642	09-10-2025	Part of : KHADDA COLONY JAIPUR,	494	Other Outage	Planned Outage	09-10-2025	11:24	09-10-2025	16:33	5:09	0.006008	REPLACEMET OF HT BUSHING ROD
643	09-10-2025	Part of : BLOCK E 2 MOLARBAND EXTENSION BADARPUR,	1469	Other Outage	Planned Outage	09-10-2025	11:11	09-10-2025	15:56	4:45	0.001583	3PH HT AB CABLE REPLACEMENT PER SPAN
644	10-10-2025	Part of : KHADDA COLONY JAIPUR	321	Other Outage	Planned Outage	10-10-2025	11:00	10-10-2025	16:30	5:30	0.005500	3PH HT AB CABLE REPLACEMENT PER SPAN
645	10-10-2025	Part of : BUDH VIHAR COLONY TAJPUR PAHARI VILLAGE BADARPUR	796	Other Outage	Planned Outage	10-10-2025	10:22	10-10-2025	15:48	5:26	0.001811	LT AB SAGGING PER SPAN
646	10-10-2025	Part of : BLOCK C & D MOLARBAND EXTENSION BADARPUR	874	Other Outage	Planned Outage	10-10-2025	11:26	10-10-2025	15:43	4:17	0.002142	3PH HT AB CABLE REPLACEMENT PER SPAN,HT BUSHING ROD REPLACEMENT,INSULATOR REPLACEMENT
647	11-10-2025	Part of : E-BLOCK MOHAN COOPERATIVE INDUSTRIAL ESTATE BADARPUR	195	Other Outage	Unplanned Outage	11-10-2025	08:25	11-10-2025	09:35	1:10	0.000000	HT SYSTEM FAULT
648	11-10-2025	Part of : KHADDA COLONY JAIPUR	2357	Other Outage	Planned Outage	11-10-2025	11:18	11-10-2025	16:11	4:53	0.004883	3PH HT AB CABLE REPLACEMENT
649	11-10-2025	Part of : C,D & E1-BLOCK MOLARBAND EXTENSION BADARPUR,MOHAN BABA NAGAR TAJPUR PAHARI VILLAGE	1303	Other Outage	Planned Outage	11-10-2025	11:10	11-10-2025	14:56	3:46	0.001883	3PH HT AB CABLE REPLACEMENT PER SPAN
650	12-10-2025	Part of : KANCHAN KUNJ, RAJ NAGAR MADANPUR KHADAR	6732	Other Outage	Unplanned Outage	12-10-2025	12:29	12-10-2025	12:57	0:28	0.000389	CABLE FAULT
651	12-10-2025	Part of : JJ COLONY, RAJ NAGAR MADANPUR KHADAR	3998	Other Outage	Unplanned Outage	12-10-2025	16:44	12-10-2025	17:21	0:37	0.000000	CABLE FAULT
652	13-10-2025	Part of : MITHAPUR,	859	Other Outage	Planned Outage	13-10-2025	11:00	13-10-2025	17:02	6:02	0.004022	LT AB SAGGING PER SPAN
653	13-10-2025	Part of : MITHAPUR,	912	Other Outage	Planned Outage	13-10-2025	10:26	13-10-2025	16:39	6:13	0.009325	REPLACEMENT OF LT BUSHING ROD,REPLACEMET OF HT BUSHING ROD,TIGHTENEING OF NUT BOLT
654	14-10-2025	Part of : POCKET B SARITA VIHAR	111	Other Outage	Planned Outage	14-10-2025	11:18	14-10-2025	13:35	2:17	0.002664	REPLACEMENT OF LT BUSHING ROD
655	15-10-2025	Part of : F-BLOCK HARI NAGAR EXTN	15	Other Outage	Planned Outage	15-10-2025	11:43	15-10-2025	13:16	1:33	0.002067	APPLY OF INSULATION TAPE HT/LT BUSHINGS
656	15-10-2025	Part of : POCKET C SARITA VIHAR	213	Other Outage	Planned Outage	15-10-2025	10:58	15-10-2025	13:22	2:24	0.002800	REPLACEMENT OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
657	16-10-2025	Part of : KHADDA COLONY JAIPUR	1	Other Outage	Planned Outage	16-10-2025	10:55	16-10-2025	13:32	2:37	0.010903	REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
658	16-10-2025	Part of : BUDH VIHAR COLONY TAJPUR PAHARI VILLAGE BADARPUR	459	Other Outage	Planned Outage	16-10-2025	11:11	16-10-2025	13:49	2:38	0.000439	REPLACEMET OF HT BUSHING ROD
659	17-10-2025	Part of : K-BLOCK SAURABH VIHAR,N-BLOCK SAURABH VIHAR,J BLOCK SAURABH VIHAR,O-BLOCK SAURABH VIHAR,ABC BLOCK HARI NAGAR MOLARBAND,E-BLOCK HARI NAGAR EXT PART-2,D-BLOCK SAURABH,RAJ NAGAR MADANPUR KHADAR,NTPC WATER TREATMENT PLANT BADARPUR	4325	Other Outage	Unplanned Outage	17-10-2025	15:02	17-10-2025	15:10	0:08	0.000122	CABLE FAULT
660	17-10-2025	Part of : ALI VILLAGE ALI,GAYATRI KUNJ ALI,LALU COLONY ALI,ALI VIHAR ALI	3045	Other Outage	Unplanned Outage	17-10-2025	14:44	17-10-2025	16:15	1:31	0.000000	TREE BRANCH FALLING ON O/H HT LINE
661	18-10-2025	Part of : Lalu Colony Ali,Gayatri Kunj Ali,	490	Other Outage	Unplanned Outage	18-10-2025	10:03	18-10-2025	11:32	1:29	0.001978	REPAIRING OF HVDS CIRCUIT
662	19-10-2025	Part of : LALU COLONY ALI, GAYATRI KUNJ ALI	490	Other Outage	Unplanned Outage	19-10-2025	12:42	19-10-2025	14:15	1:33	0.001292	REPLACEMENT OF JUMPER
663	20-10-2025	Part of : A,B,C & E-BLOCK HARI NAGAR MOLARBAND,F-BLOCK SAURABH VIHAR	4334	Other Outage	Unplanned Outage	20-10-2025	15:05	20-10-2025	15:38	0:33	0.000596	CABLE FAULT
664	21-10-2025	Part of : POCKET C SARITA VIHAR,POCKET A SARITA VIHAR	18	Other Outage	Unplanned Outage	21-10-2025	20:17	21-10-2025	20:45	0:28	0.000124	CABLE FAULT
665	22-10-2025	Part of : L, K, M, H & F-BLOCK SAURABH VIHAR	2023	Other Outage	Unplanned Outage	22-10-2025	15:47	22-10-2025	16:18	0:31	0.000000	CABLE FAULT
666	24-10-2025	Part of : KHADDA COLONY JAIPUR	321	Other Outage	Planned Outage	24-10-2025	10:59	24-10-2025	13:24	2:25	0.002417	3PH HT AB CABLE REPLACEMENT PER SPAN
667	29-10-2025	Part of : D2-BLOCK HARI NAGAR EXTN-III,	408	Other Outage	Planned Outage	29-10-2025	11:08	29-10-2025	11:43	0:35	0.000486	CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
668	29-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR,	1	Other Outage	Planned Outage	29-10-2025	10:58	29-10-2025	12:54	1:56	0.002578	3PH HT AB CABLE REPLACEMENT PER SPAN
669	29-10-2025	Part of : POCKET I SARITA VIHAR,	88	Other Outage	Planned Outage	29-10-2025	10:58	29-10-2025	13:44	2:46	0.003228	REPLACMET OF HT BUSHING ROD
670	29-10-2025	Part of : KHADDA COLONY JAIPUR,	1470	Other Outage	Planned Outage	29-10-2025	11:12	29-10-2025	13:43	2:31	0.003775	CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,REPLACEMENT OF LT BUSHING ROD
671	30-10-2025	Part of : GAUTAMPURI AWAS BADARPUR	1058	Other Outage	Planned Outage	30-10-2025	13:13	30-10-2025	15:41	2:28	0.000822	REPLACEMENT OF HT BUSHING ROD
672	30-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR	1387	Other Outage	Planned Outage	30-10-2025	11:14	30-10-2025	13:22	2:08	0.002133	3PH HT AB CABLE REPLACEMENT PER SPAN
673	31-10-2025	Part of : KHADDA COLONY JAIPUR	3	Other Outage	Planned Outage	31-10-2025	10:16	31-10-2025	14:29	4:13	0.007731	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
674	31-10-2025	Part of : GAUTAMPURI AWAS BADARPUR	1194	Other Outage	Planned Outage	31-10-2025	11:16	31-10-2025	14:12	2:56	0.000489	REPLACMET OF HT BUSHING ROD
675	31-10-2025	Part of : RAJ NAGAR MADANPUR KHADAR	151	Other Outage	Planned Outage	31-10-2025	10:58	31-10-2025	13:45	2:47	0.003247	3PH HT AB CABLE REPLACEMENT
676	01-10-2025	Part of : SAMALKA,	934	Other Outage	Planned Outage	01-10-2025	12:22	01-10-2025	12:58	0:36	0.000000	CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
677	01-10-2025	Part of : SECTOR D VASANT KUNJ,	25	Other Outage	Planned Outage	01-10-2025	11:15	01-10-2025	13:55	2:40	0.001778	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
678	01-10-2025	Part of : GHITORNI VILLAGE GHITORNI,	297	Other Outage	Planned Outage	01-10-2025	11:17	01-10-2025	13:11	1:54	0.000000	1PH DB REVAMPING,JUMPER REPLACEMENT PER POLE
679	03-10-2025	Part of : MES, MARRIED ACOMODATION RANGPURI (HT CONSUMER)	0	Other Outage	Unplanned Outage	03-10-2025	22:38	03-10-2025	23:17	0:39	0.000065	FAULT IN HT CONSUMER PANEL (MES)
680	03-10-2025	Part of : LAKHI NATH KUTI & ROOPAM WALA KUNWA MEHRAULI	3756	Other Outage	Unplanned Outage	03-10-2025	16:43	03-10-2025	17:29	0:46	0.000000	TREE TOUCHING
681	03-10-2025	Part of : MAHIPALPUR EXTENSION	639	Other Outage	Planned Outage	03-10-2025	10:55	03-10-2025	12:56	2:01	0.002857	REPLACMET OF HT BUSHING ROD
682	03-10-2025	Part of : SHAHABAD MUHAMMADPUR VILLAGE DWARKA	326	Other Outage	Planned Outage	03-10-2025	10:52	03-10-2025	15:59	5:07	0.000000	REPLACMET OF HT BUSHING ROD
683	03-10-2025	Part of : GHITORNI VILLAGE	60	Other Outage	Planned Outage	03-10-2025	10:43	03-10-2025	17:30	6:47	0.012436	HT CONDUCTOR REPLACEMENT
684	03-10-2025	Part of : POCKET B 10 SECTOR B VASANT KUNJ	140	Other Outage	Planned Outage	03-10-2025	11:30	03-10-2025	14:21	2:51	0.003800	MEASUREMET OF INSULATION RESISTANCE
685	03-10-2025	Part of : KISHANGARH VILLAGE SECTOR A VASANT KUNJ	332	Other Outage	Planned Outage	03-10-2025	10:33	03-10-2025	13:43	3:10	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
686	04-10-2025	Part of : PUSHPANJALI FARMS	289	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	12:09	0:59	0.000000	CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
687	04-10-2025	Part of : SECTOR D VASANT KUNJ	92	Other Outage	Planned Outage	04-10-2025	10:52	04-10-2025	13:46	2:54	0.001933	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
688	06-10-2025	Part of : ANAND GRAM GHITORNI	193	Other Outage	Planned Outage	06-10-2025	10:43	06-10-2025	12:12	1:29	0.002967	BIRD SPIKES INSTALLATION PER POLE,CHECKING OF EARTHING VALUE USING ONLINE TESTER,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMET PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
689	06-10-2025	Part of : GHITORNI VILLAGE	134	Other Outage	Planned Outage	06-10-2025	10:51	06-10-2025	12:15	1:24	0.002800	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS
690	06-10-2025	Part of : KAPAS HERA EXTENSION KAPAS HERA,PALAM FARMS	3336	Other Outage	Planned Outage	06-10-2025	10:59	06-10-2025	12:43	1:44	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
691	06-10-2025	Part of : POCKET A SECTOR A VASANT KUNJ	153	Other Outage	Planned Outage	06-10-2025	10:44	06-10-2025	13:28	2:44	0.000911	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
692	06-10-2025	Part of : JAWAHAR LAL NEHRU UNIVERSITY	186	Other Outage	Planned Outage	06-10-2025	11:06	06-10-2025	14:04	2:58	0.003956	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
693	07-10-2025	Part of : SAMALKA	81	Other Outage	Unplanned Outage	07-10-2025	13:08	07-10-2025	13:30	0:22	0.000703	TREE TOUCHING
694	07-10-2025	Part of : DESU COLONY VASANT KUNJ,KHANDSA COLONY MEHRAULI,BRIJBASI COLONY MEHRAULI	1813	Other Outage	Unplanned Outage	07-10-2025	04:47	07-10-2025	05:29	0:42	0.000280	HT SYSTEM FAULT
695	07-10-2025	Part of : GHITORNI VILLAGE	736	Other Outage	Planned Outage	07-10-2025	11:04	07-10-2025	12:45	1:41	0.000281	LT AB SAGGING
696	08-10-2025	Part of : MEHRAM NAGAR EAST, POLICE COLONY MEHRAM NAGAR, MEHARAM NAGAR VILLAGE	2154	Other Outage	Unplanned Outage	08-10-2025	10:05	08-10-2025	10:35	0:30	0.000633	TREE TOUCHING
697	08-10-2025	Part of : SLASH PUR VILLAGE PALAM FARMS, BIJWASAN	3392	Other Outage	Unplanned Outage	08-10-2025	02:44	08-10-2025	03:12	0:28	0.000599	TREE TOUCHING
698	08-10-2025	Part of : SETH SARAI MEHRAULI, CHRISTIAN COLONY MEHRAULI, MEHRAULI VILLAGE, LADHA SARAI, T.B HOSPITAL MEHRAULI (HTC), CES DTC DEPOT MEHRAULI (HTC)	1336	Other Outage	Unplanned Outage	08-10-2025	10:53	08-10-2025	11:38	0:45	0.001100	TREE BRANCH FALLEN ON HT O/H LINE
699	08-10-2025	Part of : SAMALKA	216	Other Outage	Planned Outage	08-10-2025	10:53	08-10-2025	12:52	1:59	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
700	08-10-2025	Part of : GHITORNI VILLAGE	1215	Other Outage	Planned Outage	08-10-2025	11:02	08-10-2025	13:34	2:32	0.000929	1PH DB REVAMPING,AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER
701	08-10-2025	Part of : JAWAHAR LAL NEHRU UNIVERSITY,POCKET B 10 SECTOR B VASANT KUNJ	135	Other Outage	Planned Outage	08-10-2025	10:30	08-10-2025	13:26	2:56	0.003911	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
702	08-10-2025	Part of : ISLAM COLONY MEHRAULI	862	Other Outage	Planned Outage	08-10-2025	10:20	08-10-2025	13:32	3:12	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
703	08-10-2025	Part of : SHAHABAD MUHAMMADPUR VILLAGE DWARKA	514	Other Outage	Planned Outage	08-10-2025	11:25	08-10-2025	13:42	2:17	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,DT OIL SAMPLING TO CHECK BDV VALUE,TIGHTENEING OF NUT BOLT
704	09-10-2025	Part of : HTC:ONGC, PLOT NO.5A 5B, VASANT KUN, HTC:DRI 11B HQ INSTITUTIONAL AREA VKJ	0	Other Outage	Unplanned Outage	09-10-2025	07:53	09-10-2025	08:50	0:57	0.000966	FAULT IN HT CONSUMER PANEL (DRI 11B HQ INSTITUTIONAL AREA)
705	09-10-2025	Part of : TEACHER COLONY MEHRAULI,	285	Other Outage	Planned Outage	09-10-2025	12:08	09-10-2025	14:00	1:52	0.000467	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,INSTALLATION OF BUS BAR
706	09-10-2025	Part of : KAPAS HERA EXTENSION KAPAS HERA,KAPAS HERA ESTATE,	2571	Other Outage	Planned Outage	09-10-2025	11:20	09-10-2025	12:59	1:39	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN,TAPPING OF JUMPERS
707	09-10-2025	Part of : ROOPAM WALA KUNWA MEHRAULI,	963	Other Outage	Planned Outage	09-10-2025	12:00	09-10-2025	13:59	1:59	0.000826	CHECKING VALUE OF FENCING EARTHING,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD
708	09-10-2025	Part of : ANAND GRAM GHITORNI,	392	Other Outage	Planned Outage	09-10-2025	11:01	09-10-2025	12:30	1:29	0.002967	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF LUGS,TIGHTENEING OF NUT BOLT
709	09-10-2025	Part of : KISHANGARH VILLAGE SECTOR A VASANT KUNJ,	486	Other Outage	Planned Outage	09-10-2025	10:25	09-10-2025	14:02	3:37	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
710	09-10-2025	Part of : SHAHABAD MUHAMMADPUR VILLAGE DWARKA,	326	Other Outage	Planned Outage	09-10-2025	10:31	09-10-2025	13:23	2:52	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMET OF HT/LT CLEATS,TIGHTENEING OF NUT BOLT MEASUREMET OF INSULATION
711	10-10-2025	Part of : MASUDPUR VILLAGE SECTOR B VASANT KUNJ	1	Other Outage	Planned Outage	10-10-2025	11:56	10-10-2025	13:02	1:06	0.001283	RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
712	10-10-2025	Part of : POCKET 9 SECTOR B VASANT KUNJ	44	Other Outage	Planned Outage	10-10-2025	10:04	10-10-2025	13:01	2:57	0.003442	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
713	10-10-2025	Part of : POCKET 4 SECTOR B VASANT KUNJ	995	Other Outage	Planned Outage	10-10-2025	10:10	10-10-2025	13:59	3:49	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING TIGHTENEING OF NUT BOLT
714	10-10-2025	Part of : GHITORNI VILLAGE	284	Other Outage	Planned Outage	10-10-2025	10:49	10-10-2025	13:25	2:36	0.005200	BIRD SPIKES INSTALLATION PER POLE,CHECKING OF EARTHING VALUE USING ONLINE TESTER,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMET PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING,GUARD WIRE LACS INSTALLTION PER SPAN,HT SLEEVE INSTALLATION PER SPAN,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
715	11-10-2025	Part of : KAPAS HERA EXTENSION	137	Other Outage	Planned Outage	11-10-2025	10:59	11-10-2025	12:37	1:38	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING
716	11-10-2025	Part of : GHITORNI VILLAGE	176	Other Outage	Planned Outage	11-10-2025	10:54	11-10-2025	13:03	2:09	0.003942	APPLY OF INSULATION TAPE HT/LT BUSHINGS
717	11-10-2025	Part of : MEHRAULI VILLAGE	487	Other Outage	Planned Outage	11-10-2025	11:22	11-10-2025	14:17	2:55	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
718	11-10-2025	Part of : SECTOR D VASANT KUNJ	25	Other Outage	Planned Outage	11-10-2025	11:14	11-10-2025	14:01	2:47	0.001856	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
719	13-10-2025	Part of : DALMIA VIHAR BIJWASAN,	17	Other Outage	Unplanned Outage	13-10-2025	13:08	13-10-2025	14:45	1:37	0.000000	REPAIR OF RMU
720	13-10-2025	Part of : KAPAS HERA EXTENSION KAPAS HERA,KAPAS HERA ESTATE,	2073	Other Outage	Planned Outage	13-10-2025	10:59	13-10-2025	11:51	0:52	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
721	13-10-2025	Part of : MEHRAULI VILLAGE MEHRAULI,	2216	Other Outage	Planned Outage	13-10-2025	12:49	13-10-2025	15:21	2:32	0.002744	INSULATOR REPLACEMENT PER POLE,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
722	13-10-2025	Part of : SAMALKA,KAPAS HERA ESTATE,PUSHPANJALI FARMS,KAPAS HERA EXTENSION KAPAS HERA,	2588	Other Outage	Planned Outage	13-10-2025	11:29	13-10-2025	16:24	4:55	0.000000	GUARD WIRE LACS INSTALLTION PER SPAN,REPLACEMENT OF CROSS-ARMS AND POLES
723	13-10-2025	Part of : ANAND GRAM GHITORNI,GHITORNI VILLAGE GHITORNI,ANDHERIA MOR VILLAGE VASANT KUNJ,ARJUN GARH AYA NAGAR,	581	Other Outage	Planned Outage	13-10-2025	10:56	13-10-2025	13:31	2:35	0.004736	BIRD SPIKES INSTALLATION PER POLE,CHECKING OF EARTHING VALUE USING ONLINE TESTER,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMET PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING,GUARD WIRE LACS INSTALLTION PER SPAN,HT SLEEVE INSTALLATION PER SPAN,JUMPER REPLACEMENT PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
724	13-10-2025	Part of : GHITORNI VILLAGE GHITORNI,	478	Other Outage	Planned Outage	13-10-2025	10:22	13-10-2025	12:45	2:23	0.000000	INSTALLATION OF BUS BAR
725	13-10-2025	Part of : POCKET 9 SECTOR B VASANT KUNJ,	298	Other Outage	Planned Outage	13-10-2025	10:44	13-10-2025	13:43	2:59	0.003481	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
726	14-10-2025	Part of : KAPAS HERA EXTENSION	620	Other Outage	Planned Outage	14-10-2025	11:09	14-10-2025	12:56	1:47	0.001724	REPLACEMENT OF HT BUSHING ROD
727	14-10-2025	Part of : GHITORNI VILLAGE	269	Other Outage	Planned Outage	14-10-2025	11:20	14-10-2025	12:56	1:36	0.000400	REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
728	14-10-2025	Part of : KAPAS HERA EXTENSION KAPAS HERA,PUSHPANJALI FARMS,PALAM FARMS	1866	Other Outage	Planned Outage	14-10-2025	11:03	14-10-2025	12:53	1:50	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER
729	14-10-2025	Part of : JAWAHAR LAL NEHRU UNIVERSITY	1	Other Outage	Planned Outage	14-10-2025	12:23	14-10-2025	15:20	2:57	0.003442	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
730	14-10-2025	Part of : DESU COLONY VASANT KUNJ,AHINSHA ENCLAVE MEHRAULI,MEHRAULI VILLAGE MEHRAULI,LADHA SARAI VILLAGE MEHRAULI	3424	Other Outage	Planned Outage	14-10-2025	10:22	14-10-2025	13:26	3:04	0.002044	BIRD SPIKES INSTALLATION PER POLE,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMENT PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING
731	15-10-2025	Part of : B & K-BLOCK MAHIPALPUR VILLAGE,NAI BASTI,RANGPURI,GHITORNI VILLAGE,MAHIPALPUR VILLAGE,POLICE COLONY MEHRAM NAGAR	628	Other Outage	Unplanned Outage	15-10-2025	01:53	15-10-2025	02:24	0:31	0.000052	CABLE FAULT
732	15-10-2025	Part of : KISHANGARH VILLAGE SECTOR A VASANT KUNJ	1171	Other Outage	Planned Outage	15-10-2025	10:23	15-10-2025	12:16	1:53	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
733	15-10-2025	Part of : VASANT KUNJ PHASE-2	12	Other Outage	Planned Outage	15-10-2025	10:14	15-10-2025	13:23	3:09	0.000525	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS
734	15-10-2025	Part of : SAMALKA,KAPAS HERA ESTATE,RAJOKRI VILLAGE,YAWANTIKA COLONY RANGPURI,AVENUE BOUGANVILLEA RANGPURI	875	Other Outage	Planned Outage	15-10-2025	11:03	15-10-2025	13:12	2:09	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS
735	15-10-2025	Part of : ANAND GRAM GHITORNI	28	Other Outage	Planned Outage	15-10-2025	10:42	15-10-2025	13:34	2:52	0.005733	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
736	15-10-2025	Part of : NAYAK PURA BIJWASAN	571	Other Outage	Planned Outage	15-10-2025	11:27	15-10-2025	16:27	5:00	0.000000	LT CIRCUIT MAINTENANCE WORK
737	16-10-2025	Part of : PALAM FARMS	28	Other Outage	Planned Outage	16-10-2025	10:56	16-10-2025	12:26	1:30	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
738	16-10-2025	Part of : SECTOR D VASANT KUNJ	25	Other Outage	Planned Outage	16-10-2025	11:05	16-10-2025	14:00	2:55	0.001944	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
739	16-10-2025	Part of : GHITORNI VILLAGE	834	Other Outage	Planned Outage	16-10-2025	10:53	16-10-2025	14:15	3:22	0.006733	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
740	16-10-2025	Part of : KHANDSA COLONY MEHRAULI	781	Other Outage	Planned Outage	16-10-2025	11:29	16-10-2025	13:44	2:15	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
741	16-10-2025	Part of : SAMALKA	32	Other Outage	Planned Outage	16-10-2025	12:26	16-10-2025	14:40	2:14	0.000000	REPLACEMENT OF HT BUSHING INULATOR
742	16-10-2025	Part of : HARIJAN BASTI RAJOKRI	315	Other Outage	Planned Outage	16-10-2025	12:26	16-10-2025	14:39	2:13	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
743	17-10-2025	Part of : GHITORNI VILLAGE GHITORNI,	39	Other Outage	Planned Outage	17-10-2025	13:45	17-10-2025	14:38	0:53	0.001619	INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
744	17-10-2025	Part of : POCKET 4 SECTOR C VASANT KUNJ,	11	Other Outage	Planned Outage	17-10-2025	10:46	17-10-2025	13:40	2:54	0.002900	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
745	17-10-2025	Part of : SLASH PUR VILLAGE PALAM FARMS,PALAM FARMS,	3426	Other Outage	Planned Outage	17-10-2025	10:45	17-10-2025	13:14	2:29	0.000000	PROPOER CLEANING OF OPERATING MECHANISM USING CRCS PER WAY,REPLACEMET OF FAULTY END BOX
746	17-10-2025	Part of : GHITORNI VILLAGE GHITORNI,	1213	Other Outage	Planned Outage	17-10-2025	10:26	17-10-2025	12:45	2:19	0.005019	BIRD SPIKES INSTALLATION PER POLE,CHECKING OF EARTHING VALUE USING ONLINE TESTER,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMET PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING,GUARD WIRES SAGGING PER SPAN,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
747	17-10-2025	Part of : TEACHER COLONY MEHRAULI,	1047	Other Outage	Planned Outage	17-10-2025	11:22	17-10-2025	13:52	2:30	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,TIGHTENEING OF NUT BOLT
748	17-10-2025	Part of : KAPAS HERA ESTATE,AVENUE BOUGANVILLEA RANGPURI,YAWANTIKA COLONY RANGPURI,AVENUE JHAKARANDA GOLDEN GRITERS RANGPURI,KAPAS HERA EXTENSION KAPAS HERA,	303	Other Outage	Planned Outage	17-10-2025	11:00	17-10-2025	13:06	2:06	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
749	17-10-2025	Part of : HARIJAN BASTI RAJOKRI,	353	Other Outage	Planned Outage	17-10-2025	11:01	17-10-2025	13:59	2:58	0.000000	REPLACEMET OF HT BUSHING ROD
750	18-10-2025	Part of : Pushpanjali Farms,Samalka	2585	Other Outage	Unplanned Outage	18-10-2025	20:53	18-10-2025	21:23	0:30	0.000608	CABLE FAULT
751	18-10-2025	Part of : GHITORNI VILLAGE	1104	Other Outage	Planned Outage	18-10-2025	13:37	18-10-2025	14:06	0:29	0.000967	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
752	18-10-2025	Part of : LAKHI NATH KUTI MEHRAULI,ROOPAM WALA KUNWA MEHRAULI	3760	Other Outage	Planned Outage	18-10-2025	11:35	18-10-2025	12:44	1:09	0.000000	CT REPLACEMENT,SF6 GAS FILLING
753	18-10-2025	Part of : KAPAS HERA EXTENSION KAPAS HERA	887	Other Outage	Planned Outage	18-10-2025	11:02	18-10-2025	12:46	1:44	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS
754	18-10-2025	Part of : AVENUE BOUGANVILLEA RANGPURI	10	Other Outage	Planned Outage	18-10-2025	11:04	18-10-2025	16:11	5:07	0.001279	REPLACEMENT OF HT BUSHING ROD
755	21-10-2025	Part of : AVENUE BOUGANVILLEA RANGPURI,	1	Other Outage	Planned Outage	21-10-2025	11:08	21-10-2025	12:05	0:57	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
756	22-10-2025	Part of : GHITORNI VILLAGE	687	Other Outage	Planned Outage	22-10-2025	10:21	22-10-2025	12:15	1:54	0.003958	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
757	22-10-2025	Part of : KAPAS HERA EXTENSION	635	Other Outage	Planned Outage	22-10-2025	10:46	22-10-2025	12:09	1:23	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
758	22-10-2025	Part of : KAPAS HERA EXTENSION	467	Other Outage	Planned Outage	22-10-2025	10:45	22-10-2025	12:10	1:25	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
759	22-10-2025	Part of : BLOCK B NANGAL DEWAT SECTOR D VASANT KUNJ	822	Other Outage	Planned Outage	22-10-2025	11:16	22-10-2025	14:09	2:53	0.000481	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
760	22-10-2025	Part of : TEACHER COLONY MEHRAULI	438	Other Outage	Planned Outage	22-10-2025	10:23	22-10-2025	12:52	2:29	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
761	23-10-2025	Part of : KAPAS HERA EXTENSION	899	Other Outage	Planned Outage	23-10-2025	10:59	23-10-2025	12:42	1:43	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
762	23-10-2025	Part of : GHITORNI VILLAGE	149	Other Outage	Planned Outage	23-10-2025	10:38	23-10-2025	11:54	1:16	0.002639	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
763	23-10-2025	Part of : SAMALKA	488	Other Outage	Planned Outage	23-10-2025	10:58	23-10-2025	12:43	1:45	0.000583	INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
764	23-10-2025	Part of : PALAM FARMS	33	Other Outage	Planned Outage	23-10-2025	10:41	23-10-2025	12:33	1:52	0.000000	PROPOER CLEANING OF OPERATING MECHANISM USING CRCS PER WAY,REPLACEMENT OF LUGS/NUT BOLTS/BOOTS
765	23-10-2025	Part of : INSTITUTIONAL AREA VASANT KUNJ	7	Other Outage	Planned Outage	23-10-2025	10:34	23-10-2025	13:33	2:59	0.002486	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS
766	23-10-2025	Part of : VASANT KUNJ PHASE-2	5	Other Outage	Planned Outage	23-10-2025	10:34	23-10-2025	13:32	2:58	0.002967	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
767	23-10-2025	Part of : KISHANGARH VILLAGE SECTOR A VASANT KUNJ	620	Other Outage	Planned Outage	23-10-2025	10:45	23-10-2025	13:45	3:00	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
768	24-10-2025	Part of : INDIRA GANDHI INTERNATIONAL AIRPORT (HT CONSUMER)	1	Other Outage	Unplanned Outage	24-10-2025	15:49	24-10-2025	16:30	0:41	0.000535	CABLE FAULT
769	24-10-2025	Part of : DALMIA VIHAR BIJWASAN	626	Other Outage	Planned Outage	24-10-2025	14:44	24-10-2025	15:25	0:41	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
770	24-10-2025	Part of : ANAND GRAM GHITORNI	61	Other Outage	Planned Outage	24-10-2025	14:21	24-10-2025	15:31	1:10	0.002333	BIRD SPIKES INSTALLATION PER POLE,CHECKING OF EARTHING VALUE USING ONLINE TESTER,CLEANING OF INSULATORS PER POLE,CONDUCTOR REPLACEMENT PER SPAN,CONNECTING OF NEW EARTHING PER EARTHING,GUARD WIRE LACS INSTALLTION PER SPAN,GUARD WIRES SAGGING PER SPAN,HT SLEEVE INSTALLATION PER SPAN,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
771	24-10-2025	Part of : SECTOR D VASANT KUNJ	63	Other Outage	Planned Outage	24-10-2025	10:25	24-10-2025	12:21	1:56	0.003867	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
772	24-10-2025	Part of : SAMALKA	51	Other Outage	Planned Outage	24-10-2025	11:01	24-10-2025	12:36	1:35	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
773	24-10-2025	Part of : NAYAK PURA BIJWASAN	580	Other Outage	Planned Outage	24-10-2025	10:48	24-10-2025	14:45	3:57	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
774	24-10-2025	Part of : POCKET C SECTOR A VASANT KUNJ	164	Other Outage	Planned Outage	24-10-2025	10:52	24-10-2025	13:46	2:54	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
775	24-10-2025	Part of : POCKET 11 SECTOR B VASANT KUNJ	162	Other Outage	Planned Outage	24-10-2025	10:40	24-10-2025	13:33	2:53	0.003844	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
776	24-10-2025	Part of : SLASH PUR VILLAGE PALAM FARMS	100	Other Outage	Planned Outage	24-10-2025	10:37	24-10-2025	14:43	4:06	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF HT/LT CLEATS
777	25-10-2025	Part of : POCKET A SECTOR A VASANT KUNJ,KISHANGARH VILLAGE SECTOR A VASANT KUNJ,POCKET 4 SECTOR B VASANT KUNJ	3352	Other Outage	Unplanned Outage	25-10-2025	08:26	25-10-2025	09:06	0:40	0.000800	BIRDAGE
778	25-10-2025	Part of : KISHANGARH VILLAGE SECTOR A VASANT KUNJ,	1219	Other Outage	Planned Outage	25-10-2025	11:07	25-10-2025	11:49	0:42	0.000292	GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
779	25-10-2025	Part of : GHITORNI VILLAGE GHITORNI,	9	Other Outage	Planned Outage	25-10-2025	10:38	25-10-2025	11:56	1:18	0.002708	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
780	25-10-2025	Part of : KAPAS HERA ESTATE,	81	Other Outage	Planned Outage	25-10-2025	11:03	25-10-2025	12:53	1:50	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
781	25-10-2025	Part of : POCKET A SECTOR A VASANT KUNJ,	419	Other Outage	Planned Outage	25-10-2025	10:49	25-10-2025	14:28	3:39	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
782	25-10-2025	Part of : POCKET 8 SECTOR D VASANT KUNJ,	101	Other Outage	Planned Outage	25-10-2025	10:43	25-10-2025	13:39	2:56	0.000978	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
783	25-10-2025	Part of : PALAM FARMS,	132	Other Outage	Planned Outage	25-10-2025	10:11	25-10-2025	12:31	2:20	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,INSTALLATION OF BUS BAR,REPLACEMET OF HT/LT CLEATS,TIGHTENEING OF NUT BOLT
784	28-10-2025	Part of : IAA COLONY, SECTOR D VASANT KUNJ	410	Other Outage	Unplanned Outage	28-10-2025	16:34	28-10-2025	17:22	0:48	0.000067	HT SYSTEM FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
785	28-10-2025	Part of : SECTOR D VASANT KUNJ	40	Other Outage	Planned Outage	28-10-2025	16:07	28-10-2025	16:55	0:48	0.001600	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
786	28-10-2025	Part of : OAK INFRA. ASSET NO. 7 AEROCITY (HTC), ASPEN BUILDTECH ASSET-11 AEROCITY (HTC), BIRD HOTEL ASSET NO.-10 AEROCITY (HTC)	2	Other Outage	Planned Outage	28-10-2025	13:47	28-10-2025	14:26	0:39	0.000758	HT SLEEVE INSTALLATION PER SPAN
787	28-10-2025	Part of : GHITORNI VILLAGE	299	Other Outage	Planned Outage	28-10-2025	10:49	28-10-2025	12:30	1:41	0.003086	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
788	28-10-2025	Part of : SLASH PUR VILLAGE PALAM FARMS	183	Other Outage	Planned Outage	28-10-2025	11:17	28-10-2025	13:36	2:19	0.000000	DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,TIGHTENEING OF NUT BOLT
789	28-10-2025	Part of : KAPAS HERA EXTENSION	984	Other Outage	Planned Outage	28-10-2025	10:48	28-10-2025	13:02	2:14	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
790	28-10-2025	Part of : IAA COLONY SECTOR D VASANT KUNJ	250	Other Outage	Planned Outage	28-10-2025	10:44	28-10-2025	13:34	2:50	0.000944	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
791	29-10-2025	Part of : HTC:BIRD HOTEL,ASSET NO.-10, AEROCITY, HTC: ASPEN BUILDTECH,ASSET-11, AEROCITY	0	Other Outage	Unplanned Outage	29-10-2025	00:32	29-10-2025	00:58	0:26	0.000455	HT SYSTEM FAULT
792	29-10-2025	Part of : POCKET 9 SECTOR C VASANT KUNJ,	141	Other Outage	Planned Outage	29-10-2025	14:26	29-10-2025	16:31	2:05	0.000347	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
793	29-10-2025	Part of : HARIJAN BASTI SECTOR B VASANT KUNJ,	343	Other Outage	Planned Outage	29-10-2025	10:28	29-10-2025	13:13	2:45	0.003667	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
794	29-10-2025	Part of : POCKET 3 SECTOR D VASANT KUNJ,	53	Other Outage	Planned Outage	29-10-2025	10:45	29-10-2025	13:07	2:22	0.004931	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
795	29-10-2025	Part of : DESU COLONY VASANT KUNJ,	455	Other Outage	Planned Outage	29-10-2025	10:32	29-10-2025	12:42	2:10	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
796	29-10-2025	Part of : AVENUE JHAKARANDA GOLDEN GRITERS RANGPURI,AVENUE BOUGANVILLEA RANGPURI,HARIJAN BASTI RAJOKRI,	2025	Other Outage	Planned Outage	29-10-2025	10:22	29-10-2025	12:51	2:29	0.000000	BIRD SPIKES INSTALLATION PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
797	29-10-2025	Part of : DALMIA VIHAR BIJWASAN,	273	Other Outage	Planned Outage	29-10-2025	09:57	29-10-2025	13:01	3:04	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,INSTALLATION OF BUS BAR,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
798	30-10-2025	Part of : DALMIA VIHAR BIJWASAN	631	Other Outage	Unplanned Outage	30-10-2025	15:47	30-10-2025	16:27	0:40	0.000000	REPAIRING OF GUARD WIRE/LACES
799	30-10-2025	Part of : GHITORNI VILLAGE	1217	Other Outage	Planned Outage	30-10-2025	10:58	30-10-2025	12:43	1:45	0.003208	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
800	30-10-2025	Part of : KAPAS HERA ESTATE	219	Other Outage	Planned Outage	30-10-2025	11:01	30-10-2025	12:47	1:46	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
801	30-10-2025	Part of : MEHRAULI VILLAGE MEHRAULI	2225	Other Outage	Planned Outage	30-10-2025	11:48	30-10-2025	15:02	3:14	0.000000	FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,LT AB SAGGING PER SPAN
802	30-10-2025	Part of : POCKET A SECTOR A VASANT KUNJ	749	Other Outage	Planned Outage	30-10-2025	11:58	30-10-2025	14:30	2:32	0.000000	INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
803	30-10-2025	Part of : POCKET A SECTOR A VASANT KUNJ	493	Other Outage	Planned Outage	30-10-2025	10:40	30-10-2025	14:37	3:57	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
804	30-10-2025	Part of : IAA COLONY SECTOR D VASANT KUNJ	224	Other Outage	Planned Outage	30-10-2025	10:14	30-10-2025	13:12	2:58	0.000989	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
805	31-10-2025	Part of : DALMIA VIHAR BIJWASAN	121	Other Outage	Unplanned Outage	31-10-2025	14:30	31-10-2025	16:00	1:30	0.000000	REPLACEMENT OF O/H CIRCUIT JUMPER
806	31-10-2025	Part of : GHITORNI VILLAGE	9	Other Outage	Planned Outage	31-10-2025	10:34	31-10-2025	12:17	1:43	0.003433	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
807	31-10-2025	Part of : HARIJAN BASTI SECTOR B VASANT KUNJ	176	Other Outage	Planned Outage	31-10-2025	10:19	31-10-2025	13:17	2:58	0.003956	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES)
808	31-10-2025	Part of : TEACHER COLONY MEHRAULI	285	Other Outage	Planned Outage	31-10-2025	12:30	31-10-2025	14:34	2:04	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
809	02-10-2025	Part of : KAKRAULA VILLAGE DWARKA,POCKET 3 SECTOR 16B DWARKA	3293	Other Outage	Unplanned Outage	02-10-2025	18:11	02-10-2025	19:09	0:58	0.001321	CABLE FAULT
810	06-10-2025	Part of : JAIN COLONY MATIALA,BLOCK G RAJAPURI MATIALA,BLOCK G JAIN COLONY MATIALA,BLOCK B RAJAPURI MATIALA,RAJAPURI MATIALA,BLOCK RZ B RAJAPURI MATIALA,BLOCK B SUBHASH PARK MATIALA	3711	Other Outage	Unplanned Outage	06-10-2025	03:14	06-10-2025	04:02	0:48	0.000760	HT SYSTEM FAULT
811	06-10-2025	Part of : POCKET 3 SECTOR 12 DWARKA	0	Other Outage	Planned Outage	06-10-2025	10:36	06-10-2025	12:24	1:48	0.000000	REPLACEMET OF HT BUSHING ROD,REPLACEMET OF LUGS
812	06-10-2025	Part of : OM VIHAR EXTN.	0	Other Outage	Planned Outage	06-10-2025	12:08	06-10-2025	14:25	2:17	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
813	06-10-2025	Part of : SECTOR 18A DWARKA	0	Other Outage	Planned Outage	06-10-2025	12:13	06-10-2025	14:24	2:11	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
814	06-10-2025	Part of : MAHAVIR ENCLAVE PART 3	470	Other Outage	Planned Outage	06-10-2025	12:12	06-10-2025	14:25	2:13	0.000000	DT REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
815	07-10-2025	Part of : PARK P HOTEL (RADISSON BLUE) SEC-13 DWARKA (HT CONSUMER)	0	Other Outage	Unplanned Outage	07-10-2025	16:59	07-10-2025	17:58	0:59	0.000737	TREE TOUCHING
816	07-10-2025	Part of : SECTOR 13 DWARKA,BHARAT VIHAR & RAJU PARAK EXTENSION DWARKA	6256	Other Outage	Unplanned Outage	07-10-2025	16:11	07-10-2025	16:56	0:45	0.000563	CABLE FAULT
817	07-10-2025	Part of : POCKET 4 SECTOR 16B DWARKA,POCKET 1 SECTOR 14 DWARKA,SECTOR 16C DWARKA	2581	Other Outage	Unplanned Outage	07-10-2025	15:51	07-10-2025	17:45	1:54	0.000000	ATTENDING WEAK POINTS/HOT SPOT
818	08-10-2025	Part of : SECTOR 3 DWARKA, HALF WAY HOME PLOT NO.-1 SEC-3 (HTC)	1716	Other Outage	Unplanned Outage	08-10-2025	10:11	08-10-2025	10:54	0:43	0.000263	BIRDAGE
819	08-10-2025	Part of : SECTOR 18A & 18B DWARKA	2764	Other Outage	Planned Outage	08-10-2025	14:30	08-10-2025	16:30	2:00	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
820	09-10-2025	Part of : SUBHASH PARK MATIALA,NANHEY PARK OM VIHAR UTTAM NAGAR,	2036	Other Outage	Unplanned Outage	09-10-2025	16:15	09-10-2025	16:50	0:35	0.000000	REPLACEMENT OF HVDS CABLE
821	10-10-2025	Part of : MAHAVIR ENCLAVE PART 3	1012	Other Outage	Planned Outage	10-10-2025	11:47	10-10-2025	13:26	1:39	0.000000	LT REPLACEMENT OF LT BUSHING ROD
822	13-10-2025	Part of : SECTOR 12 DWARKA,	1569	Other Outage	Planned Outage	13-10-2025	14:34	13-10-2025	16:32	1:58	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
823	13-10-2025	Part of : BLOCK D MATIALA,	473	Other Outage	Planned Outage	13-10-2025	13:31	13-10-2025	15:40	2:09	0.000000	REPLACEMENT OF LT BUSHING ROD
824	15-10-2025	Part of : SUBHASH PARK MATIALA,SANJAY ENCLAVE UTTAM NAGAR	3145	Other Outage	Unplanned Outage	15-10-2025	14:11	15-10-2025	14:55	0:44	0.000379	CABLE FAULT
825	15-10-2025	Part of : C-BLOCK UTTAM VIHAR BINDAPUR,G-BLOCK RAJAPURI MATIALA,BLOCK G JAIN COLONY MATIALA	5176	Other Outage	Unplanned Outage	15-10-2025	17:10	15-10-2025	18:49	1:39	0.000000	RMU REPAIR
826	15-10-2025	Part of : SUBHASH PARK MATIALA,PARAM PURI UTTAM NAGAR,NANHEY PARK OM VIHAR UTTAM NAGAR	1896	Other Outage	Unplanned Outage	15-10-2025	11:47	15-10-2025	13:35	1:48	0.000000	REPAIRING HVDS CIRCUIT
827	15-10-2025	Part of : MAHAVIR ENCLAVE PART-3	565	Other Outage	Planned Outage	15-10-2025	12:46	15-10-2025	14:02	1:16	0.000000	REPLACEMENT OF LT BUSHING ROD
828	16-10-2025	Part of : SECTOR 4 DWARKA	337	Other Outage	Unplanned Outage	16-10-2025	14:26	16-10-2025	15:25	0:59	0.000000	ATTEND WEAK POINT/HOT SPOT
829	19-10-2025	Part of : D-BLOCK MADHU VIHAR, SECTOR 6 DWARKA	2297	Other Outage	Unplanned Outage	19-10-2025	12:24	19-10-2025	13:04	0:40	0.000167	HVDS TRANSFORMER FAULTY
830	20-10-2025	Part of : HARI VIHAR SECTOR 15 DWARKA,CHANDAN PARK,BLOCK A BHARAT VIHAR	3526	Other Outage	Unplanned Outage	20-10-2025	21:38	20-10-2025	22:19	0:41	0.000695	HT SYSTEM FAULT
831	20-10-2025	Part of : SECTOR 18A & 18B DWARKA,POCKET B & C SECTOR 17 DWARKA	3023	Other Outage	Unplanned Outage	20-10-2025	06:23	20-10-2025	07:11	0:48	0.000547	BIRDAGE
832	21-10-2025	Part of : SECTOR 13 DWARKA	609	Other Outage	Unplanned Outage	21-10-2025	17:38	21-10-2025	18:37	0:59	0.000639	CABLE FAULT
833	21-10-2025	Part of : MAHAVIR ENCLAVE PART 3 MAHAVIR ENCLAVE,	772	Other Outage	Planned Outage	21-10-2025	16:20	21-10-2025	16:57	0:37	0.000000	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
834	22-10-2025	Part of : SECTOR 4 DWARKA	461	Other Outage	Unplanned Outage	22-10-2025	11:02	22-10-2025	11:49	0:47	0.000000	CABLE FAULT
835	24-10-2025	Part of : PARK P HOTEL (HT CONSUMER), RADISSON BLUE SEC-13 DWARKA	0	Other Outage	Unplanned Outage	24-10-2025	02:23	24-10-2025	03:14	0:51	0.000411	CABLE FAULT
836	25-10-2025	Part of : SECTOR 10 DWARKA	559	Other Outage	Unplanned Outage	25-10-2025	02:27	25-10-2025	03:10	0:43	0.000263	FAULT IN HT CONSUMER PANEL (VENKATESHWAR INTERNATIONAL SCHOOL)
837	28-10-2025	Part of : TRANSIT CAMP DWARKA, BHARAT VIHAR DWARKA, POCKET 1 SECTOR 14 DWARKA	2226	Other Outage	Unplanned Outage	28-10-2025	13:20	28-10-2025	13:58	0:38	0.000602	HT SYSTEM FAULT
838	28-10-2025	Part of : SECTOR 13 DWARKA, BHARAT VIHAR DWARKA, RAJU PARAK EXTENSION DWARKA	3142	Other Outage	Unplanned Outage	28-10-2025	09:05	28-10-2025	09:49	0:44	0.000526	BIRDAGE
839	28-10-2025	Part of : D-BLOCK MADHU VIHAR	730	Other Outage	Planned Outage	28-10-2025	12:32	28-10-2025	14:07	1:35	0.000000	LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
840	29-10-2025	Part of : NANHEY PARK OM VIHAR UTTAM NAGAR,	274	Other Outage	Unplanned Outage	29-10-2025	13:16	29-10-2025	15:04	1:48	0.000000	TRANSFORMER REPLACEMENT
841	29-10-2025	Part of : MAHAVIR ENCLAVE PART 3 MAHAVIR ENCLAVE,	1739	Other Outage	Planned Outage	29-10-2025	12:12	29-10-2025	14:49	2:37	0.000000	REPLACEMET OF HT BUSHING ROD,SUB STATION CLEANING
842	31-10-2025	Part of : SECTOR 4 DWARKA	462	Other Outage	Unplanned Outage	31-10-2025	06:26	31-10-2025	06:54	0:28	0.000023	CABLE FAULT
843	01-10-2025	Part of : MANDHELA KALAN VILLAGE	0	Other Outage	Unplanned Outage	01-10-2025	12:11	01-10-2025	12:49	0:38	0.000032	TRANSIENT FAULT
844	01-10-2025	Part of : SARANGPUR VILLAGE,	179	Other Outage	Planned Outage	01-10-2025	12:08	01-10-2025	14:47	2:39	0.002208	REPLACEMET OF HT BUSHING ROD
845	02-10-2025	Part of : MITRAON VILLAGE NAJAFGARH,KAIR VILLAGE,SUREHRA VILLAGE	1517	Other Outage	Unplanned Outage	02-10-2025	18:38	02-10-2025	18:59	0:21	0.000297	TREE BRANCH FALLEN ON O/H LINE
846	03-10-2025	Part of : BADHOSRA	190	Other Outage	Planned Outage	03-10-2025	10:58	03-10-2025	13:23	2:25	0.000403	REPLACEMET OF HT BUSHING ROD
847	03-10-2025	Part of : MITRAON VILLAGE NAJAFGARH	243	Other Outage	Planned Outage	03-10-2025	11:09	03-10-2025	14:00	2:51	0.002375	REPLACEMENT OF HT BUSHING ROD
848	04-10-2025	Part of : SAMAZPUR KHALSA	360	Other Outage	Planned Outage	04-10-2025	12:06	04-10-2025	13:51	1:45	0.001458	REPLACEMENT OF LT BUSHING ROD
849	04-10-2025	Part of : MITRAON VILLAGE NAJAFGARH	278	Other Outage	Planned Outage	04-10-2025	10:59	04-10-2025	12:57	1:58	0.000328	REPLACEMENT OF LT BUSHING ROD
850	04-10-2025	Part of : GOPAL NAGAR NAJAFGARH	430	Other Outage	Planned Outage	04-10-2025	13:08	04-10-2025	15:34	2:26	0.000811	REPLACEMENT OF LT BUSHING ROD
851	06-10-2025	Part of : KAIR VILLAGE	494	Other Outage	Planned Outage	06-10-2025	13:58	06-10-2025	15:48	1:50	0.001222	REPLACEMET OF HT BUSHING ROD
852	06-10-2025	Part of : KHERA DABAS VILLAGE	251	Other Outage	Planned Outage	06-10-2025	11:58	06-10-2025	13:00	1:02	0.000689	REPLACEMET OF HT BUSHING ROD
853	06-10-2025	Part of : NEAR MTNL TOWER, RAWTA MORE	0	Other Outage	Planned Outage	06-10-2025	11:58	06-10-2025	15:02	3:04	0.002044	REPLACEMET OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
854	06-10-2025	Part of : SAMAZPUR KHALSA	360	Other Outage	Planned Outage	06-10-2025	11:01	06-10-2025	13:58	2:57	0.002458	REPLACEMET OF HT BUSHING ROD
855	06-10-2025	Part of : GOPAL NAGAR NAJAFGARH	489	Other Outage	Planned Outage	06-10-2025	11:08	06-10-2025	13:18	2:10	0.001444	REPLACEMET OF HT BUSHING ROD
856	06-10-2025	Part of : GHUMAN HERA JAINPUR VILLAGE	247	Other Outage	Planned Outage	06-10-2025	11:26	06-10-2025	13:58	2:32	0.002111	REPLACEMENT OF HT BUSHING ROD
857	07-10-2025	Part of : KAIR VILLAGE	28	Other Outage	Unplanned Outage	07-10-2025	21:02	07-10-2025	21:08	0:06	0.000005	TREE TOUCHING
858	07-10-2025	Part of : KAIR VILLAGE	28	Other Outage	Unplanned Outage	07-10-2025	18:11	07-10-2025	18:24	0:13	0.000036	TREE TOUCHING
859	07-10-2025	Part of : KAIR VILLAGE,MANDHELA KHURD VILLAGE	1932	Other Outage	Unplanned Outage	07-10-2025	10:08	07-10-2025	10:41	0:33	0.000000	TRANSIENT FAULT
860	08-10-2025	Part of : ISSAPUR VILLAGE	245	Other Outage	Planned Outage	08-10-2025	10:58	08-10-2025	12:33	1:35	0.001319	REPLACEMET OF HT BUSHING ROD
861	08-10-2025	Part of : SARSWATI ENCLAVE GOPAL NAGAR NAJAFGARH, GOPAL NAGAR NAJAFGARH	449	Other Outage	Planned Outage	08-10-2025	12:00	08-10-2025	14:57	2:57	0.001967	REPLACEMET OF HT BUSHING ROD
862	08-10-2025	Part of : DARYAPUR KHURD VILLAGE	364	Other Outage	Planned Outage	08-10-2025	11:02	08-10-2025	13:25	2:23	0.001589	REPLACEMET OF HT BUSHING ROD
863	08-10-2025	Part of : RAWTA VILLAGE	278	Other Outage	Planned Outage	08-10-2025	11:09	08-10-2025	13:56	2:47	0.002319	REPLACEMET OF HT BUSHING ROD
864	09-10-2025	Part of : DHANSA VILLAGE,	144	Other Outage	Planned Outage	09-10-2025	11:22	09-10-2025	13:14	1:52	0.002489	REPLACEMENT OF LT BUSHING ROD
865	09-10-2025	Part of : SAMAZPUR KHALSA,	360	Other Outage	Planned Outage	09-10-2025	13:12	09-10-2025	15:16	2:04	0.001722	REPLACEMET OF HT BUSHING ROD
866	09-10-2025	Part of : GHUMAN HERA JAINPUR VILLAGE,	247	Other Outage	Planned Outage	09-10-2025	12:03	09-10-2025	14:58	2:55	0.002431	REPLACEMET OF HT BUSHING ROD
867	10-10-2025	Part of : SAMAZPUR KHALSA	190	Other Outage	Planned Outage	10-10-2025	14:11	10-10-2025	16:36	2:25	0.000403	REPLACEMENT OF HT BUSHING ROD
868	10-10-2025	Part of : KHARKHARI JATMAL VILLAGE	1	Other Outage	Planned Outage	10-10-2025	12:55	10-10-2025	15:02	2:07	0.000706	REPLACEMENT OF HT BUSHING ROD
869	10-10-2025	Part of : GOPAL NAGAR NAJAFGARH	487	Other Outage	Planned Outage	10-10-2025	13:27	10-10-2025	15:42	2:15	0.002250	REPLACEMENT OF LT BUSHING ROD
870	10-10-2025	Part of : JHULIHULI VILLAGE	213	Other Outage	Planned Outage	10-10-2025	10:12	10-10-2025	12:54	2:42	0.000450	REPLACEMET OF HT BUSHING ROD
871	11-10-2025	Part of : MITRAON VILLAGE NAJAFGARH	305	Other Outage	Planned Outage	11-10-2025	13:00	11-10-2025	14:43	1:43	0.001431	REPLACEMENT OF HT BUSHING ROD
872	11-10-2025	Part of : BABA HARI DAS ENCLAVE JHARODA KALAN	471	Other Outage	Planned Outage	11-10-2025	14:12	11-10-2025	16:46	2:34	0.002139	REPLACEMENT OF HT BUSHING ROD
873	11-10-2025	Part of : RAWTA JAFARPUR KALAN VILLAGE	973	Other Outage	Planned Outage	11-10-2025	11:03	11-10-2025	13:57	2:54	0.000483	REPLACEMENT OF HT BUSHING ROD
874	11-10-2025	Part of : GHALLBPUR VILLAGE	147	Other Outage	Planned Outage	11-10-2025	10:28	11-10-2025	12:57	2:29	0.001656	REPLACEMENT OF HT BUSHING ROD
875	13-10-2025	Part of : ISSAPUR VILLAGE,	45	Other Outage	Planned Outage	13-10-2025	10:37	13-10-2025	12:34	1:57	0.001625	REPLACEMENT OF HT BUSHING ROD
876	14-10-2025	Part of : SAMAZPUR KHALSA	170	Other Outage	Planned Outage	14-10-2025	10:56	14-10-2025	12:39	1:43	0.001431	REPLACEMENT OF HT BUSHING ROD
877	14-10-2025	Part of : MANDHELA KALAN VILLAGE	19	Other Outage	Planned Outage	14-10-2025	13:58	14-10-2025	16:21	2:23	0.001589	REPLACEMENT OF HT BUSHING ROD
878	14-10-2025	Part of : SARSWATI ENCLAVE GOPAL NAGAR NAJAFGARH,GOPAL NAGAR NAJAFGARH	449	Other Outage	Planned Outage	14-10-2025	11:55	14-10-2025	14:33	2:38	0.002633	REPLACEMENT OF HT BUSHING ROD
879	15-10-2025	Part of : NEHA COLONY NEW GOPAL NAGAR NAJAFGARH	188	Other Outage	Planned Outage	15-10-2025	14:59	15-10-2025	16:59	2:00	0.001333	REPLACEMENT OF HT BUSHING ROD
880	15-10-2025	Part of : BASCO COLONY ARYA NAGAR NAJAFGARH	44	Other Outage	Planned Outage	15-10-2025	14:48	15-10-2025	16:18	1:30	0.001200	REPLACEMENT OF HT BUSHING ROD
881	15-10-2025	Part of : RAWTA JAFARPUR KALAN VILLAGE	701	Other Outage	Planned Outage	15-10-2025	14:02	15-10-2025	16:58	2:56	0.002933	REPLACEMENT OF HT BUSHING ROD
882	15-10-2025	Part of : KAIR VILLAGE	675	Other Outage	Planned Outage	15-10-2025	13:03	15-10-2025	16:00	2:57	0.000000	REPLACEMENT OF LT BUSHING ROD
883	15-10-2025	Part of : MANDHELA KALAN VILLAGE	19	Other Outage	Planned Outage	15-10-2025	10:57	15-10-2025	13:39	2:42	0.002700	REPLACEMENT OF HT BUSHING ROD
884	15-10-2025	Part of : BADHOSRA	17	Other Outage	Planned Outage	15-10-2025	11:12	15-10-2025	13:33	2:21	0.001567	REPLACEMENT OF HT BUSHING ROD
885	15-10-2025	Part of : GHUMAN HERA JAINPUR VILLAGE	262	Other Outage	Planned Outage	15-10-2025	11:03	15-10-2025	14:00	2:57	0.002458	REPLACEMENT OF HT BUSHING ROD
886	16-10-2025	Part of : MANDHELA KHURD VILLAGE	16	Other Outage	Planned Outage	16-10-2025	14:10	16-10-2025	15:30	1:20	0.001333	REPLACEMENT OF LT BUSHING ROD
887	16-10-2025	Part of : GHALLBPUR VILLAGE	418	Other Outage	Planned Outage	16-10-2025	11:14	16-10-2025	13:13	1:59	0.000661	REPLACEMENT OF LT BUSHING ROD
888	16-10-2025	Part of : MITRAON VILLAGE NAJAFGARH	364	Other Outage	Planned Outage	16-10-2025	11:56	16-10-2025	14:58	3:02	0.000506	REPLACEMET OF HT BUSHING ROD
889	16-10-2025	Part of : ISSAPUR VILLAGE	45	Other Outage	Planned Outage	16-10-2025	11:31	16-10-2025	13:31	2:00	0.000333	REPLACEMET OF HT BUSHING ROD
890	16-10-2025	Part of : KRISHAN VIHAR NAJAFGARH	1	Other Outage	Planned Outage	16-10-2025	10:11	16-10-2025	13:02	2:51	0.000475	REPLACEMENT OF LT BUSHING ROD
891	16-10-2025	Part of : KHERA DABAS VILLAGE	251	Other Outage	Planned Outage	16-10-2025	10:40	16-10-2025	12:54	2:14	0.002978	REPLACEMENT OF LT BUSHING ROD
892	17-10-2025	Part of : MITRAON VILLAGE NAJAFGARH,	364	Other Outage	Planned Outage	17-10-2025	14:53	17-10-2025	15:38	0:45	0.000125	REPLACEMENT OF LT BUSHING ROD
893	17-10-2025	Part of : MANDHELA KHURD VILLAGE,	2	Other Outage	Planned Outage	17-10-2025	14:28	17-10-2025	15:38	1:10	0.000194	REPLACEMET OF HT BUSHING ROD
894	17-10-2025	Part of : BABA HARI DAS ENCLAVE JHARODA KALAN,	471	Other Outage	Planned Outage	17-10-2025	13:59	17-10-2025	15:37	1:38	0.001361	REPLACEMET OF HT BUSHING ROD
895	17-10-2025	Part of : MALIKPUR ZER VILLAGE,	332	Other Outage	Planned Outage	17-10-2025	10:59	17-10-2025	12:50	1:51	0.000308	REPLACEMENT OF LT BUSHING ROD
896	17-10-2025	Part of : JHULIHULI VILLAGE,	263	Other Outage	Planned Outage	17-10-2025	10:26	17-10-2025	13:02	2:36	0.002167	REPLACEMET OF HT BUSHING ROD
897	18-10-2025	Part of : HAIBUTPUR	369	Other Outage	Planned Outage	18-10-2025	13:29	18-10-2025	15:08	1:39	0.000275	REPLACEMENT OF HT BUSHING ROD
898	18-10-2025	Part of : MITRAON VILLAGE NAJAFGARH	365	Other Outage	Planned Outage	18-10-2025	12:07	18-10-2025	14:01	1:54	0.000317	REPLACEMENT OF HT BUSHING ROD
899	18-10-2025	Part of : RAWTA JAFARPUR KALAN VILLAGE	973	Other Outage	Planned Outage	18-10-2025	11:01	18-10-2025	13:03	2:02	0.000339	REPLACEMENT OF LT BUSHING ROD
900	23-10-2025	Part of : SARSWATI ENCLAVE GOPAL NAGAR NAJAFGARH	1021	Other Outage	Planned Outage	23-10-2025	13:42	23-10-2025	14:11	0:29	0.000081	REPLACEMENT OF HT BUSHING ROD
901	23-10-2025	Part of : JAFARPUR KALAN VILLAGE	249	Other Outage	Planned Outage	23-10-2025	14:55	23-10-2025	16:16	1:21	0.001350	REPLACEMENT OF HT BUSHING ROD
902	23-10-2025	Part of : SUREHRA VILLAGE	10	Other Outage	Planned Outage	23-10-2025	15:07	23-10-2025	16:17	1:10	0.000194	REPLACEMENT OF HT BUSHING ROD
903	23-10-2025	Part of : DHANSA VILLAGE	29	Other Outage	Planned Outage	23-10-2025	11:57	23-10-2025	14:47	2:50	0.000472	REPLACEMENT OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
904	23-10-2025	Part of : SARSWATI ENCLAVE GOPAL NAGAR NAJAFGARH	602	Other Outage	Planned Outage	23-10-2025	12:39	23-10-2025	15:10	2:31	0.002097	REPLACEMENT OF HT BUSHING ROD
905	23-10-2025	Part of : RAWTA VILLAGE	336	Other Outage	Planned Outage	23-10-2025	11:10	23-10-2025	13:50	2:40	0.000889	REPLACEMENT OF HT BUSHING ROD
906	24-10-2025	Part of : JAFARPUR KALAN VILLAGE	8	Other Outage	Planned Outage	24-10-2025	14:23	24-10-2025	15:35	1:12	0.001200	REPLACEMENT OF LT BUSHING ROD
907	24-10-2025	Part of : MALIKPUR ZER VILLAGE	285	Other Outage	Planned Outage	24-10-2025	10:58	24-10-2025	13:45	2:47	0.003711	REPLACEMENT OF LT BUSHING ROD
908	24-10-2025	Part of : JHULIHULI VILLAGE	285	Other Outage	Planned Outage	24-10-2025	10:09	24-10-2025	12:58	2:49	0.003756	REPLACEMENT OF LT BUSHING ROD
909	25-10-2025	Part of : SUREHRA VILLAGE,	465	Other Outage	Planned Outage	25-10-2025	14:01	25-10-2025	16:10	2:09	0.002150	REPLACEMET OF HT BUSHING ROD
910	25-10-2025	Part of : ISSAPUR VILLAGE,	45	Other Outage	Planned Outage	25-10-2025	14:44	25-10-2025	16:49	2:05	0.000347	REPLACEMET OF HT BUSHING ROD
911	25-10-2025	Part of : RAWTA VILLAGE,	272	Other Outage	Planned Outage	25-10-2025	11:04	25-10-2025	13:39	2:35	0.002583	REPLACEMENT OF LT BUSHING ROD
912	25-10-2025	Part of : RAWTA JAFARPUR KALAN VILLAGE,	988	Other Outage	Planned Outage	25-10-2025	11:00	25-10-2025	13:40	2:40	0.003556	REPLACEMENT OF LT BUSHING ROD
913	25-10-2025	Part of : JAFARPUR KALAN VILLAGE,	8	Other Outage	Planned Outage	25-10-2025	11:07	25-10-2025	13:38	2:31	0.002517	REPLACEMET OF HT BUSHING ROD
914	26-10-2025	Part of : MANDHELA KHURD VILLAGE,KAIR VILLAGE,MANDHELA KALAN VILLAGE,RAWTA JAFARPUR KALAN VILLAGE,MITRAON VILLAGE NAJAFGARH	926	Other Outage	Unplanned Outage	26-10-2025	11:02	26-10-2025	11:06	0:04	0.000066	HT SYSTEM FAULT
915	26-10-2025	Part of : KAIR VILLAGE,MANDHELA KHURD VILLAGE	1935	Other Outage	Unplanned Outage	26-10-2025	08:52	26-10-2025	09:18	0:26	0.000238	HT SYSTEM FAULT
916	28-10-2025	Part of : KHERA DABAS VILLAGE	157	Other Outage	Planned Outage	28-10-2025	13:58	28-10-2025	16:20	2:22	0.000394	REPLACEMET OF HT BUSHING ROD
917	28-10-2025	Part of : HAIBUTPUR	370	Other Outage	Planned Outage	28-10-2025	14:09	28-10-2025	16:48	2:39	0.000442	REPLACEMENT OF LT BUSHING ROD
918	28-10-2025	Part of : SUREHRA VILLAGE	1	Other Outage	Planned Outage	28-10-2025	12:58	28-10-2025	15:33	2:35	0.000431	REPLACEMENT OF LT BUSHING ROD
919	28-10-2025	Part of : DHANSA VILLAGE	7	Other Outage	Planned Outage	28-10-2025	11:06	28-10-2025	13:45	2:39	0.000442	REPLACEMENT OF LT BUSHING ROD
920	29-10-2025	Part of : MANDHELA KHURD VILLAGE,	16	Other Outage	Planned Outage	29-10-2025	12:17	29-10-2025	14:14	1:57	0.001300	REPLACEMET OF HT BUSHING ROD
921	29-10-2025	Part of : UJWA VILLAGE,	464	Other Outage	Planned Outage	29-10-2025	14:26	29-10-2025	16:28	2:02	0.001356	REPLACEMET OF HT BUSHING ROD
922	29-10-2025	Part of : RAWTA VILLAGE,	302	Other Outage	Planned Outage	29-10-2025	12:01	29-10-2025	14:17	2:16	0.001511	REPLACEMET OF HT BUSHING ROD
923	29-10-2025	Part of : SRI HANS NAGAR,	1	Other Outage	Planned Outage	29-10-2025	11:12	29-10-2025	13:57	2:45	0.001833	REPLACEMET OF HT BUSHING ROD
924	29-10-2025	Part of : SARANGPUR VILLAGE,	8	Other Outage	Planned Outage	29-10-2025	11:41	29-10-2025	13:58	2:17	0.001522	REPLACEMET OF HT BUSHING ROD
925	30-10-2025	Part of : JAIN PUR VILLAGE	273	Other Outage	Planned Outage	30-10-2025	13:53	30-10-2025	16:08	2:15	0.003000	REPLACEMENT OF HT BUSHING ROD
926	30-10-2025	Part of : MALIKPUR ZER VILLAGE	211	Other Outage	Planned Outage	30-10-2025	12:01	30-10-2025	14:49	2:48	0.002800	REPLACEMENT OF HT BUSHING ROD
927	30-10-2025	Part of : NEHA COLONY NEW GOPAL NAGAR NAJAFGARH	187	Other Outage	Planned Outage	30-10-2025	12:02	30-10-2025	14:48	2:46	0.000461	REPLACEMENT OF LT BUSHING ROD
928	30-10-2025	Part of : QAZIPUR VILLAGE	330	Other Outage	Planned Outage	30-10-2025	11:08	30-10-2025	13:46	2:38	0.000439	REPLACEMENT OF HT BUSHING ROD
929	30-10-2025	Part of : BABA HARI DAS ENCLAVE JHARODA KALAN	470	Other Outage	Planned Outage	30-10-2025	11:05	30-10-2025	13:47	2:42	0.000450	REPLACEMENT OF HT BUSHING ROD
930	30-10-2025	Part of : MANDHELA KALAN VILLAGE	11	Other Outage	Planned Outage	30-10-2025	10:57	30-10-2025	12:58	2:01	0.000336	REPLACEMENT OF HT BUSHING ROD
931	31-10-2025	Part of : A 1-BLOCK VINOBHA ENCLAVE,CRPF COLONY JHARODA KALAN	5	Other Outage	Planned Outage	31-10-2025	12:01	31-10-2025	14:50	2:49	0.000469	REPLACEMET OF HT BUSHING ROD
932	31-10-2025	Part of : RAWTA JAFARPUR KALAN VILLAGE	989	Other Outage	Planned Outage	31-10-2025	11:06	31-10-2025	13:48	2:42	0.002250	REPLACEMET OF HT BUSHING ROD
933	31-10-2025	Part of : MANDHELA KALAN VILLAGE	3	Other Outage	Planned Outage	31-10-2025	11:09	31-10-2025	13:49	2:40	0.000889	REPLACEMET OF HT BUSHING ROD
934	01-10-2025	Part of : DELHI MILK SSCHEME COLONY HARI NAGAR,	1010	Other Outage	Unplanned Outage	01-10-2025	14:41	01-10-2025	15:41	1:00	0.000167	REPAIR IN LT CIRCUIT
935	01-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI,	237	Other Outage	Planned Outage	01-10-2025	12:53	01-10-2025	15:18	2:25	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
936	02-10-2025	Part of : BLOCK C NANAK PURA HARI NAGAR	773	Other Outage	Unplanned Outage	02-10-2025	02:23	02-10-2025	03:13	0:50	0.001014	CABLE FAULT
937	03-10-2025	Part of : BLOCK A NANAK PURA HARI NAGAR	1090	Other Outage	Planned Outage	03-10-2025	13:16	03-10-2025	14:58	1:42	0.000000	REPLACEMET OF LT BUSHING ROD
938	03-10-2025	Part of : SHIV NAGAR EXTENSION JANAK PURI	540	Other Outage	Planned Outage	03-10-2025	11:59	03-10-2025	14:26	2:27	0.000817	APPLY OF INSULATION TAPE LT BUSHINGS
939	03-10-2025	Part of : ADITI APARTMENTS JANAK PURI	351	Other Outage	Planned Outage	03-10-2025	11:43	03-10-2025	13:53	2:10	0.000722	OIL TOP UP IN TRANSFORMER
940	03-10-2025	Part of : BLOCK C2 JANAK PURI	334	Other Outage	Planned Outage	03-10-2025	11:17	03-10-2025	13:42	2:25	0.000806	OIL TOP UP IN TRANSFORMER
941	03-10-2025	Part of : BLOCK C1 RAJOURI GARDEN	240	Other Outage	Planned Outage	03-10-2025	11:06	03-10-2025	13:23	2:17	0.000761	3PH DB REPLACEMENT
942	04-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	835	Other Outage	Planned Outage	04-10-2025	11:54	04-10-2025	13:27	1:33	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
943	04-10-2025	Part of : BLOCK CB MAYA ENCLAVE HARI NAGAR	512	Other Outage	Planned Outage	04-10-2025	11:12	04-10-2025	13:35	2:23	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
944	04-10-2025	Part of : TIHAR CENTRAL JAIL JANAK PURI	12	Other Outage	Planned Outage	04-10-2025	11:45	04-10-2025	14:01	2:16	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
945	06-10-2025	Part of : BLOCK B3 JANAK PURI,POCKET B 1 B 1 MARKET SUPER BAZAR JANAK PURI,BLOCK B 3A JANAK PURI	2097	Other Outage	Unplanned Outage	06-10-2025	02:27	06-10-2025	02:55	0:28	0.000467	CABLE FAULT
946	06-10-2025	Part of : BLOCK B2 SHIV NAGAR JANAK PURI,BLOCK BA GURUNANAK PURA JANAK PURI	1689	Other Outage	Unplanned Outage	06-10-2025	14:35	06-10-2025	15:25	0:50	0.001472	CABLE FAULT
947	06-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	836	Other Outage	Planned Outage	06-10-2025	11:55	06-10-2025	13:51	1:56	0.000644	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
948	06-10-2025	Part of : BLOCK BE HARI NAGAR	993	Other Outage	Planned Outage	06-10-2025	11:53	06-10-2025	13:50	1:57	0.000650	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
949	06-10-2025	Part of : BLOCK RZ VASHISHT PARK SAGARPUR	855	Other Outage	Planned Outage	06-10-2025	12:14	06-10-2025	14:44	2:30	0.000833	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
950	06-10-2025	Part of : BLOCK 1 ASHOK NAGAR	516	Other Outage	Planned Outage	06-10-2025	11:02	06-10-2025	13:27	2:25	0.000806	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
951	08-10-2025	Part of : POCKET J-C HARI ENCLAVE HARI NAGAR	366	Other Outage	Planned Outage	08-10-2025	11:26	08-10-2025	14:24	2:58	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
952	08-10-2025	Part of : BLOCK J BERI WALA BAGH HARI NAGAR	458	Other Outage	Planned Outage	08-10-2025	11:32	08-10-2025	14:23	2:51	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
953	08-10-2025	Part of : BLOCK C3 JANAK PURI	166	Other Outage	Planned Outage	08-10-2025	11:11	08-10-2025	13:38	2:27	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
954	08-10-2025	Part of : POCKET D 1A JANAK PURI	6	Other Outage	Planned Outage	08-10-2025	12:03	08-10-2025	14:25	2:22	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
955	08-10-2025	Part of : BLOCK A 3 ASALATPUR VILLAGE JANAK PURI	228	Other Outage	Planned Outage	08-10-2025	11:52	08-10-2025	14:24	2:32	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
956	09-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI,POCKET A 1 DTC COLONY MAYA ENCLAVE HARI NAGAR,SHIV NAGAR JANAK PURI,BLOCK C JANAK PURI,	1637	Other Outage	Planned Outage	09-10-2025	11:43	09-10-2025	15:42	3:59	0.001992	GUARD WIRES SAGGING PER SPAN,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
957	09-10-2025	Part of : BLOCK A NANAK PURA HARI NAGAR,	362	Other Outage	Planned Outage	09-10-2025	11:16	09-10-2025	13:08	1:52	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
958	09-10-2025	Part of : ASHOK NAGAR,	267	Other Outage	Planned Outage	09-10-2025	10:58	09-10-2025	14:26	3:28	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
959	09-10-2025	Part of : POCKET D 1A JANAK PURI,	25	Other Outage	Planned Outage	09-10-2025	11:41	09-10-2025	13:48	2:07	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
960	09-10-2025	Part of : C-4 BLOCK JANAK PURI,	311	Other Outage	Planned Outage	09-10-2025	10:58	09-10-2025	13:07	2:09	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
961	10-10-2025	Part of : BLOCK B3 JANAK PURI,POCKET B 1 B 1 MARKET SUPER BAZAR JANAK PURI,BLOCK B 3A JANAK PURI	2098	Other Outage	Unplanned Outage	10-10-2025	04:53	10-10-2025	05:52	0:59	0.000836	CABLE FAULT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
962	10-10-2025	Part of : BLOCK A NANAK PURA HARI NAGAR	1363	Other Outage	Planned Outage	10-10-2025	12:27	10-10-2025	14:52	2:25	0.000806	LT MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
963	10-10-2025	Part of : DISTRICT CENTRE JANAK PURI	26	Other Outage	Planned Outage	10-10-2025	12:49	10-10-2025	15:08	2:19	0.000772	LT APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
964	10-10-2025	Part of : POCKET D 1A JANAK PURI	4	Other Outage	Planned Outage	10-10-2025	11:16	10-10-2025	13:44	2:28	0.000822	LT OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
965	11-10-2025	Part of : C 3A-BLOCK RESIDENTIAL COMPLEX, C 5B, C 6B & C 4H-BLOCK JANAK PURI	2317	Other Outage	Planned Outage	11-10-2025	14:06	11-10-2025	15:27	1:21	0.000225	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES
966	11-10-2025	Part of : V-BLOCK RAJOURI GARDEN	243	Other Outage	Planned Outage	11-10-2025	11:49	11-10-2025	13:43	1:54	0.000000	LT CONDUCTOR REPLACEMENT
967	11-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	237	Other Outage	Planned Outage	11-10-2025	12:24	11-10-2025	15:17	2:53	0.000000	APPLY OF INSULATION TAPE LT BUSHINGS
968	11-10-2025	Part of : J-BLOCK BERI WALA BAGH HARI NAGAR	780	Other Outage	Planned Outage	11-10-2025	11:23	11-10-2025	14:41	3:18	0.000000	REPLACEMENT OF LT BUSHING ROD
969	11-10-2025	Part of : RZ-BLOCK SAGARPUR	262	Other Outage	Planned Outage	11-10-2025	11:38	11-10-2025	13:44	2:06	0.000000	PRC REPLACEMENT
970	11-10-2025	Part of : G-BLOCK RAJOURI GARDEN	336	Other Outage	Planned Outage	11-10-2025	11:23	11-10-2025	13:42	2:19	0.000000	FERRULE PUNCHING LT AB
971	12-10-2025	Part of : BLOCK B3 JANAK PURI, POCKET B 1 B 1 MARKET SUPER BAZAR JANAK PURI, BLOCK B 3A JANAK PURI	2098	Other Outage	Unplanned Outage	12-10-2025	11:05	12-10-2025	11:45	0:40	0.000667	CABLE FAULT
972	13-10-2025	Part of : BLOCK 3 SUBHASH NAGAR,	249	Other Outage	Planned Outage	13-10-2025	14:12	13-10-2025	15:58	1:46	0.000000	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
973	13-10-2025	Part of : BLOCK E RAGHU NAGAR DABRI,	610	Other Outage	Planned Outage	13-10-2025	11:27	13-10-2025	13:17	1:50	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
974	13-10-2025	Part of : DELHI MILK SScheme COLONY HARI NAGAR,	1010	Other Outage	Planned Outage	13-10-2025	13:17	13-10-2025	15:57	2:40	0.000000	3PH DB REVAMPING
975	13-10-2025	Part of : PRATAP NAGAR MAYA ENCLAVE HARI NAGAR,	585	Other Outage	Planned Outage	13-10-2025	11:49	13-10-2025	13:52	2:03	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
976	13-10-2025	Part of : BLOCK J 5 RAJOURI GARDEN EXTENSION RAJOURI GARDEN,	441	Other Outage	Planned Outage	13-10-2025	11:09	13-10-2025	13:49	2:40	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
977	13-10-2025	Part of : SHIV NAGAR EXTENSION JANAK PURI,	540	Other Outage	Planned Outage	13-10-2025	11:09	13-10-2025	14:15	3:06	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
978	13-10-2025	Part of : BLOCK C 6A JANAK PURI,	240	Other Outage	Planned Outage	13-10-2025	11:27	13-10-2025	13:35	2:08	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
979	14-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	835	Other Outage	Planned Outage	14-10-2025	12:43	14-10-2025	13:51	1:08	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
980	14-10-2025	Part of : BLOCK CA HARI NAGAR	477	Other Outage	Planned Outage	14-10-2025	11:17	14-10-2025	13:11	1:54	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
981	14-10-2025	Part of : BLOCK J 8 RAJOURI GARDEN EXTENSION	330	Other Outage	Planned Outage	14-10-2025	11:24	14-10-2025	12:59	1:35	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
982	14-10-2025	Part of : BLOCK I RAGHU ENCLAVE DABRI EXTENSION EAST DABRI	449	Other Outage	Planned Outage	14-10-2025	12:06	14-10-2025	14:33	2:27	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
983	14-10-2025	Part of : TIHAR CENTRAL JAIL JANAK PURI	75	Other Outage	Planned Outage	14-10-2025	11:18	14-10-2025	13:29	2:11	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
984	15-10-2025	Part of : SUBHASH NAGAR	0	Other Outage	Unplanned Outage	15-10-2025	13:38	15-10-2025	14:31	0:53	0.000000	CABLE FAULT
985	15-10-2025	Part of : ADITI APARTMENTS JANAK PURI	36	Other Outage	Planned Outage	15-10-2025	12:34	15-10-2025	13:41	1:07	0.000372	LT CIRCUIT MAINTENANCE WORK

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
986	15-10-2025	Part of : POCKET E MAYAPURI INDUSTRIAL AREA PHASE-2	458	Other Outage	Planned Outage	15-10-2025	11:19	15-10-2025	13:48	2:29	0.000828	LT CIRCUIT MAINTENANCE WORK
987	15-10-2025	Part of : J 9-BLOCK RAJOURI GARDEN EXTENSION	706	Other Outage	Planned Outage	15-10-2025	11:27	15-10-2025	13:36	2:09	0.000000	LT CIRCUIT MAINTENANCE WORK
988	15-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	836	Other Outage	Planned Outage	15-10-2025	11:23	15-10-2025	13:50	2:27	0.000817	LT CIRCUIT MAINTENANCE WORK
989	15-10-2025	Part of : TIHAR CENTRAL JAIL JANAK PURI	187	Other Outage	Planned Outage	15-10-2025	11:03	15-10-2025	13:28	2:25	0.000806	LT CIRCUIT MAINTENANCE WORK
990	16-10-2025	Part of : DISTRICT CENTRE JANAK PURI, HILTON HOTEL DISTT. CENTER JANAK PURI (HTC)	879	Other Outage	Unplanned Outage	16-10-2025	10:53	16-10-2025	11:55	1:02	0.000913	HT SYSTEM FAULT
991	16-10-2025	Part of : BLOCK A KARAN MARKET NANGAL RAYA JANAK PURI	929	Other Outage	Planned Outage	16-10-2025	11:43	16-10-2025	13:40	1:57	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
992	16-10-2025	Part of : BLOCK H NANAK PURA HARI NAGAR	654	Other Outage	Planned Outage	16-10-2025	11:08	16-10-2025	14:27	3:19	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
993	16-10-2025	Part of : BLOCK C 5B JANAK PURI	293	Other Outage	Planned Outage	16-10-2025	10:53	16-10-2025	13:21	2:28	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
994	16-10-2025	Part of : BLOCK B2 SHIV NAGAR JANAK PURI	6	Other Outage	Planned Outage	16-10-2025	11:42	16-10-2025	14:29	2:47	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
995	16-10-2025	Part of : BLOCK 1 SUBHASH NAGAR	734	Other Outage	Planned Outage	16-10-2025	11:08	16-10-2025	14:28	3:20	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
996	17-10-2025	Part of : RWA COLONY JANAK PURI,	67	Other Outage	Planned Outage	17-10-2025	11:41	17-10-2025	13:39	1:58	0.000000	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
997	17-10-2025	Part of : BLOCK 1 SUBHASH NAGAR,	342	Other Outage	Planned Outage	17-10-2025	11:42	17-10-2025	13:40	1:58	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
998	17-10-2025	Part of : ADITI APARTMENTS JANAK PURI,	427	Other Outage	Planned Outage	17-10-2025	11:44	17-10-2025	13:08	1:24	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
999	17-10-2025	Part of : BLOCK VB VIRENDRA NAGAR JANAK PURI,	258	Other Outage	Planned Outage	17-10-2025	11:17	17-10-2025	12:59	1:42	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
1000	18-10-2025	Part of : MAYAPURI PH-2 C BLK	758	Other Outage	Unplanned Outage	18-10-2025	23:59	19-10-2025	00:54	0:55	0.000504	CABLE FAULT
1001	18-10-2025	Part of : Block A Karan Market Nangal Raya Janak Puri,Block D Mayapuri Industrial Area Phase II Mayapuri,Aditi Apartments Janak Puri,Block WZ RC Basti Nangal Raya Janak Puri	4039	Other Outage	Unplanned Outage	18-10-2025	00:32	18-10-2025	01:55	1:23	0.001914	HT SYSTEM FAULT
1002	18-10-2025	Part of : Block A Mayapuri Industrial Area Phase II Mayapuri,Block EA Maya Enclave Hari Nagar,Pocket D 1A Janak Puri	818	Other Outage	Unplanned Outage	18-10-2025	02:27	18-10-2025	04:40	2:13	0.001293	CABLE FAULT
1003	18-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	230	Other Outage	Planned Outage	18-10-2025	10:54	18-10-2025	11:45	0:51	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
1004	18-10-2025	Part of : NANGAL RAYA JANAK PURI	880	Other Outage	Planned Outage	18-10-2025	12:36	18-10-2025	14:19	1:43	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMENT PER FEEDER
1005	23-10-2025	Part of : POCKET WS1 MAYAPURI INDUSTRIAL AREA PHASE-2,C & D-BOLOCK KHAJAN BASTI	2449	Other Outage	Unplanned Outage	23-10-2025	12:23	23-10-2025	13:19	0:56	0.001711	BIRDAGE
1006	24-10-2025	Part of : BLOCK A 3 ASALATPUR VILLAGE JANAK PURI	228	Other Outage	Planned Outage	24-10-2025	10:57	24-10-2025	13:26	2:29	0.000828	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1007	24-10-2025	Part of : POCKET J-B HARI ENCLAVE HARI NAGAR	691	Other Outage	Planned Outage	24-10-2025	11:19	24-10-2025	14:08	2:49	0.000939	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1008	24-10-2025	Part of : NANGAL VILLAGE DELHI CANTONMENT	844	Other Outage	Planned Outage	24-10-2025	11:21	24-10-2025	13:48	2:27	0.000817	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMENT PER FEEDER
1009	24-10-2025	Part of : BLOCK C 6A JANAK PURI	113	Other Outage	Planned Outage	24-10-2025	10:55	24-10-2025	12:55	2:00	0.000667	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1010	25-10-2025	Part of : POCKET D 1 JANAK PURI,	530	Other Outage	Planned Outage	25-10-2025	11:42	25-10-2025	13:33	1:51	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
1011	25-10-2025	Part of : BLOCK CB HARI NAGAR,	571	Other Outage	Planned Outage	25-10-2025	11:06	25-10-2025	13:32	2:26	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1012	25-10-2025	Part of : BLOCK 6 SUBHASH NAGAR,	584	Other Outage	Planned Outage	25-10-2025	11:22	25-10-2025	13:23	2:01	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
1013	25-10-2025	Part of : BLOCK A 2B ASALATPUR VILLAGE JANAK PURI,	220	Other Outage	Planned Outage	25-10-2025	11:42	25-10-2025	13:47	2:05	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
1014	27-10-2025	Part of : C & C 2C-BLOCK JANAK PURI,DDU HOSPITAL	540	Other Outage	Unplanned Outage	27-10-2025	03:17	27-10-2025	04:08	0:51	0.000368	TRANFORMER FAULTY (630 KVA)
1015	27-10-2025	Part of : CA & CB-BLOCK HARI NAGAR,CB-BLOCK MAYA ENCLAVE	3089	Other Outage	Unplanned Outage	27-10-2025	01:02	27-10-2025	01:54	0:52	0.000462	CABLE FAULT
1016	27-10-2025	Part of : C & C 2C-BLOCK JANAK PURI,DDU HOSPITAL	540	Other Outage	Unplanned Outage	27-10-2025	04:38	27-10-2025	06:13	1:35	0.000000	CABLE FAULT
1017	27-10-2025	Part of : POCKET C HARI NAGAR	486	Other Outage	Planned Outage	27-10-2025	12:29	27-10-2025	14:33	2:04	0.000689	LT CIRCUIT MAINTENANCE WORK
1018	28-10-2025	Part of : POCKET A,B & GI MAYAPURI INDUSTRIAL AREA PHASE II	728	Other Outage	Unplanned Outage	28-10-2025	13:11	28-10-2025	14:30	1:19	0.002348	CABLE FAULT
1019	28-10-2025	Part of : POCKET D 1C LAJWANTI GARDEN JANAK PURI	379	Other Outage	Planned Outage	28-10-2025	11:45	28-10-2025	13:11	1:26	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
1020	28-10-2025	Part of : DILLI HAAT JANAKPURI (HTC)	1	Other Outage	Planned Outage	28-10-2025	12:01	28-10-2025	14:33	2:32	0.000000	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE,SF6 GAS FILLING
1021	28-10-2025	Part of : BLOCK J RAJOURI GARDEN	222	Other Outage	Planned Outage	28-10-2025	11:08	28-10-2025	13:20	2:12	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
1022	28-10-2025	Part of : POCKET S MAYAPURI INDUSTRIAL AREA PHASE II	503	Other Outage	Planned Outage	28-10-2025	11:33	28-10-2025	14:17	2:44	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1023	29-10-2025	Part of : BLOCK C1 JANAK PURI	525	Other Outage	Unplanned Outage	29-10-2025	14:35	29-10-2025	15:31	0:56	0.001167	CABLE FAULT
1024	29-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI,POCKET A 1 DTC COLONY MAYA ENCLAVE HARI NAGAR,SHIV NAGAR JANAK PURI,BLOCK C JANAK PURI,	1639	Other Outage	Planned Outage	29-10-2025	12:31	29-10-2025	13:11	0:40	0.000389	GUARD WIRES SAGGING PER SPAN,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1025	29-10-2025	Part of : BLOCK C NANAK PURA HARI NAGAR,	772	Other Outage	Planned Outage	29-10-2025	12:37	29-10-2025	14:13	1:36	0.000000	MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1026	29-10-2025	Part of : BLOCK A KARAN MARKET NANGAL RAYA JANAK PURI,	142	Other Outage	Planned Outage	29-10-2025	11:47	29-10-2025	12:47	1:00	0.000000	1PH DB REVAMPING,3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE,PRC REPLACEMET PER FEEDER
1027	29-10-2025	Part of : BLOCK J RAJOURI GARDEN,	56	Other Outage	Planned Outage	29-10-2025	11:14	29-10-2025	12:53	1:39	0.000000	3PH DB REVAMPING,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
1028	29-10-2025	Part of : HTC: TIHAR JAIL NO. 5 JKP	1	Other Outage	Planned Outage	29-10-2025	13:42	29-10-2025	15:45	2:03	0.000000	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE,REPLACEMENT OF LUGS/NUT BOLTS/BOOTS
1029	29-10-2025	Part of : BLOCK A 2 ASALATPUR VILLAGE JANAK PURI,	245	Other Outage	Planned Outage	29-10-2025	11:11	29-10-2025	13:35	2:24	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
1030	30-10-2025	Part of : POCKET G HARI NAGAR JANAK PURI	237	Other Outage	Planned Outage	30-10-2025	12:01	30-10-2025	15:01	3:00	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL
1031	30-10-2025	Part of : DDU HOSPITAL, JANAKPURI (HTC)	1	Other Outage	Planned Outage	30-10-2025	12:02	30-10-2025	14:14	2:12	0.000000	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE,REPLACEMENT OF LUGS/NUT BOLTS/BOOTS,SF6 GAS FILLING
1032	31-10-2025	Part of : J-BLOCK BERI WALA BAGH HARI NAGAR	780	Other Outage	Planned Outage	31-10-2025	12:12	31-10-2025	14:41	2:29	0.001242	3PH DB REVAMPING
1033	31-10-2025	Part of : DELHI MILK SSCHEME COLONY HARI NAGAR	1327	Other Outage	Planned Outage	31-10-2025	12:14	31-10-2025	14:42	2:28	0.001233	ACB REPLACEMENT
1034	31-10-2025	Part of : NEAR BHARTI COLLEGE JANAKPURI	1	Other Outage	Planned Outage	31-10-2025	15:15	31-10-2025	16:31	1:16	0.000422	LT CIRCUIT MAINTENANCE WORK
1035	31-10-2025	Part of : G-BLOCK RAJOURI GARDEN	246	Other Outage	Planned Outage	31-10-2025	14:49	31-10-2025	16:15	1:26	0.000478	LT AB MAINTENANCE WORK
1036	31-10-2025	Part of : D-BLOCK MAYAPURI INDUSTRIAL AREA PHASE-2	210	Other Outage	Planned Outage	31-10-2025	12:19	31-10-2025	13:24	1:05	0.000361	LT AB MAINTENANCE WORK
1037	31-10-2025	Part of : BLOCK 3 SUBHASH NAGAR	249	Other Outage	Planned Outage	31-10-2025	12:20	31-10-2025	13:25	1:05	0.000361	ACB REPLACEMENT
1038	31-10-2025	Part of : SHIV NAGAR EXTENSION JANAK PURI	540	Other Outage	Planned Outage	31-10-2025	13:18	31-10-2025	15:53	2:35	0.000861	LT AB MAINTENANCE WORK
1039	01-10-2025	Part of : VEENA ENCLAVE WEST CABIN BLOCK MUNDKA, WEST CABIN BLOCK MUNDKA, GULSHAN PARK WEST CABIN BLOCK MUNDKA	350	Other Outage	Unplanned Outage	01-10-2025	13:05	01-10-2025	14:00	0:55	0.002292	HVDS FAULT
1040	02-10-2025	Part of : BLOCK C MUNDKA, MUNDKA EXTENSION MUNDKA, SAVITA VIHAR MUNDKA	338	Other Outage	Unplanned Outage	02-10-2025	19:01	02-10-2025	19:45	0:44	0.000208	CABLE FAULT
1041	02-10-2025	Part of : WEST CABIN BLOCK MUNDKA, TYAGI PARK MUNDKA	2234	Other Outage	Unplanned Outage	02-10-2025	10:47	02-10-2025	11:23	0:36	0.000800	CABLE FAULT
1042	03-10-2025	Part of : VEENA ENCLAVE, GULSHAN PARK WEST CABIN BLOCK MUNDKA	333	Other Outage	Unplanned Outage	03-10-2025	15:32	03-10-2025	16:22	0:50	0.003222	HVDS CABLE FAULT
1043	04-10-2025	Part of : WEST CABIN BLOCK MUNDKA, TYAGI PARK MUNDKA, SWARN PARK UDYOG NAGAR	2234	Other Outage	Unplanned Outage	04-10-2025	15:50	04-10-2025	16:29	0:39	0.001896	CABLE FAULT
1044	04-10-2025	Part of : TIKRI KALAN	241	Other Outage	Planned Outage	04-10-2025	14:54	04-10-2025	16:19	1:25	0.000708	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
1045	04-10-2025	Part of : NEW PVC MARKET TIKRI KALAN, TIKRI KALAN	334	Other Outage	Planned Outage	04-10-2025	10:59	04-10-2025	13:28	2:29	0.002069	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1046	05-10-2025	Part of : BLOCK A TYAGI VIHAR MUNDKA,	62	Other Outage	Planned Outage	05-10-2025	12:13	05-10-2025	13:17	1:04	0.000533	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
1047	05-10-2025	Part of : BLOCK C MUNDKA,	43	Other Outage	Planned Outage	05-10-2025	12:01	05-10-2025	14:33	2:32	0.001267	REPLACEMENT OF GAS KIT AND OIL SEAL
1048	05-10-2025	Part of : MUNDKA INDUSTRIAL AREA MUNDKA,	276	Other Outage	Planned Outage	05-10-2025	12:06	05-10-2025	14:32	2:26	0.004056	JUMPER REPLACEMENT PER POLE,REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1049	06-10-2025	Part of : POCKET Y JJ COLONY 3 NANGLOI	0	Other Outage	Planned Outage	06-10-2025	10:25	06-10-2025	14:28	4:03	0.002025	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
1050	06-10-2025	Part of : BLOCK A JJ COLONY 2 NANGLOI	1081	Other Outage	Planned Outage	06-10-2025	10:23	06-10-2025	14:26	4:03	0.002700	REPLACEMET OF HT BUSHING ROD
1051	06-10-2025	Part of : NEELWAL ROAD TIKRI VILLAGE	0	Other Outage	Planned Outage	06-10-2025	11:01	06-10-2025	13:25	2:24	0.004000	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
1052	07-10-2025	Part of : TILANGPUR KOTLA,LOKNAYAK PURAM BAKARWALA,JJ COLONY BAKARWALA,HIRAN KUDNA	5000	Other Outage	Unplanned Outage	07-10-2025	12:32	07-10-2025	13:53	1:21	0.000000	FAULT IN RMU/MAINTENANCE/REPAIR OF RMU
1053	07-10-2025	Part of : NEW PVC MARKET TIKRI KALAN	145	Other Outage	Planned Outage	07-10-2025	11:08	07-10-2025	11:58	0:50	0.000278	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1054	09-10-2025	Part of : NEW PVC MARKET TIKRI KALAN,TIKRI KALAN,	334	Other Outage	Planned Outage	09-10-2025	14:50	09-10-2025	16:35	1:45	0.001167	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1055	09-10-2025	Part of : POCKET C LOKNAYAK PURAM BAKARWALA,	205	Other Outage	Planned Outage	09-10-2025	13:37	09-10-2025	16:23	2:46	0.000922	REPLACEMET OF HT BUSHING ROD
1056	09-10-2025	Part of : MUNDKA VILLAGE MUNDKA,	195	Other Outage	Planned Outage	09-10-2025	13:36	09-10-2025	16:21	2:45	0.002108	REPLACEMENT OF GAS KIT AND OIL SEAL
1057	10-10-2025	Part of : LAXMI PARK COLONY KAMARUDDIN NAGAR	0	Other Outage	Unplanned Outage	10-10-2025	13:11	10-10-2025	14:10	0:59	0.003769	CABLE FAULT
1058	10-10-2025	Part of : RANHOLLA	2006	Other Outage	Unplanned Outage	10-10-2025	00:13	10-10-2025	00:51	0:38	0.000000	CABLE FAULT
1059	10-10-2025	Part of : TIKRI KALAN	1065	Other Outage	Planned Outage	10-10-2025	12:05	10-10-2025	15:12	3:07	0.002597	REPLACEMET OF HT BUSHING ROD
1060	11-10-2025	Part of : TIKRI KALAN	271	Other Outage	Planned Outage	11-10-2025	11:11	11-10-2025	13:02	1:51	0.000617	REPLACEMENT OF HT BUSHING ROD
1061	11-10-2025	Part of : POCKET A LOKNAYAK PURAM BAKARWALA	34	Other Outage	Planned Outage	11-10-2025	12:14	11-10-2025	14:56	2:42	0.002025	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE
1062	12-10-2025	Part of : DDA FLATS BAKKARWALA, BAKKARWALA VILLAGE	0	Other Outage	Unplanned Outage	12-10-2025	15:41	12-10-2025	16:26	0:45	0.000450	CABLE FAULT
1063	12-10-2025	Part of : RANI KHERA	1	Other Outage	Planned Outage	12-10-2025	14:03	12-10-2025	14:45	0:42	0.000467	REPLACEMET OF FAULTY END BOX
1064	12-10-2025	Part of : JAI VIHAR KAMARUDDIN NAGAR	659	Other Outage	Planned Outage	12-10-2025	11:52	12-10-2025	15:05	3:13	0.001072	REPLACEMET OF HT BUSHING ROD
1065	13-10-2025	Part of : MUNDKA VILLAGE MUNDKA,	57	Other Outage	Planned Outage	13-10-2025	14:56	13-10-2025	16:25	1:29	0.000742	REPLACEMENT OF LT BUSHING ROD
1066	13-10-2025	Part of : JOHAR VILLAGE NANGLOI EXTENSION NANGLOI,	606	Other Outage	Planned Outage	13-10-2025	12:47	13-10-2025	15:17	2:30	0.002083	REPLACEMET OF HT BUSHING ROD
1067	13-10-2025	Part of : NEELWAL VILLAGE,	427	Other Outage	Planned Outage	13-10-2025	12:29	13-10-2025	14:56	2:27	0.001225	REPLACEMET OF FAULTY END BOX
1068	13-10-2025	Part of : NEELWAL VILLAGE,	72	Other Outage	Planned Outage	13-10-2025	12:29	13-10-2025	14:57	2:28	0.001233	REPLACEMET OF FAULTY END BOX
1069	13-10-2025	Part of : VEENA ENCLAVE WEST CABIN BLOCK MUNDKA,	25	Other Outage	Planned Outage	13-10-2025	11:16	13-10-2025	13:41	2:25	0.001611	REPLACEMENT OF LT BUSHING ROD
1070	14-10-2025	Part of : NETAJI SUBHASH VIHAR MUNDKA	4	Other Outage	Planned Outage	14-10-2025	15:01	14-10-2025	16:14	1:13	0.000608	REPLACEMENT OF HT BUSHING ROD
1071	14-10-2025	Part of : JOHAR VILLAGE NANGLOI EXTENSION NANGLOI	672	Other Outage	Planned Outage	14-10-2025	13:25	14-10-2025	15:18	1:53	0.000628	REPLACEMENT OF LT BUSHING ROD
1072	15-10-2025	Part of : BANI AIR FORCE CAMP JAI VIHAR BAPROLA,NIRMAL VIHAR BAPROLA	1064	Other Outage	Planned Outage	15-10-2025	11:30	15-10-2025	13:23	1:53	0.001256	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS
1073	15-10-2025	Part of : BANI AIR FORCE CAMP JAI VIHAR BAPROLA	744	Other Outage	Planned Outage	15-10-2025	12:03	15-10-2025	16:01	3:58	0.001322	DT REPLACEMENT
1074	15-10-2025	Part of : TYAGI PARK MUNDKA	949	Other Outage	Planned Outage	15-10-2025	11:15	15-10-2025	14:14	2:59	0.003978	REPLACEMENT OF HT BUSHING ROD
1075	16-10-2025	Part of : HIRAN KUDNA,MUNDKA INDUSTRIAL AREA MUNDKA,NETAJI SUBHASH VIHAR MUNDKA	341	Other Outage	Unplanned Outage	16-10-2025	13:26	16-10-2025	14:27	1:01	0.000000	ATTEND WEAK POINT/HOT SPOT
1076	17-10-2025	Part of : BLOCK C JJ COLONY 2 NANGLOI,	2584	Other Outage	Planned Outage	17-10-2025	11:09	17-10-2025	13:38	2:29	0.001242	REPLACEMET OF HT BUSHING ROD
1077	17-10-2025	Part of : RATAN BAGH NANGLOI,	1146	Other Outage	Planned Outage	17-10-2025	11:18	17-10-2025	14:03	2:45	0.001375	REPLACEMENT OF GAS KIT AND OIL SEAL
1078	17-10-2025	Part of : BLOCK C MUNDKA,	672	Other Outage	Planned Outage	17-10-2025	11:19	17-10-2025	14:04	2:45	0.001833	REPLACEMET OF HT BUSHING ROD
1079	18-10-2025	Part of : RANHOLLA	241	Other Outage	Planned Outage	18-10-2025	10:48	18-10-2025	14:02	3:14	0.001617	CONDUCTOR REPLACEMENT PER SPAN
1080	20-10-2025	Part of : IOC PLANT GHEVARA MORE (HT CONSUMER)	0	Other Outage	Unplanned Outage	20-10-2025	00:35	20-10-2025	01:25	0:50	0.000167	CABLE FAULT
1081	21-10-2025	Part of : TIKRI KALAN,	274	Other Outage	Planned Outage	21-10-2025	10:40	21-10-2025	12:15	1:35	0.001319	REPLACEMENT OF LT BUSHING ROD
1082	24-10-2025	Part of : MUNDKA EXTENSION	2	Other Outage	Unplanned Outage	24-10-2025	12:50	24-10-2025	13:43	0:53	0.000000	CABLE FAULT
1083	24-10-2025	Part of : VEENA ENCLAVE WEST CABIN BLOCK MUNDKA	25	Other Outage	Planned Outage	24-10-2025	15:35	24-10-2025	17:12	1:37	0.000539	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1084	24-10-2025	Part of : WEST CABIN BLOCK MUNDKA	1011	Other Outage	Planned Outage	24-10-2025	15:35	24-10-2025	17:09	1:34	0.000783	REPLACEMENT OF GAS KIT AND OIL SEAL
1085	24-10-2025	Part of : WEST CABIN BLOCK MUNDKA	12	Other Outage	Planned Outage	24-10-2025	15:34	24-10-2025	17:10	1:36	0.000533	CONDUCTOR REPLACEMENT PER SPAN
1086	24-10-2025	Part of : RANHOLLA,TILANGPUR KOTLA	1546	Other Outage	Planned Outage	24-10-2025	12:46	24-10-2025	15:08	2:22	0.001183	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1087	24-10-2025	Part of : NEW PVC MARKET TIKRI KALAN,TIKRI KALAN	334	Other Outage	Planned Outage	24-10-2025	10:26	24-10-2025	13:13	2:47	0.000928	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1088	24-10-2025	Part of : BLOCK C YADAV PARK NANGLOI EXTENSION	394	Other Outage	Planned Outage	24-10-2025	11:22	24-10-2025	15:09	3:47	0.000946	REPLACEMENT OF HT BUSHING ROD
1089	25-10-2025	Part of : GULSHAN PARK WEST CABIN BLOCK MUNDKA,	18	Other Outage	Planned Outage	25-10-2025	15:55	25-10-2025	17:55	2:00	0.001167	REPLACEMENT OF LT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1090	25-10-2025	Part of : NEELWAL VILLAGE,TIKRI KALAN,NEW PVC MARKET TIKRI KALAN,NETAJI SUBHASH VIHAR MUNDKA,	3750	Other Outage	Planned Outage	25-10-2025	13:39	25-10-2025	15:43	2:04	0.000689	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1091	25-10-2025	Part of : TIKRI KALAN,	874	Other Outage	Planned Outage	25-10-2025	11:05	25-10-2025	13:36	2:31	0.000839	REPLACEMET OF FAULTY END BOX
1092	25-10-2025	Part of : BANI AIR FORCE CAMP JAI VIHAR BAPROLA,	744	Other Outage	Planned Outage	25-10-2025	11:33	25-10-2025	14:15	2:42	0.000900	CONDUCTOR REPLACEMENT PER SPAN
1093	26-10-2025	Part of : MUNDKA INDUSTRIAL AREA MUNDKA,NETAJI SUBHASH VIHAR MUNDKA	216	Other Outage	Planned Outage	26-10-2025	14:16	26-10-2025	14:57	0:41	0.000456	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1094	26-10-2025	Part of : BULBUL VATIKA SUBHASH VIHAR	0	Other Outage	Planned Outage	26-10-2025	10:58	26-10-2025	11:38	0:40	0.000444	GUARD WIRE LACS INSTALLTION PER SPAN
1095	26-10-2025	Part of : MUNDKA INDUSTRIAL AREA	24	Other Outage	Planned Outage	26-10-2025	12:56	26-10-2025	16:33	3:37	0.002411	3PH DB REPLACEMENT
1096	26-10-2025	Part of : POCKET A LOKNAYAK PURAM BAKARWALA	7	Other Outage	Planned Outage	26-10-2025	11:54	26-10-2025	15:06	3:12	0.000800	REPLACEMET OF HT BUSHING ROD
1097	26-10-2025	Part of : MUNDKA INDUSTRIAL AREA MUNDKA,NETAJI SUBHASH VIHAR MUNDKA,HIRAN KUDNA	347	Other Outage	Planned Outage	26-10-2025	11:55	26-10-2025	14:56	3:01	0.002514	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1098	28-10-2025	Part of : BLOCK C MUNDKA, MUNDKA EXTENSION, SAVITA VIHAR MUNDKA	301	Other Outage	Unplanned Outage	28-10-2025	10:35	28-10-2025	11:19	0:44	0.000990	CABLE FAULT
1099	29-10-2025	Part of : RANHOLLA,	240	Other Outage	Planned Outage	29-10-2025	11:36	29-10-2025	14:41	3:05	0.002569	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1100	29-10-2025	Part of : TIKRI KALAN,	875	Other Outage	Planned Outage	29-10-2025	11:44	29-10-2025	14:48	3:04	0.002044	LT AB SAGGING PER SPAN
1101	29-10-2025	Part of : LAXMI PARK COLONY KAMARUDDIN NAGAR,RANHOLLA,	1971	Other Outage	Planned Outage	29-10-2025	11:42	29-10-2025	13:56	2:14	0.001861	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1102	30-10-2025	Part of : MUNDKA EXTENSION MUNDKA	82	Other Outage	Planned Outage	30-10-2025	11:14	30-10-2025	13:02	1:48	0.000900	REPLACEMENT OF HT BUSHING ROD
1103	31-10-2025	Part of : TIKRI KALAN	2266	Other Outage	Planned Outage	31-10-2025	10:46	31-10-2025	13:44	2:58	0.001483	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS
1104	01-10-2025	Part of : BLOCK R 1 MOHAN GARDEN RAZAPUR KHURD,	129	Other Outage	Planned Outage	01-10-2025	12:03	01-10-2025	14:00	1:57	0.000000	3PH DB REPLACEMENT
1105	01-10-2025	Part of : NAWADA EXTENSION NAWADA,	645	Other Outage	Planned Outage	01-10-2025	11:01	01-10-2025	13:50	2:49	0.000000	CONDUCTOR REPLACEMENT PER SPAN
1106	02-10-2025	Part of : BLOCK L BHAGWATI GARDEN NAWADA,BLOCK F & M ZAILDAR ENCLAVE HASTSAL,PHASE 2 OM VIHAR NAWADA,PHASE 1 OM VIHAR NAWADA	5323	Other Outage	Unplanned Outage	02-10-2025	15:41	02-10-2025	16:39	0:58	0.001337	CABLE FAULT
1107	02-10-2025	Part of : BLOCK A, B & D BHAGWATI GARDEN EXTENSION BHAGWATI GARDEN NAWADA	3672	Other Outage	Unplanned Outage	02-10-2025	19:21	02-10-2025	20:29	1:08	0.000378	REPLACEMENT OF CONDUCTOR ON O/H HT LINE
1108	03-10-2025	Part of : BLOCK M ZAILDAR ENCLAVE HASTSAL	1825	Other Outage	Planned Outage	03-10-2025	15:16	03-10-2025	16:38	1:22	0.000000	REPLACEMET OF HT BUSHING
1109	03-10-2025	Part of : NAWADA EXTENSION NAWADA	883	Other Outage	Planned Outage	03-10-2025	15:17	03-10-2025	16:38	1:21	0.000000	3PH DB REPLACEMENT
1110	03-10-2025	Part of : BLOCK E,LH&D BHAGWATI GARDEN NAWADA	3436	Other Outage	Planned Outage	03-10-2025	12:02	03-10-2025	15:25	3:23	0.000000	DT REPLACEMENT
1111	03-10-2025	Part of : BHAGWATI GARDEN NAWADA,SHANTI PARK DWARKA,POCKET 1 SECTOR 14 DWARKA	2584	Other Outage	Planned Outage	03-10-2025	11:58	03-10-2025	15:24	3:26	0.000000	DT REPLACEMENT
1112	03-10-2025	Part of : BLOCK S,R&R1 MOHAN GARDEN RAZAPUR KHURD	2022	Other Outage	Planned Outage	03-10-2025	12:19	03-10-2025	14:28	2:09	0.000000	3PH HT AB CABLE REPLACEMENT
1113	04-10-2025	Part of : GULAB BAGH, BLOCK D MANSA RAM PARK UTTAM NAGAR, WINTER HILL SOCIETY DWARKA MOR	1610	Other Outage	Unplanned Outage	04-10-2025	10:59	04-10-2025	11:39	0:40	0.000600	HT SYSTEM FAULT
1114	04-10-2025	Part of : PHASE 2 OM VIHAR NAWADA	738	Other Outage	Unplanned Outage	04-10-2025	13:46	04-10-2025	15:35	1:49	0.000606	REPAIRING OF LT ACB
1115	04-10-2025	Part of : BLOCK A SEWAK PARK DWARKA	191	Other Outage	Unplanned Outage	04-10-2025	11:40	04-10-2025	13:14	1:34	0.001044	ATTEND WEAK PINT/HOT SPOT
1116	04-10-2025	Part of : BLOCK A,B & D BHAGWATI GARDEN EXTENSION NAWADA	3676	Other Outage	Unplanned Outage	04-10-2025	11:26	04-10-2025	13:14	1:48	0.001200	REPAIR/REPLACEMENT WORK OF HVDS CABLE
1117	04-10-2025	Part of : BLOCK P & P2 MOHAN GARDEN RAZAPUR KHURD	1314	Other Outage	Planned Outage	04-10-2025	12:09	04-10-2025	14:59	2:50	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1118	04-10-2025	Part of : RAZA PUR KHURD VIKAS NAGAR	801	Other Outage	Planned Outage	04-10-2025	10:58	04-10-2025	13:30	2:32	0.000000	REPLACEMET OF HT BUSHING ROD
1119	06-10-2025	Part of : BLOCK A BHAGWATI GARDEN EXTENSION BHAGWATI GARDEN NAWADA,BLOCK D BHAGWATI GARDEN NAWADA,BHAGWATI GARDEN EXTENSION NAWADA,BLOCK B BHAGWATI GARDEN NAWADA,	3677	Other Outage	Unplanned Outage	06-10-2025	11:58	06-10-2025	13:26	1:28	0.000611	MAINTENANCE

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1120	06-10-2025	Part of : BLOCK RK MOHAN GARDEN RAZAPUR KHURD,BLOCK R MOHAN GARDEN RAZAPUR KHURD	557	Other Outage	Planned Outage	06-10-2025	14:19	06-10-2025	16:09	1:50	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1121	06-10-2025	Part of : BLOCK M ZAILDAR ENCLAVE HASTSAL, BLOCK N 2 MOHAN GARDEN RAZAPUR KHURD, BLOCK S MOHAN GARDEN RAZAPUR KHURD, BLOCK E BHAGWATI GARDEN NAWADA,	6326	Other Outage	Planned Outage	06-10-2025	12:16	06-10-2025	14:13	1:57	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1122	06-10-2025	Part of : BLOCK C VIPIN GARDEN NAWADA, BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD, SAINIK ENCLAVE VIPIN GARDEN NAWADA	3630	Other Outage	Planned Outage	06-10-2025	11:48	06-10-2025	15:48	4:00	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1123	06-10-2025	Part of : PHASE 2 OM VIHAR NAWADA	1355	Other Outage	Planned Outage	06-10-2025	11:18	06-10-2025	15:48	4:30	0.000000	REPLACEMENT OF LT BUSHING ROD
1124	06-10-2025	Part of : NAWADA EXTENSION	645	Other Outage	Planned Outage	06-10-2025	11:24	06-10-2025	15:47	4:23	0.000000	FEEDER PILLAR REPLACEMENT
1125	07-10-2025	Part of : NAWADA EXTENSION	884	Other Outage	Unplanned Outage	07-10-2025	11:38	07-10-2025	15:31	3:53	0.001294	ACB MAINTENANCE/PREVENTIVE MAINTENANCE
1126	08-10-2025	Part of : BLOCK A,B & D BHAGWATI GARDEN NAWADA, ROSHAN GARDEN BHAGWATI GARDEN NAWADA	6192	Other Outage	Unplanned Outage	08-10-2025	15:19	08-10-2025	17:06	1:47	0.000000	ATTENDING WEAK POINTS/HOT SPOT
1127	08-10-2025	Part of : BLOCK P MOHAN GARDEN RAZAPUR KHURD	1	Other Outage	Planned Outage	08-10-2025	12:41	08-10-2025	16:17	3:36	0.001200	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
1128	08-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK E & L BHAGWATI GARDEN NAWADA	1524	Other Outage	Planned Outage	08-10-2025	12:38	08-10-2025	16:18	3:40	0.001222	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
1129	08-10-2025	Part of : BLOCK B & D BHAGWATI GARDEN NAWADA, LAXMI VIHAR NAWADA,BLOCK H BHAGWATI GARDEN NAWADA	5108	Other Outage	Planned Outage	08-10-2025	11:38	08-10-2025	14:57	3:19	0.000000	DT REPLACEMENT
1130	08-10-2025	Part of : BLOCK C VIPIN GARDEN NAWADA	1098	Other Outage	Planned Outage	08-10-2025	11:39	08-10-2025	14:54	3:15	0.000000	DT REPLACEMENT
1131	09-10-2025	Part of : BLOCK E BHAGWATI GARDEN NAWADA,BLOCK L BHAGWATI GARDEN NAWADA,BLOCK H BHAGWATI GARDEN NAWADA,BLOCK D BHAGWATI GARDEN NAWADA,BHAGWATI GARDEN EXTENSION NAWADA,	5209	Other Outage	Unplanned Outage	09-10-2025	15:00	09-10-2025	16:41	1:41	0.001824	REPAIRING OF HVDS CIRCUIT
1132	09-10-2025	Part of : BLOCK H BHAGWATI GARDEN NAWADA,BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD,	5	Other Outage	Planned Outage	09-10-2025	12:10	09-10-2025	15:47	3:37	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1133	09-10-2025	Part of : BLOCK P 2 MOHAN GARDEN RAZAPUR KHURD,BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD,BLOCK L BHAGWATI GARDEN NAWADA,BLOCK H BHAGWATI GARDEN NAWADA,BLOCK P MOHAN GARDEN RAZAPUR KHURD,	1916	Other Outage	Planned Outage	09-10-2025	12:14	09-10-2025	14:24	2:10	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1134	09-10-2025	Part of : PHASE 2 OM VIHAR NAWADA,	734	Other Outage	Planned Outage	09-10-2025	11:20	09-10-2025	15:45	4:25	0.000000	REPLACEMET OF HT BUSHING ROD
1135	09-10-2025	Part of : NAWADA EXTENSION NAWADA,	884	Other Outage	Planned Outage	09-10-2025	11:21	09-10-2025	15:44	4:23	0.000000	DT REPLACEMENT
1136	10-10-2025	Part of : RAZAPUR KHURD,RAZA PUR KHURD VIKAS NAGAR	1081	Other Outage	Unplanned Outage	10-10-2025	15:41	10-10-2025	17:22	1:41	0.000281	REPAIR OF RMU
1137	10-10-2025	Part of : BLOCK A BHAGWATI GARDEN EXTENSION BHAGWATI GARDEN NAWADA,BLOCK B & D BHAGWATI GARDEN NAWADA	3682	Other Outage	Unplanned Outage	10-10-2025	12:30	10-10-2025	14:50	2:20	0.002528	REPAIR OF RMU
1138	10-10-2025	Part of : BLOCK C VIPIN GARDEN NAWADA	1098	Other Outage	Planned Outage	10-10-2025	14:45	10-10-2025	16:36	1:51	0.000000	DT REPLACEMENT
1139	10-10-2025	Part of : BLOCK RK & WE MOHAN GARDEN RAZAPUR KHURD	803	Other Outage	Planned Outage	10-10-2025	11:25	10-10-2025	13:23	1:58	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1140	10-10-2025	Part of : SHYAM PARK NAWADA MAJRA VILLAGE NAWADA, NAWADA EXTENSION NAWADA,PHASE 2 OM VIHAR NAWADA	2537	Other Outage	Planned Outage	10-10-2025	10:42	10-10-2025	15:11	4:29	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1141	11-10-2025	Part of : NAWADA EXTENSION	1062	Other Outage	Unplanned Outage	11-10-2025	12:01	11-10-2025	13:40	1:39	0.002750	FOR TAKING LOAD ON REPAIRED CABLE
1142	11-10-2025	Part of : N 2-BLOCK MOHAN GARDEN RAZAPUR KHURD,RAZAPUR KHURD	1758	Other Outage	Planned Outage	11-10-2025	17:11	11-10-2025	17:46	0:35	0.000000	3PH HT AB CABLE REPLACEMENT
1143	11-10-2025	Part of : A, & D-BLOCK BHAGWATI GARDEN EXTENSION NAWADA	3653	Other Outage	Planned Outage	11-10-2025	15:43	11-10-2025	17:44	2:01	0.000000	3PH HT AB CABLE REPLACEMENT
1144	11-10-2025	Part of : D & H-BLOCK BHAGWATI GARDEN,BHAGWATI GARDEN EXTENSION,LAXMI VIHAR	1751	Other Outage	Planned Outage	11-10-2025	12:11	11-10-2025	14:23	2:12	0.000000	3PH HT AB CABLE REPLACEMENT
1145	11-10-2025	Part of : VIPIN GARDEN EXTENSION NAWADA	646	Other Outage	Planned Outage	11-10-2025	12:12	11-10-2025	14:58	2:46	0.000000	AUXILIARY SUPPLY FOR RELAYS,REPLACEMENT OF FAULTY END BOX

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1146	11-10-2025	Part of : RAZA PUR KHURD VIKAS NAGAR,R-BLOCK MOHAN GARDEN	1414	Other Outage	Planned Outage	11-10-2025	12:14	11-10-2025	14:29	2:15	0.000000	3PH HT AB CABLE REPLACEMENT
1147	12-10-2025	Part of : BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD	2553	Other Outage	Unplanned Outage	12-10-2025	16:02	12-10-2025	17:18	1:16	0.001056	REPAIR/REPLACEMENT WORK OF HVDS CABLE
1148	12-10-2025	Part of : BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD	2	Other Outage	Unplanned Outage	12-10-2025	15:54	12-10-2025	17:18	1:24	0.000000	REPAIR OF RMU
1149	13-10-2025	Part of : RAZA PUR KHURD VIKAS NAGAR,RAZAPUR KHURD,	713	Other Outage	Planned Outage	13-10-2025	11:33	13-10-2025	13:59	2:26	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1150	13-10-2025	Part of : BLOCK F ZAILDAR ENCLAVE NAWADA,	700	Other Outage	Planned Outage	13-10-2025	11:17	13-10-2025	15:04	3:47	0.001261	SUB STATION CLEANING
1151	14-10-2025	Part of : RAZAPUR KHURD,BLOCK N 2 & N3 MOHAN GARDEN RAZAPUR KHURD,K5 & K6 AND DEFENCE ENCLAVE PART-1 MOHAN GARDEN	3586	Other Outage	Unplanned Outage	14-10-2025	16:35	14-10-2025	17:15	0:40	0.001867	CABLE FAULT
1152	14-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK E & L BHAGWATI GARDEN NAWADA	1521	Other Outage	Planned Outage	14-10-2025	14:08	14-10-2025	16:21	2:13	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1153	14-10-2025	Part of : BLOCK D, E, L, & H BHAGWATI GARDEN NAWADA	5210	Other Outage	Planned Outage	14-10-2025	13:39	14-10-2025	15:40	2:01	0.001681	REPLACEMENT OF CROSS-ARMS AND POLES
1154	14-10-2025	Part of : RAZAPUR KHURD,VIKAS KUNJ AND VIKAS KUNJ EXTN	867	Other Outage	Planned Outage	14-10-2025	13:09	14-10-2025	15:42	2:33	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1155	14-10-2025	Part of : BLOCK A, B, B1 & C SEWAK PARK DWARKA,SHANTI PARK DWARKA	3381	Other Outage	Planned Outage	14-10-2025	13:36	14-10-2025	15:41	2:05	0.001736	REPLACEMENT OF CROSS-ARMS AND POLES
1156	14-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA	135	Other Outage	Planned Outage	14-10-2025	11:44	14-10-2025	13:54	2:10	0.000722	1PH DB REPLACEMENT
1157	14-10-2025	Part of : VIPIN GARDEN EXTENSION VIPIN GARDEN NAWADA	441	Other Outage	Planned Outage	14-10-2025	11:13	14-10-2025	13:55	2:42	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1158	14-10-2025	Part of : NAWADA EXTENSION NAWADA	649	Other Outage	Planned Outage	14-10-2025	11:43	14-10-2025	13:55	2:12	0.000000	DT REPLACEMENT
1159	15-10-2025	Part of : R & R1-BLOCK MOHAN GARDEN RAZAPUR KHURD	2034	Other Outage	Unplanned Outage	15-10-2025	13:24	15-10-2025	15:04	1:40	0.000278	REPAIRING HVDS CIRCUIT
1160	15-10-2025	Part of : A-BLOCK BHAGWATI GARDEN EXTENSION NAWADA	310	Other Outage	Unplanned Outage	15-10-2025	10:40	15-10-2025	12:12	1:32	0.001636	REPAIRING HVDS CIRCUIT
1161	15-10-2025	Part of : NAWADA EXTENSION,A & B-BLOCK MAHAVIR ENCLAVE NAWADA	2083	Other Outage	Planned Outage	15-10-2025	11:52	15-10-2025	12:56	1:04	0.000000	3PH HT AB CABLE REPLACEMENT
1162	15-10-2025	Part of : A-BLOCK BHAGWATI GARDEN EXTENSION NAWADA	309	Other Outage	Planned Outage	15-10-2025	15:11	15-10-2025	16:25	1:14	0.000000	LT CIRCUIT REPLACEMENT OF CROSS-ARMS AND POLES
1163	15-10-2025	Part of : VIPIN GARDEN EXTENSION NAWADA	102	Other Outage	Planned Outage	15-10-2025	12:04	15-10-2025	14:30	2:26	0.000000	LT CIRCUIT MAINTENANCE WORK
1164	16-10-2025	Part of : NAWADA EXTENSION	909	Other Outage	Unplanned Outage	16-10-2025	11:45	16-10-2025	13:19	1:34	0.002611	TRANSFORMER REPLACEMENT UNDER LOW IR
1165	16-10-2025	Part of : BLOCK P2,R1 & R5 MOHAN GARDEN RAZAPUR KHURD, BLOCK N1 & N2 MOHAN GARDEN RAZAPUR KHURD,BLOCK M ZAILDAR ENCLAVE HASTSAL	6326	Other Outage	Planned Outage	16-10-2025	14:02	16-10-2025	16:16	2:14	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1166	16-10-2025	Part of : LAXMI VIHAR NAWADA,BLOCK H BHAGWATI GARDEN NAWADA	1426	Other Outage	Planned Outage	16-10-2025	13:14	16-10-2025	15:33	2:19	0.000000	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
1167	17-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK E BHAGWATI GARDEN NAWADA,BLOCK L BHAGWATI GARDEN NAWADA,	1524	Other Outage	Unplanned Outage	17-10-2025	12:24	17-10-2025	14:24	2:00	0.000667	REPAIRING OF RMU
1168	17-10-2025	Part of : BLOCK A SEWAK PARK DWARKA,BLOCK B1 SEWAK PARK DWARKA,BLOCK B SEWAK PARK DWARKA,BLOCK C SEWAK PARK DWARKA,SHANTI PARK DWARKA,	3381	Other Outage	Planned Outage	17-10-2025	14:07	17-10-2025	16:16	2:09	0.000000	REGULAR TRIMMING AND REMOVAL OF TREES OR BRANCHES NEAR OVERHEAD LINES TO AVOID ELECTRICAL HAZARDS PER SPAN
1169	17-10-2025	Part of : RAZAPUR KHURD,BLOCK N 3 MOHAN GARDEN RAZAPUR KHURD,BLOCK N 2 MOHAN GARDEN RAZAPUR KHURD,K5 & K6 AND DEFENCE ENCLAVE PART-1 MOHAN GARDEN,	917	Other Outage	Planned Outage	17-10-2025	12:09	17-10-2025	14:39	2:30	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1170	18-10-2025	Part of : Razapur Khurd,Block N 2 Mohan Garden Razapur Khurd,Block N 3 Mohan Garden Razapur Khurd,K5 & K6 AND DEFENCE ENCLAVE PART-1 MOHAN GARDEN,	3593	Other Outage	Unplanned Outage	18-10-2025	13:02	18-10-2025	14:29	1:27	0.001208	RMU REPAIRING
1171	18-10-2025	Part of : BLOCK R, RK & R1 MOHAN GARDEN RAZAPUR KHURD	557	Other Outage	Planned Outage	18-10-2025	14:55	18-10-2025	15:54	0:59	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1172	18-10-2025	Part of : BLOCK D & H BHAGWATI GARDEN NAWADA,LAXMI VIHAR NAWADA	1751	Other Outage	Planned Outage	18-10-2025	12:53	18-10-2025	15:08	2:15	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1173	21-10-2025	Part of : SHANTI PARK DWARKA,BLOCK C SEWAK PARK DWARKA,	348	Other Outage	Unplanned Outage	21-10-2025	13:49	21-10-2025	15:17	1:28	0.001320	REPAIRING OF HVDS CIRCUIT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1174	21-10-2025	Part of : BLOCK A BHAGWATI GARDEN EXTENSION BHAGWATI GARDEN NAWADA,BLOCK D BHAGWATI GARDEN NAWADA,BHAGWATI GARDEN EXTENSION NAWADA,BLOCK B BHAGWATI GARDEN NAWADA,	3653	Other Outage	Planned Outage	21-10-2025	15:32	21-10-2025	16:58	1:26	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1175	21-10-2025	Part of : BLOCK N 2 MOHAN GARDEN RAZAPUR KHURD,RAZAPUR KHURD,	1758	Other Outage	Planned Outage	21-10-2025	12:23	21-10-2025	14:44	2:21	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1176	22-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK A MAHAVIR ENCLAVE NAWADA,BLOCK B BHAGWATI GARDEN NAWADA	457	Other Outage	Planned Outage	22-10-2025	14:23	22-10-2025	16:07	1:44	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1177	22-10-2025	Part of : BLOCK R MOHAN GARDEN RAZAPUR KHURD	721	Other Outage	Planned Outage	22-10-2025	14:03	22-10-2025	16:06	2:03	0.000000	3PH DB REPLACEMENT
1178	24-10-2025	Part of : PHASE 1 OM VIHAR NAWADA	629	Other Outage	Unplanned Outage	24-10-2025	15:01	24-10-2025	16:17	1:16	0.002111	TRANSFORMER REPLACEMENT UNDER LOW IR
1179	24-10-2025	Part of : LAXMI VIHAR NAWADA,BLOCK B,D & H BHAGWATI GARDEN NAWADA,ROSHAN GARDEN BHAGWATI GARDEN NAWADA	6214	Other Outage	Unplanned Outage	24-10-2025	12:29	24-10-2025	13:33	1:04	0.000960	REPAIRING OF HVDS CIRCUIT
1180	24-10-2025	Part of : NAWADA EXTENSION	645	Other Outage	Planned Outage	24-10-2025	11:43	24-10-2025	13:35	1:52	0.000000	DT REPLACEMENT
1181	24-10-2025	Part of : RAZA PUR KHURD VIKAS NAGAR,RAZAPUR KHURD,BLOCK R MOHAN GARDEN RAZAPUR KHURD	1414	Other Outage	Planned Outage	24-10-2025	12:11	24-10-2025	14:50	2:39	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1182	24-10-2025	Part of : BLOCK B1 SEWAK PARK DWARKA	332	Other Outage	Planned Outage	24-10-2025	12:09	24-10-2025	15:05	2:56	0.000000	DT REPLACEMENT
1183	25-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK E BHAGWATI GARDEN NAWADA,BLOCK L BHAGWATI GARDEN NAWADA,	1524	Other Outage	Planned Outage	25-10-2025	12:13	25-10-2025	13:52	1:39	0.002750	3PH HT AB CABLE REPLACEMENT PER SPAN
1184	25-10-2025	Part of : BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD,	2536	Other Outage	Planned Outage	25-10-2025	12:10	25-10-2025	14:36	2:26	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1185	25-10-2025	Part of : BLOCK R 5 MOHAN GARDEN RAZAPUR KHURD,	1652	Other Outage	Planned Outage	25-10-2025	11:27	25-10-2025	13:50	2:23	0.001589	REPLACEMENT OF CROSS-ARMS AND POLES
1186	25-10-2025	Part of : BLOCK R 1 MOHAN GARDEN RAZAPUR KHURD,	129	Other Outage	Planned Outage	25-10-2025	13:53	25-10-2025	15:37	1:44	0.000000	DT REPLACEMENT
1187	27-10-2025	Part of : VARDHMAN MARKET,NAWADA HOUSING PARK-1	0	Other Outage	Unplanned Outage	27-10-2025	23:23	27-10-2025	23:53	0:30	0.000025	CABLE FAULT
1188	27-10-2025	Part of : A,B & E-BLOCK INDRA PARK MASUDABAD NAJAFGARH,NANGLI SANKRANTI NANGLI SAKRAWATI	2623	Other Outage	Unplanned Outage	27-10-2025	14:04	27-10-2025	14:55	0:51	0.000397	BIRDAGE
1189	28-10-2025	Part of : BLOCK A RAMA PARK NAWADA,BLOCK E & L BHAGWATI GARDEN NAWADA	1521	Other Outage	Planned Outage	28-10-2025	14:10	28-10-2025	16:14	2:04	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1190	28-10-2025	Part of : BLOCK A & B MAHAVIR ENCLAVE NAWADA	703	Other Outage	Planned Outage	28-10-2025	12:16	28-10-2025	14:39	2:23	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1191	28-10-2025	Part of : BLOCK R,R1 & S MOHAN GARDEN RAZAPUR KHURD,RAZAPUR KHURD	2013	Other Outage	Planned Outage	28-10-2025	12:10	28-10-2025	14:34	2:24	0.000000	DT REPLACEMENT
1192	28-10-2025	Part of : SEWAK PARK DWARKA,SHANTI PARK DWARKA	3394	Other Outage	Planned Outage	28-10-2025	11:29	28-10-2025	13:37	2:08	0.000000	3PH DB REPLACEMENT
1193	28-10-2025	Part of : BLOCK B1 SEWAK PARK DWARKA	493	Other Outage	Planned Outage	28-10-2025	11:45	28-10-2025	14:41	2:56	0.000000	3PH DB REVAMPING
1194	28-10-2025	Part of : BLOCK B1 SEWAK PARK DWARKA	332	Other Outage	Planned Outage	28-10-2025	11:30	28-10-2025	13:34	2:04	0.000000	3PH DB REPLACEMENT
1195	29-10-2025	Part of : SAINIK ENCLAVE VIPIN GARDEN NAWADA	1289	Other Outage	Unplanned Outage	29-10-2025	13:55	29-10-2025	14:23	0:28	0.000303	CABLE FAULT
1196	29-10-2025	Part of : BLOCK C VIPIN GARDEN NAWADA	1	Other Outage	Unplanned Outage	29-10-2025	13:49	29-10-2025	14:23	0:34	0.000340	CABLE FAULT
1197	29-10-2025	Part of : BLOCK A RAMA PARK BHAGWATI GARDEN NAWADA,BLOCK A MAHAVIR ENCLAVE NAWADA,BLOCK B BHAGWATI GARDEN NAWADA,	456	Other Outage	Planned Outage	29-10-2025	14:15	29-10-2025	15:58	1:43	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1198	29-10-2025	Part of : NAWADA EXTENSION NAWADA,BLOCK A MAHAVIR ENCLAVE NAWADA,BLOCK B MAHAVIR ENCLAVE NAWADA,	2077	Other Outage	Planned Outage	29-10-2025	11:32	29-10-2025	12:48	1:16	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1199	29-10-2025	Part of : BLOCK H BHAGWATI GARDEN NAWADA,	838	Other Outage	Planned Outage	29-10-2025	12:46	29-10-2025	15:35	2:49	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1200	29-10-2025	Part of : BLOCK R 1 MOHAN GARDEN RAZAPUR KHURD,	129	Other Outage	Planned Outage	29-10-2025	12:07	29-10-2025	14:11	2:04	0.000000	3PH DB REPLACEMENT
1201	30-10-2025	Part of : BLOCK R MOHAN GARDEN RAZAPUR KHURD,RAZAPUR KHURD,RAZA PUR KHURD VIKAS NAGAR	1423	Other Outage	Unplanned Outage	30-10-2025	14:34	30-10-2025	15:52	1:18	0.000217	REPAIRING OF HVDS CIRCUIT
1202	31-10-2025	Part of : A,B & D-BLOCK BHAGWATI GARDEN EXTENSION BHAGWATI GARDEN NAWADA	3653	Other Outage	Planned Outage	31-10-2025	14:50	31-10-2025	16:12	1:22	0.000000	3PH HT AB CABLE REPLACEMENT
1203	31-10-2025	Part of : D & H-BLOCK BHAGWATI GARDEN NAWADA,LAXMI VIHAR NAWADA	1751	Other Outage	Planned Outage	31-10-2025	12:56	31-10-2025	16:09	3:13	0.000000	3PH HT AB CABLE REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
1204	31-10-2025	Part of : RAZAPUR KHURD, N 2, N 3, K 5 & K 6-BLOCK MOHAN GARDEN RAZAPUR KHURD	917	Other Outage	Planned Outage	31-10-2025	11:28	31-10-2025	13:37	2:09	0.000000	DT REPLACEMENT
1205	31-10-2025	Part of : NAWADA EXTENSION	861	Other Outage	Planned Outage	31-10-2025	11:18	31-10-2025	13:36	2:18	0.000000	DT REPLACEMENT
1206	01-10-2025	Part of : BLOCK S JAWALAPURI EXTENSION PASCHIM VIHAR,	341	Other Outage	Planned Outage	01-10-2025	12:04	01-10-2025	15:29	3:25	0.001139	REPLACEMET OF HT BUSHING ROD
1207	01-10-2025	Part of : BLOCK B JAWALAPURI PASCHIM VIHAR,	754	Other Outage	Planned Outage	01-10-2025	14:00	01-10-2025	15:37	1:37	0.000269	REPLACEMET OF HT BUSHING ROD
1208	01-10-2025	Part of : BLOCK L JJ COLONY 3 NANGLOI,	861	Other Outage	Planned Outage	01-10-2025	12:21	01-10-2025	15:29	3:08	0.000522	REPLACEMENT OF LT BUSHING ROD
1209	01-10-2025	Part of : BLOCK A MIRA BAGH PASCHIM VIHAR,	297	Other Outage	Planned Outage	01-10-2025	11:01	01-10-2025	14:02	3:01	0.000503	REPLACEMENT OF HT BUSHING ROD
1210	03-10-2025	Part of : SHRI RAM COLONY,SHIV VIHAR A & B BLOCK,SIHV RAM PARK	1772	Other Outage	Planned Outage	03-10-2025	13:45	03-10-2025	16:46	3:01	0.002514	REPLACEMENT OF CROSS-ARMS AND POLES
1211	03-10-2025	Part of : RISALA GARDEN NILOTHI	167	Other Outage	Planned Outage	03-10-2025	13:48	03-10-2025	16:48	3:00	0.001500	REPLACEMET OF LT BUSHING ROD
1212	03-10-2025	Part of : RISALA GARDEN NILOTHI	316	Other Outage	Planned Outage	03-10-2025	13:48	03-10-2025	16:45	2:57	0.001475	REPLACEMET OF LT BUSHING ROD
1213	03-10-2025	Part of : ADHYAPAK NAGAR NANGLOI	490	Other Outage	Planned Outage	03-10-2025	11:02	03-10-2025	14:04	3:02	0.000758	REPLACEMENT OF LT BUSHING ROD
1214	03-10-2025	Part of : BLOCK 13 SUNDER VIHAR PASCHIM VIHAR	224	Other Outage	Planned Outage	03-10-2025	11:03	03-10-2025	14:03	3:00	0.002000	REPLACEMET OF LT BUSHING ROD
1215	04-10-2025	Part of : HARIJAN BASTI, SHIV VIHAR NANGLOI,BLOCK B LAXMI PARK VANDANA VIHAR, NANGLOI JAT	2952	Other Outage	Unplanned Outage	04-10-2025	23:38	05-10-2025	00:14	0:36	0.000170	HT SYSTEM FAULT
1216	04-10-2025	Part of : BLOCK G NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	2183	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	13:46	2:36	0.000000	REPLACEMET OF HT BUSHING ROD
1217	04-10-2025	Part of : NILOTHI VILLAGE	468	Other Outage	Planned Outage	04-10-2025	11:10	04-10-2025	13:44	2:34	0.000856	REPLACEMET OF HT BUSHING ROD
1218	05-10-2025	Part of : PWD STREET LIGHT RANHOLLA, D BLK JAI VIHAR 25 FT ROAD, C BLK JAI VIHAR 25 FT ROAD, HARPHOOL VIHAR, HARPHOOL VIHAR (NEAR NALA), AMBEDKAR SCHOOL	7715	Other Outage	Unplanned Outage	05-10-2025	12:23	05-10-2025	13:09	0:46	0.001176	HT SYSTEM FAULT
1219	05-10-2025	Part of : POCKET A NARESH PARK NANGLOI,	106	Other Outage	Planned Outage	05-10-2025	12:07	05-10-2025	14:43	2:36	0.001083	REPLACEMET OF HT BUSHING ROD
1220	05-10-2025	Part of : BLOCK A DELHI STATE INDUSTRIAL DEVELOPMENT CORPORATION NANGLOI,	48	Other Outage	Planned Outage	05-10-2025	11:01	05-10-2025	14:12	3:11	0.000531	REPLACEMET OF HT BUSHING ROD
1221	05-10-2025	Part of : EKTA ENCLAVE PEERAGARHI VILLAGE PASCHIM VIHAR,	131	Other Outage	Planned Outage	05-10-2025	11:07	05-10-2025	14:11	3:04	0.000511	REPLACEMET OF HT BUSHING ROD
1222	06-10-2025	Part of : DASS GARDEN,RAJIV RATAN AWAS FLATS,PRADHAN ENCLAVE	5978	Other Outage	Unplanned Outage	06-10-2025	02:24	06-10-2025	03:03	0:39	0.000000	CABLE FAULT
1223	06-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR,BLOCK C JAWALAPURI PASCHIM VIHAR,BLOCK S JAWALAPURI EXTENSION PASCHIM VIHAR,CAMP 5 JAWALAPURI PASCHIM VIHAR,	2655	Other Outage	Unplanned Outage	06-10-2025	14:07	06-10-2025	14:55	0:48	0.000000	PREDICTIVE MAINTENANCE
1224	06-10-2025	Part of : JAI VIHAR PH-1, RANHOLLA,TILANGPUR KOTLA VILLAGE,PRATAP VIHAR	2552	Other Outage	Planned Outage	06-10-2025	10:02	06-10-2025	13:50	3:48	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1225	06-10-2025	Part of : BLOCK GH 12 PASCHIM VIHAR	302	Other Outage	Planned Outage	06-10-2025	11:00	06-10-2025	14:12	3:12	0.000000	REPLACEMET OF HT BUSHING ROD
1226	06-10-2025	Part of : NATIONAL MARKET PIRA GARHI VILLAGE PASCHIM VIHAR,BHERA ENCLAVE PASCHIM VIHAR,PIRA GARHI VILLAGE PASCHIM VIHAR	1018	Other Outage	Planned Outage	06-10-2025	10:56	06-10-2025	14:32	3:36	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1227	06-10-2025	Part of : SIHV RAM PARK ADHYAPAK NAGAR NANGLOI	1136	Other Outage	Planned Outage	06-10-2025	10:53	06-10-2025	14:11	3:18	0.000000	REPLACEMET OF HT BUSHING ROD
1228	07-10-2025	Part of : UDYOG NAGAR MANGOLPURI	121	Other Outage	Unplanned Outage	07-10-2025	04:53	07-10-2025	05:23	0:30	0.000442	HT SYSTEM FAULT
1229	08-10-2025	Part of : SUNDER VIHAR PASCHIM VIHAR	2051	Other Outage	Unplanned Outage	08-10-2025	16:50	08-10-2025	17:40	0:50	0.000986	CABLE FAULT
1230	08-10-2025	Part of : BLOCK GH 13 PASCHIM VIHAR	185	Other Outage	Planned Outage	08-10-2025	13:12	08-10-2025	14:18	1:06	0.000000	REPLACEMET OF FAULTY END BOX
1231	08-10-2025	Part of : MIANWALI NAGAR, RICHMOND SCHOOL (HT CONSUMER)	1	Other Outage	Planned Outage	08-10-2025	13:06	08-10-2025	14:16	1:10	0.000000	SF6 GAS FILLING
1232	08-10-2025	Part of : GURUNANAK VIHAR	402	Other Outage	Planned Outage	08-10-2025	11:58	08-10-2025	16:34	4:36	0.000000	REPLACEMET OF HT BUSHING ROD
1233	08-10-2025	Part of : BLOCK H VANDANA VIHAR NANGLOI	784	Other Outage	Planned Outage	08-10-2025	11:01	08-10-2025	13:40	2:39	0.001104	REPLACEMENT OF LT BUSHING ROD
1234	08-10-2025	Part of : INDER ENCLAVE PASCHIM VIHAR	91	Other Outage	Planned Outage	08-10-2025	11:09	08-10-2025	13:42	2:33	0.000425	REPLACEMENT OF LT BUSHING ROD
1235	08-10-2025	Part of : TILANGPUR KOTLA	370	Other Outage	Planned Outage	08-10-2025	10:53	08-10-2025	13:39	2:46	0.000461	REPLACEMENT OF LT BUSHING ROD
1236	09-10-2025	Part of : RANJEET VIHAR,UDAI VIHAR,	2523	Other Outage	Planned Outage	09-10-2025	11:16	09-10-2025	14:40	3:24	0.001417	3PH HT AB CABLE REPLACEMENT PER SPAN
1237	09-10-2025	Part of : TILANGPUR KOTLA VILLAGE,	292	Other Outage	Planned Outage	09-10-2025	10:30	09-10-2025	13:27	2:57	0.000983	REPLACEMENT OF LT BUSHING ROD
1238	09-10-2025	Part of : SHIV VIHAR NANGLOI,	1376	Other Outage	Planned Outage	09-10-2025	08:26	09-10-2025	11:09	2:43	0.000000	REPLACEMENT OF LT BUSHING ROD
1239	09-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR,	44	Other Outage	Planned Outage	09-10-2025	11:04	09-10-2025	14:18	3:14	0.000539	REPLACEMET OF HT BUSHING ROD
1240	09-10-2025	Part of : BLOCK NS MIYANWALI NAGAR PASCHIM VIHAR,	301	Other Outage	Planned Outage	09-10-2025	11:02	09-10-2025	14:19	3:17	0.000821	REPLACEMET OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1241	10-10-2025	Part of : PIRA GARHI VILLAGE PASCHIM VIHAR, EKTA ENCLAVE PEERAGARHI VILLAGE PASCHIM VIHAR	1119	Other Outage	Planned Outage	10-10-2025	13:52	10-10-2025	16:09	2:17	0.001522	REPLACEMENT OF CROSS-ARMS AND POLES
1242	10-10-2025	Part of : BLOCK GH10 SUNDER VIHAR PASCHIM VIHAR	332	Other Outage	Planned Outage	10-10-2025	12:01	10-10-2025	13:52	1:51	0.000463	LT REPLACEMET OF HT BUSHING ROD
1243	10-10-2025	Part of : DDA PARK NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	1065	Other Outage	Planned Outage	10-10-2025	12:33	10-10-2025	15:08	2:35	0.001507	LT REPLACEMET OF HT BUSHING ROD
1244	10-10-2025	Part of : TILANGPUR KOTLA VILLAGE	1103	Other Outage	Planned Outage	10-10-2025	11:03	10-10-2025	14:18	3:15	0.001083	LT REPLACEMET OF HT BUSHING ROD
1245	10-10-2025	Part of : UDYOG NAGAR MANGOLPURI	285	Other Outage	Planned Outage	10-10-2025	11:26	10-10-2025	14:21	2:55	0.000486	LT REPLACEMET OF HT BUSHING ROD
1246	11-10-2025	Part of : SHRI RAM COLONY,A & B-SHIV VIHAR,SIHV RAM PARK,TEK CHAND COLONY,CHANDER VIHAR	1772	Other Outage	Planned Outage	11-10-2025	11:04	11-10-2025	13:58	2:54	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1247	11-10-2025	Part of : D-BLOCK NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	1037	Other Outage	Planned Outage	11-10-2025	12:11	11-10-2025	14:53	2:42	0.000900	REPLACEMENT OF LT BUSHING ROD
1248	11-10-2025	Part of : GURU HARKISHAN NAGAR PASCHIM VIHAR	211	Other Outage	Planned Outage	11-10-2025	11:03	11-10-2025	13:56	2:53	0.001442	REPLACEMENT OF LT BUSHING ROD
1249	12-10-2025	Part of : BLOCK B DELHI STATE INDUSTRIAL DEVELOPMENT CORPORATION NANGLOI	17	Other Outage	Planned Outage	12-10-2025	11:23	12-10-2025	14:11	2:48	0.000933	REPLACEMET OF HT BUSHING ROD
1250	12-10-2025	Part of : NANGLOI JAT	12	Other Outage	Planned Outage	12-10-2025	14:08	12-10-2025	16:59	2:51	0.000713	REPLACEMET OF HT BUSHING ROD
1251	13-10-2025	Part of : SHIV VIHAR NANGLOI,BLOCK B LAXMI PARK VANDANA VIHAR NANGLOI,NANGLOI JAT NANGLOI	2970	Other Outage	Unplanned Outage	13-10-2025	11:35	13-10-2025	12:26	0:51	0.000198	CABLE FAULT
1252	13-10-2025	Part of : RISHAL GARDEN,	1515	Other Outage	Planned Outage	13-10-2025	11:57	13-10-2025	14:08	2:11	0.000910	REPLACEMET OF HT BUSHING ROD
1253	13-10-2025	Part of : BLOCKC MIYANWALI NAGAR PASCHIM VIHAR,	243	Other Outage	Planned Outage	13-10-2025	11:17	13-10-2025	13:56	2:39	0.000530	REPLACEMET OF HT BUSHING ROD
1254	13-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR,	143	Other Outage	Planned Outage	13-10-2025	11:23	13-10-2025	13:58	2:35	0.000215	REPLACEMET OF HT BUSHING ROD
1255	13-10-2025	Part of : BLOCK B LAXMI PARK VANDANA VIHAR NANGLOI,	910	Other Outage	Planned Outage	13-10-2025	11:10	13-10-2025	13:57	2:47	0.001624	REPLACEMET OF HT BUSHING ROD
1256	14-10-2025	Part of : BLOCK F VANDANA VIHAR NANGLOI	986	Other Outage	Planned Outage	14-10-2025	15:49	14-10-2025	17:11	1:22	0.000000	REPLACEMENT OF HT BUSHING ROD
1257	14-10-2025	Part of : GURUNANAK VIHAR	402	Other Outage	Planned Outage	14-10-2025	12:59	14-10-2025	15:44	2:45	0.000000	REPLACEMENT OF HT BUSHING ROD
1258	14-10-2025	Part of : BLOCK F VANDANA VIHAR NANGLOI	357	Other Outage	Planned Outage	14-10-2025	10:48	14-10-2025	13:34	2:46	0.000922	REPLACEMENT OF HT BUSHING ROD
1259	14-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR	34	Other Outage	Planned Outage	14-10-2025	11:10	14-10-2025	13:32	2:22	0.000394	REPLACEMENT OF HT BUSHING ROD
1260	14-10-2025	Part of : RANJEET VIHAR	361	Other Outage	Planned Outage	14-10-2025	10:47	14-10-2025	13:30	2:43	0.001811	REPLACEMENT OF HT BUSHING ROD
1261	15-10-2025	Part of : JAI VIHAR PH-1 & 3,BAPROLLA VILLAGE,RAJIV RATAN AWAS FLATS,HARPHOOL VIHAR,SATYAM VIHAR,TILANGPUR KOTLA VILLAGE	5239	Other Outage	Unplanned Outage	15-10-2025	03:48	15-10-2025	04:30	0:42	0.000000	TRANSIENT FAULT
1262	15-10-2025	Part of : SH ISHWAR VATIKA ADHYAPAK NAGAR NANGLOI,TILANGPUR KOTLA VILLAGE,RISHAL GARDEN,TILANGPUR KOTLA,RANHOLLA	8643	Other Outage	Planned Outage	15-10-2025	14:09	15-10-2025	16:46	2:37	0.000654	REPLACEMENT OF CROSS-ARMS AND POLES
1263	15-10-2025	Part of : NANGLOI JAT NANGLOI	624	Other Outage	Planned Outage	15-10-2025	11:08	15-10-2025	14:15	3:07	0.002857	REPLACEMENT OF LT BUSHING ROD
1264	15-10-2025	Part of : NANGLOI JAT	845	Other Outage	Planned Outage	15-10-2025	11:09	15-10-2025	14:13	3:04	0.001533	REPLACEMENT OF LT BUSHING ROD
1265	15-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR	40	Other Outage	Planned Outage	15-10-2025	11:29	15-10-2025	14:14	2:45	0.000229	REPLACEMENT OF LT BUSHING ROD
1266	15-10-2025	Part of : C-BLOCK MIYANWALI NAGAR PASCHIM VIHAR	50	Other Outage	Planned Outage	15-10-2025	11:14	15-10-2025	13:19	2:05	0.001389	REPLACEMENT OF LT BUSHING ROD
1267	16-10-2025	Part of : RANJEET VIHAR,CHANDER VIHAR,BLOCK G UDAY VIHAR 2 ADHYAPAK NAGAR NANGLOI	5867	Other Outage	Unplanned Outage	16-10-2025	13:14	16-10-2025	15:56	2:42	0.000000	REPAIR OF RMU
1268	16-10-2025	Part of : BLOCK S JAWALAPURI EXTENSION PASCHIM VIHAR	462	Other Outage	Planned Outage	16-10-2025	11:06	16-10-2025	13:57	2:51	0.000238	REPLACEMET OF HT BUSHING ROD
1269	16-10-2025	Part of : BLOCK 13 SUNDER VIHAR PASCHIM VIHAR	399	Other Outage	Planned Outage	16-10-2025	10:58	16-10-2025	13:55	2:57	0.000983	REPLACEMENT OF CROSS-ARMS AND POLES
1270	16-10-2025	Part of : BLOCK GH 7 PASCHIM VIHAR	261	Other Outage	Planned Outage	16-10-2025	14:15	16-10-2025	16:14	1:59	0.000496	REPLACEMENT OF LT BUSHING ROD
1271	16-10-2025	Part of : BLOCK G NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	1309	Other Outage	Planned Outage	16-10-2025	13:26	16-10-2025	14:53	1:27	0.000604	REPLACEMET OF HT BUSHING ROD
1272	16-10-2025	Part of : BLOCK G NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	874	Other Outage	Planned Outage	16-10-2025	13:27	16-10-2025	14:55	1:28	0.000611	REPLACEMET OF HT BUSHING ROD
1273	16-10-2025	Part of : CHANDER VIHAR	778	Other Outage	Planned Outage	16-10-2025	10:56	16-10-2025	13:11	2:15	0.001500	REPLACEMET OF HT BUSHING ROD
1274	16-10-2025	Part of : BLOCK B AMANPURI KAMRUDDIN NAGAR NANGLOI	1991	Other Outage	Planned Outage	16-10-2025	11:09	16-10-2025	13:57	2:48	0.001400	REPLACEMENT OF LT BUSHING ROD
1275	17-10-2025	Part of : TEACHER VIHAR,VIKASPURI EXTN,GRAM SABHA COLONY,GURUNANAK VIHAR	5027	Other Outage	Unplanned Outage	17-10-2025	08:47	17-10-2025	09:32	0:45	0.000775	BIRDAGE

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1276	17-10-2025	Part of : BLOCK B JAWALAPURI PASCHIM VIHAR,BLOCK A JAWALAPURI PASCHIM VIHAR,RAO VIHAR NANGLOI,HANUMAN ENCLAVE NANGLOI,SHIV VIHAR NANGLOI,	6515	Other Outage	Planned Outage	17-10-2025	11:54	17-10-2025	15:06	3:12	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1277	17-10-2025	Part of : BLOCK GH 9 PASCHIM VIHAR,	21	Other Outage	Planned Outage	17-10-2025	11:06	17-10-2025	13:44	2:38	0.000878	REPLACEMET OF HT BUSHING ROD
1278	17-10-2025	Part of : CHANDER VIHAR,	1254	Other Outage	Planned Outage	17-10-2025	11:06	17-10-2025	13:43	2:37	0.000436	REPLACEMET OF HT BUSHING ROD
1279	18-10-2025	Part of : Inder Enclave Paschim Vihar,Virat Apartment Paschim Vihar	1640	Other Outage	Unplanned Outage	18-10-2025	03:05	18-10-2025	03:47	0:42	0.000175	CABLE FAULT
1280	18-10-2025	Part of : ADHYAPAK NAGAR NANGLOI	405	Other Outage	Planned Outage	18-10-2025	11:14	18-10-2025	14:11	2:57	0.000492	REPLACEMENT OF HT BUSHING ROD
1281	18-10-2025	Part of : CHANDER VIHAR	1345	Other Outage	Planned Outage	18-10-2025	10:59	18-10-2025	14:12	3:13	0.000536	REPLACEMENT OF HT BUSHING ROD
1282	21-10-2025	Part of : T.P. KOTLA VILLAGE S/STN-1, BUS STAND RANHOLLA, T P KHOTLA PH-2 S/S -2, HTC:T.P.KOTLA SEWAGE PLANT	8311	Other Outage	Unplanned Outage	21-10-2025	13:53	21-10-2025	14:34	0:41	0.000661	BIRDAGE
1283	23-10-2025	Part of : SHIV VIHAR NANGLOI	708	Other Outage	Planned Outage	23-10-2025	11:46	23-10-2025	12:21	0:35	0.000243	REPLACEMENT OF LT BUSHING ROD
1284	24-10-2025	Part of : SPS DJB NILOTHI (HT CONSUMER)	1	Other Outage	Unplanned Outage	24-10-2025	14:31	24-10-2025	15:16	0:45	0.000588	HT SYSTEM FAULT
1285	24-10-2025	Part of : BLOCK A & B NARESH PARK EXTENSION NANGLOI,BLOCK B AMANPURI KAMRUDDIN NAGAR NANGLOI	268	Other Outage	Planned Outage	24-10-2025	15:29	24-10-2025	16:55	1:26	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1286	24-10-2025	Part of : BLOCK A&B JAWALAPURI PASCHIM VIHAR,RAO VIHAR NANGLOI,SHIV VIHAR NANGLOI	6515	Other Outage	Planned Outage	24-10-2025	15:31	24-10-2025	16:52	1:21	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1287	24-10-2025	Part of : GURUNANAK VIHAR	884	Other Outage	Planned Outage	24-10-2025	13:47	24-10-2025	16:34	2:47	0.000928	REPLACEMENT OF HT BUSHING ROD
1288	24-10-2025	Part of : RISALA GARDEN NILOTHI	180	Other Outage	Planned Outage	24-10-2025	13:52	24-10-2025	16:33	2:41	0.000894	REPLACEMENT OF LT BUSHING ROD
1289	24-10-2025	Part of : RISALA GARDEN NILOTHI	180	Other Outage	Planned Outage	24-10-2025	11:41	24-10-2025	13:51	2:10	0.000542	OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1290	24-10-2025	Part of : BHERA ENCLAVE PASCHIM VIHAR	130	Other Outage	Planned Outage	24-10-2025	11:01	24-10-2025	13:50	2:49	0.000469	REPLACEMENT OF LT BUSHING ROD
1291	24-10-2025	Part of : AMBIKA VIHAR PASCHIM VIHAR	280	Other Outage	Planned Outage	24-10-2025	11:00	24-10-2025	13:50	2:50	0.000472	CONDUCTOR REPLACEMENT PER SPAN,LT AB SAGGING PER SPAN
1292	25-10-2025	Part of : BLOCK G NIHAL VIHAR ADHYAPAK NAGAR NANGLOI,	1449	Other Outage	Planned Outage	25-10-2025	11:04	25-10-2025	14:03	2:59	0.001492	REPLACEMET OF HT BUSHING ROD
1293	25-10-2025	Part of : BLOCK 13 SUNDER VIHAR PASCHIM VIHAR,	224	Other Outage	Planned Outage	25-10-2025	10:55	25-10-2025	14:02	3:07	0.000519	REPLACEMET OF HT BUSHING ROD
1294	25-10-2025	Part of : DASS GARDEN,	590	Other Outage	Planned Outage	25-10-2025	10:15	25-10-2025	13:52	3:37	0.000904	REPLACEMET OF HT BUSHING ROD
1295	26-10-2025	Part of : BLOCK A DELHI STATE INDUSTRIAL DEVELOPMENT CORPORATION NANGLOI	12	Other Outage	Planned Outage	26-10-2025	11:00	26-10-2025	14:09	3:09	0.000000	REPLACEMET OF HT BUSHING ROD
1296	28-10-2025	Part of : RISALA GARDEN NILOTHI,NILOTHI VILLAGE,CHANDER VIHAR	1713	Other Outage	Planned Outage	28-10-2025	14:34	28-10-2025	17:05	2:31	0.002936	HT BUSHING ROD REPLACEMENT
1297	28-10-2025	Part of : DDA PARK NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	1929	Other Outage	Planned Outage	28-10-2025	11:06	28-10-2025	13:59	2:53	0.001922	REPLACEMET OF HT BUSHING ROD
1298	28-10-2025	Part of : SH ISHWAR VATIKA ADHYAPAK NAGAR NANGLOI,TILANGPUR KOTLA VILLAGE,RISHAL GARDEN	8733	Other Outage	Planned Outage	28-10-2025	11:00	28-10-2025	13:29	2:29	0.002897	GUARD WIRE LACS INSTALLTION PER SPAN
1299	28-10-2025	Part of : JAI VIHAR PH-1, RANHOLLA,TILANGPUR KOTLA VILLAGE,PRATAP VIHAR	2586	Other Outage	Planned Outage	28-10-2025	10:59	28-10-2025	13:30	2:31	0.002936	GUARD WIRE LACS INSTALLTION PER SPAN
1300	28-10-2025	Part of : DDA PARK NIHAL VIHAR ADHYAPAK NAGAR NANGLOI	209	Other Outage	Planned Outage	28-10-2025	11:07	28-10-2025	14:03	2:56	0.001956	REPLACEMET OF HT BUSHING ROD
1301	29-10-2025	Part of : BLOCK G UDAY VIHAR 2 ADHYAPAK NAGAR NANGLOI,	139	Other Outage	Planned Outage	29-10-2025	11:17	29-10-2025	14:06	2:49	0.001408	REPLACEMET OF HT BUSHING ROD
1302	29-10-2025	Part of : BLOCK D DELHI STATE INDUSTRIAL DEVELOPMENT CORPORATION NANGLOI,	977	Other Outage	Planned Outage	29-10-2025	12:24	29-10-2025	14:07	1:43	0.000286	REPLACEMET OF HT BUSHING ROD
1303	30-10-2025	Part of : NILOTHI SEWAGE PLANT (HTC)	0	Other Outage	Unplanned Outage	30-10-2025	23:29	31-10-2025	00:09	0:40	0.001278	HT SYSTEM FAULT
1304	30-10-2025	Part of : CHANDER VIHAR	2138	Other Outage	Unplanned Outage	30-10-2025	14:43	30-10-2025	15:59	1:16	0.000000	REPAIRING OF RMU
1305	30-10-2025	Part of : JAI VIHAR PH-1, PH-3,JAI VIHAR BAPROLA	4652	Other Outage	Planned Outage	30-10-2025	15:00	30-10-2025	16:36	1:36	0.000000	GUARD WIRE LACS INSTALLTION PER SPAN
1306	30-10-2025	Part of : NANGLOI JAT NANGLOI	273	Other Outage	Planned Outage	30-10-2025	11:15	30-10-2025	14:25	3:10	0.000000	REPLACEMENT OF HT BUSHING ROD
1307	30-10-2025	Part of : UDAI VIHAR,RANJEET VIHAR	1714	Other Outage	Planned Outage	30-10-2025	10:35	30-10-2025	14:16	3:41	0.000000	GUARD WIRES SAGGING PER SPAN
1308	30-10-2025	Part of : BLOCK GH 9 PASCHIM VIHAR	118	Other Outage	Planned Outage	30-10-2025	11:07	30-10-2025	14:19	3:12	0.000000	REPLACEMENT OF HT BUSHING ROD
1309	31-10-2025	Part of : RISALA GARDEN,NILOTHI VILLAGE,CHANDER VIHAR	1713	Other Outage	Planned Outage	31-10-2025	13:05	31-10-2025	15:49	2:44	0.002733	3PH HT AB CABLE REPLACEMENT
1310	31-10-2025	Part of : SIHV RAM PARK ADHYAPAK NAGAR NANGLOI	478	Other Outage	Planned Outage	31-10-2025	10:56	31-10-2025	14:48	3:52	0.000967	REPLACEMET OF HT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1311	31-10-2025	Part of : BAPROLLA VILLAGE,JAI VIHAR PH-1 & 3,TILANGPUR KOTLA VILLAGE,HARPHOOL VIHAR,PRASHANT ENCLAVE,NIRMAL VIHAR BAPROLA	6687	Other Outage	Planned Outage	31-10-2025	11:00	31-10-2025	13:56	2:56	0.002444	REPLACEMENT OF CROSS-ARMS AND POLES
1312	31-10-2025	Part of : VIRAT APARTMENT PASCHIM VIHAR,C & S-BLOCK JAWALAPURI,CAMP 5 JAWALAPURI PASCHIM VIHAR	2653	Other Outage	Planned Outage	31-10-2025	11:09	31-10-2025	13:55	2:46	0.000231	REPLACEMENT OF CROSS-ARMS AND POLES
1313	31-10-2025	Part of : A-BLOCK MIRA BAGH PASCHIM VIHAR	297	Other Outage	Planned Outage	31-10-2025	11:07	31-10-2025	13:58	2:51	0.001425	REPLACEMET OF LT BUSHING ROD
1314	01-10-2025	Part of : BLOCK A QUTUB VIHAR PHASE 1 QUTUB VIHAR,GOYALA DAIRY QUTUB VIHAR,	322	Other Outage	Unplanned Outage	01-10-2025	13:14	01-10-2025	15:10	1:56	0.001450	HVDS CIRCUIT REPAIR
1315	01-10-2025	Part of : BLOCK B POCHANPUR DWARKA,POCHANPUR DWARKA,	2278	Other Outage	Planned Outage	01-10-2025	12:43	01-10-2025	14:18	1:35	0.000000	REPLACEMENT OF LT BUSHING ROD,REPLACEMET OF HT BUSHING ROD
1316	02-10-2025	Part of : JHATIKARA,BADUSARAI,PAPRAWAT VILLAGE,SHIKARPUR VILLAGE,PIND WALA KHURD VILLAGE,PREM NAGAR PAPRAWAT VILLAGE,DAULATPUR VILLAGE	2139	Other Outage	Unplanned Outage	02-10-2025	20:37	02-10-2025	21:12	0:35	0.000000	TREE BRANCH FALLEN ON O/H LINE
1317	02-10-2025	Part of : BLOCK E SHYAM VIHAR I NAJAFGARH,DURGA PARK NAJAFGARH,DINARPUR EXTENSION NAJAFGARH,SHYAM ENCLAVE DINPUR	3359	Other Outage	Unplanned Outage	02-10-2025	18:55	02-10-2025	19:36	0:41	0.000831	TREE BRANCH FALLEN ON O/H LINE
1318	03-10-2025	Part of : NEW HIRA NAGAR DICHAN KALAN	4	Other Outage	Unplanned Outage	03-10-2025	15:53	03-10-2025	16:22	0:29	0.000532	CABLE FAULT
1319	03-10-2025	Part of : TODARMAL COLONY NAJAFGARH	506	Other Outage	Planned Outage	03-10-2025	10:01	03-10-2025	11:48	1:47	0.000594	REPLACEMET OF HT BUSHING ROD
1320	03-10-2025	Part of : BLOCK B POCHANPUR DWARKA	424	Other Outage	Planned Outage	03-10-2025	15:14	03-10-2025	17:24	2:10	0.000722	REPLACEMET OF HT BUSHING ROD
1321	03-10-2025	Part of : RANAJI ENCLAVE MASUDABAD NAJAFGARH	867	Other Outage	Planned Outage	03-10-2025	10:36	03-10-2025	12:52	2:16	0.000756	REPLACEMET OF HT BUSHING ROD
1322	03-10-2025	Part of : PIND WALA KALAN VILLAGE	396	Other Outage	Planned Outage	03-10-2025	12:06	03-10-2025	14:38	2:32	0.000844	REPLACEMET OF HT BUSHING ROD
1323	03-10-2025	Part of : JHARODA KALAN	398	Other Outage	Planned Outage	03-10-2025	11:31	03-10-2025	14:07	2:36	0.002167	REPLACEMENT OF LT BUSHING ROD
1324	04-10-2025	Part of : DURGA VIHAR I, TODARMAL COLONY NAJAFGARH, DATA RAM PARK DINPUR, SHANTI VIHAR DINPUR,DINPUR LAL DORA EXTN	3744	Other Outage	Unplanned Outage	04-10-2025	08:26	04-10-2025	09:01	0:35	0.000000	BIRDAGE
1325	04-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	63	Other Outage	Planned Outage	04-10-2025	10:53	04-10-2025	12:18	1:25	0.001417	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,INSTALLATION OF BUS BAR,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER
1326	04-10-2025	Part of : NIRMAL VIHAR DICHAN KALAN	1039	Other Outage	Planned Outage	04-10-2025	12:03	04-10-2025	14:49	2:46	0.004150	REPLACEMET OF HT BUSHING ROD
1327	04-10-2025	Part of : DELHI TEACHERS COLONY DINDARPUR NAJAFGARH	573	Other Outage	Planned Outage	04-10-2025	10:52	04-10-2025	13:27	2:35	0.000861	REPLACEMET OF HT BUSHING ROD
1328	04-10-2025	Part of : NATHU RAM PARK MASUDABAD NAJAFGARH	96	Other Outage	Planned Outage	04-10-2025	10:41	04-10-2025	13:25	2:44	0.002733	REPLACEMENT OF LT BUSHING ROD
1329	06-10-2025	Part of : RANAJI ENCLAVE MASUDABAD NAJAFGARH	184	Other Outage	Planned Outage	06-10-2025	13:42	06-10-2025	15:32	1:50	0.001069	REPLACEMET OF FAULTY END BOX
1330	06-10-2025	Part of : SARASWATI ENCLAVE HAIBUTPUR	53	Other Outage	Planned Outage	06-10-2025	13:41	06-10-2025	15:22	1:41	0.002525	REPLACEMENT OF LT BUSHING ROD
1331	06-10-2025	Part of : KHARKHARI NAHA VILLAGE	2	Other Outage	Planned Outage	06-10-2025	10:58	06-10-2025	13:21	2:23	0.000397	REPLACEMET OF HT BUSHING ROD
1332	08-10-2025	Part of : ROSHAN PURA NAJAFGARH	335	Other Outage	Planned Outage	08-10-2025	10:56	08-10-2025	13:23	2:27	0.000408	REPLACEMET OF HT BUSHING ROD
1333	08-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	82	Other Outage	Planned Outage	08-10-2025	11:56	08-10-2025	14:14	2:18	0.000000	REPLACEMET OF HT BUSHING ROD
1334	08-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR	1159	Other Outage	Planned Outage	08-10-2025	11:23	08-10-2025	14:21	2:58	0.004450	REPLACEMENT OF LT BUSHING ROD
1335	09-10-2025	Part of : POCHANPUR DWARKA,	1501	Other Outage	Planned Outage	09-10-2025	11:14	09-10-2025	13:05	1:51	0.000000	AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1336	09-10-2025	Part of : NAJAFGARH VILLAGE,	637	Other Outage	Planned Outage	09-10-2025	11:02	09-10-2025	13:44	2:42	0.000900	REPLACEMET OF HT BUSHING ROD
1337	09-10-2025	Part of : PIND WALA KALAN VILLAGE,	396	Other Outage	Planned Outage	09-10-2025	12:11	09-10-2025	15:01	2:50	0.000472	REPLACEMET OF HT BUSHING ROD
1338	09-10-2025	Part of : DHARAMPURA NAJAFGARH,	1350	Other Outage	Planned Outage	09-10-2025	10:54	09-10-2025	13:17	2:23	0.000794	REPLACEMET OF HT BUSHING ROD
1339	10-10-2025	Part of : PAPRAWAT VILLAGE	792	Other Outage	Planned Outage	10-10-2025	13:11	10-10-2025	15:01	1:50	0.000458	REPLACEMET OF HT BUSHING ROD
1340	10-10-2025	Part of : DURGA PARK NAJAFGARH,DINARPUR EXTENSION NAJAFGARH,SHYAM ENCLAVE DINPUR,SHIV PURI I DINPUR	922	Other Outage	Planned Outage	10-10-2025	10:50	10-10-2025	13:01	2:11	0.002911	REPLACEMENT OF CROSS-ARMS AND POLES

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1341	11-10-2025	Part of : SARASWATI KUNJ,LOKESH PARK EXTN,B-BLOCK NAVEEN PALACE,SURYA KUNJ,DHANAK MOHALLA,INDRA MARKET,BABA HARIDAS ENCLAVE,KRISHNA ENCLAVE,NEW VISION COLONY,AGARWAL COLONY	3857	Other Outage	Planned Outage	11-10-2025	14:15	11-10-2025	15:39	1:24	0.002100	REPLACEMENT OF HT BUSHING ROD,SUB STATION CLEANING
1342	11-10-2025	Part of : B-BLOCK POCHANPUR DWARKA	78	Other Outage	Planned Outage	11-10-2025	12:11	11-10-2025	13:19	1:08	0.000189	REPLACEMENT OF HT BUSHING ROD
1343	11-10-2025	Part of : DAULATPUR VILLAGE	239	Other Outage	Planned Outage	11-10-2025	12:53	11-10-2025	15:36	2:43	0.001811	REPLACEMENT OF LT BUSHING ROD
1344	11-10-2025	Part of : QUTUB VIHAR PHASE 2	27	Other Outage	Planned Outage	11-10-2025	10:44	11-10-2025	13:42	2:58	0.000989	REPLACEMENT OF GAS KIT AND OIL SEAL
1345	11-10-2025	Part of : KHAIRA VILLAGE	573	Other Outage	Planned Outage	11-10-2025	11:51	11-10-2025	14:53	3:02	0.002528	REPLACEMENT OF HT BUSHING ROD
1346	11-10-2025	Part of : SHIV NAGAR & DICHHAON ENCLAVE DICHHAON KALAN	262	Other Outage	Planned Outage	11-10-2025	12:04	11-10-2025	15:06	3:02	0.000000	AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER
1347	11-10-2025	Part of : DHARAMPURA NAJAFGARH,E-BLOCK NEW ROSHAN PURA NAJAFGARH	989	Other Outage	Planned Outage	11-10-2025	10:09	11-10-2025	12:41	2:32	0.000844	REPLACEMENT OF HT BUSHING ROD
1348	12-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	119	Other Outage	Planned Outage	12-10-2025	10:07	12-10-2025	12:51	2:44	0.002278	REPLACEMENT OF LT BUSHING ROD
1349	13-10-2025	Part of : BABA HARIDAS ENCLAVE,JHARODA KALAN,SHIV NAGAR DICHHAON KALAN,BABA HARI DAS ENCLAVE JHARODA KALAN,TIKRI KALAN,BLOCK A NAVEEN PALACE JHARODA KALAN	3075	Other Outage	Unplanned Outage	13-10-2025	15:20	13-10-2025	15:43	0:23	0.000000	CABLE FAULT
1350	13-10-2025	Part of : QUTUB VIHAR PHASE 2 QUTUB VIHAR,	687	Other Outage	Planned Outage	13-10-2025	10:35	13-10-2025	12:30	1:55	0.002875	REPLACEMENT OF GAS KIT AND OIL SEAL
1351	13-10-2025	Part of : NIRMAL VIHAR DICHHAON KALAN,	1040	Other Outage	Planned Outage	13-10-2025	13:00	13-10-2025	15:50	2:50	0.002361	REPLACEMENT OF LT BUSHING ROD
1352	13-10-2025	Part of : VIRENDRA MARKET,	263	Other Outage	Planned Outage	13-10-2025	11:59	13-10-2025	14:44	2:45	0.004125	REPLACEMENT OF LT BUSHING ROD
1353	13-10-2025	Part of : BLOCK E NEW ROSHAN PURA NAJAFGARH,	537	Other Outage	Planned Outage	13-10-2025	11:01	13-10-2025	13:55	2:54	0.002417	REPLACEMET OF HT BUSHING ROD
1354	13-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI,	82	Other Outage	Planned Outage	13-10-2025	07:11	13-10-2025	09:56	2:45	0.000000	REPLACEMET OF HT BUSHING ROD
1355	14-10-2025	Part of : SAI BABA ENCLAVE MASUDABAD NAJAFGARH	5	Other Outage	Unplanned Outage	14-10-2025	12:19	14-10-2025	13:16	0:57	0.000792	REPAIRING OF HVDS CIRCUIT
1356	14-10-2025	Part of : SAI BABA ENCLAVE MASUDABAD NAJAFGARH	325	Other Outage	Planned Outage	14-10-2025	15:23	14-10-2025	17:06	1:43	0.002289	REPLACEMENT OF LT BUSHING ROD
1357	14-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR	945	Other Outage	Planned Outage	14-10-2025	10:54	14-10-2025	12:49	1:55	0.000000	3PH HT AB END TERMINATION REPLACEMENT
1358	14-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	63	Other Outage	Planned Outage	14-10-2025	10:52	14-10-2025	13:49	2:57	0.000000	REPLACEMENT OF HT BUSHING ROD
1359	14-10-2025	Part of : QUTUB VIHAR PHASE 2 QUTUB VIHAR	1238	Other Outage	Planned Outage	14-10-2025	10:55	14-10-2025	13:50	2:55	0.000972	REPLACEMENT OF HT BUSHING ROD
1360	14-10-2025	Part of : PIND WALA KHURD VILLAGE	199	Other Outage	Planned Outage	14-10-2025	11:26	14-10-2025	13:46	2:20	0.000778	REPLACEMENT OF LT BUSHING ROD
1361	14-10-2025	Part of : KHAIRA VILLAGE	59	Other Outage	Planned Outage	14-10-2025	10:29	14-10-2025	13:23	2:54	0.000967	REPLACEMENT OF HT BUSHING ROD
1362	14-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR	1159	Other Outage	Planned Outage	14-10-2025	11:48	14-10-2025	14:49	3:01	0.001006	REPLACEMENT OF LT BUSHING ROD
1363	14-10-2025	Part of : DHARAMPURA NAJAFGARH	343	Other Outage	Planned Outage	14-10-2025	10:05	14-10-2025	12:48	2:43	0.000906	REPLACEMENT OF HT BUSHING ROD
1364	15-10-2025	Part of : B-BLOCK POCHANPUR DWARKA	596	Other Outage	Planned Outage	15-10-2025	11:06	15-10-2025	11:33	0:27	0.000075	AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,CONDUCTOR REPLACEMENT
1365	15-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR	396	Other Outage	Planned Outage	15-10-2025	14:06	15-10-2025	16:14	2:08	0.000000	REPLACEMENT OF HT BUSHING ROD
1366	15-10-2025	Part of : NEW HEERA PARK NAJAFGARH	64	Other Outage	Planned Outage	15-10-2025	13:05	15-10-2025	15:13	2:08	0.002844	REPLACEMENT OF HT BUSHING ROD
1367	15-10-2025	Part of : ROSHAN PURA & PREM NAGAR NAJAFGARH	839	Other Outage	Planned Outage	15-10-2025	11:10	15-10-2025	13:27	2:17	0.001903	REPLACEMENT OF HT BUSHING ROD
1368	15-10-2025	Part of : NANGLI DAIRY NANGLI SAKRAWATI	321	Other Outage	Planned Outage	15-10-2025	11:11	15-10-2025	13:30	2:19	0.000000	REPLACEMENT OF HT BUSHING ROD
1369	15-10-2025	Part of : ROSHAN PURA NAJAFGARH	282	Other Outage	Planned Outage	15-10-2025	10:07	15-10-2025	12:48	2:41	0.000671	REPLACEMENT OF HT BUSHING ROD
1370	15-10-2025	Part of : A-BLOCK QUTUB VIHAR PHASE-1	435	Other Outage	Planned Outage	15-10-2025	10:27	15-10-2025	13:00	2:33	0.000850	REPLACEMENT OF HT BUSHING ROD
1371	16-10-2025	Part of : DURGA VIHAR I DINPUR, TODARMAL COLONY NAJAFGARH, DURGA VIHAR II DINPUR,GANGA VIHAR,SHANTI VIHAR DINPUR, DEENPUR VILLAGE	3749	Other Outage	Unplanned Outage	16-10-2025	07:29	16-10-2025	08:05	0:36	0.000000	HVDS FAULT
1372	16-10-2025	Part of : KHAIRA VILLAGE	573	Other Outage	Planned Outage	16-10-2025	12:47	16-10-2025	15:45	2:58	0.002967	REPLACEMET OF HT BUSHING ROD
1373	16-10-2025	Part of : VIRENDRA MARKET	263	Other Outage	Planned Outage	16-10-2025	10:29	16-10-2025	12:45	2:16	0.003022	REPLACEMENT OF LT BUSHING ROD
1374	16-10-2025	Part of : SARIKA VIHAR DINPUR	234	Other Outage	Planned Outage	16-10-2025	10:42	16-10-2025	13:38	2:56	0.000733	REPLACEMENT OF LT BUSHING ROD
1375	16-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	610	Other Outage	Planned Outage	16-10-2025	09:15	16-10-2025	11:29	2:14	0.000000	REPLACEMET OF HT BUSHING ROD
1376	16-10-2025	Part of : CHAWLA,RAGHOPUR VILLAGE	26	Other Outage	Planned Outage	16-10-2025	10:54	16-10-2025	13:50	2:56	0.000000	REPLACEMET OF HT BUSHING ROD
1377	16-10-2025	Part of : BLOCK E NEW ROSHAN PURA NAJAFGARH	606	Other Outage	Planned Outage	16-10-2025	10:25	16-10-2025	12:47	2:22	0.000789	REPLACEMET OF HT BUSHING ROD
1378	17-10-2025	Part of : BLOCK X NEW ROSHAN PURA NAJAFGARH,	203	Other Outage	Planned Outage	17-10-2025	12:15	17-10-2025	13:55	1:40	0.000556	REPLACEMET OF HT BUSHING ROD
1379	17-10-2025	Part of : GANDHI PARK DINPUR,	364	Other Outage	Planned Outage	17-10-2025	10:24	17-10-2025	11:54	1:30	0.000250	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1380	17-10-2025	Part of : DURGA VIHAR II DINPUR,	212	Other Outage	Planned Outage	17-10-2025	10:23	17-10-2025	12:42	2:19	0.000579	REPLACEMENT OF LT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1381	17-10-2025	Part of : PIND WALA KALAN VILLAGE,SHERPUR EXTENTION,KHARKHARI ROND VILLAGE,PIND WALA KHURD VILLAGE,KHERA DABAS VILLAGE,	1961	Other Outage	Planned Outage	17-10-2025	10:13	17-10-2025	13:07	2:54	0.001933	REPLACEMET OF HT BUSHING ROD
1382	17-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR,QUTUB VIHAR PHASE 2 QUTUB VIHAR,	263	Other Outage	Planned Outage	17-10-2025	10:27	17-10-2025	13:20	2:53	0.002403	REPLACEMENT OF LT BUSHING ROD
1383	17-10-2025	Part of : HASANPUR VILLAGE,	247	Other Outage	Planned Outage	17-10-2025	10:16	17-10-2025	13:08	2:52	0.000478	REPLACEMET OF HT BUSHING ROD
1384	17-10-2025	Part of : NAJAFGARH VILLAGE,	637	Other Outage	Planned Outage	17-10-2025	08:23	17-10-2025	10:28	2:05	0.000000	REPLACEMET OF HT BUSHING ROD
1385	18-10-2025	Part of : KHARKHARI NAHA VILLAGE	307	Other Outage	Planned Outage	18-10-2025	11:35	18-10-2025	13:53	2:18	0.000767	REPLACEMENT OF HT BUSHING ROD
1386	18-10-2025	Part of : GHASIPURA,ARJUN PARK NANGLI SAKRAWATI,NANGLI DAIRY NANGLI SAKRAWATI,PREM VIHAR COLONY GHASIPURA	4338	Other Outage	Planned Outage	18-10-2025	11:26	18-10-2025	14:56	3:30	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1387	21-10-2025	Part of : SULTAN GARDEN,	187	Other Outage	Planned Outage	21-10-2025	11:43	21-10-2025	13:39	1:56	0.002900	REPLACEMET OF HT BUSHING ROD
1388	21-10-2025	Part of : NANAK HERI VILLAGE,	304	Other Outage	Planned Outage	21-10-2025	11:22	21-10-2025	14:14	2:52	0.001911	REPLACEMENT OF LT BUSHING ROD
1389	21-10-2025	Part of : BLOCK A INDRA PARK MASUDABAD NAJAFGARH,BLOCK B INDRA PARK MASUDABAD NAJAFGARH,BLOCK E INDRA PARK MASUDABAD NAJAFGARH,NANGLI SANKRANTI NANGLI SAKRAWATI,OLD DHARAMPURA MASUDABAD NAJAFGARH,	2670	Other Outage	Planned Outage	21-10-2025	11:18	21-10-2025	13:57	2:39	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1390	21-10-2025	Part of : ROSHAN PURA NAJAFGARH,	289	Other Outage	Planned Outage	21-10-2025	11:45	21-10-2025	14:12	2:27	0.000613	REPLACEMET OF HT BUSHING ROD
1391	22-10-2025	Part of : ROSHAN PURA NAJAFGARH,PREM NAGAR NAJAFGARH	841	Other Outage	Planned Outage	22-10-2025	11:29	22-10-2025	14:21	2:52	0.003344	REPLACEMET OF HT BUSHING ROD
1392	22-10-2025	Part of : SHIV NAGAR DICHAN KALAN	225	Other Outage	Planned Outage	22-10-2025	10:57	22-10-2025	13:08	2:11	0.003275	REPLACEMENT OF LT BUSHING ROD
1393	22-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	79	Other Outage	Planned Outage	22-10-2025	09:13	22-10-2025	12:13	3:00	0.000000	REPLACEMET OF HT BUSHING ROD
1394	24-10-2025	Part of : BHARTHAL VILLAGE DWARKA	301	Other Outage	Planned Outage	24-10-2025	13:48	24-10-2025	14:44	0:56	0.000311	REPLACEMENT OF HT BUSHING ROD
1395	24-10-2025	Part of : BLOCK E NEW ROSHAN PURA NAJAFGARH	527	Other Outage	Planned Outage	24-10-2025	10:31	24-10-2025	12:25	1:54	0.002217	REPLACEMENT OF GAS KIT AND OIL SEAL
1396	24-10-2025	Part of : ROSHAN PURA NAJAFGARH,PREM NAGAR NAJAFGARH	841	Other Outage	Planned Outage	24-10-2025	10:28	24-10-2025	13:24	2:56	0.003911	REPLACEMENT OF LT BUSHING ROD
1397	24-10-2025	Part of : SAINIK ENCLAVE	298	Other Outage	Planned Outage	24-10-2025	10:30	24-10-2025	13:23	2:53	0.004325	REPLACEMENT OF LT BUSHING ROD
1398	24-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	232	Other Outage	Planned Outage	24-10-2025	07:24	24-10-2025	10:19	2:55	0.000000	REPLACEMENT OF HT BUSHING ROD
1399	25-10-2025	Part of : SECTOR 27 DWARKA,	147	Other Outage	Planned Outage	25-10-2025	13:45	25-10-2025	15:26	1:41	0.001403	REPLACEMET OF HT BUSHING ROD
1400	25-10-2025	Part of : KHARKHARI NAHA VILLAGE,PIND WALA KALAN VILLAGE,	657	Other Outage	Planned Outage	25-10-2025	11:03	25-10-2025	13:00	1:57	0.001300	REPLACEMET OF HT BUSHING ROD
1401	25-10-2025	Part of : NATHU RAM PARK MASUDABAD NAJAFGARH,	179	Other Outage	Planned Outage	25-10-2025	12:57	25-10-2025	15:45	2:48	0.004200	REPLACEMENT OF LT BUSHING ROD
1402	25-10-2025	Part of : NANGLI DAIRY NANGLI SAKRAWATI,	915	Other Outage	Planned Outage	25-10-2025	11:17	25-10-2025	14:10	2:53	0.000000	REPLACEMET OF HT BUSHING ROD
1403	25-10-2025	Part of : DICHAN ENCLAVE DICHAN KALAN,	238	Other Outage	Planned Outage	25-10-2025	11:18	25-10-2025	13:48	2:30	0.003750	REPLACEMET OF HT BUSHING ROD
1404	25-10-2025	Part of : GANDHI PARK DINPUR,	509	Other Outage	Planned Outage	25-10-2025	12:17	25-10-2025	15:00	2:43	0.001811	3PH HT AB CABLE REPLACEMENT PER SPAN
1405	25-10-2025	Part of : NAJAFGARH VILLAGE,	637	Other Outage	Planned Outage	25-10-2025	10:51	25-10-2025	13:48	2:57	0.004425	REPLACEMENT OF HT BUSHING ROD
1406	25-10-2025	Part of : DHARAMPURA NAJAFGARH,	880	Other Outage	Planned Outage	25-10-2025	10:30	25-10-2025	12:32	2:02	0.000678	REPLACEMET OF HT BUSHING ROD
1407	25-10-2025	Part of : NIRMAL VIHAR DICHAN KALAN,	1042	Other Outage	Planned Outage	25-10-2025	10:58	25-10-2025	14:00	3:02	0.004550	REPLACEMENT OF LT BUSHING ROD
1408	26-10-2025	Part of : NANGLI SANKRANTI NANGLI SAKRAWATI	119	Other Outage	Planned Outage	26-10-2025	07:11	26-10-2025	09:42	2:31	0.003775	REPLACEMENT OF LT BUSHING ROD
1409	27-10-2025	Part of : A,B & E-BLOCK INDRA PARK MASUDABAD NAJAFGARH,NANGLI SANKRANTI NANGLI SAKRAWATI	2708	Other Outage	Unplanned Outage	27-10-2025	14:08	27-10-2025	14:47	0:39	0.000000	BIRDAGE
1410	28-10-2025	Part of : RANAJI ENCLAVE MASUDABAD NAJAFGARH	261	Other Outage	Planned Outage	28-10-2025	15:02	28-10-2025	16:32	1:30	0.000000	REPLACEMENT OF GAS KIT AND OIL SEAL
1411	28-10-2025	Part of : BLOCK B POCHANPUR DWARKA	374	Other Outage	Planned Outage	28-10-2025	13:21	28-10-2025	14:33	1:12	0.001800	REPLACEMET OF HT BUSHING ROD
1412	28-10-2025	Part of : PAPRAWAT VILLAGE	1	Other Outage	Planned Outage	28-10-2025	14:15	28-10-2025	16:55	2:40	0.000444	REPLACEMET OF HT BUSHING ROD
1413	28-10-2025	Part of : PIND WALA KHURD VILLAGE	360	Other Outage	Planned Outage	28-10-2025	11:37	28-10-2025	14:00	2:23	0.000397	REPLACEMET OF HT BUSHING ROD
1414	28-10-2025	Part of : ROSHAN PURA NAJAFGARH,PREM NAGAR NAJAFGARH	841	Other Outage	Planned Outage	28-10-2025	12:10	28-10-2025	15:07	2:57	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1415	29-10-2025	Part of : BLOCK E SHYAM VIHAR I NAJAFGARH,	471	Other Outage	Planned Outage	29-10-2025	15:23	29-10-2025	17:16	1:53	0.000628	REPLACEMET OF HT BUSHING ROD
1416	29-10-2025	Part of : POCHANPUR DWARKA,	905	Other Outage	Planned Outage	29-10-2025	13:56	29-10-2025	15:48	1:52	0.000000	3PH DB REPLACEMENT,AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER
1417	29-10-2025	Part of : BHARTHAL VILLAGE DWARKA,	168	Other Outage	Planned Outage	29-10-2025	11:03	29-10-2025	12:57	1:54	0.000000	3PH DB REVAMPING,AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER
1418	29-10-2025	Part of : SECTOR 29 DWARKA,	403	Other Outage	Planned Outage	29-10-2025	12:25	29-10-2025	13:28	1:03	0.001575	REPLACEMENT OF LT BUSHING ROD
1419	29-10-2025	Part of : CHAWLA,	659	Other Outage	Planned Outage	29-10-2025	10:02	29-10-2025	11:53	1:51	0.000000	AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,CONDUCTOR REPLACEMENT PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1420	29-10-2025	Part of : ROSHAN VIHAR 1 NAJAFGARH,	85	Other Outage	Planned Outage	29-10-2025	10:28	29-10-2025	13:01	2:33	0.000638	REPLACEMET OF HT BUSHING ROD
1421	29-10-2025	Part of : NAJAFGARH PARK COLONY NAJAFGARH,	641	Other Outage	Planned Outage	29-10-2025	10:47	29-10-2025	13:02	2:15	0.003563	REPLACEMENT OF LT BUSHING ROD
1422	29-10-2025	Part of : BLOCK E NEW ROSHAN PURA NAJAFGARH,	496	Other Outage	Planned Outage	29-10-2025	10:16	29-10-2025	13:05	2:49	0.000939	REPLACEMET OF HT BUSHING ROD
1423	30-10-2025	Part of : BLOCK A, B & E INDRA PARK MASUDABAD NAJAFGARH,NANGLI SANKRANTI NANGLI SAKRAWATI,OLD DHARAMPURA MASUDABAD NAJAFGARH	2710	Other Outage	Unplanned Outage	30-10-2025	08:47	30-10-2025	08:51	0:04	0.000000	REPAIRING OF HVDS CIRCUIT
1424	30-10-2025	Part of : SAMTA ENCLAVE QUTUB VIHAR	1164	Other Outage	Planned Outage	30-10-2025	12:25	30-10-2025	14:23	1:58	0.000000	CONDUCTOR REPLACEMENT PER SPAN,LT AB SAGGING PER SPAN
1425	30-10-2025	Part of : DHARAMPURA NAJAFGARH	685	Other Outage	Planned Outage	30-10-2025	10:10	30-10-2025	12:05	1:55	0.000319	REPLACEMENT OF GAS KIT AND OIL SEAL
1426	30-10-2025	Part of : BHARTHAL VILLAGE DWARKA	492	Other Outage	Planned Outage	30-10-2025	12:06	30-10-2025	13:59	1:53	0.000000	DAMAGED BUSHING REPLACEMENT BY WORKSHOP PER PHASE,REPLACEMENT OF FAULTY END BOX
1427	30-10-2025	Part of : PIND WALA KHURD VILLAGE	379	Other Outage	Planned Outage	30-10-2025	11:38	30-10-2025	14:16	2:38	0.000439	REPLACEMENT OF HT BUSHING ROD
1428	30-10-2025	Part of : PAPRAWAT VILLAGE	1	Other Outage	Planned Outage	30-10-2025	10:37	30-10-2025	12:51	2:14	0.000372	REPLACEMENT OF LT BUSHING ROD
1429	30-10-2025	Part of : NAJAFGARH VILLAGE NAJAFGARH	2	Other Outage	Planned Outage	30-10-2025	10:49	30-10-2025	13:42	2:53	0.000000	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF HT BUSHING ROD
1430	30-10-2025	Part of : BABA HARIDAS ENCLAVE,JHARODA KALAN,SHIV NAGAR DICHAN KALAN,BABA HARI DAS ENCLAVE JHARODA KALAN,TIKRI KALAN,BLOCK A NAVEEN PALACE JHARODA KALAN	2967	Other Outage	Planned Outage	30-10-2025	11:23	30-10-2025	14:14	2:51	0.002375	REPLACEMENT OF LT BUSHING ROD,SUB STATION CLEANING
1431	31-10-2025	Part of : BHARTHAL VILLAGE DWARKA	343	Other Outage	Planned Outage	31-10-2025	14:05	31-10-2025	15:28	1:23	0.002075	REPLACEMET OF HT BUSHING ROD
1432	31-10-2025	Part of : ROSHAN PURA NAJAFGARH	345	Other Outage	Planned Outage	31-10-2025	13:07	31-10-2025	14:47	1:40	0.000417	REPLACEMET OF HT BUSHING ROD
1433	31-10-2025	Part of : DAULATPUR VILLAGE,ASALETPUR KHAWAD VILLAGE,HASANPUR VILLAGE,JHATIKARA,UJWA VILLAGE,KHERA DABAS VILLAGE	3195	Other Outage	Planned Outage	31-10-2025	10:39	31-10-2025	13:22	2:43	0.001811	REPLACEMET OF HT BUSHING ROD
1434	31-10-2025	Part of : EKTA VIHAR & RAJIV VIHAR	351	Other Outage	Planned Outage	31-10-2025	10:56	31-10-2025	13:51	2:55	0.004375	REPLACEMET OF HT BUSHING ROD
1435	31-10-2025	Part of : CHAWLA	613	Other Outage	Planned Outage	31-10-2025	12:21	31-10-2025	15:16	2:55	0.002431	REPLACEMET OF HT BUSHING ROD
1436	31-10-2025	Part of : SHYAM VIHAR I NAJAFGARH	550	Other Outage	Planned Outage	31-10-2025	10:11	31-10-2025	13:01	2:50	0.000944	REPLACEMET OF HT BUSHING ROD
1437	31-10-2025	Part of : D-BLOCK LAXMI VIHAR COLONY NANGLI SAKRAWATI	43	Other Outage	Planned Outage	31-10-2025	07:51	31-10-2025	10:12	2:21	0.000000	REPLACEMET OF HT BUSHING ROD
1438	01-10-2025	Part of : WEST PUNJABI BAGH PUNJABI BAGH,PUNJABI BAGH EXTENSION PUNJABI BAGH	1088	Other Outage	Unplanned Outage	01-10-2025	00:20	01-10-2025	01:10	0:50	0.000708	CABLE FAULT
1439	01-10-2025	Part of : WEST PUNJABI BAGH PUNJABI BAGH,	269	Other Outage	Planned Outage	01-10-2025	13:01	01-10-2025	14:56	1:55	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER.SUB STATION CLEANING
1440	01-10-2025	Part of : BLOCK A 4 PASCHIM VIHAR,	291	Other Outage	Planned Outage	01-10-2025	13:37	01-10-2025	15:02	1:25	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1441	01-10-2025	Part of : BLOCK BG 3 PASCHIM VIHAR,	463	Other Outage	Planned Outage	01-10-2025	10:04	01-10-2025	12:50	2:46	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1442	02-10-2025	Part of : BLOCK E JANTA COLONY PASCHIM VIHAR,PASCHIM VIHAR EXTENSION PASCHIM VIHAR	4521	Other Outage	Unplanned Outage	02-10-2025	05:18	02-10-2025	06:03	0:45	0.000950	CABLE FAULT
1443	03-10-2025	Part of : C & H-BLOCK KARAMPURA WEST,B-BLOCK NEW MOTI NAGAR,B 1-BLOCK NEW MOTI NAGAR PHASE 1	3278	Other Outage	Unplanned Outage	03-10-2025	11:16	03-10-2025	11:58	0:42	0.000000	CABLE FAULT
1444	03-10-2025	Part of : BLOCK A NEW MOTI NAGAR MOTI NAGAR	728	Other Outage	Planned Outage	03-10-2025	11:56	03-10-2025	13:37	1:41	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1445	03-10-2025	Part of : PASCHIM VIHAR EXTENSION	2506	Other Outage	Planned Outage	03-10-2025	11:09	03-10-2025	13:38	2:29	0.000000	APPLY OF INSULATION TAPE HT BUSHINGS,OIL TOP UP IN TRANSFORMER
1446	03-10-2025	Part of : BLOCK A 5 KRISHNA APARTMENT PASCHIM VIHAR	475	Other Outage	Planned Outage	03-10-2025	10:38	03-10-2025	13:09	2:31	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS
1447	04-10-2025	Part of : BLOCK H KARAMPURA WEST KARAMPURA	1199	Other Outage	Unplanned Outage	04-10-2025	10:57	04-10-2025	13:23	2:26	0.000811	REPAIR/REPLACEMENT OF BURNT EQUIPMENTS
1448	04-10-2025	Part of : BLOCK A 6 PASCHIM VIHAR	392	Other Outage	Planned Outage	04-10-2025	10:36	04-10-2025	12:31	1:55	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1449	06-10-2025	Part of : RAILWAY COLONY NORTH SHAKURBASTI	439	Other Outage	Planned Outage	06-10-2025	11:39	06-10-2025	13:04	1:25	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
1450	06-10-2025	Part of : BLOCK B 3 PASCHIM VIHAR	331	Other Outage	Planned Outage	06-10-2025	10:19	06-10-2025	12:07	1:48	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1451	08-10-2025	Part of : JWALAHARI VILLAGE PASCHIM VIHAR	616	Other Outage	Planned Outage	08-10-2025	10:08	08-10-2025	12:03	1:55	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1452	08-10-2025	Part of : POCKET 3 PASCHIM PURI PASCHIM VIHAR	1751	Other Outage	Planned Outage	08-10-2025	12:41	08-10-2025	15:07	2:26	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1453	09-10-2025	Part of : BLOCK B 1 PHASE 1 NEW MOTI NAGAR MOTI NAGAR,	435	Other Outage	Planned Outage	09-10-2025	10:57	09-10-2025	11:57	1:00	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
1454	09-10-2025	Part of : BLOCK A 1 ASHIRWAD PASCHIM VIHAR,	269	Other Outage	Planned Outage	09-10-2025	10:56	09-10-2025	12:51	1:55	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1455	10-10-2025	Part of : BLOCK C JAIDEV PARK PUNJABI BAGH EAST,GOLDEN PARK TRI NAGAR,BLOCK B MADAN PARK PUNJABI BAGH EAST	1892	Other Outage	Unplanned Outage	10-10-2025	11:34	10-10-2025	11:48	0:14	0.000156	HT SYSTEM FAULT
1456	10-10-2025	Part of : BLOCK A NEW MOTI NAGAR,BLOCK P PHASE 3 NEW MOTI NAGAR,KARAMPURA INDUSTRIAL AREA	1493	Other Outage	Unplanned Outage	10-10-2025	17:17	10-10-2025	18:00	0:43	0.000597	BIRDAGE
1457	10-10-2025	Part of : BLOCK BG 8 PASCHIM VIHAR	185	Other Outage	Planned Outage	10-10-2025	10:36	10-10-2025	12:37	2:01	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1458	10-10-2025	Part of : MADIPUR PUNJABI BAGH	494	Other Outage	Planned Outage	10-10-2025	10:35	10-10-2025	12:38	2:03	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1459	11-10-2025	Part of : STATE BANK COLONY PASCHIM VIHAR	397	Other Outage	Planned Outage	11-10-2025	13:46	11-10-2025	15:05	1:19	0.000329	PRC REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1460	13-10-2025	Part of : BLOCK A 3 SHAKSHAR APARTMENT PASCHIM VIHAR,	838	Other Outage	Planned Outage	13-10-2025	10:45	13-10-2025	12:26	1:41	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1461	13-10-2025	Part of : JANTA COLONY PASCHIM VIHAR,	1198	Other Outage	Planned Outage	13-10-2025	10:39	13-10-2025	12:25	1:46	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER,SUB STATION CLEANING
1462	13-10-2025	Part of : BLOCK I KARAMPURA WEST KARAMPURA,	248	Other Outage	Planned Outage	13-10-2025	10:17	13-10-2025	12:25	2:08	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1463	14-10-2025	Part of : MADIPUR PUNJABI BAGH	1463	Other Outage	Planned Outage	14-10-2025	14:11	14-10-2025	15:47	1:36	0.000667	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1464	14-10-2025	Part of : BLOCK A PASCHIM PURI PASCHIM VIHAR	916	Other Outage	Planned Outage	14-10-2025	10:50	14-10-2025	12:17	1:27	0.000604	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1465	14-10-2025	Part of : BLOCK M SURYA ENCLAVE SHAKURBASTI	532	Other Outage	Planned Outage	14-10-2025	10:43	14-10-2025	12:18	1:35	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1466	15-10-2025	Part of : C & E-BLOCK KARAMPURA INDUSTRIAL AREA	2786	Other Outage	Unplanned Outage	15-10-2025	09:05	15-10-2025	09:48	0:43	0.000597	CABLE FAULT
1467	15-10-2025	Part of : MADIPUR PUNJABI BAGH	495	Other Outage	Planned Outage	15-10-2025	14:30	15-10-2025	15:36	1:06	0.000275	REPLACEMENT OF HT BUSHING ROD
1468	15-10-2025	Part of : C-BLOCK SHIVAJI PARK PUNJABI BAGH	699	Other Outage	Planned Outage	15-10-2025	10:40	15-10-2025	12:15	1:35	0.000528	REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS
1469	15-10-2025	Part of : BG 6-BLOCK PASCHIM VIHAR	879	Other Outage	Planned Outage	15-10-2025	10:30	15-10-2025	12:16	1:46	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1470	15-10-2025	Part of : JANTA COLONY PASCHIM VIHAR	1527	Other Outage	Planned Outage	15-10-2025	11:09	15-10-2025	14:05	2:56	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING
1471	16-10-2025	Part of : RBI ENCLAVE PASCHIM VIHAR	239	Other Outage	Planned Outage	16-10-2025	14:23	16-10-2025	15:39	1:16	0.000422	RELAY REPLACEMET/VPI/FPI,REPLACEMET OF FAULTY END BOX
1472	16-10-2025	Part of : POCKET 3 PASCHIM PURI PASCHIM VIHAR	1766	Other Outage	Planned Outage	16-10-2025	11:33	16-10-2025	12:57	1:24	0.000583	REPLACEMET OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
1473	16-10-2025	Part of : RBI ENCLAVE PASCHIM VIHAR	163	Other Outage	Planned Outage	16-10-2025	12:15	16-10-2025	14:21	2:06	0.000700	CT REPLACEMET,PROPER SEALING RMU PER WAY,PROPOER CLEANING OF OPERATING MECHANISM USING CRCS PER WAY,RELAY REPLACEMET/VPI/FPI,REPLACEMET OF FAULTY END BOX,SF6 GAS FILLING
1474	16-10-2025	Part of : INDIRA COLONY TRI NAGAR	104	Other Outage	Planned Outage	16-10-2025	09:53	16-10-2025	12:47	2:54	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1475	16-10-2025	Part of : BLOCK A JANTA COLONY PASCHIM VIHAR	274	Other Outage	Planned Outage	16-10-2025	12:16	16-10-2025	14:25	2:09	0.000538	CONDUCTOR REPLACEMENT PER SPAN,FERRULE PUNCHING LT AB TO LT AB PER FEEDER
1476	17-10-2025	Part of : BLOCK BG 3 PASCHIM VIHAR,BLOCK B 5 PASCHIM VIHAR,BLOCK BG 6 PASCHIM VIHAR,BLOCK BG 5 PASCHIM VIHAR	2224	Other Outage	Unplanned Outage	17-10-2025	02:36	17-10-2025	03:22	0:46	0.000460	CABLE FAULT
1477	17-10-2025	Part of : BLOCK D JANTA COLONY PASCHIM VIHAR,	1161	Other Outage	Planned Outage	17-10-2025	10:22	17-10-2025	13:23	3:01	0.000754	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,REPLACEMET OF LUGS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1478	18-10-2025	Part of : BLOCK BG 1 PASCHIM VIHAR	644	Other Outage	Planned Outage	18-10-2025	13:29	18-10-2025	14:37	1:08	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
1479	18-10-2025	Part of : BLOCK BG 1 PASCHIM VIHAR	644	Other Outage	Planned Outage	18-10-2025	10:17	18-10-2025	12:50	2:33	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING
1480	18-10-2025	Part of : POCKET 1 PASCHIM PURI PASCHIM VIHAR	576	Other Outage	Planned Outage	18-10-2025	10:44	18-10-2025	12:51	2:07	0.000529	REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,REPLACEMENT OF LUGS
1481	22-10-2025	Part of : JWALAHERI VILLAGE PASCHIM VIHAR,BLOCK B 3 PASCHIM VIHAR,IFCI COLONY PASCHIM VIHAR	1789	Other Outage	Unplanned Outage	22-10-2025	21:29	22-10-2025	22:20	0:51	0.000553	CABLE FAULT
1482	23-10-2025	Part of : STATE BANK COLONY PASCHIM VIHAR	173	Other Outage	Planned Outage	23-10-2025	13:16	23-10-2025	14:18	1:02	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1483	24-10-2025	Part of : ARIHANT NAGAR PUNJABI BAGH	570	Other Outage	Planned Outage	24-10-2025	10:30	24-10-2025	12:27	1:57	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unserved (MU) due to outage	Remarks
						Date	Time	Date	Time			
1484	24-10-2025	Part of : AVTAR ENCLAVE PASCHIM VIHAR	194	Other Outage	Planned Outage	24-10-2025	10:36	24-10-2025	12:27	1:51	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMENT OF HT BUSHING ROD,REPLACEMENT OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1485	25-10-2025	Part of : BLOCK C SHIVAJI PARK PUNJABI BAGH,	265	Other Outage	Planned Outage	25-10-2025	10:30	25-10-2025	12:28	1:58	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1486	25-10-2025	Part of : STATE BANK COLONY PASCHIM VIHAR,	361	Other Outage	Planned Outage	25-10-2025	10:14	25-10-2025	12:27	2:13	0.000000	CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING
1487	26-10-2025	Part of : PUNJABI BAGH COOPERATIVE HOUSING SOCEITY PUNJABI BAGH EAST	334	Other Outage	Unplanned Outage	26-10-2025	07:41	26-10-2025	08:25	0:44	0.000440	CABLE FAULT
1488	29-10-2025	Part of : BLOCK A PASCHIM VIHAR EXTENSION PASCHIM VIHAR,	859	Other Outage	Planned Outage	29-10-2025	10:39	29-10-2025	12:33	1:54	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1489	29-10-2025	Part of : RBI ENCLAVE PASCHIM VIHAR,	11	Other Outage	Planned Outage	29-10-2025	10:40	29-10-2025	12:32	1:52	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER,CHECKING VALUE OF FENCING EARTHING,DT OIL SAMPLING TO CHECK BDV VALUE,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF HT BOOTS,MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES),MEASUREMET OF INSULATION RESISTANCE(INCLUDING DISCONNECTION OF HT/LT CABLES) (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD,REPLACEMENT OF SILICAGEL IN BREATHER,REPLACEMET OF HT BUSHING ROD,REPLACEMET OF HT/LT CLEATS,SUB STATION CLEANING,TIGHTENEING OF NUT BOLT
1490	29-10-2025	Part of : STATE BANK COLONY PASCHIM VIHAR,	706	Other Outage	Planned Outage	29-10-2025	12:54	29-10-2025	14:55	2:01	0.000504	FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,JUMPER REPLACEMENT PER POLE,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1491	30-10-2025	Part of : COTTAGE ENCLAVE PASCHIM VIHAR	232	Other Outage	Planned Outage	30-10-2025	11:28	30-10-2025	13:20	1:52	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1492	30-10-2025	Part of : RAILWAY COLONY NORTH SHAKURBASTI	450	Other Outage	Planned Outage	30-10-2025	11:14	30-10-2025	12:37	1:23	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1493	30-10-2025	Part of : PUNJABI BAGH COOPERATIVE HOUSING SOCEITY PUNJABI BAGH EAST	359	Other Outage	Planned Outage	30-10-2025	10:26	30-10-2025	12:36	2:10	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,REPLACEMENT OF GAS KIT AND OIL SEAL,REPLACEMENT OF SILICAGEL IN BREATHER
1494	31-10-2025	Part of : POCKET 1 & 3 PASCHIM PURI PASCHIM VIHAR,JANTA COLONY PASCHIM VIHAR	3688	Other Outage	Unplanned Outage	31-10-2025	07:34	31-10-2025	08:28	0:54	0.000885	HT SYSTEM FAULT
1495	31-10-2025	Part of : A 3-BLOCK PASCHIM VIHAR	382	Other Outage	Planned Outage	31-10-2025	10:12	31-10-2025	12:04	1:52	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING OF EARTHING VALUE OF BODY EARTHING AND NEUTRAL EARTHING USING ONLINE EARTH TESTER
1496	31-10-2025	Part of : ROAD NO. 33 WEST PUNJABI BAGH	389	Other Outage	Planned Outage	31-10-2025	11:09	31-10-2025	14:20	3:11	0.000000	APPLY OF INSULATION TAPE HT/LT BUSHINGS,CHECKING VALUE OF FENCING EARTHING,OIL TOP UP IN TRANSFORMER
1497	01-10-2025	Part of : BLOCK E SITAPURI PART 1 SITAPURI,	1097	Other Outage	Planned Outage	01-10-2025	15:15	01-10-2025	16:28	1:13	0.000406	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1498	01-10-2025	Part of : DABRI VILLAGE DABRI,	674	Other Outage	Planned Outage	01-10-2025	12:14	01-10-2025	14:00	1:46	0.000589	LT AB SAGGING PER SPAN
1499	01-10-2025	Part of : SECTOR 22 DWARKA,	16	Other Outage	Planned Outage	01-10-2025	11:08	01-10-2025	12:39	1:31	0.000506	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1500	01-10-2025	Part of : SECTOR 22 DWARKA,	1	Other Outage	Planned Outage	01-10-2025	14:27	01-10-2025	16:55	2:28	0.000822	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1501	01-10-2025	Part of : BLOCK RZ GEETANJALI PARK SAGARPUR WEST SAGARPUR,	1698	Other Outage	Planned Outage	01-10-2025	10:56	01-10-2025	13:35	2:39	0.000883	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1502	02-10-2025	Part of : SECTOR 9 DWARKA,BAGDAULA VILLAGE SECTOR 8 DWARKA,POCKET 2 SECTOR 9 DWARKA,BLOCK B SECTOR 8 DWARKA,BLOCK A SECTOR 8 DWARKA	2427	Other Outage	Unplanned Outage	02-10-2025	18:25	02-10-2025	19:18	0:53	0.000972	TREE BRANCH FALLEN ON O/H LINE
1503	03-10-2025	Part of : POCKET 2 SECTOR 1 DWARKA	247	Other Outage	Planned Outage	03-10-2025	12:25	03-10-2025	17:10	4:45	0.001583	HT CONDUCTOR REPLACEMET
1504	03-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1	829	Other Outage	Planned Outage	03-10-2025	11:07	03-10-2025	14:17	3:10	0.001056	REPLACEMET OF HT BUSHING ROD
1505	03-10-2025	Part of : BLOCK A SITAPURI PART 1	770	Other Outage	Planned Outage	03-10-2025	11:07	03-10-2025	15:16	4:09	0.001383	APPLY OF INSULATION TAPE LT BUSHINGS
1506	03-10-2025	Part of : MAHAVIR ENCLAVE PART 2	1322	Other Outage	Planned Outage	03-10-2025	10:48	03-10-2025	13:36	2:48	0.000933	APPLY OF INSULATION TAPE LT BUSHINGS
1507	03-10-2025	Part of : SECTOR 22 DWARKA	3	Other Outage	Planned Outage	03-10-2025	11:26	03-10-2025	13:50	2:24	0.000800	APPLY OF INSULATION TAPE LT BUSHINGS
1508	04-10-2025	Part of : MAHAVIR ENCLAVE PART 2, PALAM COLONY MAHAVIR ENCLAVE PART 2	526	Other Outage	Planned Outage	04-10-2025	11:18	04-10-2025	14:15	2:57	0.000983	LT BUSHING REPLACEMENT
1509	04-10-2025	Part of : POCKET 1 SECTOR 22 DWARKA	167	Other Outage	Planned Outage	04-10-2025	11:24	04-10-2025	12:51	1:27	0.000483	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1510	04-10-2025	Part of : NAVEEN KUNJ SOCIETY NARSIRPUR	158	Other Outage	Planned Outage	04-10-2025	11:44	04-10-2025	16:11	4:27	0.001483	LT AB SAGGING PER SPAN
1511	04-10-2025	Part of : SYNDICATE ENCLAVE DABRI	337	Other Outage	Planned Outage	04-10-2025	11:13	04-10-2025	15:15	4:02	0.001344	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1512	04-10-2025	Part of : BLOCK C PALAM EXTENSION	827	Other Outage	Planned Outage	04-10-2025	11:13	04-10-2025	14:01	2:48	0.000933	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1513	06-10-2025	Part of : SECTOR 23 DWARKA,POCHANPUR DWARKA	905	Other Outage	Unplanned Outage	06-10-2025	16:34	06-10-2025	17:00	0:26	0.000737	HT SYSTEM FAULT
1514	06-10-2025	Part of : BLOCK R INDRA PARK PALEM KAILASHPURI MAIN PALAM,INDRA PARK PALEM KAILASHPURI MAIN PALAM,KAILASHPURI MAIN PALAM	2879	Other Outage	Planned Outage	06-10-2025	10:41	06-10-2025	13:50	3:09	0.001050	DB REVAMPING,HT BUSHING ROD REPLACEMENT
1515	06-10-2025	Part of : BLOCK G RAJ NAGAR 2	711	Other Outage	Planned Outage	06-10-2025	14:43	06-10-2025	16:58	2:15	0.000750	LT AB SAGGING PER SPAN
1516	06-10-2025	Part of : SECTOR 22 DWARKA	153	Other Outage	Planned Outage	06-10-2025	13:06	06-10-2025	16:12	3:06	0.001033	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1517	06-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1	280	Other Outage	Planned Outage	06-10-2025	11:24	06-10-2025	14:32	3:08	0.001044	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1518	06-10-2025	Part of : DABRI EXTENSION EAST DABRI	599	Other Outage	Planned Outage	06-10-2025	11:06	06-10-2025	14:25	3:19	0.001106	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1519	06-10-2025	Part of : BLOCK C SADH NAGAR II PALAM	952	Other Outage	Planned Outage	06-10-2025	11:33	06-10-2025	16:05	4:32	0.001511	LT AB SAGGING PER SPAN
1520	06-10-2025	Part of : MAHAVIR ENCLAVE PART 2	1367	Other Outage	Planned Outage	06-10-2025	12:15	06-10-2025	16:01	3:46	0.001256	LT AB SAGGING PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1521	06-10-2025	Part of : BLOCK F RAJ NAGAR EXTENSION	1347	Other Outage	Planned Outage	06-10-2025	11:05	06-10-2025	13:09	2:04	0.000689	LT AB SAGGING PER SPAN
1522	07-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1,MIRZAPUR,G 1-BLOCK MAHAVIR ENCLAVE PART 1	5281	Other Outage	Unplanned Outage	07-10-2025	02:24	07-10-2025	02:52	0:28	0.000226	TRANSIENT FAULT
1523	08-10-2025	Part of : BLOCK C MAHAVIR ENCLAVE PART 1	1484	Other Outage	Planned Outage	08-10-2025	11:21	08-10-2025	12:36	1:15	0.000417	LT AB SAGGING PER SPAN
1524	08-10-2025	Part of : POCKET 10 SECTOR I DASRATHPURI	151	Other Outage	Planned Outage	08-10-2025	12:34	08-10-2025	15:01	2:27	0.000817	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1525	08-10-2025	Part of : BLOCK E SITAPURI PART 1	1101	Other Outage	Planned Outage	08-10-2025	12:33	08-10-2025	16:13	3:40	0.001222	LT AB SAGGING PER SPAN
1526	08-10-2025	Part of : MAHAVIR ENCLAVE PART 2	599	Other Outage	Planned Outage	08-10-2025	11:48	08-10-2025	14:06	2:18	0.000767	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1527	08-10-2025	Part of : SECTOR 22 DWARKA	11	Other Outage	Planned Outage	08-10-2025	11:47	08-10-2025	14:27	2:40	0.000889	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1528	09-10-2025	Part of : BLOCK C DASRATHPURI,BLOCK B 2 DASRATHPURI,DURGA PARK COLONY DASRATHPURI,	868	Other Outage	Planned Outage	09-10-2025	11:06	09-10-2025	14:42	3:36	0.001200	DB REVAMPING,LT BUSHING REPLACEMENT
1529	09-10-2025	Part of : BLOCK A POCKET 9 PINK APARTMENTS NARSIRPUR,	642	Other Outage	Planned Outage	09-10-2025	10:53	09-10-2025	17:10	6:17	0.002094	LT AB SAGGING PER SPAN
1530	09-10-2025	Part of : POCKET 13 MANGALPURI II PALAM,	404	Other Outage	Planned Outage	09-10-2025	11:13	09-10-2025	14:33	3:20	0.001111	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1531	09-10-2025	Part of : SECTOR 22 DWARKA,	79	Other Outage	Planned Outage	09-10-2025	11:02	09-10-2025	14:34	3:32	0.001178	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1532	10-10-2025	Part of : SECTOR 22 DWARKA	106	Other Outage	Planned Outage	10-10-2025	13:33	10-10-2025	14:43	1:10	0.000389	REPLACEMET OF FAULTY END BOX
1533	10-10-2025	Part of : BLOCK RZ KAMAL PARK KAILASHPURI MAIN PALAM,POCKET B KAILASHPURI EAST KAILASHPURI MAIN PALAM	1787	Other Outage	Planned Outage	10-10-2025	10:24	10-10-2025	13:08	2:44	0.000456	DB REVAMPING,HT BUSHING ROD REPLACEMENT
1534	10-10-2025	Part of : BLOCK B DASRATHPURI,DABRI VILLAGE DABRI,VAISHALI EXTENSION DASRATHPURI	246	Other Outage	Planned Outage	10-10-2025	10:45	10-10-2025	13:53	3:08	0.001044	DB REVAMPING,LT BUSHING REPLACEMENT
1535	10-10-2025	Part of : PALAM VILLAGE	594	Other Outage	Planned Outage	10-10-2025	15:38	10-10-2025	16:37	0:59	0.000328	LT LT AB SAGGING PER SPAN
1536	10-10-2025	Part of : BLOCK B RAJ NAGAR 2	1462	Other Outage	Planned Outage	10-10-2025	11:58	10-10-2025	14:24	2:26	0.000811	LT LT AB SAGGING PER SPAN
1537	10-10-2025	Part of : BLOCK R INDRA PARK PALEM KAILASHPURI MAIN PALAM	688	Other Outage	Planned Outage	10-10-2025	11:57	10-10-2025	17:01	5:04	0.001689	LT LT AB SAGGING PER SPAN
1538	10-10-2025	Part of : JAGDAMBA VIHAR SAGARPUR WEST	1256	Other Outage	Planned Outage	10-10-2025	10:59	10-10-2025	16:39	5:40	0.001889	LT LT AB SAGGING PER SPAN
1539	10-10-2025	Part of : BLOCK J PALAM	4	Other Outage	Planned Outage	10-10-2025	11:20	10-10-2025	14:17	2:57	0.000983	LT APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1540	11-10-2025	Part of : MAHAVIR ENCLAVE PART-2	1367	Other Outage	Planned Outage	11-10-2025	12:10	11-10-2025	14:28	2:18	0.000767	LT AB SAGGING
1541	11-10-2025	Part of : A-BLOCK SADH NAGAR-2 PALAM	535	Other Outage	Planned Outage	11-10-2025	11:16	11-10-2025	14:27	3:11	0.001061	APPLY OF INSULATION TAPE LT BUSHINGS
1542	11-10-2025	Part of : HARIJAN BASTI PALAM EXTENSION	823	Other Outage	Planned Outage	11-10-2025	11:05	11-10-2025	14:35	3:30	0.001167	APPLY OF INSULATION TAPE LT BUSHINGS
1543	11-10-2025	Part of : C-BLOCK MAHAVIR ENCLAVE PART-1	1049	Other Outage	Planned Outage	11-10-2025	11:03	11-10-2025	14:05	3:02	0.001011	LT AB SAGGING
1544	11-10-2025	Part of : SECTOR 22 DWARKA	86	Other Outage	Planned Outage	11-10-2025	11:25	11-10-2025	15:51	4:26	0.001478	APPLY OF INSULATION TAPE LT BUSHINGS
1545	13-10-2025	Part of : BLOCK B SECTOR 8 DWARKA,	193	Other Outage	Planned Outage	13-10-2025	13:47	13-10-2025	14:59	1:12	0.000200	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
1546	13-10-2025	Part of : BLOCK E SITAPURI PART 1 SITAPURI,	1103	Other Outage	Planned Outage	13-10-2025	11:44	13-10-2025	14:29	2:45	0.000917	LT AB SAGGING PER SPAN
1547	13-10-2025	Part of : BLOCK F RAJ NAGAR EXTENSION RAJ NAGAR,	364	Other Outage	Planned Outage	13-10-2025	11:36	13-10-2025	13:51	2:15	0.000750	GUARD WIRES SAGGING PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1548	13-10-2025	Part of : POCKET 10 SECTOR I DASRATHPURI,BLOCK B 2 DASRATHPURI,DURGA PARK COLONY DASRATHPURI,	582	Other Outage	Planned Outage	13-10-2025	11:36	13-10-2025	13:42	2:06	0.000700	DB REVAMPING,LT BUSHING REPLACEMENT
1549	13-10-2025	Part of : MAHAVIR ENCLAVE PART 2 MAHAVIR ENCLAVE,	1064	Other Outage	Planned Outage	13-10-2025	10:56	13-10-2025	14:33	3:37	0.001206	HT BUSHING ROD REPLACEMENT,LT BUSHING REPLACEMENT
1550	13-10-2025	Part of : BLOCK G RAJ NAGAR 2 RAJ NAGAR,	711	Other Outage	Planned Outage	13-10-2025	14:04	13-10-2025	16:40	2:36	0.000867	LT AB SAGGING PER SPAN
1551	13-10-2025	Part of : VEER NAGAR SAGARPUR WEST SAGARPUR,	403	Other Outage	Planned Outage	13-10-2025	12:08	13-10-2025	16:18	4:10	0.001389	LT AB SAGGING PER SPAN
1552	13-10-2025	Part of : DABRI VILLAGE DABRI,	674	Other Outage	Planned Outage	13-10-2025	11:16	13-10-2025	16:04	4:48	0.001600	LT AB SAGGING PER SPAN
1553	13-10-2025	Part of : TAMILAR ENCLAVE VIJAY ENCLAVE MAHAVIR ENCLAVE,	354	Other Outage	Planned Outage	13-10-2025	11:25	13-10-2025	14:09	2:44	0.000911	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1554	13-10-2025	Part of : BLOCK A 1 VIJAY ENCLAVE MAHAVIR ENCLAVE,	811	Other Outage	Planned Outage	13-10-2025	11:28	13-10-2025	14:58	3:30	0.001167	REPLACEMENT OF LT BUSHING ROD
1555	13-10-2025	Part of : SECTOR 22 DWARKA,	4	Other Outage	Planned Outage	13-10-2025	11:52	13-10-2025	15:33	3:41	0.001228	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1556	14-10-2025	Part of : KAILASHPURI WEST PALAM,KAILASHPURI MAIN PALAM,INDIRA PARK EXTENSION KAILASHPURI MAIN PALAM	2044	Other Outage	Planned Outage	14-10-2025	11:26	14-10-2025	13:24	1:58	0.000656	DB REVAMPING,LT BUSHING REPLACEMENT
1557	14-10-2025	Part of : BLOCK B PATEL BLOCK RAGHU NAGAR DABRI	1012	Other Outage	Planned Outage	14-10-2025	12:18	14-10-2025	15:27	3:09	0.001050	LT AB SAGGING PER SPAN
1558	14-10-2025	Part of : NAVEEN KUNJ SOCIETY NARSIRPUR	158	Other Outage	Planned Outage	14-10-2025	11:53	14-10-2025	14:35	2:42	0.000900	LT AB SAGGING PER SPAN
1559	14-10-2025	Part of : BLOCK C SADH NAGAR II PALAM	952	Other Outage	Planned Outage	14-10-2025	11:45	14-10-2025	15:32	3:47	0.001261	LT AB SAGGING PER SPAN
1560	14-10-2025	Part of : SECTOR 22 DWARKA	51	Other Outage	Planned Outage	14-10-2025	11:39	14-10-2025	14:27	2:48	0.000933	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1561	14-10-2025	Part of : MANGALPURI I PALAM	1077	Other Outage	Planned Outage	14-10-2025	10:35	14-10-2025	13:19	2:44	0.000911	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1562	15-10-2025	Part of : SECTOR 22 DWARKA	97	Other Outage	Planned Outage	15-10-2025	13:48	15-10-2025	16:21	2:33	0.000425	REPLACEMENT OF FAULTY END BOX
1563	15-10-2025	Part of : VAISHALI EXTENSION DASRATHPURI	602	Other Outage	Planned Outage	15-10-2025	14:27	15-10-2025	16:15	1:48	0.000300	LT AB SAGGING
1564	15-10-2025	Part of : A-BLOCK POCKET 9 PINK APARTMENTS NARSIRPUR	324	Other Outage	Planned Outage	15-10-2025	14:26	15-10-2025	16:16	1:50	0.000306	LT AB SAGGING
1565	15-10-2025	Part of : JAGDAMBA VIHAR SAGARPUR WEST	563	Other Outage	Planned Outage	15-10-2025	13:30	15-10-2025	14:57	1:27	0.000483	LT CIRCUIT MAINTENANCE WORK
1566	15-10-2025	Part of : DABRI VILLAGE	673	Other Outage	Planned Outage	15-10-2025	11:25	15-10-2025	14:01	2:36	0.000867	LT CIRCUIT MAINTENANCE WORK
1567	15-10-2025	Part of : POCKET 1 SECTOR 22 DWARKA	45	Other Outage	Planned Outage	15-10-2025	10:54	15-10-2025	13:46	2:52	0.000956	LT CIRCUIT MAINTENANCE WORK
1568	15-10-2025	Part of : E-BLOCK PALAM EXTENSION	277	Other Outage	Planned Outage	15-10-2025	11:14	15-10-2025	13:47	2:33	0.000850	LT CIRCUIT MAINTENANCE WORK
1569	16-10-2025	Part of : SAGARPUR WEST, BLOCK C DASRATHPURI,JAGDAMBA VIHAR SAGARPUR WEST,DURGA PARK COLONY DASRATHPURI	7815	Other Outage	Unplanned Outage	16-10-2025	16:17	16-10-2025	17:02	0:45	0.001463	BIRDAGE
1570	16-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1,MIRZAPUR MAHAVIR ENCLAVE	834	Other Outage	Planned Outage	16-10-2025	12:16	16-10-2025	13:17	1:01	0.000339	1PH HT AB END TERMINATION REPLACEMENT,DB REVAMPING
1571	16-10-2025	Part of : DABRI VILLAGE	674	Other Outage	Planned Outage	16-10-2025	12:33	16-10-2025	13:20	0:47	0.000261	LT AB SAGGING PER SPAN
1572	16-10-2025	Part of : BLOCK RZ SAGARPUR	1624	Other Outage	Planned Outage	16-10-2025	12:30	16-10-2025	13:19	0:49	0.000272	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1573	16-10-2025	Part of : BLOCK B CHANDAR VIHAR PALAM EXTENSION	612	Other Outage	Planned Outage	16-10-2025	12:17	16-10-2025	13:18	1:01	0.000339	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1574	16-10-2025	Part of : BLOCK D RAJ NAGAR 1	864	Other Outage	Planned Outage	16-10-2025	12:05	16-10-2025	13:50	1:45	0.000583	LT AB SAGGING PER SPAN
1575	16-10-2025	Part of : PALAM VILLAGE	594	Other Outage	Planned Outage	16-10-2025	10:33	16-10-2025	12:03	1:30	0.000500	LT AB SAGGING PER SPAN
1576	16-10-2025	Part of : BLOCK C VINODPURI VIJAY ENCLAVE MAHAVIR ENCLAVE	483	Other Outage	Planned Outage	16-10-2025	12:10	16-10-2025	14:37	2:27	0.000817	LT AB SAGGING PER SPAN
1577	16-10-2025	Part of : BLOCK A DABRI EXTENSION EAST	591	Other Outage	Planned Outage	16-10-2025	12:10	16-10-2025	14:37	2:27	0.000817	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1578	16-10-2025	Part of : SECTOR 22 DWARKA	38	Other Outage	Planned Outage	16-10-2025	10:54	16-10-2025	13:43	2:49	0.000939	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1579	16-10-2025	Part of : VEER NAGAR SAGARPUR WEST	1269	Other Outage	Planned Outage	16-10-2025	10:56	16-10-2025	13:43	2:47	0.000928	LT AB SAGGING PER SPAN
1580	16-10-2025	Part of : JAGDAMBA VIHAR SAGARPUR WEST	1138	Other Outage	Planned Outage	16-10-2025	10:58	16-10-2025	13:22	2:24	0.000800	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1581	17-10-2025	Part of : BLOCK G RAJ NAGAR 2 RAJ NAGAR,	1569	Other Outage	Planned Outage	17-10-2025	11:59	17-10-2025	13:31	1:32	0.000511	LT AB SAGGING PER SPAN
1582	17-10-2025	Part of : BLOCK C MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,	508	Other Outage	Planned Outage	17-10-2025	11:58	17-10-2025	14:08	2:10	0.000722	LT AB SAGGING PER SPAN
1583	17-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,	460	Other Outage	Planned Outage	17-10-2025	10:59	17-10-2025	13:32	2:33	0.000850	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1584	17-10-2025	Part of : SECTOR 22 DWARKA,	52	Other Outage	Planned Outage	17-10-2025	11:56	17-10-2025	14:45	2:49	0.000939	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1585	17-10-2025	Part of : BLOCK RZB SABZI MANDI SAGARPUR MAIN SAGARPUR,	980	Other Outage	Planned Outage	17-10-2025	10:43	17-10-2025	12:57	2:14	0.000744	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1586	17-10-2025	Part of : BLOCK A POCKET 9 PINK APARTMENTS NARSIRPUR,	204	Other Outage	Planned Outage	17-10-2025	11:13	17-10-2025	13:52	2:39	0.000883	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1587	18-10-2025	Part of : Sector 8 Dwarka	2	Other Outage	Unplanned Outage	18-10-2025	12:08	18-10-2025	12:43	0:35	0.000010	CABLE FAULT
1588	18-10-2025	Part of : Block T Gandhi Market Sagarpur,Sant Mohalla Sagarpur Main Sagarpur	4516	Other Outage	Unplanned Outage	18-10-2025	10:56	18-10-2025	11:40	0:44	0.000880	HT SYSTEM FAULT
1589	18-10-2025	Part of : BLOCK A POCKET 9 PINK APARTMENTS NARSIRPUR	324	Other Outage	Planned Outage	18-10-2025	14:17	18-10-2025	17:01	2:44	0.000911	GUARD WIRE LACS INSTALLTION PER SPAN
1590	18-10-2025	Part of : KHERA VILLAGE SADH NAGAR 1 PALAM	196	Other Outage	Planned Outage	18-10-2025	11:41	18-10-2025	13:17	1:36	0.000533	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER
1591	21-10-2025	Part of : BLOCK G RAJ NAGAR 2 RAJ NAGAR,BLOCK F RAJ NAGAR EXTENSION RAJ NAGAR,SECTOR 9 DWARKA	5153	Other Outage	Unplanned Outage	21-10-2025	07:47	21-10-2025	08:10	0:23	0.000434	HT SYSTEM FAULT
1592	21-10-2025	Part of : BLOCK A 1 VIJAY ENCLAVE MAHAVIR ENCLAVE,	808	Other Outage	Planned Outage	21-10-2025	12:02	21-10-2025	14:38	2:36	0.000867	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1593	21-10-2025	Part of : BLOCK RZB SABZI MANDI SAGARPUR MAIN SAGARPUR,	355	Other Outage	Planned Outage	21-10-2025	10:56	21-10-2025	13:22	2:26	0.000811	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1594	22-10-2025	Part of : BLOCK J SAGARPUR WEST	839	Other Outage	Planned Outage	22-10-2025	11:47	22-10-2025	12:51	1:04	0.000356	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER
1595	22-10-2025	Part of : BLOCK F MAHAVIR ENCLAVE PART 1	1892	Other Outage	Planned Outage	22-10-2025	11:05	22-10-2025	13:20	2:15	0.000750	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1596	22-10-2025	Part of : SECTOR 22 DWARKA	64	Other Outage	Planned Outage	22-10-2025	11:47	22-10-2025	14:14	2:27	0.000817	APPLY OF INSULATION TAPE HT/LT BUSHINGS,SUB STATION CLEANING
1597	24-10-2025	Part of : SECTOR 22 DWARKA	11	Other Outage	Planned Outage	24-10-2025	13:47	24-10-2025	15:24	1:37	0.000539	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
1598	24-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART	1105	Other Outage	Planned Outage	24-10-2025	10:57	24-10-2025	13:47	2:50	0.000944	1PH HT AB END TERMINATION REPLACEMENT,DB REVAMPING
1599	24-10-2025	Part of : SECTOR 22 DWARKA	51	Other Outage	Planned Outage	24-10-2025	12:02	24-10-2025	14:32	2:30	0.000833	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1600	24-10-2025	Part of : BLOCK F DASRATHPURI	962	Other Outage	Planned Outage	24-10-2025	11:28	24-10-2025	14:16	2:48	0.000933	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1601	24-10-2025	Part of : BLOCK A POCKET 9 PINK APARTMENTS NARSIRPUR	641	Other Outage	Planned Outage	24-10-2025	11:23	24-10-2025	13:39	2:16	0.000756	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1602	25-10-2025	Part of : BLOCK C MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,	1002	Other Outage	Planned Outage	25-10-2025	10:57	25-10-2025	13:33	2:36	0.000867	DB REVAMPING,HT BUSHING ROD REPLACEMENT
1603	25-10-2025	Part of : SECTOR 22 DWARKA,	86	Other Outage	Planned Outage	25-10-2025	13:23	25-10-2025	14:47	1:24	0.000467	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1604	25-10-2025	Part of : BLOCK H RAGHU NAGAR DABRI,	1270	Other Outage	Planned Outage	25-10-2025	11:10	25-10-2025	12:54	1:44	0.000578	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS,INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1605	25-10-2025	Part of : BLOCK E SITAPURI PART 1 SITAPURI,	407	Other Outage	Planned Outage	25-10-2025	11:09	25-10-2025	12:52	1:43	0.000572	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1606	25-10-2025	Part of : POCKET 13 MANGALPURI II PALAM,	451	Other Outage	Planned Outage	25-10-2025	11:08	25-10-2025	12:49	1:41	0.000561	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1607	25-10-2025	Part of : DABRI EXTENSION EAST DABRI,	1063	Other Outage	Planned Outage	25-10-2025	11:10	25-10-2025	12:50	1:40	0.000556	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1608	25-10-2025	Part of : BLOCK A SECTOR 8 DWARKA,	353	Other Outage	Planned Outage	25-10-2025	10:44	25-10-2025	13:37	2:53	0.000961	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS,OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1609	25-10-2025	Part of : BLOCK B 3 MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,	1296	Other Outage	Planned Outage	25-10-2025	10:57	25-10-2025	13:15	2:18	0.000767	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1610	25-10-2025	Part of : BLOCK D RAJ NAGAR 1 RAJ NAGAR,	869	Other Outage	Planned Outage	25-10-2025	10:45	25-10-2025	16:04	5:19	0.001772	LT AB SAGGING PER SPAN
1611	28-10-2025	Part of : SANT MOHALLA SAGARPUR, BLOCK RZ GANDHI MARKET SAGARPUR MAIN, GALI NO.-4 SAGARPUR	3736	Other Outage	Unplanned Outage	28-10-2025	19:38	28-10-2025	20:19	0:41	0.000501	CABLE FAULT
1612	28-10-2025	Part of : GEETANJALI PARK, BLOCK RZB SABZI MANDI SAGARPUR MAIN, VEER NAGAR SAGARPUR WEST	3836	Other Outage	Unplanned Outage	28-10-2025	12:13	28-10-2025	13:00	0:47	0.000548	CABLE FAULT
1613	28-10-2025	Part of : NANDA BLOCK MAHAVIR ENCLAVE PART 1,MIRZAPUR MAHAVIR ENCLAVE	834	Other Outage	Planned Outage	28-10-2025	13:46	28-10-2025	15:26	1:40	0.000556	1PH HT AB END TERMINATION REPLACEMENT,DB REVAMPING
1614	28-10-2025	Part of : BLOCK B SECTOR 8 DWARKA,BLOCK F RAJ NAGAR EXTENSION	959	Other Outage	Planned Outage	28-10-2025	11:07	28-10-2025	15:58	4:51	0.001617	GUARD WIRES SAGGING PER SPAN
1615	28-10-2025	Part of : BLOCK F & J RAJ NAGAR EXTENSION,BLOCK B SECTOR 8 DWARKA	1325	Other Outage	Planned Outage	28-10-2025	11:08	28-10-2025	15:57	4:49	0.001606	GUARD WIRES SAGGING PER SPAN
1616	28-10-2025	Part of : PALAM COLONY MAHAVIR ENCLAVE PART 2,MAHAVIR ENCLAVE PART 2	526	Other Outage	Planned Outage	28-10-2025	11:06	28-10-2025	13:51	2:45	0.000917	DB REVAMPING,HT BUSHING ROD REPLACEMENT,LT BUSHING REPLACEMENT
1617	28-10-2025	Part of : VAISHALI EXTENSION DASRATHPURI	602	Other Outage	Planned Outage	28-10-2025	11:16	28-10-2025	14:46	3:30	0.001167	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1618	29-10-2025	Part of : DABRI VILLAGE DABRI,BLOCK B DASRATHPURI,VAISHALI EXTENSION DASRATHPURI,	246	Other Outage	Planned Outage	29-10-2025	13:06	29-10-2025	13:54	0:48	0.000267	LT AB SAGGING PER SPAN
1619	29-10-2025	Part of : POCKET B KAILASHPURI EAST KAILASHPURI MAIN PALAM,BLOCK R INDRA PARK PALEM KAILASHPURI MAIN PALAM,INDRA PARK PALEM KAILASHPURI MAIN PALAM,KAILASHPURI MAIN PALAM,	2879	Other Outage	Planned Outage	29-10-2025	14:16	29-10-2025	15:51	1:35	0.000528	DB REVAMPING,LT BUSHING REPLACEMENT
1620	29-10-2025	Part of : SECTOR 22 DWARKA,	49	Other Outage	Planned Outage	29-10-2025	14:59	29-10-2025	16:51	1:52	0.000622	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1621	29-10-2025	Part of : SECTOR 22 DWARKA,	37	Other Outage	Planned Outage	29-10-2025	11:32	29-10-2025	14:06	2:34	0.000856	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1622	29-10-2025	Part of : BLOCK A MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,TAMILAR ENCLAVE VIJAY ENCLAVE MAHAVIR ENCLAVE,BLOCK A 1 VIJAY ENCLAVE MAHAVIR ENCLAVE,BLOCK B VIJAY ENCLAVE MAHAVIR ENCLAVE,BLOCK B 3 MAHAVIR ENCLAVE PART 1 MAHAVIR ENCLAVE,	3525	Other Outage	Planned Outage	29-10-2025	11:04	29-10-2025	13:56	2:52	0.000956	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEAINING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1623	29-10-2025	Part of : BLOCK R INDRA PARK PALEM KAILASHPURI MAIN PALAM.	687	Other Outage	Planned Outage	29-10-2025	11:35	29-10-2025	14:19	2:44	0.000911	LT AB SAGGING PER SPAN

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1624	29-10-2025	Part of : POCKET 10 SECTOR I DASRATHPURI,	366	Other Outage	Planned Outage	29-10-2025	11:20	29-10-2025	14:11	2:51	0.000950	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER ,OIL TOP UP IN TRANSFORMER ,SUB STATION CLEANING
1625	30-10-2025	Part of : MAHAVIR ENCLAVE PART 2	1064	Other Outage	Planned Outage	30-10-2025	11:04	30-10-2025	13:00	1:56	0.000644	DB REVAMPING,LT BUSHING REPLACEMENT
1626	30-10-2025	Part of : SECTOR 23 DWARKA	29	Other Outage	Planned Outage	30-10-2025	12:58	30-10-2025	15:52	2:54	0.000967	GUARD WIRES SAGGING PER SPAN
1627	30-10-2025	Part of : BLOCK J & G SAGARPUR WEST SAGARPUR	645	Other Outage	Planned Outage	30-10-2025	11:49	30-10-2025	14:39	2:50	0.000944	DB REVAMPING,HT BUSHING ROD REPLACEMENT
1628	30-10-2025	Part of : BLOCK C VINODPURI VIJAY ENCLAVE MAHAVIR ENCLAVE	650	Other Outage	Planned Outage	30-10-2025	12:00	30-10-2025	12:28	0:28	0.000156	APPLY OF INSULATION TAPE HT/LT BUSHINGS
1629	30-10-2025	Part of : BLOCK C MAHAVIR ENCLAVE PART 1	1485	Other Outage	Planned Outage	30-10-2025	14:26	30-10-2025	15:35	1:09	0.000383	LT AB SAGGING PER SPAN
1630	30-10-2025	Part of : BLOCK C PALAM EXTENSION PALAM	840	Other Outage	Planned Outage	30-10-2025	11:15	30-10-2025	13:55	2:40	0.000889	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),INSTALLATION OF BUS BAR,INSTALLATION OF HT BOOTS
1631	30-10-2025	Part of : BLOCK D RAJ NAGAR 1	910	Other Outage	Planned Outage	30-10-2025	11:01	30-10-2025	13:54	2:53	0.000961	LT AB SAGGING PER SPAN
1632	30-10-2025	Part of : SECTOR 22 DWARKA	53	Other Outage	Planned Outage	30-10-2025	11:34	30-10-2025	14:26	2:52	0.000956	APPLY OF INSULATION TAPE HT/LT BUSHINGS,GENERAL SURFACE CLEANING OF HT/LT BUSHINGS (DRY DT),OIL TOP UP IN TRANSFORMER
1633	31-10-2025	Part of : KAILASHPURI MAIN & WEST PALAM,INDIRA PARK EXTENSION	2044	Other Outage	Planned Outage	31-10-2025	10:44	31-10-2025	12:37	1:53	0.000628	DB REVAMPING,HT BUSHING ROD REPLACEMENT
1634	31-10-2025	Part of : B-BLOCK SECTOR 8 DWARKA	193	Other Outage	Planned Outage	31-10-2025	11:25	31-10-2025	16:32	5:07	0.001706	HT CONDUCTOR REPLACEMET
1635	31-10-2025	Part of : TAMILAR ENCLAVE VIJAY ENCLAVE MAHAVIR ENCLAVE	356	Other Outage	Planned Outage	31-10-2025	11:38	31-10-2025	15:28	3:50	0.001278	RMU REPLACEMENT INCLUDING MAKE OF END TERMINATION
1636	31-10-2025	Part of : POCKET 1 SECTOR 22 DWARKA	203	Other Outage	Planned Outage	31-10-2025	13:40	31-10-2025	15:08	1:28	0.000489	LT AB MAINTENANCE WORK
1637	31-10-2025	Part of : POCKET 1 SECTOR 22 DWARKA	220	Other Outage	Planned Outage	31-10-2025	11:41	31-10-2025	13:02	1:21	0.000450	LT AB MAINTENANCE WORK
1638	31-10-2025	Part of : NASEERPUR POCKET 10	1545	Other Outage	Planned Outage	31-10-2025	12:48	31-10-2025	14:53	2:05	0.000694	LT AB MAINTENANCE WORK
1639	31-10-2025	Part of : MIRZAPUR MAHAVIR ENCLAVE	1278	Other Outage	Planned Outage	31-10-2025	11:50	31-10-2025	14:37	2:47	0.000928	LT AB MAINTENANCE WORK
1640	31-10-2025	Part of : B 3-BLOCK MAHAVIR ENCLAVE PART 1	1148	Other Outage	Planned Outage	31-10-2025	11:38	31-10-2025	14:14	2:36	0.000867	LT AB MAINTENANCE WORK
1641	02-10-2025	Part of : BLOCK WZ KESHAVPUR VEGETABLE MARKET CHAUKHANDI VISHNU GARDEN	512	Other Outage	Unplanned Outage	02-10-2025	22:34	02-10-2025	23:28	0:54	0.001485	HT SYSTEM FAULT
1642	03-10-2025	Part of : WZ-BLOCK KESHAVPUR VEGETABLE MARKET CHAUKHANDI VISHNU GARDEN	512	Other Outage	Unplanned Outage	03-10-2025	01:14	03-10-2025	02:10	0:56	0.001789	CABLE FAULT
1643	03-10-2025	Part of : BLOCK 16 TILAK NAGAR	248	Other Outage	Planned Outage	03-10-2025	11:04	03-10-2025	14:03	2:59	0.000497	REPLACEMENT OF HT BUSHING INSULATOR
1644	04-10-2025	Part of : SHIVAJI ENCLAVE TAGORE GARDEN EXTENSION	283	Other Outage	Planned Outage	04-10-2025	11:33	04-10-2025	15:05	3:32	0.000883	REPLACEMET OF HT BUSHING ROD
1645	04-10-2025	Part of : BLOCK 18 TILAK NAGAR	156	Other Outage	Planned Outage	04-10-2025	11:16	04-10-2025	14:13	2:57	0.000492	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1646	04-10-2025	Part of : BLOCK WZ MUKERJI PARK CHAUKHANDI VISHNU GARDEN	908	Other Outage	Planned Outage	04-10-2025	11:35	04-10-2025	15:04	3:29	0.000000	3PH DB REPLACEMENT
1647	04-10-2025	Part of : BLOCK R JANTA COLONY TAGORE GARDEN EXTENSION	797	Other Outage	Planned Outage	04-10-2025	11:12	04-10-2025	14:12	3:00	0.000000	3PH DB REPLACEMENT
1648	04-10-2025	Part of : CHAUKHANDI VISHNU GARDEN	591	Other Outage	Planned Outage	04-10-2025	10:01	04-10-2025	13:02	3:01	0.000000	CONDUCTOR REPLACEMENT PER SPAN
1649	05-10-2025	Part of : SHIVAJI ENCLAVE TAGORE GARDEN EXTENSION,	283	Other Outage	Planned Outage	05-10-2025	11:23	05-10-2025	14:33	3:10	0.000792	REPLACEMET OF LUGS
1650	06-10-2025	Part of : BLOCK N RAGHUBIR NAGAR TAGORE GARDEN EXTENSION	528	Other Outage	Planned Outage	06-10-2025	10:17	06-10-2025	13:28	3:11	0.000000	3PH DB REPLACEMENT
1651	07-10-2025	Part of : CHAUKHANDI VISHNU GARDEN	2992	Other Outage	Unplanned Outage	07-10-2025	17:14	07-10-2025	18:03	0:49	0.000735	CABLE FAULT
1652	07-10-2025	Part of : BLOCK 6 TILAK NAGAR	256	Other Outage	Planned Outage	07-10-2025	11:04	07-10-2025	13:59	2:55	0.000486	REPLACEMENT OF HT BUSHING INULATOR
1653	07-10-2025	Part of : S-BLOCK KHAYALA VISHNU GARDEN	386	Other Outage	Planned Outage	07-10-2025	12:54	07-10-2025	15:52	2:58	0.000000	LT AB SAGGING
1654	08-10-2025	Part of : BLOCK EF JANTA COLONY TAGORE GARDEN EXTENSION	246	Other Outage	Planned Outage	08-10-2025	10:40	08-10-2025	13:40	3:00	0.002100	REPLACEMET OF HT BUSHING ROD
1655	08-10-2025	Part of : BLOCK WZ MUKERJI PARK CHAUKHANDI VISHNU GARDEN	908	Other Outage	Planned Outage	08-10-2025	11:01	08-10-2025	12:45	1:44	0.000000	3PH DB REPLACEMENT
1656	08-10-2025	Part of : MUKHERJI PARK CHAUKHANDI VISHNU GARDEN	423	Other Outage	Planned Outage	08-10-2025	10:21	08-10-2025	13:39	3:18	0.000000	3PH DB REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1657	09-10-2025	Part of : BLOCK EF JANTA COLONY TAGORE GARDEN EXTENSION,BLOCK M RAGHUBIR NAGAR TAGORE GARDEN EXTENSION,BLOCK FD JANTA COLONY TAGORE GARDEN EXTENSION,BLOCK G JANTA COLONY TAGORE GARDEN EXTENSION,BLOCK A JANTA COLONY TAGORE GARDEN EXTENSION,	5535	Other Outage	Unplanned Outage	09-10-2025	13:47	09-10-2025	14:23	0:36	0.000150	LAYING OF NEW U/G CABLE
1658	09-10-2025	Part of : VIKASHपुरI EXTENSION TILAK NAGAR,	285	Other Outage	Planned Outage	09-10-2025	11:05	09-10-2025	14:07	3:02	0.000506	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMET OF HT BUSHING ROD
1659	09-10-2025	Part of : BLOCK FD JANTA COLONY TAGORE GARDEN EXTENSION,	139	Other Outage	Planned Outage	09-10-2025	12:36	09-10-2025	13:46	1:10	0.000000	GUARD WIRE LACS INSTALTION PER SPAN,GUARD WIRES SAGGING PER SPAN
1660	09-10-2025	Part of : BLOCK R JANTA COLONY TAGORE GARDEN EXTENSION,	796	Other Outage	Planned Outage	09-10-2025	10:28	09-10-2025	13:32	3:04	0.000511	CONDUCTOR REPLACEMENT PER SPAN
1661	10-10-2025	Part of : BLOCK EA & EC VISHAL ENCLAVE TAGORE GARDEN EXTENSION	1871	Other Outage	Unplanned Outage	10-10-2025	10:22	10-10-2025	11:58	1:36	0.000533	SHIFTING OF CABLE
1662	10-10-2025	Part of : BLOCK WZ MUKERJI PARK CHAUKHANDI VISHNU GARDEN	908	Other Outage	Planned Outage	10-10-2025	12:58	10-10-2025	16:06	3:08	0.000522	OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1663	10-10-2025	Part of : BLOCK N SHAM NAGAR VISHNU GARDEN	1409	Other Outage	Planned Outage	10-10-2025	10:17	10-10-2025	13:34	3:17	0.000547	REPLACEMET OF HT BUSHING ROD
1664	10-10-2025	Part of : CHAUKHANDI VISHNU GARDEN	592	Other Outage	Planned Outage	10-10-2025	09:57	10-10-2025	13:11	3:14	0.000000	LT INSTALLATION OF PHASE SEPERATOR PER SPAN,JUMPER REPLACEMENT PER POLE,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1665	11-10-2025	Part of : WZ-BLOCK MBS NAGAR CHAUKHANDI VISHNU GARDEN	1291	Other Outage	Planned Outage	11-10-2025	10:40	11-10-2025	14:31	3:51	0.001283	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF HT BUSHING ROD
1666	11-10-2025	Part of : N-BLOCK RAGHUBIR NAGAR TAGORE GARDEN EXTENSION	528	Other Outage	Planned Outage	11-10-2025	10:40	11-10-2025	14:31	3:51	0.000642	3PH DB REVAMPING
1667	13-10-2025	Part of : CHAUKHANDI VISHNU GARDEN	2604	Other Outage	Unplanned Outage	13-10-2025	19:38	13-10-2025	20:27	0:49	0.001034	HT SYSTEM FAULT
1668	13-10-2025	Part of : BLOCK S4 MAHAVIR NAGAR NEW TILAK NAGAR,	640	Other Outage	Planned Outage	13-10-2025	13:19	13-10-2025	16:22	3:03	0.000508	REPLACEMET OF HT BUSHING ROD
1669	13-10-2025	Part of : BLOCK J SHAM NAGAR VISHNU GARDEN,	351	Other Outage	Planned Outage	13-10-2025	12:09	13-10-2025	14:55	2:46	0.000461	REPLACEMET OF HT BUSHING ROD
1670	13-10-2025	Part of : BLOCK C GANESH NAGAR TILAK NAGAR,	822	Other Outage	Planned Outage	13-10-2025	10:58	13-10-2025	14:05	3:07	0.001039	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1671	14-10-2025	Part of : BLOCK 1, 16 & 24 TILAK NAGAR,BLOCK 17 CENTRAL MARKET TILAK NAGAR,	2857	Other Outage	Unplanned Outage	14-10-2025	11:35	14-10-2025	13:09	1:34	0.000261	REPLACEMENT OF CONDUCTOR
1672	14-10-2025	Part of : BLOCK S4 MAHAVIR NAGAR NEW TILAK NAGAR	721	Other Outage	Planned Outage	14-10-2025	10:58	14-10-2025	13:57	2:59	0.000497	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1673	14-10-2025	Part of : BLOCK EA VISHAL ENCLAVE TAGORE GARDEN EXTENSION	425	Other Outage	Planned Outage	14-10-2025	10:57	14-10-2025	13:34	2:37	0.001526	REPLACEMENT OF LT BUSHING ROD
1674	14-10-2025	Part of : BLOCK S KHAYALA VISHNU GARDEN	1837	Other Outage	Planned Outage	14-10-2025	11:45	14-10-2025	14:58	3:13	0.000536	3PH DB REVAMPING,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1675	15-10-2025	Part of : BLOCK 6,7,8,9,4A,4B, & 5A TILAK NAGAR	1586	Other Outage	Planned Outage	15-10-2025	11:06	15-10-2025	13:53	2:47	0.000000	REPLACEMENT OF HT BUSHING ROD
1676	16-10-2025	Part of : BLOCK B GANESH NAGAR TILAK NAGAR	1098	Other Outage	Planned Outage	16-10-2025	10:51	16-10-2025	13:49	2:58	0.000494	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1677	16-10-2025	Part of : MUKHERJI PARK CHAUKHANDI VISHNU GARDEN	423	Other Outage	Planned Outage	16-10-2025	10:15	16-10-2025	13:08	2:53	0.000481	REPLACEMET OF HT BUSHING ROD
1678	17-10-2025	Part of : BLOCK EC VISHAL ENCLAVE TAGORE GARDEN EXTENSION,BLOCK EA VISHAL ENCLAVE TAGORE GARDEN EXTENSION	1871	Other Outage	Unplanned Outage	17-10-2025	05:44	17-10-2025	06:35	0:51	0.000000	BIRDAGE
1679	17-10-2025	Part of : BLOCK EC VISHAL ENCLAVE TAGORE GARDEN EXTENSION,BLOCK EA VISHAL ENCLAVE TAGORE GARDEN EXTENSION,	1871	Other Outage	Unplanned Outage	17-10-2025	12:27	17-10-2025	12:29	0:02	0.000008	REPAIRING OF HT O/H CIRCUIT
1680	17-10-2025	Part of : BLOCK R JANTA COLONY TAGORE GARDEN EXTENSION,	1349	Other Outage	Planned Outage	17-10-2025	11:03	17-10-2025	14:22	3:19	0.000553	INSTALLATION OF PHASE SEPERATOR PER SPAN,LT AB SAGGING PER SPAN,OD END BOX INSTALLATION ON ACB END AND POLE END PER XLPE CABLE
1681	17-10-2025	Part of : BLOCK B 2 RAGHUBIR NAGAR TAGORE GARDEN EXTENSION,	957	Other Outage	Planned Outage	17-10-2025	11:07	17-10-2025	14:21	3:14	0.000539	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMET OF HT BUSHING ROD
1682	17-10-2025	Part of : BLOCK 7 TILAK NAGAR,	559	Other Outage	Planned Outage	17-10-2025	10:48	17-10-2025	14:17	3:29	0.001161	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD
1683	24-10-2025	Part of : BLOCK EA VISHAL ENCLAVE TAGORE GARDEN EXTENSION	1323	Other Outage	Planned Outage	24-10-2025	10:56	24-10-2025	14:05	3:09	0.001313	REPLACEMENT OF HT BUSHING ROD
1684	24-10-2025	Part of : KRISHNA PARK EXTENSION TILAK NAGAR	873	Other Outage	Planned Outage	24-10-2025	10:48	24-10-2025	13:56	3:08	0.001044	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1685	24-10-2025	Part of : BLOCK S KHAYALA VISHNU GARDEN	1411	Other Outage	Planned Outage	24-10-2025	13:50	24-10-2025	16:37	2:47	0.000000	CONDUCTOR REPLACEMENT PER SPAN,EARTHING VALUE OF POLE EARTHING USING ONLINE TESTER,FERRULE PUNCHING LT AB TO LT AB PER FEEDER ,INSTALLATION OF PHASE SEPERATOR PER SPAN,INSULATOR REPLACEMENT PER POLE,LT AB SAGGING PER SPAN
1686	24-10-2025	Part of : MUKHERJI PARK CHAUKHANDI VISHNU GARDEN	423	Other Outage	Planned Outage	24-10-2025	10:13	24-10-2025	13:19	3:06	0.000000	AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,CONDUCTOR REPLACEMENT PER SPAN
1687	25-10-2025	Part of : BLOCK 13 TILAK NAGAR,	504	Other Outage	Planned Outage	25-10-2025	10:48	25-10-2025	13:59	3:11	0.000531	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1688	25-10-2025	Part of : BLOCK B 2 RAGHUBIR NAGAR TAGORE GARDEN EXTENSION,	35	Other Outage	Planned Outage	25-10-2025	11:01	25-10-2025	14:02	3:01	0.000503	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1689	25-10-2025	Part of : BLOCK N SHAM NAGAR VISHNU GARDEN,	1398	Other Outage	Planned Outage	25-10-2025	10:09	25-10-2025	13:33	3:24	0.000567	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMENT OF LT BUSHING ROD
1690	25-10-2025	Part of : POCKET A SHAM NAGAR VISHNU GARDEN,	823	Other Outage	Planned Outage	25-10-2025	11:03	25-10-2025	14:05	3:02	0.000000	3PH DB REVAMPING,AL LUGS PUCHING ON LT XLPE TO LT AB PER FEEDER ,LT AB SAGGING PER SPAN
1691	26-10-2025	Part of : BLOCK WZ MUKERJI PARK CHAUKHANDI VISHNU GARDEN	909	Other Outage	Planned Outage	26-10-2025	11:04	26-10-2025	12:35	1:31	0.000000	CONDUCTOR REPLACEMENT PER SPAN
1692	27-10-2025	Part of : EA & EC-BLOCK VISHAL ENCLAVE TAGORE GARDEN EXTENSION	1871	Other Outage	Unplanned Outage	27-10-2025	18:11	27-10-2025	18:58	0:47	0.000744	CABLE FAULT
1693	27-10-2025	Part of : NEW CHAUKHANDI VISHNU GARDEN,SANT NAGAR	2198	Other Outage	Unplanned Outage	27-10-2025	09:58	27-10-2025	10:48	0:50	0.000861	CABLE FAULT
1694	29-10-2025	Part of : CHAND NAGAR VISHNU GARDEN,	2542	Other Outage	Planned Outage	29-10-2025	10:54	29-10-2025	13:55	3:01	0.000503	REPLACEMET OF HT BUSHING ROD,TIGHTENEING OF NUT BOLT
1695	29-10-2025	Part of : BLOCK P RAGHUBIR NAGAR TAGORE GARDEN EXTENSION,	877	Other Outage	Planned Outage	29-10-2025	10:54	29-10-2025	13:49	2:55	0.000486	REPLACEMENT OF HT BUSHING INULATOR,REPLACEMENT OF LT BUSHING ROD
1696	29-10-2025	Part of : BLOCK WZ MBS NAGAR CHAUKHANDI VISHNU GARDEN,	1442	Other Outage	Planned Outage	29-10-2025	11:00	29-10-2025	13:37	2:37	0.000436	REPLACEMENT OF LT BUSHING INSULATOR,REPLACEMET OF HT BUSHING ROD
1697	30-10-2025	Part of : BLOCK BA, EA, FB & D TAGORE GARDEN TAGORE GARDEN EXTENSION	2267	Other Outage	Unplanned Outage	30-10-2025	14:52	30-10-2025	15:06	0:14	0.000078	REPAIRING OF DEFECTIVE MECHANISM
1698	30-10-2025	Part of : SHIVAJI ENCLAVE TAGORE GARDEN EXTENSION,BLOCK A, EA & EC VISHAL ENCLAVE TAGORE GARDEN EXTENSION	1139	Other Outage	Unplanned Outage	30-10-2025	15:06	30-10-2025	16:24	1:18	0.000325	REPAIRING OF DEFECTIVE MECHANISM
1699	31-10-2025	Part of : WZ-BLOCK SHAHPURA CHAUKHANDI VISHNU GARDEN	2702	Other Outage	Planned Outage	31-10-2025	11:09	31-10-2025	14:20	3:11	0.001061	REPLACEMET OF HT BUSHING ROD
1700	31-10-2025	Part of : G-BLOCK JANTA COLONY TAGORE GARDEN EXTENSION	889	Other Outage	Planned Outage	31-10-2025	11:34	31-10-2025	14:06	2:32	0.000422	REPLACEMET OF HT BUSHING ROD
1701	02-10-2025	Part of : GULABHI BAGH OM VIHAR UTTAM NAGAR	2486	Other Outage	Unplanned Outage	02-10-2025	18:11	02-10-2025	19:04	0:53	0.000000	HT SYSTEM FAULT
1702	03-10-2025	Part of : SANTOSH PARK UTTAM NAGAR	1927	Other Outage	Unplanned Outage	03-10-2025	02:35	03-10-2025	03:13	0:38	0.001077	CABLE FAULT
1703	03-10-2025	Part of : BLOCK A & H SITAPURI PART 2	658	Other Outage	Planned Outage	03-10-2025	12:23	03-10-2025	15:15	2:52	0.000000	3PH HT AB CABLE REPLACEMENT
1704	03-10-2025	Part of : BLOCK A KIRAN GARDENS UTTAM NAGAR	2393	Other Outage	Planned Outage	03-10-2025	12:22	03-10-2025	15:07	2:45	0.000000	MOBILE TRANSFORMER INSTALLATION FOR PLINT REPLACEMET
1705	03-10-2025	Part of : BHAGAT ENCLAVE BINDAPUR	993	Other Outage	Planned Outage	03-10-2025	12:04	03-10-2025	15:44	3:40	0.000000	LT CIRCUIT REPLACEMENT
1706	03-10-2025	Part of : BLOCK E UTTAM VIHAR BINDAPUR	584	Other Outage	Planned Outage	03-10-2025	12:16	03-10-2025	15:05	2:49	0.000000	LT CIRCUIT REPLACEMENT
1707	03-10-2025	Part of : BLOCK E UTTAM VIHAR BINDAPUR	331	Other Outage	Planned Outage	03-10-2025	11:07	03-10-2025	15:06	3:59	0.000000	LT CIRCUIT REPLACEMENT
1708	04-10-2025	Part of : UTTAM NAGAR SHOE MARKET, BLOCK D MILAP NAGAR UTTAM NAGAR, BLOCK E PARAM PURI UTTAM NAGAR	660	Other Outage	Unplanned Outage	04-10-2025	08:20	04-10-2025	09:09	0:49	0.000177	CABLE FAULT
1709	04-10-2025	Part of : UTTAM VIHAR BINDAPUR	1421	Other Outage	Planned Outage	04-10-2025	13:38	04-10-2025	15:53	2:15	0.000000	DT REPLACEMENT
1710	04-10-2025	Part of : BLOCK C UTTAM VIHAR BINDAPUR	1149	Other Outage	Planned Outage	04-10-2025	13:38	04-10-2025	15:53	2:15	0.000000	DT REPLACEMENT
1711	04-10-2025	Part of : BHAGWATI VIHAR BINDAPUR	1959	Other Outage	Planned Outage	04-10-2025	10:52	04-10-2025	13:56	3:04	0.000000	REPLACEMET OF HT BUSHING ROD
1712	06-10-2025	Part of : BLOCK E PARAM PURI UTTAM NAGAR	729	Other Outage	Planned Outage	06-10-2025	16:47	06-10-2025	17:27	0:40	0.000000	DT REPLACEMENT
1713	06-10-2025	Part of : BLOCK C MILAP NAGAR UTTAM NAGAR	406	Other Outage	Planned Outage	06-10-2025	11:18	06-10-2025	15:46	4:28	0.000000	MOBILE TRANSFORMER INSTALLATION FOR PLINT REPLACEMET
1714	06-10-2025	Part of : BLOCK A3 UTTAM VIHAR BINDAPUR	436	Other Outage	Planned Outage	06-10-2025	11:15	06-10-2025	14:58	3:43	0.000000	DT REPLACEMENT
1715	08-10-2025	Part of : BLOCK A,B & H SITAPURI PART 2, ANUP NAGAR ADARSH NAGAR BINDAPUR	1671	Other Outage	Unplanned Outage	08-10-2025	13:01	08-10-2025	14:03	1:02	0.000517	TO CHECK PROTECTION CIRCUIT
1716	08-10-2025	Part of : SANTOSH PARK UTTAM NAGAR	1580	Other Outage	Unplanned Outage	08-10-2025	10:56	08-10-2025	12:07	1:11	0.000000	REPAIRING OF FEEDER PILLAR
1717	08-10-2025	Part of : INDIRA PARK BINDAPUR	2427	Other Outage	Planned Outage	08-10-2025	11:31	08-10-2025	14:53	3:22	0.000000	DT REPLACEMENT
1718	08-10-2025	Part of : BHAGWATI VIHAR BINDAPUR	2437	Other Outage	Planned Outage	08-10-2025	12:12	08-10-2025	14:50	2:38	0.000000	DT REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1719	08-10-2025	Part of : MANAS KUNJ NEW UTTAM NAGAR	618	Other Outage	Planned Outage	08-10-2025	11:56	08-10-2025	16:16	4:20	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1720	08-10-2025	Part of : BHAGAT ENCLAVE BINDAPUR	981	Other Outage	Planned Outage	08-10-2025	11:12	08-10-2025	14:45	3:33	0.000000	DT REPLACEMENT
1721	09-10-2025	Part of : INDIRA PARK BINDAPUR,BLOCK F JEEVAN PARK BINDAPUR	3929	Other Outage	Unplanned Outage	09-10-2025	22:27	09-10-2025	23:06	0:39	0.000271	TRANSIENT FAULT
1722	09-10-2025	Part of : UTTAM VIHAR BINDAPUR,	2401	Other Outage	Planned Outage	09-10-2025	15:33	09-10-2025	15:52	0:19	0.000000	DT REPLACEMENT
1723	09-10-2025	Part of : UTTAM VIHAR BINDAPUR,	985	Other Outage	Planned Outage	09-10-2025	11:05	09-10-2025	15:34	4:29	0.000000	DT REPLACEMENT
1724	09-10-2025	Part of : BLOCK T PARAM PURI UTTAM NAGAR,	1304	Other Outage	Planned Outage	09-10-2025	12:30	09-10-2025	15:48	3:18	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1725	11-10-2025	Part of : BHAGAT ENCLAVE BINDAPUR	993	Other Outage	Planned Outage	11-10-2025	13:38	11-10-2025	15:49	2:11	0.000000	DT REPLACEMENT
1726	13-10-2025	Part of : BLOCK C UTTAM VIHAR BINDAPUR,	2392	Other Outage	Planned Outage	13-10-2025	14:57	13-10-2025	17:47	2:50	0.000000	DT REPLACEMENT
1727	13-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR,	744	Other Outage	Planned Outage	13-10-2025	14:58	13-10-2025	17:47	2:49	0.000000	DT REPLACEMENT
1728	13-10-2025	Part of : BLOCK D2 MILAP NAGAR UTTAM NAGAR,	1004	Other Outage	Planned Outage	13-10-2025	12:47	13-10-2025	17:06	4:19	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1729	13-10-2025	Part of : OLD JANKI PURI BINDAPUR,	550	Other Outage	Planned Outage	13-10-2025	12:51	13-10-2025	15:05	2:14	0.000000	DT REPLACEMENT
1730	14-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR	1225	Other Outage	Planned Outage	14-10-2025	12:13	14-10-2025	14:44	2:31	0.000000	DT REPLACEMENT
1731	14-10-2025	Part of : BLOCK C UTTAM VIHAR BINDAPUR	1	Other Outage	Planned Outage	14-10-2025	12:12	14-10-2025	14:43	2:31	0.000000	DT REPLACEMENT
1732	14-10-2025	Part of : OLD JANKI PURI BINDAPUR	635	Other Outage	Planned Outage	14-10-2025	11:47	14-10-2025	13:53	2:06	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1733	14-10-2025	Part of : BLOCK E SITAPURI PART 2	388	Other Outage	Planned Outage	14-10-2025	11:27	14-10-2025	13:09	1:42	0.000000	DT REPLACEMENT
1734	15-10-2025	Part of : OLD JANKI PURI BINDAPUR	1275	Other Outage	Planned Outage	15-10-2025	12:10	15-10-2025	13:55	1:45	0.000000	DT REPLACEMENT
1735	15-10-2025	Part of : E-BLOCK PARAM PURI UTTAM NAGAR	818	Other Outage	Planned Outage	15-10-2025	11:34	15-10-2025	13:56	2:22	0.000000	DT REPLACEMENT
1736	15-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR	471	Other Outage	Planned Outage	15-10-2025	10:42	15-10-2025	13:51	3:09	0.000000	LT CIRCUIT MAINTENANCE WORK
1737	15-10-2025	Part of : MAHAVIR ENCLAVE PART-3	1205	Other Outage	Planned Outage	15-10-2025	11:14	15-10-2025	13:54	2:40	0.000000	LT CIRCUIT MAINTENANCE WORK
1738	16-10-2025	Part of : BHAGWATI VIHAR BINDAPUR	2429	Other Outage	Planned Outage	16-10-2025	11:36	16-10-2025	13:31	1:55	0.000000	DT REPLACEMENT
1739	16-10-2025	Part of : BLOCK A UTTAM VIHAR BINDAPUR	446	Other Outage	Planned Outage	16-10-2025	12:07	16-10-2025	15:01	2:54	0.000000	DT REPLACEMENT
1740	17-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR,BLOCK A SITAPURI PART 2 SITAPURI,MAHAVIR ENCLAVE PART 3 MAHAVIR ENCLAVE	3258	Other Outage	Unplanned Outage	17-10-2025	02:38	17-10-2025	03:12	0:34	0.000359	HVDS FAULT
1741	17-10-2025	Part of : SANTOSH PARK UTTAM NAGAR,	1395	Other Outage	Planned Outage	17-10-2025	12:15	17-10-2025	14:30	2:15	0.000000	DT REPLACEMENT
1742	17-10-2025	Part of : BLOCK C MAHINDRA PARK BINDAPUR,	793	Other Outage	Planned Outage	17-10-2025	11:31	17-10-2025	13:36	2:05	0.000000	DT REPLACEMENT
1743	18-10-2025	Part of : BLOCK K PARAM PURI UTTAM NAGAR	1205	Other Outage	Planned Outage	18-10-2025	12:16	18-10-2025	14:50	2:34	0.000000	DT REPLACEMENT
1744	18-10-2025	Part of : BLOCK A & H SITAPURI PART 2,ANUP NAGAR ADARSH NAGAR BINDAPUR	674	Other Outage	Planned Outage	18-10-2025	11:24	18-10-2025	13:38	2:14	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1745	21-10-2025	Part of : BLOCK A 3 HARIAN COLONY SITAPURI PART 1 SITAPURI,	1130	Other Outage	Planned Outage	21-10-2025	11:03	21-10-2025	13:48	2:45	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1746	24-10-2025	Part of : MAHAVIR ENCLAVE PART 3,ANUP NAGAR ADARSH NAGAR BINDAPUR	1475	Other Outage	Unplanned Outage	24-10-2025	13:35	24-10-2025	15:02	1:27	0.000363	LOAD SHIFTING FROM HVDS TRANSFORMER
1747	24-10-2025	Part of : OLD JANKI PURI BINDAPUR	637	Other Outage	Planned Outage	24-10-2025	12:07	24-10-2025	13:42	1:35	0.000000	DT REPLACEMENT
1748	24-10-2025	Part of : UTTAM VIHAR BINDAPUR	2417	Other Outage	Planned Outage	24-10-2025	11:58	24-10-2025	13:43	1:45	0.000000	DT REPLACEMENT
1749	24-10-2025	Part of : BLOCK D JJ COLONY UTTAM NAGAR	176	Other Outage	Planned Outage	24-10-2025	11:30	24-10-2025	13:36	2:06	0.000000	DT REPLACEMENT
1750	24-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR	1282	Other Outage	Planned Outage	24-10-2025	11:37	24-10-2025	13:41	2:04	0.000000	DT REPLACEMENT
1751	25-10-2025	Part of : BLOCK B SITAPURI PART 2 SITAPURI,BLOCK H SITAPURI PART 2 SITAPURI,BLOCK A SITAPURI PART 2 SITAPURI,BLOCK E SITAPURI PART 2 SITAPURI,	997	Other Outage	Planned Outage	25-10-2025	11:37	25-10-2025	13:51	2:14	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1752	25-10-2025	Part of : BLOCK E UTTAM VIHAR BINDAPUR,	782	Other Outage	Planned Outage	25-10-2025	10:33	25-10-2025	13:53	3:20	0.000000	DT REPLACEMENT
1753	25-10-2025	Part of : BHAGAT ENCLAVE BINDAPUR,	996	Other Outage	Planned Outage	25-10-2025	11:36	25-10-2025	13:56	2:20	0.000000	DT REPLACEMENT
1754	27-10-2025	Part of : F-BLOCK JEEVAN PARK,OLD JANKI PURI & C-BLOCK MAHINDRA PARK BINDAPUR	5333	Other Outage	Unplanned Outage	27-10-2025	05:20	27-10-2025	05:55	0:35	0.000360	BIRDAGE
1755	28-10-2025	Part of : BHAGWATI VIHAR BINDAPUR	2431	Other Outage	Planned Outage	28-10-2025	11:15	28-10-2025	13:37	2:22	0.000000	DT REPLACEMENT
1756	29-10-2025	Part of : BLOCK C MAHINDRA PARK BINDAPUR,	804	Other Outage	Planned Outage	29-10-2025	12:21	29-10-2025	13:33	1:12	0.000000	DT REPLACEMENT
1757	29-10-2025	Part of : BLOCK F UTTAM VIHAR BINDAPUR,	2833	Other Outage	Planned Outage	29-10-2025	11:12	29-10-2025	13:32	2:20	0.000000	DT REPLACEMENT
1758	30-10-2025	Part of : BLOCK E PARAM PURI UTTAM NAGAR	2413	Other Outage	Unplanned Outage	30-10-2025	12:55	30-10-2025	13:42	0:47	0.000653	CABLE FAULT
1759	30-10-2025	Part of : OLD JANKI PURI BINDAPUR	550	Other Outage	Planned Outage	30-10-2025	11:08	30-10-2025	13:19	2:11	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1760	31-10-2025	Part of : ANUP NAGAR ADARSH NAGAR BINDAPUR	995	Other Outage	Planned Outage	31-10-2025	11:05	31-10-2025	13:37	2:32	0.000000	DT REPLACEMENT
1761	31-10-2025	Part of : D-BLOCK JJ COLONY UTTAM NAGAR	1170	Other Outage	Planned Outage	31-10-2025	11:23	31-10-2025	13:35	2:12	0.000000	DT REPLACEMENT
1762	01-10-2025	Part of : HTC:KESHOPUR PLANT	0	Other Outage	Unplanned Outage	01-10-2025	12:44	01-10-2025	13:35	0:51	0.000028	TRANSIENT FAULT
1763	01-10-2025	Part of : BUDHELA VILLAGE VIKAS PURI,	961	Other Outage	Planned Outage	01-10-2025	11:17	01-10-2025	11:44	0:27	0.000000	DT REPLACEMENT

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1764	02-10-2025	Part of : A, C, D & E-BLOCK SHIV VIHAR JJ COLONY,GOVT SCHOOL	3594	Other Outage	Unplanned Outage	02-10-2025	20:35	02-10-2025	21:16	0:41	0.000820	CABLE FAULT
1765	04-10-2025	Part of : YADAV ENCLAVE AND VIKAS VIHAR	922	Other Outage	Planned Outage	04-10-2025	13:03	04-10-2025	15:54	2:51	0.000000	DT REPLACEMENT
1766	04-10-2025	Part of : KRISHNA COLONY HASTSAL VILLAGE	557	Other Outage	Planned Outage	04-10-2025	14:17	04-10-2025	15:02	0:45	0.000000	DT REPLACEMENT
1767	06-10-2025	Part of : VIKAS KUNJ AND VIKAS KUNJ EXTN.	1595	Other Outage	Planned Outage	06-10-2025	11:25	06-10-2025	15:44	4:19	0.000000	DT REPLACEMENT
1768	06-10-2025	Part of : JJ COLONY UTTAM NAGAR	0	Other Outage	Planned Outage	06-10-2025	11:24	06-10-2025	15:44	4:20	0.000000	DT REPLACEMENT
1769	06-10-2025	Part of : BLOCK GG2 VIKAS PURI	227	Other Outage	Planned Outage	06-10-2025	10:40	06-10-2025	14:22	3:42	0.000000	REPLACEMENT OF LT BUSHING ROD
1770	06-10-2025	Part of : BHIM ENCLAVE	1358	Other Outage	Planned Outage	06-10-2025	11:23	06-10-2025	15:43	4:20	0.000000	DT REPLACEMENT
1771	08-10-2025	Part of : BLOCK P MOHAN GARDEN RAZAPUR KHURD,BLOCK M ZAILDAR ENCLAVE HASTSAL,L1A AND L- BLOCK MOHAN GARDEN	2823	Other Outage	Planned Outage	08-10-2025	11:04	08-10-2025	14:52	3:48	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1772	08-10-2025	Part of : BLOCK A SHANKER GARDEN VIKAS PURI	277	Other Outage	Planned Outage	08-10-2025	10:21	08-10-2025	13:52	3:31	0.000000	REPLACEMENT OF LT BUSHING ROD
1773	10-10-2025	Part of : BLOCK M ZAILDAR ENCLAVE HASTSAL, PRESS ENCLAVE, L1A & L- BLOCK MOHAN GARDEN,BLOCK N 3 MOHAN GARDEN RAZAPUR KHURD	5975	Other Outage	Unplanned Outage	10-10-2025	09:37	10-10-2025	11:16	1:39	0.000000	ATTENDING WEAK POINTS/HOT SPOT
1774	10-10-2025	Part of : JJ COLONY UTTAM NAGAR	1760	Other Outage	Planned Outage	10-10-2025	11:29	10-10-2025	15:08	3:39	0.000000	LT DT REPLACEMENT
1775	10-10-2025	Part of : BLOCK M ZAILDAR ENCLAVE HASTSAL	2428	Other Outage	Planned Outage	10-10-2025	11:30	10-10-2025	15:05	3:35	0.000000	LT DT REPLACEMENT
1776	11-10-2025	Part of : BEHIND BODELLA-2 GRID AT PWD ROAD	0	Other Outage	Unplanned Outage	11-10-2025	11:40	11-10-2025	13:03	1:23	0.000000	FIXING OF COVER
1777	11-10-2025	Part of : YADAV ENCLAVE & VIKAS VIHAR,A&B BLOCK VIKAS VIHAR & SAI ENCLAVE,SURKAKHA ENCLAVE & M- BLOCK COMMONDER CHOWK,SAINIK ENCLAVE AND PANCHSHEEL ENCLAVE	1494	Other Outage	Planned Outage	11-10-2025	11:12	11-10-2025	13:44	2:32	0.000000	3PH HT AB CABLE REPLACEMENT
1778	11-10-2025	Part of : DG 1-BLOCK VIKAS PURI	270	Other Outage	Planned Outage	11-10-2025	10:07	11-10-2025	13:42	3:35	0.000000	LT CIRCUIT MAINTENANCE WORK
1779	12-10-2025	Part of : K-5 EXT.N. AND DEEPAK VIHAR, ZAILDAR ENCLAVE HASTSAL, MOHAN GARDEN RAZAPUR KHURD, DEFENCE ENCLAVE PART-1 MOHAN GARDEN	5977	Other Outage	Unplanned Outage	12-10-2025	09:56	12-10-2025	10:10	0:14	0.000004	BIRDAGE
1780	13-10-2025	Part of : SHIV VIHAR COLONY,	1783	Other Outage	Planned Outage	13-10-2025	11:58	13-10-2025	16:09	4:11	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1781	13-10-2025	Part of : BLOCK FG1 VIKAS PURI,	567	Other Outage	Planned Outage	13-10-2025	14:37	13-10-2025	17:46	3:09	0.000000	DT REPLACEMENT
1782	13-10-2025	Part of : SHIV VIHAR HASTSAL,	453	Other Outage	Planned Outage	13-10-2025	12:58	13-10-2025	17:05	4:07	0.000000	DT REPLACEMENT
1783	13-10-2025	Part of : POCKET C1 KRISHNA PARK VIKAS PURI,	194	Other Outage	Planned Outage	13-10-2025	10:41	13-10-2025	14:37	3:56	0.000000	DT REPLACEMENT
1784	14-10-2025	Part of : K5 & K6 AND DEFENCE ENCLAVE PART-1 MOHAN GARDEN,K-5 EXT.N. AND DEEPAK VIHAR,PRESS ENCLAVE,BLOCK N 3 MOHAN GARDEN RAZAPUR KHURD	1054	Other Outage	Unplanned Outage	14-10-2025	13:05	14-10-2025	13:59	0:54	0.000000	REPAIRING OF HVDS CIRCUIT
1785	14-10-2025	Part of : A,B&C-BLOCK MAHARANI ENCLAVE	87	Other Outage	Planned Outage	14-10-2025	11:23	14-10-2025	13:51	2:28	0.000000	3PH DB REVAMPING
1786	14-10-2025	Part of : JJ COLONY UTTAM NAGAR	608	Other Outage	Planned Outage	14-10-2025	10:47	14-10-2025	13:52	3:05	0.000000	DT REPLACEMENT
1787	14-10-2025	Part of : VIKAS KUNJ AND VIKAS KUNJ EXTN	2230	Other Outage	Planned Outage	14-10-2025	11:22	14-10-2025	13:46	2:24	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1788	14-10-2025	Part of : BUDHELA VILLAGE VIKAS PURI	785	Other Outage	Planned Outage	14-10-2025	10:26	14-10-2025	13:11	2:45	0.000000	DT REPLACEMENT
1789	15-10-2025	Part of : DEEPAK VIHAR,M-BLOCK ZAILDAR ENCLAVE,P,P2,L,L1,N2 & N3-BLOCK MOHAN GARDEN RAZAPUR KHURD,DEFENCE ENCLAVE PART-1,PRESS ENCLAVE	5981	Other Outage	Unplanned Outage	15-10-2025	15:31	15-10-2025	16:30	0:59	0.000000	REPAIR OF DEFECTIVE MECHANISM
1790	15-10-2025	Part of : F-BLOCK VIKAS NAGAR	1983	Other Outage	Unplanned Outage	15-10-2025	13:04	15-10-2025	14:07	1:03	0.000000	REPAIRING HVDS CIRCUIT
1791	15-10-2025	Part of : B-BLOCK JJ COLONY UTTAM NAGAR	935	Other Outage	Planned Outage	15-10-2025	14:14	15-10-2025	16:24	2:10	0.000000	LT CIRCUIT MAINTENANCE WORK
1792	15-10-2025	Part of : M-BLOCK ZAILDAR ENCLAVE HASTSAL	449	Other Outage	Planned Outage	15-10-2025	11:27	15-10-2025	13:50	2:23	0.000000	LT CIRCUIT MAINTENANCE WORK
1793	15-10-2025	Part of : KESHOPUR VILLAGE VIKAS PURI	523	Other Outage	Planned Outage	15-10-2025	10:38	15-10-2025	12:54	2:16	0.000000	LT CIRCUIT MAINTENANCE WORK
1794	16-10-2025	Part of : DEEPAK VIHAR,PRESS ENCLAVE,SURKAKHA ENCLAVE AND M- BLOCK COMMONDER CHOWK,VIKAS NAGAR EXT.N.	1694	Other Outage	Planned Outage	16-10-2025	12:11	16-10-2025	14:33	2:22	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1795	16-10-2025	Part of : BLOCK A 3 UTTAM NAGAR	1059	Other Outage	Planned Outage	16-10-2025	11:39	16-10-2025	13:30	1:51	0.000000	DT REPLACEMENT
1796	16-10-2025	Part of : BLOCK B VIKAS PURI	121	Other Outage	Planned Outage	16-10-2025	11:37	16-10-2025	13:29	1:52	0.000000	REPLACEMENT OF CROSS-ARMS AND POLES
1797	16-10-2025	Part of : BHIM ENCLAVE	1359	Other Outage	Planned Outage	16-10-2025	12:09	16-10-2025	14:59	2:50	0.000000	DT REPLACEMENT
1798	16-10-2025	Part of : BLOCK D DDA MARKET VIKAS PURI	321	Other Outage	Planned Outage	16-10-2025	10:29	16-10-2025	13:17	2:48	0.000000	DT REPLACEMENT
1799	17-10-2025	Part of : K5 & K6 AND DEFENCE ENCLAVE PART-1 MOHAN GARDEN,	1054	Other Outage	Unplanned Outage	17-10-2025	11:21	17-10-2025	13:07	1:46	0.000000	REPAIRING OF HVDS CABLE

Sr. No.	Date	Area Effected	No. of consumer affected	Capacity of DT	Wether Planned Outage or Unplanned Outage	Outage Detail						
						From		To		Duration	Unservd (MU) due to outage	Remarks
						Date	Time	Date	Time			
1800	17-10-2025	Part of : YADAV ENCLAVE AND VIKAS VIHAR,A&B BLOCK VIKAS VIHAR AND SAI ENCLAVCE,SURKAKHA ENCLAVE AND M- BLOCK COMMONDER CHOWK,SAINIK ENCLAVE AND PANCHSHEEL ENCLAVE,	1494	Other Outage	Planned Outage	17-10-2025	11:16	17-10-2025	13:11	1:55	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1801	17-10-2025	Part of : BLOCK GG2 VIKAS PURI,	263	Other Outage	Planned Outage	17-10-2025	11:06	17-10-2025	13:17	2:11	0.000000	DT REPLACEMENT
1802	18-10-2025	Part of : BLOCK M DISTRICT PARK VIKAS PURI	281	Other Outage	Planned Outage	18-10-2025	10:55	18-10-2025	13:38	2:43	0.000000	DT REPLACEMENT
1803	22-10-2025	Part of : AK MARKET VIKAS PURI	287	Other Outage	Planned Outage	22-10-2025	10:06	22-10-2025	12:45	2:39	0.000000	DT REPLACEMENT
1804	24-10-2025	Part of : SURKAKHA ENCLAVE, M- BLOCK COMMONDER CHOWK,SAINIK ENCLAVE,VIKRANT VIHAR	4593	Other Outage	Unplanned Outage	24-10-2025	17:05	24-10-2025	17:42	0:37	0.000051	HVDS FAULT
1805	24-10-2025	Part of : C&D BLOCK VIKAS NAGAR,SHIV VIHAR HASTSAL,VIKAS NAGAR EXTN,DEEPAK VIHAR	3108	Other Outage	Unplanned Outage	24-10-2025	00:38	24-10-2025	01:16	0:38	0.000296	HVDS FAULT
1806	24-10-2025	Part of : KRISHNA COLONY HASTSAL VILLAGE	185	Other Outage	Planned Outage	24-10-2025	10:54	24-10-2025	13:47	2:53	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1807	24-10-2025	Part of : BUDHELA VILLAGE VIKAS PURI	961	Other Outage	Planned Outage	24-10-2025	10:29	24-10-2025	12:33	2:04	0.000000	DT REPLACEMENT
1808	25-10-2025	Part of : HTC:KESHOPUR PLANT	0	Other Outage	Unplanned Outage	25-10-2025	20:32	25-10-2025	21:15	0:43	0.000000	CABLE FAULT
1809	25-10-2025	Part of : BLOCK H3 VIKAS PURI,BLOCK H KESHOPUR INDUSTRIAL AREA VIKAS PURI,BLOCK H2 VIKAS PURI,KESHOPUR VIKAS PURI,	1106	Other Outage	Unplanned Outage	25-10-2025	11:00	25-10-2025	11:24	0:24	0.000000	REPAIRING OF RMU
1810	25-10-2025	Part of : BLOCK H3 VIKAS PURI,BLOCK H KESHOPUR INDUSTRIAL AREA VIKAS PURI,BLOCK H2 VIKAS PURI,KESHOPUR VIKAS PURI,	1106	Other Outage	Unplanned Outage	25-10-2025	11:23	25-10-2025	12:29	1:06	0.000000	REPAIRING OF HT O/H CIRCUIT
1811	25-10-2025	Part of : BLOCK M DISTRICT PARK VIKAS PURI,	70	Other Outage	Planned Outage	25-10-2025	10:08	25-10-2025	12:54	2:46	0.000000	DT REPLACEMENT
1812	26-10-2025	Part of : BLOCK A 2 UTTAM NAGAR,KRISHNA COLONY HASTSAL VILLAGE HASTSAL,PHASE 2 OM VIHAR HASTSAL	3142	Other Outage	Unplanned Outage	26-10-2025	10:20	26-10-2025	11:14	0:54	0.000510	HVDS FAULT
1813	28-10-2025	Part of : PHASE 1 OM VIHAR NAWADA,PHASE 3 OM VIHAR HASTSAL,PHASE 4 OM VIHAR HASTSAL,HOSTAL VIHAR OM VIHAR	1287	Other Outage	Planned Outage	28-10-2025	11:20	28-10-2025	13:34	2:14	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1814	28-10-2025	Part of : BLOCK GG2 VIKAS PURI	174	Other Outage	Planned Outage	28-10-2025	10:13	28-10-2025	12:32	2:19	0.000000	DT REPLACEMENT
1815	29-10-2025	Part of : SAINIK ENCLAVE AND PANCHSHEEL ENCLAVE,VIKRANT VIHAR,A&B BLOCK VIKAS VIHAR AND SAI ENCLAVCE,SAINIK ENCLAVE,	3058	Other Outage	Planned Outage	29-10-2025	12:29	29-10-2025	14:31	2:02	0.000000	3PH HT AB CABLE REPLACEMENT PER SPAN
1816	29-10-2025	Part of : BLOCK DG 1 VIKAS PURI,	271	Other Outage	Planned Outage	29-10-2025	10:24	29-10-2025	12:49	2:25	0.000000	DT REPLACEMENT
1817	31-10-2025	Part of : P,P 2, N 1,L, L1A-BLOCK MOHAN GARDEN,SHIV VIHAR,LIG MIG FLATS,POCKET C HASTSAL,M-BLOCK ZAILDAR ENCLAVE	4737	Other Outage	Unplanned Outage	31-10-2025	10:05	31-10-2025	11:16	1:11	0.000000	FAULT IN RMU/MAINTENANCE/REPAIR OF RMU
1818	31-10-2025	Part of : HOSTAL VIHAR,OM VIHAR PHASE 2 HASTSAL	663	Other Outage	Planned Outage	31-10-2025	12:13	31-10-2025	14:37	2:24	0.000000	3PH HT AB CABLE REPLACEMENT
1819	31-10-2025	Part of : M-BLOCK ZAILDAR ENCLAVE HASTSAL,L1A, L2,L & ABC- BLOCK MOHAN GARDEN	2424	Other Outage	Planned Outage	31-10-2025	15:05	31-10-2025	16:16	1:11	0.000000	3PH HT AB CABLE REPLACEMENT
1820	31-10-2025	Part of : GG 2-BLOCK VIKAS PURI	537	Other Outage	Planned Outage	31-10-2025	10:23	31-10-2025	12:17	1:54	0.000000	LT AB MAINTENANCE WORK