

Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Apr’ 2026
Year: 2026

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI/AEI	Remedies suggested by CEI/EI/AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	Chandni Chowk: A "current on pole" complaint (260401100978) was at 18:44 hrs received from 4582, Cloth Market, Chandni Chowk, Delhi. As per complainant, an unidentified person was electrocuted while repairing a shop shed; however, no victim was found at site. NCC staff reached the site promptly. The team identified current leakage from an inverter through the internal wiring of Shop No. 4586. The matter was informed to and recorded in the presence of the IO, Delhi Police, P.S. Lahori Gate.	01.04.2026	Public (Fatal)	Based on site inspection, probable cause is consumer Internal wiring.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
2	A PCR complaint (26042200951) regarding current leakage was received from Gali No. 1, Khajani Nagar, Delhi-110094. Site inspection revealed that a sewer cleaning vehicle DL-1L Z1214 driven by Sh. Narender S/o Sh. Rampal, hit HT pole No. KWNZ808, causing it to tilt/fall onto the wall of House No. 40, Khajani Nagar, Delhi. Two ladies (approx. 22-30 years) suffered electric shock. Supply was restored by installing a new RCC pole with 25 kVA DT after police clearance.	22.04.2026	Public (Non-Fatal)	Probable cause is HT pole damage due to vehicle hit (DL-1L Z1214) leading to pole tilting.	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA

(Signature of the Licensee)