

<b>CORRIGENDUM 4</b>		Reply of bidder's queries		
<b>Date:</b>		20.06.2022		
<b>BYPL NIT NO:</b>		CMC/BY/21-22/RS/SvS/AS/12 DT: 13.05.2022		
<b>Work:</b>		Award of Contract for Repairing and Servicing of Damaged/Failed Oil Filled Distribution Transformers of various Rating at BYPL's Workshop		
Sl.No	Clause Reference	Description	Bidder's Query	BYPL Response
1	Section-IV, Scope of Work, Annexure -1	Repairing : terms & condition for Repairing of DT : Vendors to provide : Minimum no. of 19 nos. of dedicated Manpower is required to maintain quantity ,quality, decorum, safety and proper monitoring. Supervisor -1 no.,Main Technician -01 No.,Certified Welder – 1 no. ,Skilled workers – 10 nos. ( Winder or coil fabricator, Core coil tanker and un-tanker , Core coil assembler ),Semiskilled – 4 nos.Painter – 1 no. ,Housekeeping – 1 no.	Remove this point as manpower requirement is changed as per requirement	> Minimum 12 nos. of dedicated Manpower (Supervisor -1 no., Main Technician -01 no., Skilled workers – 10 nos inclusive of Winder or coil fabricator, Core coil tanker and un-tanker , Core coil assembler) are required to maintain quantity ,quality, decorum, safety and proper monitoring.  > Manpower given above are minimum requirement only. However, contractor has to deploy the additional manpower as per requirement of the work and direction of BYPL Engineer in charge.
2	Section-I, RFQ, QR-CI 1.3 (iv), page 5	Bidder must provide proof of having solvency of an amount equal to Rs. 50 Lacs or more from any nationalized/ scheduled commercial bank. (Not older than 1st April 2022).	1) Solvency certificate :- kindly wave off the solvency certificate clause because we are a regular vendor with your extreme organization for long time. 2) Please consider solvency of Rs 25 Lacs in place of Rs 50 Lacs.	Bidder must provide proof of having solvency of an amount equal to Rs. 25 Lacs or more from any nationalized/ scheduled commercial bank. (Not older than 1st April 2022).